

FINAL

**PRE-DEMOLITION  
HAZARDOUS BUILDING MATERIALS ASSESSMENT  
FORMER CONSTRUCTION CAMP SITES  
BAY D'ESPOIR – AVALON TRANSMISSION LINE (TL202/TL206)  
NEWFOUNDLAND AND LABRADOR**

Submitted to:

**Newfoundland and Labrador Hydro,  
a Nalcor Energy Company**  
Hydro Place, 500 Columbus Drive  
PO Box 12400  
St. John's, NL A1B 4K7

Submitted by:

**Wood Environment & Infrastructure Solutions,  
a Division of Wood Canada Limited**  
133 Crosbie Road  
PO Box 13216  
St. John's, NL A1B 4A5

April 2019

Wood Project #: TF18104243.2000

#### **IMPORTANT NOTICE**

This report was prepared exclusively for Newfoundland and Labrador Hydro (Hydro), a Nalcor Energy Company, by Wood Environment & Infrastructure Solutions, a Division of Wood Canada Limited (Wood). The quality of information, conclusions and estimates contained herein is consistent with the level of effort involved in Wood's services and based on: i) information available at the time of preparation, ii) data supplied by outside sources and iii) the assumptions, conditions and qualifications set forth in this report. This report is intended to be used by Hydro only, subject to the terms and conditions of its contract with Wood. Any other use of, or reliance on, this report by any third party is at that party's sole risk.

## EXECUTIVE SUMMARY

Wood Environment & Infrastructure Solutions, a Division of Wood Canada Limited (Wood), was retained by Newfoundland and Labrador Hydro (Hydro), a Nalcor Energy Company, to conduct a Pre-Demolition Hazardous Building Materials Assessment (HBMA) of six (6) former construction camp sites (Camp #1, Camp #2, Mitchell's Pond Camp, Hungry Grove Camp, Camp 100 and Medonnegonik Lake Camp) located along the Bay d'Espoir – Avalon Transmission Line TL202 and TL206 and recently constructed TL267 (BDE – Avalon TL), herein referred to as the "sites". This assessment was required to provide Hydro with an evaluation of known and potential hazardous building materials in the cabins and other related infrastructure at the sites that are slated for demolition, herein referred to as the "site buildings".

During the construction of the BDE Hydroelectric Generating Station, which was developed the late 1960's/early 1970's, approximately 840 kilometres (km) of high-voltage transmission lines were built (running east to west) to facilitate a province-wide power network that connected St. John's, BDE, Grand Falls, Corner Brook and Stephenville. During the construction phase, six (6) camps were set-up along the right-of-way (RoW) of the transmission line and used as accommodations for construction personnel. Each camp site typically contained a cabin, an outhouse and a drum storage area.

A newly built 188-km, high voltage transmission line (TL267) was completed by Hydro between BDE and the Avalon Peninsula and placed into service in early December 2017. The new 230 kilovolt (kV) transmission line's route parallels two existing transmission lines between the BDE Generating Station and the Western Avalon Terminal Station near Chapel Arm. As the former construction camps have not been in use within the past 15 years, Hydro plans to decommission these sites and demolish and remove all associated camp infrastructure.

The former construction camp sites are situated throughout the Bay Du Nord Wilderness Reserve, between the communities of Conne River and Swift Current, near the southeastern coast of Newfoundland. The two eastern most camp sites (Camp #1 and Camp #2) are currently accessible by gravel access road from the Burin Peninsula Highway (Route 210) in the community of Swift Current (near Piper's Hole River). The other four camp sites (Mitchell's Pond Camp, Hungry Grove Camp, Camp 100 and Medonnegonik Lake Camp) are currently assessable by gravel access road from the BDE Highway (Route 360) in the community of Conne River, near the Jipujjkiei Kuespem Provincial Park.

The objectives of the Pre-Demolition HBMA were to determine if hazardous building materials are present in the site buildings and to identify the condition and approximate quantity of these materials. The scope of work for the Pre-Demolition HBMA was completed in accordance with Wood's workplan entitled, "*Professional Services for Six (6) Construction Camp Sites, Bay d'Espoir – Avalon Transmission Line, Newfoundland and Labrador – Workplan for Phase I/II Environmental Site Assessment and Pre-Demolition Hazardous Building Materials Assessment*". It is important to note that the Phase I/II Environmental Site Assessment is provided under separate report cover.

This HBMA report is structured in the following manner:

**Table 1-1: Report Structure**

| <b>Section</b> | <b>Description</b>                     | <b>Appendices</b> |
|----------------|--|-------------------|
| 1.0            | Introduction                           | A1 to B1          |
| 2.0            | Findings - Camp #1 Site                | A2 to D2          |
| 3.0            | Findings - Camp #2 Site                | A3 to D3          |
| 4.0            | Findings - Mitchell's Pond Camp Site   | A4 to D4          |
| 5.0            | Findings - Hungry Grove Camp Site      | A5 to D5          |
| 6.0            | Findings - Camp 100 Site               | A6 to D6          |
| 7.0            | Findings - Medonnegonik Lake Camp Site | A7 to D7          |
| 8.0            | Closure                                | A8 to D8          |
| 9.0            | References                             |                   |

For reporting purposes, the findings, conclusions and recommendations for future actions, where warranted, for each site has been provided in a separate section within the report. It is also important to note that the report has been structured such that each section includes a separate table of contents.

## TABLE OF CONTENTS

|  |    |
|--|----|
| EXECUTIVE SUMMARY .....  | I  |
| 1.0 INTRODUCTION .....   | 1  |
| 1.1 Background.....  | 1  |
| 1.2 Site Description.....  | 1  |
| 1.2.1 Camp 1.....  | 1  |
| 1.2.2 Camp 2.....  | 2  |
| 1.2.3 Mitchell’s Pond Camp.....                                      | 2  |
| 1.2.4 Hungry Grove Camp.....   | 2  |
| 1.2.5 Camp 100.....  | 2  |
| 1.2.6 Medonnegonik Lake Camp .....                                   | 2  |
| 1.3 Report Structure .....   | 3  |
| 1.4 Objectives.....  | 3  |
| 1.5 Scope of Work.....   | 3  |
| 1.6 Environmental Regulatory Framework .....                         | 4  |
| 1.6.1 Asbestos-containing Materials.....                             | 5  |
| 1.6.2 Lead in Paint .....  | 6  |
| 1.6.3 Mercury in Paint.....  | 6  |
| 1.6.4 PCBs in Paint and Other Materials.....                         | 7  |
| 1.6.5 Mould Impacted Materials.....                                  | 7  |
| 1.6.6 Treated Wood Chemicals .....                                   | 8  |
| 1.7 Methodology .....  | 8  |
| 1.7.1 Visual Inspection.....   | 8  |
| 1.7.2 Bulk Material Sampling and Laboratory Analytical Program ..... | 9  |
| 1.7.3 Paint Sampling and Laboratory Analytical Program.....          | 9  |
| 1.8 Quality Assurance / Quality Control Program .....                | 10 |

## LIST OF APPENDICES

- APPENDIX A1: FIGURES
- APPENDIX B1: PHOTOGRAPHIC RECORD

## 1.0 INTRODUCTION

Wood Environment & Infrastructure Solutions, a Division of Wood Canada Limited (Wood), was retained by Newfoundland and Labrador Hydro (Hydro), a Nalcor Energy Company, to conduct a Pre-Demolition Hazardous Building Materials Assessment (HBMA) of six former construction camp sites (Camp 1, Camp 2, Camp 100, Hungry Grove Camp, Medonnegonik Lake Camp and Mitchell's Pond Camp) located along the Bay d'Espoir – Avalon Transmission Line TL202 and TL206 and recently constructed TL267 (BDE-Avalon TL), herein referred to as the "sites". This assessment was required to provide Hydro with an evaluation of known and potential hazardous building materials in cabins and other related infrastructure at the sites that are slated for demolition, herein referred to as the "site buildings".

### 1.1 Background

During the construction of the BDE Hydroelectric Generating Station, which was developed in the late 1960's/early 1970's, approximately 840 kilometres (km) of high-voltage transmission lines were built (running east to west) to facilitate a province-wide power network that connected St. John's, BDE, Grand Falls, Corner Brook and Stephenville. During the construction phase, six (6) camps were set-up along the right-of-way (RoW) of the transmission lines and used as accommodations for construction personnel. Each camp site typically contained a cabin, an outhouse and a drum storage area.

A newly built 188-km, high voltage transmission line (TL267) was completed by Hydro between BDE and the Avalon Peninsula and placed into service in early December 2017. The new 230 kilovolt (kV) transmission line's route parallels two existing transmission lines between the BDE Generating Station and the Western Avalon Terminal Station near Chapel Arm. As the former construction camps have not been in use within the past 15 years, Hydro plans to decommission these sites and demolish and remove all associated camp infrastructure.

### 1.2 Site Description

The six former construction camp sites are situated throughout the Bay Du Nord Wilderness Reserve, between the communities of Conne River and Swift Current, near the southeastern coast of Newfoundland (refer to Figure 1.1, Appendix A1). The two eastern most camp sites (Camp 1 and Camp 2) are currently accessible by gravel access road from the Burin Peninsula Highway (Route 210) near the community of Swift Current (near Piper's Hole River). The other four camp sites (Mitchell's Pond Camp, Hungry Grove Camp, Camp 100 and Medonnegonik Lake Camp) are currently assessable by gravel access road from the BDE Highway (Route 360) in the community of Conne River, near the Jipujjkkuei Kuespem Provincial Park. Access bridges were scheduled to be removed, subsequently, access to the sites are limited to either all terrain vehicle (ATV) or a helicopter.

#### 1.2.1 Camp #1

Camp #1 site is comprised of an accommodations cabin and an outhouse (refer to Photos 1 and 2, Appendix B1). The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 61 m<sup>2</sup>. The floor plan of the cabin consists of a kitchen, a bedroom and a washroom, with an attached generator shed. The outhouse is a one-storey, rectangular structure with a footprint area of approximately 3 m<sup>2</sup>.

## **1.2.2 Camp #2**

Camp #2 site is comprised of an accommodations cabin and an outhouse (refer to Photos 3 and 4, Appendix B1). The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 61 m<sup>2</sup>. The floor plan of the cabin consists of a kitchen, a bedroom and a washroom, with an attached generator shed. The outhouse is a one-storey, rectangular structure with a footprint area of approximately 4 m<sup>2</sup>.

## **1.2.3 Mitchell's Pond Camp**

Mitchell's Pond Camp site is comprised of an accommodations cabin and an outhouse (refer to Photos 5 and 6, Appendix B1). The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 71 m<sup>2</sup>. The floor plan of the cabin consists of a kitchen with a bunk area, a pantry and a washroom. The outhouse is a one-storey, rectangular structure with a footprint area of approximately 3 m<sup>2</sup>.

## **1.2.4 Hungry Grove Camp**

Hungry Grove Camp site is comprised of an accommodations cabin and an outhouse (refer to Photos 7 and 8, Appendix B1). The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 67 m<sup>2</sup>. The floor plan of the cabin consists of a kitchen with a bunk area and three other rooms. The northwest side of the cabin, which contains the three rooms, appears to be an add-on section (date of construction unknown). The outhouse is a one-storey, rectangular structure with a footprint area of approximately 3 m<sup>2</sup>.

## **1.2.5 Camp 100**

Camp 100 site is comprised of an accommodations cabin and an outhouse (refer to Photos 9 and 10, Appendix B1). The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 66 m<sup>2</sup>. The floor plan of the cabin consists of a kitchen with a bunk area, a pantry and a storage room. The outhouse is a one-storey, rectangular structure with a footprint area of approximately 3 m<sup>2</sup>.

## **1.2.6 Medonnegonik Lake Camp**

Medonnegonik Lake Camp site is comprised of an accommodations cabin, an outhouse and a helipad (refer to Photos 11, 12 and 13, Appendix B1). The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 67 m<sup>2</sup>. The floor plan of the cabin consists of a kitchen with a bunk area, a washroom, a porch and a bedroom. The east side of the cabin, which contains the washroom, porch and bedroom, appears to be an add-on section (date of construction unknown). The outhouse is a one-storey, rectangular structure with a footprint area of approximately 3 m<sup>2</sup>. The helipad is a rectangular platform structure with a footprint area of approximately 15 m<sup>2</sup>.

### 1.3 Report Structure

This HBMA report is structured in the following manner:

- Section 1.0: Introduction
- Section 2.0: Findings - Camp #1
- Section 3.0: Findings - Camp #2
- Section 4.0: Findings - Mitchell's Pond Camp
- Section 5.0: Findings - Hungry Grove Camp
- Section 6.0: Findings - Camp 100
- Section 7.0: Findings - Medonnegonik Lake Camp
- Section 8.0: Closure

For reporting purposes, the findings, conclusions and recommendations for future actions, where warranted, for each site has been provided in a separate section within the report. It is also important to note that the report has been structured such that each section includes a separate table of contents.

### 1.4 Objectives

The objectives of the Pre-Demolition HBMA were to determine if hazardous building materials are present in the site buildings and to identify the condition and approximate quantity of these materials.

### 1.5 Scope of Work

The scope of work for the HBMA, as per Wood's workplan<sup>1</sup> included:

- Preparing a site-specific Health and Safety Plan (HASP) and submitting the plan to Hydro.
- Conducting a site reconnaissance to visually inspect potential hazardous building materials within the site buildings, including:
  - Asbestos-containing materials (ACMs);
  - Lead-based paint (LBP) and other lead-containing materials or equipment;
  - Mercury-based paint (MBP) and other mercury-containing materials or equipment;
  - Polychlorinated biphenyl (PCB)-based paint and other PCB-containing materials;
  - Treated timber materials;
  - Urea formaldehyde foam insulation (UFFI);
  - Suspected visible mould growth (SVG); and
  - Other potentially hazardous building materials and equipment.

---

<sup>1</sup> Wood. June 19, 2018. Professional Services for Six (6) Construction Camp Sites, Bay d'Espoir – Avalon Transmission Line, Newfoundland and Labrador – Workplan for Phase I/II Environmental Site Assessment and Pre-Demolition Hazardous Building Materials Assessment. Prepared for Newfoundland and Labrador Hydro, Environmental Services.



- Inspecting all accessible thermostats to assess the presence or absence of mercury-containing switches.
- Documenting the number and type of fluorescent light fixtures identified during the assessment.
- Documenting the location of any fire-rated doors identified during the assessment.
- Documenting the location of ozone depleting substance (ODS)-containing appliances and equipment identified during the assessment.
- Performing cavity inspections to attempt to identify any hidden and potentially hazardous building materials that may be concealed by walls or ceiling systems.
- Sampling and laboratory testing of suspected ACMs to confirm the presence or absence of asbestos fibres.
- Sampling and laboratory testing of paint to determine the concentrations of lead and mercury, and if warranted based on the concentrations of lead and mercury, laboratory testing of paint for lead and mercury leachate using the Toxicity Characteristic Leaching Procedure (TCLP) to determine proper disposal options for painted materials.
- Sampling and laboratory testing of paint and other suspected PCB-containing materials to determine the concentrations of PCBs.
- Sampling and laboratory testing of suspected mould impacted materials to confirm the presence or absence of mould.
- Depending on the type of chemical treatment applied, sampling and laboratory testing of treated timber materials to determine the concentrations of “pressure treated” inorganic preservatives, creosote or chlorophenolic formulations using the TCLP to determine proper disposal options for treated timber materials.
- Preparing a written report documenting the methodologies and findings of the Pre-Demolition HBMA, with recommendations for handling and disposal of any identified hazardous materials.

The findings of the Pre-Demolition HBMA were based on the interpretation of data from the areas investigated and analytical results pertaining to specific samples collected and tested. It is possible that materials exist that could not be reasonably identified within the scope of the work or which were not apparent or accessible during the site visit.

Inspecting accessible fluorescent lights for PCB-containing light ballasts and sampling of potential PCB-containing electrical cables or equipment was not included in the scope of work for the Pre-Demolition HBMA.

## 1.6 Environmental Regulatory Framework

The federal and provincial governments in Canada have prepared and/or adopted numerous acts, regulations, guidelines, policies, and procedures related to the protection of the environment and the investigation of sites containing hazardous building materials. Regulations and guidelines that were used to evaluate analytical results for samples of suspected hazardous materials collected during this assessment are discussed in the following sections.

## 1.6.1 Asbestos-containing Materials

There are over 3,000 ACMs that are commercially available, which can be divided into two broad categories: friable and non-friable. Friable ACMs are defined as materials that can be crumbled, pulverized and reduced to powder when dry using hand pressure. Typical friable materials include acoustical or decorative spray applications, fireproofing and thermal insulation. Non-friable ACMs are hard or manufactured products such as floor tiles, fire blankets, pre-formed manufactured cementitious insulation and wallboards, pipes, and siding, wherein the asbestos fibres are bound to the substrate. Although a product may be considered non-friable when new, the product may release fine dust when disturbed (e.g., deterioration, removal, renovation) and the free dust is considered friable.

Asbestos products are subject to various prohibitions and restrictions under Provincial and Federal legislation. While ACMs are still manufactured globally and were available for limited use in Canada prior to 2019, the building products available since the late 1980s to early 1990s tend to be low risk, non-friable materials. Buildings constructed between 1986 and 1990 are unlikely to contain high risk ACMs such as mechanical or spray applied insulation and newer buildings (post-1992) are less likely to contain non-friable ACMs.

In October 2018, new and more stringent Federal regulations were finalized in Canada which prohibit the import, sale and use of asbestos, as well as the manufacture, import, sale and use of products containing asbestos, with a limited number of exclusions. These new regulations, entitled "*Prohibition of Asbestos and Asbestos Products Regulations*", officially came into force on December 30, 2018 and repeal the former *Asbestos Products Regulations*. However, these regulations do not apply to asbestos that is integrated into a structure or infrastructure if the integration occurred before the day on which these regulations came into force.

The legislative requirements for safe handling of ACMs in workplaces in the Province of NL are currently provided in the *NL Asbestos Abatement Regulations (Reg. 111/98)*, under the *NL Occupational Health and Safety Act*. In accordance with these Provincial regulations, all buildings constructed during the period when asbestos was readily used in construction must have a written assessment and management plan (where applicable) for potential ACMs. The *NL Asbestos Abatement Regulations* define materials containing greater than 1% asbestos by dry weight as ACMs. It is also important to consider, in the event that asbestos is detected in a material at a level less than 1%, while it is not considered a regulated ACM under these Provincial regulations, the material would be subject to control measures under the *NL Occupational Health and Safety Regulations*.

In addition to the *NL Asbestos Abatement Regulations (Reg. 111/98)*, there are Provincial guidance documents available for low risk (Type I) and moderate risk (Type II) asbestos abatement. These guidelines were issued by the NL Occupational Health and Safety (OHS) Division in July 2010 and are entitled, "*Low Risk Asbestos Abatement Projects*" and "*Moderate Risk Asbestos Abatement Projects*". High risk asbestos abatement activities or those outside the scope of these guidelines are still required to follow the *NL Asbestos Abatement Regulations (Reg. 111/98)*.

The NL OHS Division may also require additional controls than those included in these guidance documents. All asbestos abatement projects require the completion of a risk assessment by a competent individual and the work procedures must be modified accordingly.

## 1.6.2 Lead in Paint

Lead compounds have been used in paint as pigment and durability additives since the early 1800s. The *Surface Coating Material Regulations*, under the *Canada Consumer Product Safety Act*, state that a surface coating material must not contain more than 90 mg/kg total lead when a dried sample is tested in accordance with a method that conforms to good laboratory practices. These regulations define a surface coating material as a paint or other similar material, with or without pigment, that dries to a solid film after it is applied to a surface but does not include material that becomes a part of the substrate. It is important to consider, in the event that lead is detected in paint or other surface coating materials at a concentration less than 90 mg/kg, while it is not considered a LBP in accordance with the *Surface Coating Material Regulations*, the paint would be subject to control measures under the *NL Occupational Health and Safety Regulations*.

Prior to the *Canada Consumer Product Safety Act*, lead in surface coating materials was regulated under the *Federal Hazardous Products Act*. In 1976, the *Liquid Coating Materials Regulations*, under the *Hazardous Products Act*, restricted the lead content of paints and other liquid coatings on furniture, household products, children's products, and exterior and interior surfaces of any building frequented by children to 0.5% by weight (5,000 mg/kg). In order to determine disposal options, the former *Hazardous Products Act* criterion of 5,000 mg/kg lead in paint is typically used as a Provincial disposal guideline to determine whether or not paint samples should be submitted for leachate analysis. Paint samples that contain less than 5,000 mg/kg are not likely to be leachable, and therefore, may be disposed of at an approved landfill facility, pending landfill and Provincial regulatory approval. Paint samples with lead concentrations in excess of 5,000 mg/kg should be subjected to leachability testing.

The NL Department of Environment (currently the NL Department of Municipal Affairs and Environment (MAE)), 2003 Guidance Document for Leachable Toxic Waste, Testing and Disposal (GD-PPD-26.1) guideline of 5.00 mg/L lead should be used to assess the results of the leachability testing to determine disposal options for any lead-containing paint to be removed during renovation or demolition activities. Any paints that require disposal and exceed the lead leachate guideline are considered to be leachable toxic waste and must be disposed of at an approved hazardous waste disposal site and not a landfill disposal site.

## 1.6.3 Mercury in Paint

Mercury compounds have been used in paint as anti-microbial additives up until the 1990s. The *Surface Coating Material Regulations*, under the *Canada Consumer Product Safety Act*, state that a surface coating material must not contain more than 10 mg/kg total mercury when a dried sample is tested in accordance with a method that conforms to good laboratory practices. It is important to consider, in the event that mercury is detected in paint or other surface coating materials at a concentration less than 10 mg/kg, while it is not considered a MBP under the *Surface Coating Material Regulations*, the paint would be subject to control measures under the *NL Occupational Health and Safety Regulations*.

In order to determine disposal options, the Canadian Council of Ministers of the Environment (CCME) Canadian Soil Quality Guidelines (CSQG) criterion of 50 mg/kg for mercury in soil at an industrial site is typically used as a Provincial disposal guideline to determine whether or not paint samples should be submitted for leachate analysis. Paint samples with a mercury concentration of less than 50 mg/kg are not likely to be leachable, and

therefore, may be disposed of at an approved landfill facility, pending landfill and Provincial regulatory approval. Paint samples with a mercury concentration in excess of 50 mg/kg should be subjected to leachability testing.

The NL Department of Environment (currently the NL MAE), 2003 Guidance Document for Leachable Toxic Waste, Testing and Disposal (GD-PPD-26.1) guideline of 0.10 mg/L mercury should be used to assess the results of the leachability testing to determine disposal options for any mercury-containing paint to be removed during renovation or demolition activities. Any paints that require disposal and exceed the mercury leachate guideline are considered to be leachable toxic waste and must be disposed of at an approved hazardous waste disposal site and not a landfill disposal site.

### **1.6.4 PCBs in Paint and Other Materials**

PCBs were used in paint as plasticizers and corrosion resistance additives from the 1950s to the 1970s.

Analytical results for PCBs in paint and/or other materials (i.e., caulking, sealants, tar, etc.) were compared to the CCME CSQG criterion of 33 mg/kg for PCBs in soil at an industrial site. The Federal HPA does not include any assessment criteria for PCBs in paint.

In order to determine disposal options for paint and/or other suspected PCB-containing materials, concentrations of PCBs in building materials should be compared to the criterion of 50 mg/kg for PCB solid provided in the NL Department of MAE, 2003 Guidance Document for Leachable Toxic Waste, Testing and Disposal (GD-PPD-26.1) and the Federal Transportation of Dangerous Goods (TDG) Regulations. Any building materials (i.e., paints, caulking, etc.) that require disposal and exceed the PCB solid criterion must be disposed of at an approved hazardous waste disposal site and not a landfill disposal site.

### **1.6.5 Mould Impacted Materials**

There are currently no regulations in Canada specifically covering exposure to mould, and there are no occupational exposure limits that define acceptable levels of mould exposure without adverse health effects. However, Section 4 of the *NL Occupational Health and Safety Act* states that an employer shall ensure, where it is reasonably practicable, the health, safety and welfare of his or her workers, and Section 42 of the *NL Occupational Health and Safety Regulations* states that an employer shall monitor the use or presence of substances at the workplace that may be hazardous to the health and safety of workers. This includes exposure to moulds and other biological matter. Since there are no clear regulatory limits for determining an acceptable exposure limit to moulds, there is no numerical guideline for determining safe or unsafe concentrations of surface mould growth. Therefore, interpretation of sampling results is subjective.

Although there are currently no regulations for mould remediation practices, there are mould assessment and remediation guidelines available in Canada. The Canadian Construction Association (CCA)<sup>2</sup> and the Environmental Abatement Council of Ontario (EACO)<sup>3</sup> have developed guidelines that are intended to provide safe work practices for workers involved in mould abatement/remediation. In recent years remediation strategies have been based (in part) on the quantity of mould observed, assuming that potential exposure increases with an

---

<sup>2</sup> CCA. 2018. Mould Guidelines for the Canadian Construction Industry.

<sup>3</sup> EACO. 2015. EACO Mould Abatement Guidelines, Edition 3.

increase in overall mould concentrations. The risk criteria used during this assessment was based on the 2015 EACO guidelines.

### **1.6.6 Treated Wood Chemicals**

The chemicals that are used to protect and preserve wood products from insect attack and fungal decay may pose risks to human health and the environment. Depending on the wood treatment used, treated wood materials may be considered hazardous waste upon disposal.

In order to determine disposal options for treated wood materials, depending on the type of chemical treatment applied, treated wood samples should be subjected to leachability testing. The NL Department of MAE (formerly NL Department of Environment), 2015 Guidance Document for Treated Wood Waste Disposal (GD-PPD-075.1) landfill disposal standards should be used to assess the results of leachability testing to determine disposal options for any treated wood waste (TWW) to be removed during any disturbance, demolition or renovation activities. Any TWW that requires disposal and exceeds the applicable landfill disposal standards is considered to be leachable toxic waste and must be disposed of at an approved hazardous waste disposal site and not a landfill disposal site.

## **1.7 Methodology**

The following sections present the methodology of the document review, visual inspection (intrusive and non-intrusive), bulk material and paint sampling, laboratory analytical program, and QA/QC program for the HBMA. Various site visits were conducted between July 30 and October 4, 2018 after regular working hours. Wood field personnel were accompanied at all times while on-site by building security personnel (Canadian Corps of Commissionaires).

The site inspection and sampling for the Pre-Demolition HBMA were conducted by Wood personnel on August 7, 8 and 13, 2018. Wood was accompanied by a representative of Hydro (Environmental Coordinator) during the site visit.

### **1.7.1 Visual Inspection**

A site reconnaissance was conducted to visually inspect potential hazardous building materials, including potential ACMs, LBPs, MBPs, and other potential hazardous building materials and equipment. The inspection also included searching for visible signs or evidence of water staining/damage, excess moisture/infiltration and mould growth, and identifying potential sources of ODS. Thermostats (if present) were visually inspected by removing the casings and checking for the presence of mercury-containing switches. In addition, a survey of fire-rated doors was completed, which included searching for fire-rating labels located on the hinge side or top edge of doors and on the hinge side of door frames.

Intrusive cavity inspections were performed (where possible) at pre-selected locations throughout the site buildings by removing ceiling and floor panels, opening wall/ceiling access hatches, and where necessary, by cutting holes in the drywall surfaces of walls/ceilings to create openings for visual inspection and to allow access to sample any suspected hazardous building materials, if identified.

## 1.7.2 Bulk Material Sampling and Laboratory Analytical Program

Building materials suspected of containing asbestos or suspected of being impacted by mould growth were sampled by removing a 2.0 cm by 2.0 cm piece of material (where possible) and placing the sampled materials into Glad® or Ziploc® plastic bags. Building materials suspected of containing PCBs (e.g., caulking) were sampled by cutting and removing a 2.0 cm long piece of material (where possible) and placing the sampled materials into Glad® or Ziploc® plastic bags. Building materials suspected of containing wood preservatives were sampled by cutting off a 2.5 cm thick section of the material (where possible) using a reciprocating saw and placing the sampled materials into Glad® or Ziploc® plastic bags.

Bulk material samples suspected of containing asbestos were submitted to the EMSL Canada Inc. (EMSL) laboratory located in Mississauga, Ontario (ON) for the analysis of asbestos using Polarized Light Microscopy (PLM) with dispersion staining. The analysis was conducted in accordance with the United States Environmental Protection Agency (USEPA) Method EPA 600/R-93/116 (Method for the Determination of Asbestos in Bulk Building Materials). EMSL is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) and the American Industrial Hygiene Association (AIHA) for bulk asbestos fibre analysis by PLM.

Bulk material samples suspected of being impacted by mould growth were submitted to the EMC Scientific Inc. (EMC) laboratory located in Mississauga, ON for direct microscopic examination (DME) to identify the type of mould to the genus level. EMC is an AIHA Environmental Microbiology Proficiency Analytical Testing (EMPAT) program participant.

Bulk material samples suspected of containing PCBs were submitted to the AGAT Laboratories (AGAT) branch located in St. John's, NL for the analysis of PCBs. The analysis of PCBs was conducted in accordance with EPA Method 8082A (SW-846) using gas chromatography (GC).

Bulk material samples suspected of containing wood preservatives were submitted to the AGAT laboratory branch located in St. John's, NL for the analysis of TCLP analyses of arsenic, chromium, benzo(a)pyrene and pentachlorophenol.

## 1.7.3 Paint Sampling and Laboratory Analytical Program

Paint samples were collected from painted surfaces by cutting out a section of painted drywall paper or by scraping areas of flaking paint from hard surfaces using clean knives and scrapers. Samples were collected down to bare substrate (e.g., drywall, concrete and wood) and in some instances included the substrate (e.g., wood and drywall paper). A minimum of 15 grams (where possible) of paint was obtained from each sampling location and the samples were placed in Glad® or Ziploc® plastic bags.

Paint samples were submitted to the AGAT Laboratories (AGAT) laboratory located in Dartmouth, Nova Scotia (NS) for the analysis of lead and mercury. The lead analysis was conducted in accordance with the EPA 6020A/3050B (SW-846), method analysis for metals using inductively coupled plasma – mass spectrometry (ICP-MS) and acid digestion. The mercury analysis was conducted in accordance with EPA methods 245.5 and SM3112B using cold vapour atomic absorption spectroscopy (CV/AAS). AGAT is accredited under the Standards Council of Canada (SCC) to perform analysis of lead and mercury in paint.

Paint samples were also submitted to the AGAT branch located in St. John's, NL for the analysis of lead, mercury, leachable lead, leachable mercury and PCBs. The analyses of lead, mercury and leachable lead was conducted in accordance with EPA 6020A using inductively coupled plasma – mass spectrometry (ICP-MS). The analysis of leachable mercury was conducted in accordance with EPA 245.1 using cold vapor atomic absorption (CVAA). The analysis of PCBs was conducted in accordance with EPA Method 8082A (SW-846) using GC. Maxxam is accredited under the Standards Council of Canada (SCC) to perform analysis of lead, mercury and PCBs in paint samples.

## 1.8 Quality Assurance / Quality Control Program

Laboratory blanks, duplicates and quality control (QC) standard samples were analyzed to assess the reliability of the analyses. In order to minimize cross contamination during sampling, a field quality assurance / quality control (QA/QC) program was implemented, which included the following measures:

- Latex or nitrile gloves were worn during sampling (i.e., new pair of gloves used for each sample).
- All sampling equipment was thoroughly cleaned prior to sampling to ensure that samples were unaffected by cross-contamination from previous samples.
- Each sample was photographed, given a unique sample ID and logged onto a chain of custody form before shipment to the laboratory.

The laboratories utilized have extensive QA/QC programs in place to ensure that reliable results are consistently obtained. Some of the specific laboratory QA/QC measures include:


- Chain of Custody and sample integrity inspection.
- Strict documentation control and files.
- Trained personnel prepare and analyze samples according to Standard Operating Procedures (SOPs).
- All analytical methods are based on accepted procedures and are fully validated prior to use.
- Precision is monitored by performing replicate analysis of samples.
- Accuracy is verified by analyzing spiked samples and reference materials.
- Instrument calibration integrity is ensured by analyzing calibration check standards within each run sequence.
- Extensive use is made of reference material for routine procedure evaluation.
- Highest available purity analytical standards.
- Predefined analytical sequences ensure all results are traceable to calibration and QC data.
- Hard copy reports displaying all of the required data are generated for each instrument.
- Analytical results are determined only from instrument responses that fall within the calibration range.
- Acceptable QC performance must be demonstrated prior to data authorization.
- On-going method and instrument performance records are maintained for all analysis.
- A full-time QA Scientist evaluates the QA program on an on-going basis.

Hydro  
Pre-Demolition HBMA, Former Construction Camp Sites, BDE – Avalon TL, NL (Final)  
Section 1.0: Introduction  
Wood Project #: TF18104243.2000  
April 2019



## **APPENDIX A1: FIGURES**






**NOTES:**  
 THIS DRAWING BASED ON 1:50,000 TOPOGRAPHIC MAPS 01 M/14, 01 M/15, 02 D/02 AND 02 D/03.  
 THIS DRAWING IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION IN SUPPORT OF THIS REPORT.

**NOTES:**  
 1. ALL DIMENSIONS ARE IN METERS.  
 2. DO NOT SCALE FROM FIGURE.  
 3. THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.  
 4. ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.  
 5. THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.  
 6. THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



newfoundland labrador  
 a nalcor energy company

**Wood**  
 Environment & Infrastructure Solutions  
 133 Crosbie Road  
 St. John's, NL A1B 4A5  
 709-722-7023



Drawn by:  
T. Rideout

Approved by:  
C. Finney

Scale:  
NTS

Project:  
Pre-Demolition Hazardous Building Materials Assessment,  
Former Construction Camp Sites,  
Bay d'Espoir - Avalon Transmission Line, NL

Title:  
Site Location Plan

Date:  
April 2019

Project No.  
TF18104243.2000

Rev. No.  
0

Figure No.  
1.1

Hydro  
Pre-Demolition HBMA, Former Construction Camp Sites, BDE – Avalon TL, NL (Final)  
Section 1.0: Introduction  
Wood Project #: TF18104243.2000  
April 2019



## **APPENDIX B1: PHOTOGRAPHIC RECORD**



Photo 1: View of accomodations cabin at Camp #1.



Photo 2: View of the outhouse at Camp #1.



Photo 3: View of accomodations cabin at Camp #2.



Photo 4: View of the outhouse at Camp #2.



Photo 5: View of accomodations cabin at Camp 100.



Photo 6: View of the outhouse at Camp 100.



Photo 7: View of accomodations cabin at Hungry Grove Camp.



Photo 8: View of the outhouse at Hungry Grove Camp.



Photo 9: View of accomodations cabin at Medonnegonik Camp.



Photo 10: View of the outhouse at Medonnegonik Camp.



Photo 11: View of accomodations cabin at Mitchell's Pond Camp.



Photo 12: View of the outhouse at Mitchell's Pond Camp.

## TABLE OF CONTENTS

|         |   |      |
|---------|---|------|
| 2.0     | CAMP # 1 SITE.....  | 2-1  |
| 2.1     | BUILDING DESCRIPTION .....  | 2-1  |
| 2.2     | ROOM DESIGNATION .....  | 2-2  |
| 2.3     | FINDINGS .....  | 2-2  |
| 2.3.1   | Asbestos-Containing Materials (ACMs).....                         | 2-3  |
| 2.3.1.1 | Friable Materials.....  | 2-3  |
| 2.3.1.2 | Non-Friable and Potentially Friable Materials.....                | 2-3  |
| 2.3.2   | Paint Additives .....   | 2-5  |
| 2.3.2.1 | Lead in Paint.....  | 2-5  |
| 2.3.2.2 | Mercury in Paint.....   | 2-6  |
| 2.3.2.3 | PCBs in Paint.....  | 2-6  |
| 2.3.3   | Urea Formaldehyde Foam Insulation (UFFI).....                     | 2-6  |
| 2.3.4   | Suspected Visible Mould Growth (SVG) .....                        | 2-6  |
| 2.3.5   | Mercury-Containing Thermostats.....                               | 2-6  |
| 2.3.6   | PCB-Containing Light Ballasts.....                                | 2-6  |
| 2.3.7   | Potential Sources of ODS and Halocarbons .....                    | 2-7  |
| 2.3.8   | Other Potentially Hazardous Building Materials or Substances..... | 2-7  |
| 2.3.8.1 | Lead-Containing Materials and Equipment.....                      | 2-7  |
| 2.3.8.2 | Mercury-Containing Materials and Equipment.....                   | 2-7  |
| 2.3.8.3 | PCB-Containing Materials and Equipment.....                       | 2-7  |
| 2.3.8.4 | Treated Wood Chemicals .....                                      | 2-8  |
| 2.3.8.5 | Silica.....   | 2-8  |
| 2.3.8.6 | Radioactive Materials.....  | 2-8  |
| 2.4     | CONCLUSIONS AND RECOMMENDATIONS .....                             | 2-8  |
| 2.4.1   | ACMs.....   | 2-8  |
| 2.4.2   | Lead, Mercury and PCBs in Paint.....                              | 2-10 |
| 2.4.3   | Potential UFFI.....   | 2-11 |
| 2.4.4   | Mould .....   | 2-12 |
| 2.4.5   | Potential ODS .....   | 2-12 |
| 2.4.6   | Potential Lead-Containing Materials/Equipment .....               | 2-12 |
| 2.4.7   | Potential Mercury-Containing Materials/Equipment .....            | 2-13 |
| 2.4.8   | Potential PCB-Containing Materials/Equipment.....                 | 2-13 |
| 2.4.9   | Silica Containing Materials .....                                 | 2-13 |
| 2.4.10  | Potential Radioactive Materials .....                             | 2-13 |
| 2.4.11  | Summary of Findings.....  | 2-13 |

Hydro  
Pre-Demolition HBMA, Former Construction Camp Sites, BDE – Avalon TL, NL (Final)  
Section 2.0: Camp #1 Site  
Wood Project #: TF18104243.2000  
April 2019



## **APPENDICES**

- APPENDIX A2 Figures
- APPENDIX B2 Photographic Record
- APPENDIX C2 Sample and Analytical Summary Tables
- APPENDIX D2 Room-By-Room Inspection Sheets

## 2.0 CAMP # 1 SITE

Camp #1 site is located approximately 10 km (along a gravel access road) from the Burin Peninsula Highway (Route 210) near the community of Swift Current (near Piper’s Hole River) (refer to Figure 2.1, Appendix A2 and Photos 1 to 4, Appendix B2). Camp #1 site is comprised of an accommodations cabin and an outhouse.

### 2.1 BUILDING DESCRIPTION

The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 61 m<sup>2</sup> (refer to Photos 5 to 14, Appendix B2). The floor plan of the cabin consists of a kitchen, a bedroom and a washroom, with an attached generator shed (refer to Figure 2.2, Appendix A2). The foundation of the accommodations cabin consists of concrete footings, with a concrete slab for the generator shed. The structure of the accommodations cabin and generator shed consists of concrete block and wood framing. The exterior walls on the accommodations cabin is finished with metal siding and the roof is finished with asphalt shingles. The window and exterior door openings on the accommodations cabin are barricaded with metal covers for security purposes. Interior wall and ceiling finishes in the accommodations cabin consists of painted plywood. Floors/floor finishes consist of plywood. Incandescent lighting was observed on the interior and exterior of the building. The accommodations cabin is not currently heated. The accommodations cabin consists of a kitchen (Room 1), bedroom (Room 2) and a washroom (Room 3).

The outhouse is a one-storey, rectangular structure with a footprint area of approximately 3 m<sup>2</sup> (refer to Figure 2.2, Appendix A2). The foundation and structure of the outhouse consists of wood framing. The exterior walls on the outhouse are finished with plywood and the roof is finished with asphalt shingles. Interior wall and ceiling finishes in the outhouse consist of painted plywood. Floor finishes consist of plywood. The outhouse does not contain any lighting or heating (refer to Photos 15 and 16, Appendix B2).

A description of the accommodations cabin is outlined in Table 2-1 and a description of the outhouse is outlined in Table 2-2. Photographs of the site buildings are provided in Appendix B2.

**Table 2-1: Site Building Description – Accommodations Cabin**

| Building Name             | Accommodations Cabin  | Photo No. (Appendix B2) |
|---------------------------|---|-------------------------|
| Date of Construction      | Approximately late 1960’s/early 1970’s (exact date not known) | -                       |
| Date of Renovations       | Unknown   | -                       |
| No. of Stories            | One   | 5 and 6                 |
| Crawl Space (Yes/No)      | No  | -                       |
| Attic (Yes/No)            | Yes   | -                       |
| Type of Structure         | Concrete blocks and Wood Frame                                | 5 and 6                 |
| Type of Foundation        | Wood Beams on concrete and concrete blocks                    | 19 and 23               |
| Exterior                  | Metal Siding  | 5 and 6                 |
| Window/Door Frames        | Painted Metal and Wood  | 5                       |
| Exterior Doors            | Painted Metal   | 5                       |
| Roofing Materials         | Asphalt Shingles  | 6 and 22                |
| Interior Walls Finishes   | Painted Plywood   | 7 to 11                 |
| Interior Ceiling Finishes | Plywood   | 7                       |
| Floor Finishes            | Plywood   | 8 to 11                 |



**Table 2-1: Site Building Description – Accommodations Cabin**

| Building Name     | Accommodations Cabin | Photo No. (Appendix B2) |
|-------------------|----------------------|-------------------------|
| Interior Doors    | NA                   | -                       |
| Interior Lighting | Incandescent         | 7                       |
| Exterior Lighting | Incandescent         | 5                       |
| Heating           | Previously Oil       | 9                       |

**Table 2-2: Site Building Description – Outhouse**

| Building Name             | Outhouse  | Photo No. (Appendix B2) |
|---------------------------|---|-------------------------|
| Date of Construction      | Approximately late 1960's/early 1970's (exact date not known) | -                       |
| Date of Renovations       | Unknown   | -                       |
| No. of Stories            | One   | 15                      |
| Crawl Space (Yes/No)      | No  | -                       |
| Attic (Yes/No)            | No  | -                       |
| Type of Structure         | Wood Frame  | 15 and 16               |
| Type of Foundation        | Wood Frame  | 15 and 16               |
| Exterior                  | Plywood   | 15                      |
| Window/Door Frames        | Wood  | -                       |
| Exterior Doors            | NA  | -                       |
| Roofing Materials         | Asphalt Shingles  | 15                      |
| Interior Walls Finishes   | Painted Plywood   | 16 and 29               |
| Interior Ceiling Finishes | Plywood   | -                       |
| Floor Finishes            | Plywood   | 15                      |
| Interior Doors            | NA  | -                       |
| Interior Lighting         | NA  | -                       |
| Exterior Lighting         | NA  | -                       |
| Heating                   | NA  | -                       |

## 2.2 ROOM DESIGNATION

Each room at Camp #1 was assigned a specific room name. The designated room names are presented in Table 2-3 and graphically illustrated on the sample location plan (refer to Figure 2.2, Appendix A2).

**Table 2-3: Assigned Rooms**

| Level No. | Room Name – Accommodations Cabin | Room Number |
|-----------|----------------------------------|-------------|
| 1         | Kitchen                          | Room 1      |
| 1         | Bedroom                          | Room 2      |
| 1         | Bathroom                         | Room 3      |
| 1         | Outhouse                         | Outhouse    |

## 2.3 FINDINGS

The findings documented in this section are based on observations made by Wood personnel at the time of the site visit on August 13, 2018 and the results of laboratory analyses of samples collected from Camp #1. During the Pre-Demolition HBMA site visit, Wood personnel were accompanied by a representative of Hydro (Mr. Wayne Lidster). Copies of room-by-room inspection sheets for the accommodations building

and outhouse are provided in Appendix D2. Photos of the samples collected from the accommodations building and outhouse during the site visits are provided in Appendix B2.

### **2.3.1 Asbestos-Containing Materials (ACMs)**

There are over 3,000 ACMs that are commercially available, which can be divided into two broad categories: friable and non-friable. ACMs were discontinued from use in Canada in the late 1970s/early 1980s, although non-friable asbestos is still found in many more recent buildings.

During the Pre-Demolition HBMA site visit, a total of five (5) building material samples (C1-AS-1 to C1-AS-5) were collected from the accommodations cabin and 1 building material sample (C1-PP-AS1) from the outhouse (refer to Photos 17 to 22, Appendix B2) and analyzed for asbestos content. Bulk sample descriptions and asbestos analytical results are summarized in Table C2-1, Appendix C2. Sample locations and analytical results are graphically illustrated in Figure 2.2, Appendix A2.

#### **2.3.1.1 Friable Materials**

Friable ACMs are defined as materials that can be crumbled, pulverized and reduced to powder when dry using hand pressure. Typical friable materials include acoustical or decorative spray applications, fireproofing and thermal insulation.

##### **2.3.1.1.1 *Spray-Applied Fireproofing, Insulation and Texture Finishes***

There were no spray-applied fireproofing, insulation or texture finishes observed in the accommodations cabin or outhouse during the Pre-Demolition HBMA site visit; therefore, no samples of these materials were collected for analysis.

##### **2.3.1.1.2 *Building and Thermal System Insulation***

During the Pre-Demolition HBMA site visit, fiberglass batt insulation was observed in the attic and walls of the accommodations cabin (refer to Photos 12, 17 and 18, Appendix B2). Thermal system insulation was not observed at Camp #1.

Two (2) samples of building insulation (C1-AS-1 and C1-AS-2) were collected from the attic and wall of the accommodations cabin and analyzed for asbestos content. Sample C1-AS-1 was collected from the interior wall and consisted of black paper backing and pink fiberglass insulation. Sample C1-AS-2 was collected from the attic and consisted of black paper backing and yellow fiberglass insulation. Asbestos was not detected in the insulation samples.

#### **2.3.1.2 Non-Friable and Potentially Friable Materials**

Non-friable ACMs are hard or manufactured products such as floor tiles, fire blankets, pre-formed manufactured cementitious insulation and wallboards, pipes, and siding, wherein the asbestos fibres are bound to the substrate. Note that although a product may be considered non-friable when new, the product may release fine dust when disturbed (e.g., deterioration, removal, renovations) and the free dust is considered friable.

### **2.3.1.2.1 Ceiling Tile**

There were no ceiling tiles observed at Camp #1 during the Pre-Demolition HBMA site visit; therefore, no samples of ceiling tile were collected for analysis.

### **2.3.1.2.2 Drywall Joint Compound**

There was no drywall joint compound observed at Camp #1 during the Pre-Demolition HBMA site visit; therefore, no samples of drywall joint compound were collected for analysis.

### **2.3.1.2.3 Vinyl Flooring Products and Mastics**

There was no vinyl flooring or products observed at Camp #1 during the Pre-Demolition HBMA site visit; therefore, no samples of vinyl flooring or products were collected for analysis.

### **2.3.1.2.4 Baseboard, Carpet and Stair Tread Adhesives/Mastics**

There were no baseboard, carpet or stair tread adhesives/mastics observed at Camp #1 during the Pre-Demolition HBMA site visit; therefore, no samples of these types of adhesives/mastics were collected for analysis.

### **2.3.1.2.5 Roofing Products**

During the Pre-Demolition HBMA site visit, one (1) sample of black asphalt shingle and tar (C1-AS-5) was collected from the roof of the accommodations cabin and one (1) sample of black asphalt shingle and tar (C1-PP-AS-1) was collected from the roof of the outhouse and analyzed for asbestos content (refer to Photos 21 and 22, Appendix B2). Asbestos was not detected in the roofing product samples analyzed.

It is important to note that, due to height constraints, no samples of building materials around roof penetrations (e.g., caulking or sealants around vents or electrical conduit) or roof seams were collected for analysis (refer to Photo 6, Appendix B2).

### **2.3.1.2.6 Caulking/Sealant**

There were caulking/sealants observed at Camp #1 during the Pre-Demolition HBMA site visit; therefore, no samples of caulking/sealants were collected for analysis.

### **2.3.1.2.7 Mortar, Grout and Other Cementitious Materials**

During the Pre-Demolition HBMA site visit, one (1) sample of concrete (C1-AS-3) was collected from the concrete foundation of the accommodations cabin and one (1) sample of concrete block and mortar (C1-AS-4) was collected from the foundation of the accommodations cabin and analyzed for asbestos content (refer to Photos 19 and 20, Appendix B2). Asbestos was not detected in the concrete and concrete block and mortar samples analyzed.

### **2.3.1.2.8 Fire-Rated Doors**

Fire-rated doors and door frames were not observed during the Pre-Demolition HBMA site visit.

### **2.3.1.2.9 Other Potential ACMs**

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to, electrical and mechanical components and insulators such as wiring and gaskets, heat shields inside incandescent light fixtures, and caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations.

Other possible hidden and inaccessible ACMs have the potential to be present within the accommodations building but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include concrete leveling compound (existing concrete foundation), possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components or gaskets inside appliances, concrete lining the interior of hot water boiler tanks, and underground infrastructure or piping.

## **2.3.2 Paint Additives**

Lead compounds have been used in paint as pigment and durability additives since the early 1800s. Mercury compounds have been used in paint as anti-microbial additives up until the 1990s. PCBs have been used in paint as plasticizers and corrosion resistance additives from the 1950s to the 1970s.

During the Pre-Demolition HBMA site visit, six (6) samples (C1-PS1 to C1-PS6) were collected from painted surfaces of the accommodations cabin and three (3) samples (C1-PP-PS1 to C1-PP-PS3) were collected from painted surfaces of the outhouse and analyzed for lead, mercury and PCB content (refer to Photos 23 to 31, Appendix B2). Paint sample descriptions and lead, mercury and PCBs analytical results are summarized in Tables C2-2 to C2-4, Appendix C2. Sample locations and analytical results are graphically illustrated in Figure 2.1, Appendix A2.

### **2.3.2.1 Lead in Paint**

Concentrations of lead in the six (6) samples (C1-PS1 to C1-PS6) collected from painted surfaces of the accommodations cabin and three (3) samples (C1-PP-PS1 to C1-PP-PS3) collected from the painted surfaces of the outhouse ranged from 36 mg/kg to 319 mg/kg (refer to Table C2-2, Appendix C2). Five (5) paint samples (C1-PS4, C1-PS5, C1-PS6, C1-PP-PS1 and C1-PP-PS2) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg (refer to Photos 26 to 30, Appendix B2). The concentrations of lead in the other four (4) samples were below the Federal HPA criterion (90 mg/kg).

### **2.3.2.2 Mercury in Paint**

The concentrations of mercury in the six (6) samples (C1-PS1 to C1-PS6) collected from painted surfaces of the accommodations cabin and three (3) samples (C1-PP-PS1 to C1-PP-PS3) collected from the painted surfaces of the outhouse ranged from non-detect (<0.05 mg/kg) to 1.8 mg/kg, and therefore were below the Federal HPA criterion (10 mg/kg) (refer to Table C2-3, Appendix C2).

### **2.3.2.3 PCBs in Paint**

PCBs were not detected (<0.5 mg/kg) in any of the paint samples analyzed, and therefore were below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg) (refer to Table C2-4, Appendix C2).

### **2.3.3 Urea Formaldehyde Foam Insulation (UFFI)**

Visual indicators suggesting the potential presence of UFFI were not observed at Camp #1. The nature of the insulation in the walls and ceilings throughout the accommodations cabin consisted of fiberglass batt insulation (refer to Photos 12, 17 and 18, Appendix B2).

Since the original date of construction of Camp #1 (assumed construction commenced the same timeframe as the original transmission line, late 1960's/early 1970's) is unknown, it is possible that UFFI may be present.

In the event that UFFI is present, the CMHC state that "tests show that UFFI is not a source of over-exposure to formaldehyde after the initial curing and release of excess gas". The general view based on studies concerning formaldehyde emissions is that as a product ages, the amount of formaldehyde off-gassed from the product decreases over time. The amount of formaldehyde released is reportedly dependent on temperature, humidity and whether or not the product is exposed to excessive moisture or water.

### **2.3.4 Suspected Visible Mould Growth (SVG)**

Wood inspected the interior areas of the accommodations cabin and outhouse for visual or olfactory evidence of suspected mould. No SVG was noted during the Pre-Demolition HBMA site visit, however, water staining and peeling paint was observed in Rooms 1 (Kitchen) and 2 (Bedroom) of the accommodations cabin (refer to Photos 7 and 32, Appendix B2).

### **2.3.5 Mercury-Containing Thermostats**

Thermostats were not identified inside the accommodations cabin at Camp #1 during the Pre-Demolition HBMA site visit.

### **2.3.6 PCB-Containing Light Ballasts**

Incandescent light fixtures were observed on the exterior and interior of the accommodations cabin during the Pre-Demolition HBMA site visit (refer to Photos 5, 7, and 32, Appendix B2). There are no florescent lights present inside the site building.

### 2.3.7 Potential Sources of ODS and Halocarbons

During the Pre-Demolition HBMA, a potential source of ODS was identified within the accommodations cabin. Results of the ODS inspection is summarized in Table 2-4.

**Table 2-4: Potential Sources of ODSs**

| Item    | Manufacturer | Model (Serial No.) | Location Observed | Photo No. (Appendix B2) | Refrigerant | Potential ODS |
|---------|--------------|--------------------|-------------------|-------------------------|-------------|---------------|
| Freezer | General      | GC-7L-1            | Room 1            | 33                      | R12         | Yes           |

Based on observations made during the site visit, ODSs are present in the accommodations cabin in the form of refrigerant R12 contained in a freezer located in Room 1 (refer to Photo 33, Appendix B2). This refrigerant (R12) is a hydrochlorofluorocarbon (HCFC) and is regulated under the Federal Halocarbon Regulations.

Fire extinguishers were not observed at Camp #1 during the Pre-Demolition HBMA site visit.

### 2.3.8 Other Potentially Hazardous Building Materials or Substances

Other potentially hazardous building materials or substances identified during this assessment are presented in the following sections.

#### 2.3.8.1 Lead-Containing Materials and Equipment

Lead is typically associated with plumbing solder and older pipe materials (e.g., cast iron pipe joints), as well as products such as radiation protective shielding and lead-acid batteries. Lead can also be present in steel and iron primer, industrial electrical jacketing, roof flashing and tank linings.

Since the actual date that Camp #1 was constructed is unknown (assumed to be 1966/1969), it is possible that lead solder is present in plumbing and piping (i.e., cast iron and copper piping) in this section of the building, as lead solder for use in potable water distribution pipes was not banned until the late 1980s (refer to Photos 34 and 35, Appendix B2).

#### 2.3.8.2 Mercury-Containing Materials and Equipment

The light tubes and bulbs in HID and fluorescent light fixtures often contain limited quantities of mercury in a powder or vapour form. Incandescent light fixtures were observed on the exterior and the interior of the accommodations cabin during the Pre-Demolition HBMA site visit. There are no florescent lights present inside the site building.

#### 2.3.8.3 PCB-Containing Materials and Equipment

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, and as mentioned previously, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

### **2.3.8.4 Treated Wood Chemicals**

The chemicals that are used to protect and preserve wood products from insect attack and fungal decay may pose risks to human health and the environment. Depending on the wood treatment used, treated wood may be considered a hazardous waste upon disposal. The NL Department of Environment and Conservation (currently the NL MAE), 2015 Guidance Document for Treated Wood Waste Disposal (GD-PPD-075.1) provides landfill disposal standards for “pressure treated” inorganic preservatives (i.e., arsenic and chromium) and creosote (i.e., total cresol and benzo(a)pyrene) and chlorophenolic (i.e., pentachlorophenol) formulations used to preserve wood. These landfill disposal standards for treated wood waste (TWW) are used to assess the results of leachability testing to determine disposal options for treated wood to be removed during renovation or demolition activities.

Treated wood was not identified during the Pre-Demolition HBMA site visit.

### **2.3.8.5 Silica**

According to the CPWR – The Center for Construction Research and Training, many common construction materials contain silica including, asphalt, brick, cement, concrete, drywall, grout, mortar, stone, sand and tile. The dust created by cutting, grinding, drilling or otherwise disturbing these materials can contain crystalline silica particles.

Based on the Pre-Demolition HBMA site visit, silica is expected to be present in concrete used in the construction of the foundation for the accommodations building. Silica may also be present in the asphalt shingles used in the construction of the accommodations building.

### **2.3.8.6 Radioactive Materials**

Smoke detectors were not observed during the Pre-Demolition HBMA site visit. Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called “ion chamber smoke alarms”.

## **2.4 CONCLUSIONS AND RECOMMENDATIONS**

Based on observations made and information gathered during the Pre-Demolition HBMA, the following conclusions and recommendations are made with respect to the potential and actual presence of hazardous building materials at Camp #1.

### **2.4.1 ACMs**

Results of the asbestos sampling and analytical program revealed that all building materials sampled at the time of the Pre-Demolition HBMA were non-detect for asbestos.

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to:

- Electrical and mechanical components and insulators such as wiring and gaskets.

- Heat shields inside incandescent light fixtures.
- Caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations.

Other possible hidden and inaccessible ACMs have the potential to be present within the buildings at Camp #1 but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include concrete leveling compound (existing concrete foundation), possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components, concrete lining the interior of hot water boiler tanks, and underground infrastructure or piping.

If other potential ACMs that were not sampled as part of this assessment are encountered in the future, these materials should be treated as ACMs or samples should be collected and tested to verify asbestos content. This should be done as soon as these materials are encountered and before these materials are disturbed. This includes materials that are currently concealed by walls and ceiling systems. In accordance with the NL Asbestos Abatement Regulations (Reg. 111/98), which provide the legislative requirements for safe handling of ACMs in workplaces in the Province of NL, the following is recommended:

- Safe work procedures shall be established.
- All buildings constructed during the period when asbestos was readily used in construction (generally prior to the early 1980s) or any buildings that are suspected as having asbestos must have a written assessment and management plan (where applicable) for potential ACMs.
- Materials suspected of containing asbestos are required to be handled as ACMs, until analysis by a competent laboratory determines whether or not it does contain asbestos.
- Prior to general demolition, all ACMs must be safely removed from the building and disposed of in accordance with appropriate environmental guidelines by an asbestos abatement contractor registered with the Occupational Health and Safety (OHS) Division of Service NL.
- Most work involving ACMs (i.e., disturbance, removal and encapsulation) must be conducted by a contractor registered with the OHS Division of Service NL.
- ACMs in good condition should be inspected on an annual basis.
- ACMs in poor condition should be removed from the building and transported off-site for proper disposal.
- Workers should don adequate respiratory protection and personal protective equipment (PPE) when working with ACMs.

Prior to the removal and/or abatement of any identified ACMs (or any other hazardous building materials), an abatement plan including technical specifications should be designed, prepared and supervised by a qualified professional and should be undertaken by qualified trades, in accordance with applicable standards. Activities involving the disturbance and/or removal of ACMs should be carried out in a manner that ensures asbestos fiber concentrations do not exceed the applicable American Conference of Governmental Industrial Hygienists (ACGIH) threshold limit value (TLV). ACMs can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.



## 2.4.2 Lead, Mercury and PCBs in Paint

Results of the paint sampling and analytical program revealed the following:

- **Lead and Leachable Lead in Paint**

- The concentrations of lead in the six (6) samples (C1-PS1 to C1-PS6) collected from painted surfaces of the accommodations cabin and three (3) samples (C1-PP-PS1 to C1-PP-PS3) collected from paint surfaces of the outhouse ranged from non-detect (<5.0 mg/kg) to 319 mg/kg.
- Five (5) paint samples (C1-PS4, C1-PS5, C1-PS6, C1-PP-PS1, and C1-PP-PS2) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg; therefore, these paints are considered to be LBPs but are not likely to be leachable for lead.
- The concentrations of lead in the other four (4) samples were below the Federal HPA criterion (90 mg/kg); therefore, these paints are not considered to be LBPs and are not likely to be leachable for lead.

- **Mercury and Leachable Mercury in Paint**

- The concentrations of mercury in the six (6) samples (C1-PS1 to C1-PS6) collected from painted surfaces of the accommodations cabin and three (3) samples (C1-PP-PS1 to C1-PP-PS3) from the outhouse ranged from non-detect (<0.05 mg/kg) to 1.8 mg/kg; below the Federal HPA criterion (10 mg/kg). These paints are not considered to be MBPs and are not likely to be leachable for mercury.

- **PCBs in Paint**

- PCBs were not detected (<0.5 mg/kg) in the six (6) samples (C1-PS1 to C1-PS6) collected from painted surfaces of the accommodations cabin and three (3) samples (C1-PP-PS1 to C1-PP-PS3) collected from paint surfaces of the outhouse analyzed, and therefore, below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg).

Based on the paint sample analytical results, the paint samples collected from accommodations cabin and outhouse are not likely to be leachable for lead or mercury, and do not contain PCBs. Should disposal be required (e.g., renovation or demolition activities), the paints analyzed for lead, mercury and PCB content may be disposed of at an approved landfill facility, pending landfill and Provincial regulatory approval.

It is important to note that the red paint on the door, window/door covers, window/door trims and plywood of outhouse exterior appear to be the same as the red paint sampled at Camp 2, where a concentration (10, 400 mg/kg) of lead was detected in paint sample PP-PS6 (red paint on the exterior door of the accommodations cabin) above the former Federal HPA criterion of 5,000 mg/kg. Therefore, lead leachate analysis is required to determine whether or not the painted surfaces of the door, window/door covers and window/door trims can be disposed of at a landfill. Alternatively, the metal door and associated trim may be sent to a metal recycling facility, provided the facility is informed about the concentration of lead in the paint. Given the nature of the paint on the exterior door (thin layer of paint on metal), it may not be possible to collect enough volume of paint for leachate analysis.

There are potential adverse human health impacts associated with disturbing (e.g., scraping, sanding, burning, etc.) lead-containing paint finishes, due to the potential for dust, mist or fumes to be released

and inhaled or ingested by workers. As a precautionary measure, Wood recommends handling these paint finishes, as follows:

- In areas of minor peeling or flaking, the paint should be removed using wet scraping techniques.
- In areas of extensive peeling and flaking, the paint should be removed and more extensive particulate control measures may be required.
- In areas where lead-containing paint finishes are present and in poor condition, an experienced contractor should be utilized for renovating, decommissioning or demolition activities.
- Prior to renovation, dismantling or demolition activities, all areas of extensive peeling and flaking of lead-containing paint finishes and paint debris/dust should be removed and/or remediated to ensure that building occupants/workers are protected from associated dust/particulate.
- Procedures should be implemented to ensure that workers and anyone present in and around areas being renovated, dismantled or demolished are protected. The contractor should also ensure that dust generation and migration is minimized.
- Precautions should be taken to prevent/reduce exposure to paint dust during any disturbance of lead-containing paint finishes, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas.
- Where possible, lead-containing paint finishes should be removed from metal surfaces prior to welding or cutting these materials.

If potential lead, mercury or PCB containing paint finishes that were not sampled during this assessment are encountered in future, prior to any disturbance or removal, samples should be obtained and tested to verify concentrations of lead, mercury and PCBs. This includes materials that are currently concealed by walls and ceiling systems.

Any disturbance or removal of lead, mercury or PCB-containing paint finishes that may generate dust or respirable aerosols must conform to the Federal and Provincial OHS Regulations. All work should be carried out by individuals wearing proper PPE. The type of respiratory protection and control measures to be implemented during the removal of these types of paint finishes should be determined by a qualified person and based on the risk level of a particular work activity (i.e., scraping, sanding, abrasive blasting, etc.). Activities involving the disturbance and/or removal of lead, mercury or PCB-containing paint finishes should be carried out in a manner that ensures paint dust concentrations do not exceed the applicable ACGIH TLVs.

### **2.4.3 Potential UFFI**

The sale and installation of UFFI was banned in 1980; since the original date of construction is unknown, it is possible that UFFI may be present in the building. Visual indicators suggesting the potential presence of UFFI were not observed in the building. It can be inferred that any UFFI present within the building is unlikely to affect the indoor air quality due to the amount of time that has passed since the insulation was likely installed (i.e., pre-1980) along with the likelihood that formaldehyde has off-gassed over this period of time. It should be noted that, the presence and concentration of formaldehyde cannot be determined or quantified without conducting site-specific testing for formaldehyde.

Although there is currently no Provincial regulations requiring that the removal of UFFI be conducted by a licensed/registered abatement contractor, based on discussions with representatives of the OHS Division

of Service NL, it is strongly recommended that this material be abated using similar methods as required for asbestos abatement and that the insulation must be removed in a dry condition. Based on discussions with representatives of the NL MAE, for the purposes of disposal of UFFI, this material is permitted to be bagged and transported to an approved WDS and disposed in the special waste area (unlined area) of the site.

#### **2.4.4 Mould**

The ceiling of Room 1 in the accommodations cabin is peeling and contains some water staining. Existing conditions in the building (e.g., suspected water infiltration due to leaks) may potentially contribute to or enhance mould growth inside the building.

Mould spores are present in all indoor environments and cannot be completely eliminated. Cellulose based building materials provide a nutrient base for many mould species; however, mould cannot grow unless an adequate amount of excess moisture is present. The most effective way to prevent mould growth within a building is the prompt removal of any porous building materials with water damage or mould growth and repairing the building components that lead to the water infiltration.

#### **2.4.5 Potential ODS**

Based on observations made during the site visit, ODSs are present in the accommodations cabin in the form of refrigerant R12 contained in a freezer located in Room 1. This refrigerant (R12) is a hydrochlorofluorocarbon (HCFC) and is regulated under the Federal Halocarbon Regulations.

Ozone depleting substances (ODS), if present, should be removed by an approved contractor prior to disposing of any cooling and/or refrigeration equipment from the building. The use, storage, operation, maintenance, decommissioning, and disposal of ODS containing equipment, in general, is regulated at both a Provincial and Federal level and must comply with the most recent NL Halocarbon Regulations and the Federal Halocarbon Regulations. The status of the potential ODS containing equipment should be confirmed through a mechanical contractor or consultant.

#### **2.4.6 Potential Lead-Containing Materials/Equipment**

Lead solder is likely to be present in plumbing and piping (e.g., cast iron and copper piping) in the accommodations cabin.

The disturbance, control or disposal of lead-containing material/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of lead in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a metal recycling facility and not a landfill. Removal of lead-containing batteries should be completed in a manner that ensures structural integrity and no loss of fluid from the batteries. Should disposal be required, disposal of lead-containing batteries should be completed in accordance with hazardous waste procedures/guidelines (i.e., at an approved facility).

Sampling drinking water for the analysis of lead was not included in the scope of work for the Pre-Demolition HBMA.

#### **2.4.7 Potential Mercury-Containing Materials/Equipment**

Should disposal be required, mercury-containing equipment should be removed intact and returned to the manufacturer for recycling or disposed of at an approved hazardous waste disposal facility. The disturbance, control or disposal of mercury-containing materials/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of mercury in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a recycling or hazardous waste disposal facility and not a landfill.

#### **2.4.8 Potential PCB-Containing Materials/Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

If PCB-containing materials or equipment are encountered in the future, and should disposal be required, the PCB content in the materials or equipment should be confirmed prior to disposal.

Any PCB-containing equipment (if present) should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations. Any PCB-containing equipment requiring removal from the building should be transported and disposed of at an approved hazardous waste disposal site, and not a landfill disposal site, by a registered hazardous waste transporter in accordance with applicable regulations.

#### **2.4.9 Silica Containing Materials**

Silica is expected to be present in concrete used in the construction of the foundation for the accommodations cabin. Silica may also be present in asphalt shingles used in the construction of accommodations cabin. Precautions should be taken to prevent/reduce exposure to silica dust during any disturbance/ demolition of silica-containing products, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas. Activities involving the disturbance and/or demolition of silica-containing materials should be carried out in a manner that ensures silica dust concentrations do not exceed the applicable ACGIH TLV.

#### **2.4.10 Potential Radioactive Materials**

Smoke detectors were not observed during the Pre-Demolition HBMA site visit. Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called "ion chamber smoke alarms".

#### **2.4.11 Summary of Findings**

Hazardous building materials identified at Camp #1 during this Pre-Demolition HBMA and disposal options, if required, are summarized in Table 2-4. Conclusions and recommendations made with respect to the potential and actual presence of hazardous building materials within the accommodations cabin

and outhouse are provided in Section 2.4 and should be reviewed in conjunction with Table 2-5.

**Table 2-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| Hazardous Material    | Applicable Acts, Regulations or Guidance Documents  | Description and Location   | Disposal  |
|-----------------------|---|--|---|
| <b>ACMs</b>           | NL Asbestos Abatement Regulations (Reg. 111/98)   | None identified<br><br>Note that other possible hidden and inaccessible ACMs have the potential to be present within the accommodations building but were not identified during the Pre-Demolition HBMA site visit.  | ACMs cannot be disposed of at a Construction & Demolition Site; however, these materials can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.<br><br>The transportation and disposal of asbestos should be conducted in accordance with the NL Asbestos Abatement Regulations (Reg. 111/98) and with Standard Operating Procedures (SOPs) for disposal of ACMs at the landfill.  |
| <b>LBP</b>            | Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)<br><br>Federal HPA (R.S.1985, c. H-3)<br><br>Federal TDG Act (1992, c. 34)<br><br>Surface Coating Materials Regulations (SOR/2016-193) | LBP (white on green) on plywood in Room 1 of accommodations cabin.<br><br>LBP (red) on concrete on exterior of accommodations cabin.<br><br>LBP (red over light green over white) on wood trim on exterior of accommodations cabin.<br><br>LBP (grey) on plywood on interior of outhouse.<br><br>LBP (red) on plywood on exterior of outhouse. | Paints that were analyzed for lead and contained <5,000 mg/kg lead, may be disposed of at a Regional Solid Waste Disposal Facility (landfill), provided permission is obtained from the landfill.<br><br>Red paint on the door, window/door covers, window/door trims and plywood of outhouse exterior appear to be the same as the red paint sampled at Camp 2, where a concentration (10, 400 mg/kg) of lead was detected in paint sample PP-PS6 (red paint on the exterior door of the accommodations cabin) above the former Federal HPA criterion of 5,000 mg/kg. Therefore, lead leachate analysis is required to determine whether or not the painted surfaces of the door, window/door covers and window/door trims can be disposed of at a landfill. Alternatively, the metal door and associated trim may be sent to a metal recycling facility, provided the facility is informed about the concentration of lead in the paint. Given the nature of the paint on the exterior door (thin layer of paint on metal), it may not be possible to collect enough volume of paint for leachate analysis. |
| <b>Potential UFFI</b> | Federal HPA (R.S.1985, c. H-3)  | None Identified  | UFFI is permitted to be bagged and transported to an approved WDS and disposed in the special waste area of the site.   |

**Table 2-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b>                                | <b>Applicable Acts, Regulations or Guidance Documents</b>   | <b>Description and Location</b>  | <b>Disposal</b>   |
|--|---|--|---|
| <b>Mould</b>   | <p>Mould Guidelines for the Canadian Construction Industry, Canadian Construction Industry (CCI), 2004;</p> <p>Mould Abatement Guidelines, Environmental Abatement Council of Ontario (EACO), 2010</p>  | <p>Some water staining noted on the ceiling in the accommodations trailer.</p> | <p>All mould impacted materials may be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.</p>   |
| <b>Potential ODS</b>                                     | <p>Federal Halocarbon Regulations (SOR/2003-289)</p>  | <p>R12 refrigerant in freezer in Room 1.</p>                                   | <p>Materials containing ODS should be received by a contractor or facility that has the proper approvals to remove, handle and/or dispose of ODS. The remaining materials can be disposed of at a recycling facility, provided permission is obtained from the facility.</p>  |
| <b>Potential Lead-Containing Materials/ Equipment</b>    | <p>Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)</p> <p>Federal HPA (R.S.1985, c. H-3)</p> <p>Federal TDG Act (1992, c. 34)</p> <p>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301)</p> | <p>Potential lead-containing solder (piping and plumbing)</p>                  | <p>Lead-containing materials and equipment can be disposed of at a metal recycling or hazardous waste disposal facility, in accordance with applicable regulations.</p> <p>The transportation and disposal of hazardous lead-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility.</p> |
| <b>Potential Mercury-Containing Materials/ Equipment</b> | <p>Federal HPA (R.S.1985, c. H-3)</p> <p>Federal TDG Act (1992, c. 34)</p> <p>Products Containing Mercury Regulations (SOR/2014-254)</p>  | <p>None identified</p>   | <p>Mercury-containing materials and equipment can be disposed of at a recycling or hazardous waste disposal facility, in accordance with applicable regulations.</p> <p>The transportation and disposal of hazardous mercury-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility.</p> |

**Table 2-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b>                            | <b>Applicable Acts, Regulations or Guidance Documents</b>   | <b>Description and Location</b> | <b>Disposal</b>   |
|--|---|---------------------------------|---|
| <b>Potential PCB-Containing Materials/ Equipment</b> | Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)<br>Federal TDG Act (1992, c. 34)<br>Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)<br>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301)<br>PCB Regulations (SOR/2008-273)<br>PCB Waste Export Regulations (SOR/97-109)<br>Regulations Amending the PCB Regulations (SOR/2010-57) | None identified                 | Any PCB-containing materials and equipment should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations.<br><br>Any PCB-containing materials and equipment requiring removal from the building should be transported and disposed of by a registered hazardous waste transporter in accordance with applicable regulations.<br><br>The transportation and disposal of PCB containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility. |
| <b>Silica-Containing Materials</b>                   | NL OHS Act (RSNL1990 Chapter O-3)<br>NL OHS Regulations (5/12)  | Asphalt shingles and concrete.  | These materials can be disposed of at a Regional Solid Waste Disposal Facility (landfill).  |
| <b>Potential Radioactive Materials</b>               | Federal TDG Act (1992, c. 34)   | None identified                 | Smoke detectors that contain low level radioactive materials must be transported, as per Federal TDG Regulations, to a licensed disposal facility.  |

## **APPENDIX A2**


### **FIGURES**





**NOTES:**  
 1. ALL DIMENSIONS ARE IN METERS.  
 2. DO NOT SCALE FROM FIGURE.  
 3. THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.  
 4. ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.  
 5. THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.  
 6. THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



newfoundland labrador  
**hydro**  
 a nalcor energy company

---

**Wood**  
 Environment & Infrastructure Solutions  
 133 Crosbie Road  
 St. John's, NL A1B 4A5  
 709-722-7023



Drawn by:  
 T. Rideout

Approved by:  
 C. Finney

Scale:  
 As Shown

Project:  
 Pre-Demolition Hazardous Building Materials Assessment,  
 Former Construction Camp Sites,  
 Bay d'Espoir - Avalon Transmission Line, NL


Title:  
 Site Location Plan (Aerial) - Camp #1 Site

Date:  
 April 2019


Project No.  
 TF18104243.2000

Rev. No.  
 0

Figure No.  
 2.1




OUTHOUSE



ACCOMMODATIONS CABIN


LEGEND:

- ASBESTOS SAMPLE LOCATION - ASBESTOS NOT DETECTED
- ▲ PAINT SAMPLE LOCATION - RESULTS EXCEED 90 mg/kg AND LESS THAN 5000 mg/kg FOR LEAD AND NO CRITERIA EXCEEDANCES FOR MERCURY OR PCBs WHERE APPLICABLE
- ▲ PAINT SAMPLE LOCATION - NO CRITERIA EXCEEDANCES FOR LEAD OR MERCURY OR PCBs WHERE APPLICABLE



**NOTES:**  
 1. ALL DIMENSIONS ARE IN METERS.  
 2. DO NOT SCALE FROM FIGURE.  
 3. THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.  
 4. ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.  
 5. THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.  
 6. THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



newfoundland labrador  
 a nalcor energy company

**Wood**  
 Environment & Infrastructure Solutions  
 133 Crosbie Road  
 St. John's, NL A1B 4A5  
 709-722-7023



Drawn by:  
T. Rideout

Approved by:  
C. Finney

Scale:  
As Shown

Project:  
Pre-Demolition Hazardous Building Materials Assessment,  
Former Construction Camp Sites,  
Bay d'Espoir - Avalon Transmission Line, NL

Title:  
Sample Location Plan - Camp #1 Site

Date:  
April 2019

Project No.  
TF18104243.2000

Rev. No.  
0

Figure No.  
2.2

**APPENDIX B2**  
**PHOTOGRAPHIC RECORD**



Photo 1: View of the gravel access road at Camp #1 site, looking northeast.



Photo 2: View of transmission lines near Camp #1 site, looking east.



Photo 3: View of pond and transmission lines near Camp #1 site, looking south.



Photo 4: View of the gravel access road at Camp #1 site, looking southwest.



Photo 5: View of the accommodations cabin at Camp #1 site, looking northwest (Note: attached generator shed).



Photo 6: View of the accommodations cabin at Camp #1 site, looking northeast (Note: attached generator shed).



Photo 7: View of the kitchen (Room 1) inside the accommodations cabin at Camp #1.



Photo 8: View of the kitchen (Room 1) inside the accommodations cabin at Camp #1.



Photo 9: View of the kitchen (Room 1) inside the accommodations cabin at Camp #1.



Photo 10: View of the bedroom (Room 2) inside the accommodations cabin at Camp #1.



Photo 11: View of the washroom (Room 3) inside the accommodations cabin at Camp #1.



Photo 12: View of the attic inside the accommodations cabin at Camp #1  
(Note: attic hatch in the ceiling of Room 1).



Photo 13: View of interior of the generator shed (attached to the accommodations cabin) at Camp #1.



Photo 14: View of cavity inspection location in an exterior wall of the accommodations cabin at Camp #1.



Photo 15: View of the outhouse at Camp #1, looking northeast.



Photo 16: View of interior of the outhouse at Camp #1.



Photo 17: View of bulk material sample C1-AS-1, black paper backing and pink fibreglass insulation, cabin interior.



Photo 18: View of bulk material sample C1-AS-2, black paper backing and yellow fibreglass insulation, cabin interior.



Photo 19: View of bulk material sample C1-AS-3, concrete, cabin exterior.



Photo 20: View of bulk material sample C1-AS-4, concrete block and mortar, cabin exterior.





Photo 21: View of bulk material sample C1-AS-5, black shingle and tar, cabin exterior.



Photo 22: View of bulk material sample C1-PP-AS1, black shingle and tar, outhouse exterior.



Photo 23: View of paint sample C1-PS1, floor, cabin interior.



Photo 24: View of paint sample C1-PS2, wall, cabin interior.



Photo 25: View of paint sample C1-PS3, wall, cabin exterior.



Photo 26: View of paint sample C1-PS4, ceiling, cabin interior.



Photo 27: View of paint sample C1-PS5, wall, cabin exterior.



Photo 28: View of paint sample C1-PS6, wall, cabin exterior.



Photo 29: View of paint sample C1-PP-PS1, wall, outhouse interior.



Photo 30: View of paint sample C1-PP-PS2, wall, outhouse exterior.



Photo 31: View of paint sample C1-PP-PS3, wall, outhouse exterior.



Photo 32: View of incandescent lighting inside accommodations cabin.



Photo 33: View of freezer inside the accomodations cabin, containing R12 refridgerant.



Photo 34: View of propane hot water tank inside the accomodations cabin.



Photo 35: View of copper piping under the sink in kitchen of the accomodations cabin.



Photo 36: View of propane canisters located on the interior of the accomodations cabin.



Photo 37: View of kerosene located on the interior of the accommodations cabin.

**APPENDIX C2**

**SAMPLE AND ANALYTICAL SUMMARY TABLES**

**Table C2-1: Bulk Sample Descriptions and Asbestos Analytical Results (Camp #1)**

| Sample ID  | Room No. | Room Description    | Photo No. | Sample Location | Sample Description                                    | Layers Analyzed            | Analytical Result |
|------------|----------|---------------------|-----------|-----------------|---|----------------------------|-------------------|
| C1-AS-1    | 1        | Kitchen             | 17        | Interior Wall   | Black paper backing over pink fibreglass insulation   | Black paper and insulation | ND                |
| C1-AS-2    | 1        | Kitchen             | 18        | Ceiling         | Black paper backing over yellow fibreglass insulation | Black paper and insulation | ND                |
| C1-AS-3    | Exterior | Exterior - Cabin    | 19        | Foundation      | Concrete  | concrete                   | ND                |
| C1-AS-4    | Exterior | Exterior - Cabin    | 20        | Foundation      | Concrete block and mortar                             | Concrete and mortar        | ND                |
| C1-AS-5    | Exterior | Exterior - Cabin    | 21        | Roof            | Black shingle and black tar                           | Shingle and tar            | ND                |
| C1-PP-AS-1 | Exterior | Exterior - Outhouse | 22        | Roof            | Black shingle and black tar                           | Shingle and tar            | ND                |

**Notes:**

**Bold and underlined value indicates asbestos was detected but is below 1% by dry weight.**

ACM: Asbestos containing material

Shaded value exceeds 1% asbestos by dry weight and is considered to be an ACM as outlined in the Newfoundland and Labrador Asbestos Abatement Regulations (Reg. 111/98).

**Table C2-2: Paint Sample Descriptions and Lead Analytical Results (Camp #1)**

| Sample ID | Room No. | Room Description | Photo No. | Sample Location | Substrate | Sample Description  | RDL (mg/kg) | Lead (mg/kg)      |
|-----------|----------|------------------|-----------|-----------------|-----------|---|-------------|-------------------|
| C1-PS1    | 2        | Bedroom          | 23        | Floor           | Plywood   | Grey on plywood (sample includes plywood)                                 | 5.0         | 60                |
| C1-PS2    | 1        | Kitchen          | 24        | Wall            | Plywood   | White on plywood (sample includes loose paint and paint on wood)          | 5.0         | 57                |
| C1-PS3    | Exterior | Exterior - Cabin | 25        | Wall            | Metal     | Blue (sample includes metal siding)                                       | 5.0         | 36                |
| C1-PS4    | 1        | Kitchen          | 26        | Ceiling         | Plywood   | White on green on plywood (sample includes loose paint and paint on wood) | 5.0         | <b><u>194</u></b> |
| C1-PS5    | Exterior | Exterior - Cabin | 27        | Exterior        | Concrete  | Red on concrete (sample includes paint on concrete)                       | 5.0         | <b><u>300</u></b> |
| C1-PS6    | Exterior | Exterior - Cabin | 28        | Wall            | Wood Trim | Red over light green over white (sample includes paint on wood)           | 5.0         | <b><u>259</u></b> |
| C1-PP-PS1 | 1        | Outhouse         | 29        | Wall            | Plywood   | Grey on plywood (sample includes plywood)                                 | 5.0         | <b><u>319</u></b> |
| C1-PP-PS2 | Exterior | Outhouse         | 30        | Wall            | Plywood   | Red on plywood (sample includes plywood)                                  | 5.0         | <b><u>122</u></b> |
| C1-PP-PS3 | Exterior | Outhouse         | 31        | Wall            | Wood Trim | White on wood trim (sample includes wood)                                 | 5.0         | 40                |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

**Bold and underlined value exceeds Federal HPA criterion (90 mg/kg).**

**Shaded value exceeds former Federal HPA criterion (5,000 mg/kg).**



**Table C2-3: Paint Sample Descriptions and Mercury Analytical Results (Camp #1)**

| Sample ID | Room No. | Room Description | Photo No. | Sample Location | Substrate | Sample Description  | RDL<br>(mg/kg) | Mercury<br>(mg/kg) |
|-----------|----------|------------------|-----------|-----------------|-----------|---|----------------|--------------------|
| C1-PS1    | 2        | Bedroom          | 23        | Floor           | Plywood   | Grey on plywood (sample includes plywood)                                 | 0.05           | 0.11               |
| C1-PS2    | 1        | Kitchen          | 24        | Wall            | Plywood   | White on plywood (sample includes loose paint and paint on wood)          | 0.05           | 1.04               |
| C1-PS3    | Exterior | Exterior - Cabin | 25        | Wall            | Metal     | Blue (sample includes metal siding)                                       | 0.05           | <0.05              |
| C1-PS4    | 1        | Kitchen          | 26        | Ceiling         | Plywood   | White on green on plywood (sample includes loose paint and paint on wood) | 0.05           | 1.8                |
| C1-PS5    | Exterior | Exterior - Cabin | 27        | Exterior        | Concrete  | Red on concrete (sample includes paint on concrete)                       | 0.05           | <0.05              |
| C1-PS6    | Exterior | Exterior - Cabin | 28        | Wall            | Wood Trim | Red over light green over white (sample includes paint on wood)           | 0.05           | 0.34               |
| C1-PP-PS1 | 1        | Outhouse         | 29        | Wall            | Plywood   | Grey on plywood (sample includes plywood)                                 | 0.05           | <0.05              |
| C1-PP-PS2 | Exterior | Outhouse         | 30        | Wall            | Plywood   | Red on plywood (sample includes plywood)                                  | 0.05           | <0.05              |
| C1-PP-PS3 | Exterior | Outhouse         | 31        | Wall            | Wood Trim | White on wood trim (sample includes wood)                                 | 0.05           | <0.05              |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

**Bold and underlined value exceeds Federal HPA criterion (10 mg/kg).**

**Shaded value exceeds CCME CSQG for an industrial site (50 mg/kg).**

**Table C2-4: Paint Sample Descriptions and PCB Analytical Results (Camp #1)**

| Sample ID | Room No. | Room Description | Photo No. | Sample Location | Substrate | Sample Description  | RDL (mg/kg) | Total PCB (mg/kg) |
|-----------|----------|------------------|-----------|-----------------|-----------|---|-------------|-------------------|
| C1-PS1    | 2        | Bedroom          | 23        | Floor           | Plywood   | Grey on plywood (sample includes plywood)                                 | 0.5         | <0.5              |
| C1-PS2    | 1        | Kitchen          | 24        | Wall            | Plywood   | White on plywood (sample includes loose paint and paint on wood)          | 0.5         | <0.5              |
| C1-PS3    | Exterior | Exterior - Cabin | 25        | Wall            | Metal     | Blue (sample includes metal siding)                                       | 0.5         | <0.5              |
| C1-PS4    | 1        | Kitchen          | 26        | Ceiling         | Plywood   | White on green on plywood (sample includes loose paint and paint on wood) | 0.5         | <0.5              |
| C1-PS5    | Exterior | Exterior - Cabin | 27        | Exterior        | Concrete  | Red on concrete (sample includes paint on concrete)                       | 0.5         | <0.5              |
| C1-PS6    | Exterior | Exterior - Cabin | 28        | Wall            | Wood Trim | Red over light green over white (sample includes paint on wood)           | 0.5         | <0.5              |
| C1-PP-PS1 | 1        | Outhouse         | 29        | Wall            | Plywood   | Grey on plywood (sample includes plywood)                                 | 0.5         | <0.5              |
| C1-PP-PS2 | Exterior | Outhouse         | 30        | Wall            | Plywood   | Red on plywood (sample includes plywood)                                  | 0.5         | <0.5              |
| C1-PP-PS3 | Exterior | Outhouse         | 31        | Wall            | Wood Trim | White on wood trim (sample includes wood)                                 | 0.5         | <0.5              |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

NL MAE: Newfoundland and Labrador Department of Municipal Affairs and Environment

TDG: Transportation of Dangerous Goods

\*Sample collected by Hydro on May 5, 2018.

**Shaded value exceeds the criterion for PCB solid provided in the NL MAE Leachable Toxic Waste, Testing and Disposal Guidance Document and the TDG Regulations (50 mg/kg).**

Shaded value exceeds the criterion for PCB solid provided in the NL MAE Leachable Toxic Waste, Testing and Disposal Guidance Document and the TDG Regulations (50 mg/kg).

**APPENDIX D2**

**ROOM-BY-ROOM INSPECTION SHEETS**

| Building | Room # | Floor # | Room Description | Dimensions                   |
|----------|--------|---------|------------------|------------------------------|
| Camp 1   | 1      | 1       | Kitchen          | L = 16'<br>W = 16'<br>H = 8' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|--|--|----------------------------|--|
| <b>Floor</b>  | Wood   |  |                            |  |
| <b>Walls</b><br>(include window caulking)   | Wood   |  |                            |  |
| <b>Ceiling</b>  | Wood   |  |                            |  |
| <b>Paint</b><br>(and substrate)   | Walls: White<br>Ceiling: White/grey<br>Floor: Grey<br>Other:   |  |                            |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Pink Fibre Paper backing<br>Fire Door Manufacturer:<br>Fire Door Serial #:   |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —  |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>—  | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 4 incandescent   |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted —<br>Dial  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | Copper water & propane lines.  |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>ceiling.  |  |                            |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext   |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br>General Freezer GC-7L-1, R-12<br>Propane Hotwater tank, Model - R030-32P |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                   |
|----------|--------|---------|------------------|------------------------------|
| Camp 1   | 2      | 1       | Bunk Room        | L = 18'<br>W = 16'<br>H = 8' |

|   | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|---|--|----------------------------|--|
| <b>Floor</b>  | Wood  |  |                            |  |
| <b>Walls</b><br>(include window caulking)   | Wood  |  |                            |  |
| <b>Ceiling</b>  | Wood  |  |                            |  |
| <b>Paint</b><br>(and substrate)   | Walls: White<br>Ceiling: White<br>Floor: Grey<br>Other:   |  |                            |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:  |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  |   |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:  | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | incandescent  |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial   | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | Copper pipes for propane  |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>Paint peeling.   |  |                            |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br><br>—   |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br><br>— |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                 |
|----------|--------|---------|------------------|----------------------------|
| Camp 1   | 3      | 1       | Bathroom         | L = 6'<br>W = 6'<br>H = 8' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|--|--|----------------------------|--|
| <b>Floor</b>  | Wood   |  |                            |  |
| <b>Walls</b><br>(include window caulking)   | Wood   |  |                            |  |
| <b>Ceiling</b>  | Wood   |  |                            |  |
| <b>Paint</b><br>(and substrate)   | Walls: white<br>Ceiling: white<br>Floor: grey<br>Other:  |  |                            |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:   |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —  |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>—  | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | incandescent   |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | Copper pipes.  |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>Paint peeling off <del>wall</del> ceiling   |  |                            |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—  |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br>20L of kerosene. |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room #   | Floor # | Room Description | Dimensions                   |
|----------|----------|---------|------------------|------------------------------|
| Camp 1   | Exterior | 1       | Exterior         | L = 32'<br>W = 18'<br>H = 8' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|--|--|---------------------------|--|
| <b>Floor</b>  | <del>Concrete</del>  |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | Concrete foundation<br>Cinder block walls, blue metal siding,                                |  |                           |  |
| <b>Ceiling</b>  | Shingles   |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls: Blue on siding<br>Ceiling: Red on small metal<br>Floor: Security covers<br>Other:     |  |                           |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #: —   |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —  |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #: —   | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | —  |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted ✓<br>Dial                                | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —  |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>—   |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—  |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                 |
|----------|--------|---------|------------------|----------------------------|
| Camp 1   |        |         | Bathroom         | L = 6'<br>W = 5'<br>H = 7' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|--|--|---------------------------|--|
| <b>Floor</b>  | WOOD   |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | WOOD   |  |                           |  |
| <b>Ceiling</b>  | WOOD<br>Black Shingles   |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls: Red (Ext)<br>Ceiling: Grey (Int)<br>Floor:<br>Other:                                  |  |                           |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer: —<br>Fire Door Serial #:   |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —  |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #: —   | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   |  |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —  |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>—   |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—  |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**



## TABLE OF CONTENTS

|         |   |      |
|---------|---|------|
| 3.0     | CAMP #2 SITE.....   | 3-1  |
| 3.1     | BUILDING DESCRIPTIONS.....  | 3-1  |
| 3.2     | ROOM DESIGNATION.....   | 3-2  |
| 3.3     | FINDINGS.....   | 3-3  |
| 3.3.1   | Asbestos-Containing Materials (ACMs).....                         | 3-3  |
| 3.3.1.1 | Friable Materials.....  | 3-3  |
| 3.3.1.2 | Non-Friable and Potentially Friable Materials.....                | 3-4  |
| 3.3.2   | Paint Additives.....  | 3-5  |
| 3.3.2.1 | Lead in Paint.....  | 3-5  |
| 3.3.2.2 | Mercury in Paint.....   | 3-6  |
| 3.3.2.3 | PCBs in Paint.....  | 3-6  |
| 3.3.3   | Urea Formaldehyde Foam Insulation (UFFI).....                     | 3-6  |
| 3.3.4   | Suspected Visible Mould Growth (SVG).....                         | 3-6  |
| 3.3.5   | Mercury-Containing Thermostats.....                               | 3-7  |
| 3.3.6   | PCB-Containing Light Ballasts.....                                | 3-7  |
| 3.3.7   | Potential Sources of ODS and Halocarbons.....                     | 3-7  |
| 3.3.8   | Other Potentially Hazardous Building Materials or Substances..... | 3-7  |
| 3.3.8.1 | Lead-Containing Materials and Equipment.....                      | 3-7  |
| 3.3.8.2 | Mercury-Containing Materials and Equipment.....                   | 3-8  |
| 3.3.8.3 | PCB-Containing Materials and Equipment.....                       | 3-8  |
| 3.3.8.4 | Treated Wood Chemicals.....                                       | 3-8  |
| 3.3.8.5 | Silica.....   | 3-8  |
| 3.3.8.6 | Radioactive Materials.....  | 3-9  |
| 3.4     | CONCLUSIONS AND RECOMMENDATIONS.....                              | 3-9  |
| 3.4.1   | ACMs.....   | 3-9  |
| 3.4.2   | Lead, Mercury and PCBs in Paint.....                              | 3-10 |
| 3.4.3   | Potential UFFI.....   | 3-12 |
| 3.4.4   | Mould.....  | 3-13 |
| 3.4.5   | Potential ODS.....  | 3-13 |
| 3.4.6   | Potential Lead-Containing Materials/Equipment.....                | 3-13 |
| 3.4.7   | Potential Mercury-Containing Materials/Equipment.....             | 3-13 |
| 3.4.8   | Potential PCB-Containing Materials/Equipment.....                 | 3-14 |
| 3.4.9   | Silica Containing Materials.....                                  | 3-14 |
| 3.4.10  | Potential Radioactive Materials.....                              | 3-14 |
| 3.4.11  | Summary of Findings.....  | 3-14 |

## APPENDICES

- APPENDIX A3 Figures
- APPENDIX B3 Photographic Record
- APPENDIX C3 Sample and Analytical Summary Tables
- APPENDIX D3 Room-By-Room Inspection Sheets

### 3.0 CAMP #2 SITE

Camp #2 is currently accessible by a gravel access road from the Burin Peninsula Highway (Route 210) in the community of Swift Current, NL (near Piper’s Hole River) and is located approximately 23 km west of Camp #1 (refer to Figure 3.1, Appendix A3 and Photos 1 to 4, Appendix B3). Camp #2 site is comprised of an accommodation cabin and an outhouse.

#### 3.1 BUILDING DESCRIPTIONS

The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 61 m<sup>2</sup> (refer to Photos 5 to 12, Appendix B3). The floor plan of the cabin consists of a kitchen, a bedroom and a washroom, with an attached generator shed (refer to Figure 3.2, Appendix A3). The foundation of the accommodations cabin consists of concrete footings, with a concrete slab for the attached generator shed. The structure of the accommodations cabin and generator shed consists of concrete block and wood framing. The exterior walls on the accommodations cabin is finished with metal siding and the roof is finished with asphalt shingles. The window and exterior door openings on the accommodations cabin are barricaded with metal covers for security purposes. Interior wall and ceiling finishes in the accommodations cabin consists of painted plywood. Floors/floor finishes consist of plywood. Incandescent lighting was observed on the interior and exterior of the building. The accommodations cabin is not currently heated. The accommodations cabin consists of a kitchen (Room 1), bedroom (Room 2) and a washroom (Room 3).

The outhouse is a one-storey, rectangular structure with a former footprint area of approximately 3 m<sup>2</sup> (refer to Figure 3.2, Appendix A3). The outhouse structure has been damaged and removed from the former foundation and is currently tipped over onto the ground (refer to Photos 13 and 14, Appendix B3). The outhouse consists of wood framing, the exterior walls are finished with plywood and the roof is finished with asphalt shingles. Interior walls, floors and ceiling finishes in the outhouse consist of painted plywood. The outhouse does not contain any lighting or heating.

A description of accommodations cabin is outlined in Table 3-1 and a description of the outhouse is outlined in Table 3-2. Photographs of the buildings are provided in Appendix B3.

**Table 3-1: Site Building Description – Accommodations Cabin**

| Building Name        | Accommodations cabin  | Photo No. (Appendix B3) |
|----------------------|---|-------------------------|
| Date of Construction | Approximately late 1960’s/early 1970’s (exact date not known) | -                       |
| Date of Renovations  | Unknown   | -                       |
| No. of Stories       | One   | 5 to 7                  |
| Crawl Space (Yes/No) | No  | -                       |
| Attic (Yes/No)       | Yes   | -                       |
| Type of Structure    | Concrete blocks and Wood Frame                                | 5 to 7 and 15           |
| Type of Foundation   | Wood Beams on concrete footing                                | 7 and 16                |
| Exterior             | Metal Siding  | 5 to 7                  |
| Window/Door Frames   | Painted Metal and Wood  | 5 to 7 and 12           |
| Exterior Doors       | Painted Metal   | 5 to 7                  |
| Roofing Materials    | Asphalt Shingles  | 19                      |

**Table 3-1: Site Building Description – Accommodations Cabin**

| Building Name             | Accommodations cabin             | Photo No. (Appendix B3) |
|---------------------------|----------------------------------|-------------------------|
| Interior Walls Finishes   | Painted Plywood                  | 8 to 12                 |
| Interior Ceiling Finishes | Plywood                          | 8, 10 and 11            |
| Floor Finishes            | Plywood                          | 33                      |
| Interior Doors            | NA                               | -                       |
| Interior Lighting         | Incandescent and propane lantern | 8, 10 and 11            |
| Exterior Lighting         | Incandescent                     | 5 and 6                 |
| Heating                   | Propane Stove                    | 36                      |

**Table 3-2: Site Building Description – Outhouse**

| Building Name             | Outhouse  | Photo No. (Appendix B3) |
|---------------------------|---|-------------------------|
| Date of Construction      | Approximately late 1960's/early 1970's (exact date not known) | -                       |
| Date of Renovations       | Unknown   | -                       |
| No. of Stories            | One   | 13                      |
| Crawl Space (Yes/No)      | No  | -                       |
| Attic (Yes/No)            | No  | -                       |
| Type of Structure         | Wood Frame  | 13                      |
| Type of Foundation        | Wood Frame  | 14                      |
| Exterior                  | Plywood   | 13                      |
| Window/Door Frames        | NA  | -                       |
| Exterior Doors            | NA  | -                       |
| Roofing Materials         | Asphalt Shingles  | 13                      |
| Interior Walls Finishes   | Painted Plywood   | 13                      |
| Interior Ceiling Finishes | Plywood   | -                       |
| Floor Finishes            | NA  | -                       |
| Interior Doors            | NA  | -                       |
| Interior Lighting         | NA  | -                       |
| Exterior Lighting         | NA  | -                       |
| Heating                   | NA  | -                       |

### 3.2 ROOM DESIGNATION

Each room at Camp #2 was assigned a specific room name. The designated room names are presented in Table 3-3 and graphically illustrated on the sample location plan (refer to Figure 3.2, Appendix A3).

**Table 3-3: Assigned Rooms**

| Level No. | Room Name – Accommodations Cabin | Room Number |
|-----------|----------------------------------|-------------|
| 1         | Kitchen                          | Room 1      |
| 1         | Bedroom                          | Room 2      |
| 1         | Bathroom                         | Room 3      |
| 1         | Outhouse                         | Outhouse    |

### **3.3 FINDINGS**

The findings documented in this section are based on observations made by Wood personnel at the time of the site visit on August 13, 2018 and the results of laboratory analyses of samples collected from Camp #2. During the Pre-Demolition HBMA site visit, Wood personnel were accompanied by a representative of Hydro (Mr. Wayne Lidster). Copies of room-by-room inspection sheets for the accommodations building and outhouse are provided in Appendix D3. Photos of the samples collected from the accommodations building and outhouse during the site visit are provided in Appendix B3.

#### **3.3.1 Asbestos-Containing Materials (ACMs)**

There are over 3,000 ACMs that are commercially available, which can be divided into two broad categories: friable and non-friable. ACMs were discontinued from use in Canada in the late 1970s/early 1980s, although non-friable asbestos is still found in many more recent buildings.

During the Pre-Demolition HBMA site visit, a total of five (5) building material samples (PP-AS-1 to PP-AS-5) were collected from the accommodations cabin and one (1) building material sample (PP-PP-AS1) was collected from the outhouse (refer to Photos 13 to 18, Appendix B2) and analyzed for asbestos content. Bulk sample descriptions and asbestos analytical results are summarized in Table C3-1, Appendix C3. Sample locations and analytical results are graphically illustrated in Figure 3.2, Appendix A3.

##### **3.3.1.1 Friable Materials**

Friable ACMs are defined as materials that can be crumbled, pulverized and reduced to powder when dry using hand pressure. Typical friable materials include acoustical or decorative spray applications, fireproofing and thermal insulation.

###### **3.3.1.1.1 Spray-Applied Fireproofing, Insulation and Texture Finishes**

There were no spray-applied fireproofing, insulation or texture finishes observed in the accommodations cabin or outhouse during the Pre-Demolition HBMA site visit; therefore, no samples of these materials were collected for analysis.

###### **3.3.1.1.2 Building and Thermal System Insulation**

During the Pre-Demolition HBMA site visit, fiberglass insulation was observed in the attic and walls of the accommodations cabin (refer to Photos 17 and 18, Appendix B3). Thermal system insulation was not observed at Camp #2.

Two (2) samples of building insulation (PP-AS-1 and PP-AS-2) were collected from the wall of the accommodations cabin and analyzed for asbestos content. Sample PP-AS-1 was collected from the interior wall and consisted of black paper backing and pink fiberglass insulation. Sample PP-AS-2 was collected from the interior wall and consisted of tar paper. Asbestos was not detected in the insulation samples.

### **3.3.1.2 Non-Friable and Potentially Friable Materials**

Non-friable ACMs are hard or manufactured products such as floor tiles, fire blankets, pre-formed manufactured cementitious insulation and wallboards, pipes, and siding, wherein the asbestos fibres are bound to the substrate. Note that although a product may be considered non-friable when new, the product may release fine dust when disturbed (e.g., deterioration, removal, renovations) and the free dust is considered friable.

#### **3.3.1.2.1 Ceiling Tile**

There were no ceiling tiles observed at Camp #2 during the Pre-Demolition HBMA site visit; therefore, no samples of ceiling tile were collected for analysis.

#### **3.3.1.2.2 Drywall Joint Compound**

There was no drywall joint compound observed at Camp #2 during the Pre-Demolition HBMA site visit; therefore, no samples of drywall joint compound were collected for analysis.

#### **3.3.1.2.3 Vinyl Flooring Products and Mastics**

There was no vinyl flooring or products observed at Camp #2 during the Pre-Demolition HBMA site visit; therefore, no samples of vinyl flooring or products were collected for analysis.

#### **3.3.1.2.4 Baseboard, Carpet and Stair Tread Adhesives/Mastics**

There were no baseboard, carpet or stair tread adhesives/mastics observed at Camp #2 during the Pre-Demolition HBMA site visit; therefore, no samples of these types of adhesives/mastics were collected for analysis.

#### **3.3.1.2.5 Roofing Products**

During the Pre-Demolition HBMA site visit, one (1) sample of black asphalt shingle (PP-AS-3) was collected from the roof of the accommodations cabin and one (1) sample of black asphalt shingle and tar (PP-PP-AS-1) was collected from the roof of the outhouse and analyzed for asbestos content (refer to Photos 19 and 22, Appendix B3). Asbestos was detected in PP-AS-3 containing 2.2 % chrysotile asbestos and in PP-PP-AS1 containing 1.1% chrysotile asbestos. According to the NL asbestos abatement regulations (Reg. 111/98), both materials are considered asbestos-containing materials.

It is important to note that, due to height constraints, no samples of building materials around roof penetrations (e.g., caulking or sealants around vents or electrical conduit) or roof seams were collected for analysis (refer to Photo 7, Appendix B3).

#### **3.3.1.2.6 Caulking/Sealant**

There were no caulking/sealants observed at Camp #2 during the Pre-Demolition HBMA site visit; therefore, no samples of caulking/sealants were collected for analysis.

### **3.3.1.2.7 Mortar, Grout and Other Cementitious Materials**

During the Pre-Demolition HBMA site visit, one (1) sample of concrete (PP-AS-4) was collected from the concrete foundation footing of the accommodation cabin and one (1) sample of concrete block and mortar (PP-AS-5) was collected from the exterior wall of the accommodation cabin and analyzed for asbestos content (refer to Photos 20 and 21, Appendix B3). Asbestos was not detected in the concrete or the concrete block and mortar samples analyzed.

### **3.3.1.2.8 Fire-Rated Doors**

Fire-rated doors and door frames were not observed during the Pre-Demolition HBMA site visit.

### **3.3.1.2.9 Other Potential ACMs**

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to, electrical and mechanical components and insulators such as wiring and gaskets, heat shields inside incandescent light fixtures, and caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations (refer to Photos 7, 8, 10, 11, 33 and 34, Appendix B2).

Other possible hidden and inaccessible ACMs have the potential to be present within the accommodations cabin but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include concrete leveling compound (existing concrete foundation), possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components or gaskets inside appliances, concrete lining the interior of hot water tanks, and underground infrastructure or piping.

## **3.3.2 Paint Additives**

Lead compounds have been used in paint as pigment and durability additives since the early 1800s. Mercury compounds have been used in paint as anti-microbial additives up until the 1990s. PCBs have been used in paint as plasticizers and corrosion resistance additives from the 1950s to the 1970s.

During the Pre-Demolition HBMA site visit, six (6) samples (PP-PS1 to PP-PS6) were collected from painted surfaces of the accommodations cabin and one (1) sample (PP-PP-PS1) was collected from the painted surfaces of the outhouse and analyzed for lead, mercury and PCB content (refer to Photos 23 to 29, Appendix B3). Paint sample descriptions and lead, mercury and PCBs analytical results are summarized in Tables C3-2 to C3-4, Appendix C3. Sample locations and analytical results are graphically illustrated in Figure 3.1, Appendix A3.

### **3.3.2.1 Lead in Paint**

The concentrations of lead in the six (6) samples (PP-PS1 to PP-PS6) collected from painted surfaces of the accommodations cabin and one (1) sample (PP-PP-PS1) collected from the outhouse ranged from non-detect (<5.0 mg/kg) to 10,400 mg/kg (refer to Table C3-2, Appendix C3). One (1) paint sample (PP-PS6), red paint collected from the exterior door of the accommodations cabin, contained lead at a

concentration (10, 400 mg/kg) above both the Federal HPA criterion of 90 mg/kg and the former Federal HPA criterion of 5,000 mg/kg (refer to Photo 28, Appendix B3). Two (2) paint samples (PP-PS1 and PP-PS3) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg (refer to Photos 23 and 25, Appendix B2). The concentrations of lead in the other four (4) samples were below the Federal HPA criterion (90 mg/kg).

There was insufficient sample available to conduct a lead leachate analysis for PP-PS6.

### **3.3.2.2 Mercury in Paint**

The concentrations of mercury in the six (6) samples (PP-PS1 to PP-PS6) collected from painted surfaces of the accommodations cabin and one (1) sample (PP-PP-PS1) collected from the outhouse ranged from non-detect (<0.05 mg/kg) to 2.35 mg/kg and therefore, were below the Federal HPA criterion (10 mg/kg) (refer to Table C3-3, Appendix C3).

### **3.3.2.3 PCBs in Paint**

PCBs were not detected in any of the paint samples analyzed (<0.5 mg/kg), and therefore, were below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg) (refer to Table C3-4, Appendix C3).

## **3.3.3 Urea Formaldehyde Foam Insulation (UFFI)**

Visual indicators suggesting the potential presence of UFFI were not observed at Camp #2. The nature of the insulation in the walls and ceilings throughout the accommodations cabin consisted of fiberglass insulation (refer to Photos 17 and 18, Appendix B3).

Since the original date of construction of Camp #2 (assumed construction commenced the same timeframe as the original transmission line, late 1960's/early 1970's) is unknown, it is possible that UFFI may be present.

In the event that UFFI is present, the CMHC state that "tests show that UFFI is not a source of over-exposure to formaldehyde after the initial curing and release of excess gas". The general view based on studies concerning formaldehyde emissions is that as a product ages, the amount of formaldehyde off-gassed from the product decreases over time. The amount of formaldehyde released is reportedly dependent on temperature, humidity and whether or not the product is exposed to excessive moisture or water.

## **3.3.4 Suspected Visible Mould Growth (SVG)**

Wood inspected the interior areas of the accommodations cabin and outhouse for visual or olfactory evidence of suspected mould. SVG was noted on much of the ceiling and wall surfaces inside the accommodations cabin during the Pre-Demolition HBMA site visit. A sample (PP-MS-1) of the suspect mould material was collected from Room 1 for laboratory analysis to confirm the presence/absence of mould (refer to Figure 3.2, Appendix A3 and refer to Photo 30, Appendix B3).

The results of mould analysis determined that bulk sample PP-MS1 contained Cladosporium mould with abundant growth (refer to Table C3-6, Appendix C3).

### 3.3.5 Mercury-Containing Thermostats

Thermostats were not identified inside the accommodations cabin at Camp #2 during the Pre-Demolition HBMA site visit.

### 3.3.6 PCB-Containing Light Ballasts

Incandescent light fixtures were observed on the exterior and interior of the accommodations cabin and propane lanterns in Room 2 during the Pre-Demolition HBMA site visit (refer to Photos 5, 10, 11, and 35, Appendix B3). No fluorescent lights were observed.

### 3.3.7 Potential Sources of ODS and Halocarbons

During the Pre-Demolition HBMA site visit, a potential source of ODS was identified within the accommodations cabin. Results of the ODS inspection is summarized in Table 3-4.

**Table 3-4: Potential Sources of ODSs**

| Item         | Manufacturer | Model (Serial No.) | Location Observed | Photo No. (Appendix B2) | Refrigerant | Potential ODS |
|--------------|--------------|--------------------|-------------------|-------------------------|-------------|---------------|
| Freezer      | Kelvinator   | CA08-4D            | Room 1            | 31                      | R12         | Yes           |
| Refrigerator | Danby        | DPR-2260-1         | Room 1            | 32                      | NA          | No            |

Based on observations made during the site visit, ODSs are present in the accommodations cabin in the form of refrigerant R12 contained within the freezer located in Room 1 (refer to Photo 31, Appendix B3). This refrigerant (R12) is a hydrochlorofluorocarbon (HCFC) and is regulated under the Federal Halocarbon Regulations.

Fire extinguishers were not observed at Camp #2 during the Pre-Demolition HBMA site visit.

### 3.3.8 Other Potentially Hazardous Building Materials or Substances

Other potentially hazardous building materials or substances identified during this assessment are presented in the following sections.

#### 3.3.8.1 Lead-Containing Materials and Equipment

Lead is typically associated with plumbing solder and older pipe materials (e.g., cast iron pipe joints), as well as products such as radiation protective shielding and lead-acid batteries. Lead can also be present in steel and iron primer, industrial electrical jacketing, roof flashing and tank linings.

Since the actual date that Camp #2 was constructed is unknown (assumed to be late 1960's/early 1970's), it is possible that lead solder is present in plumbing and piping (i.e., cast iron and copper piping) in the



accommodations cabin, as lead solder for use in potable water distribution pipes was not banned until the late 1980s (refer to Photos 33 and 34, Appendix B2).

### **3.3.8.2 Mercury-Containing Materials and Equipment**

The light tubes and bulbs in HID and fluorescent light fixtures often contain limited quantities of mercury in a powder or vapour form. Incandescent light fixtures and propane lanterns were observed on the exterior and the interior of the accommodations cabin during the Pre-Demolition HBMA site visit (Photos 5, 10, 11, and 35, Appendix B2). No fluorescent lights were observed.

### **3.3.8.3 PCB-Containing Materials and Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, and as mentioned previously, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

### **3.3.8.4 Treated Wood Chemicals**

The chemicals that are used to protect and preserve wood products from insect attack and fungal decay may pose risks to human health and the environment. Depending on the wood treatment used, treated wood may be considered a hazardous waste upon disposal. The NL Department of Environment and Conservation (currently the NL MAE), 2015 Guidance Document for Treated Wood Waste Disposal (GD-PPD-075.1) provides landfill disposal standards for “pressure treated” inorganic preservatives (i.e., arsenic and chromium) and creosote (i.e., total cresol and benzo(a)pyrene) and chlorophenolic (i.e., pentachlorophenol) formulations used to preserve wood. These landfill disposal standards for treated wood waste (TWW) are used to assess the results of leachability testing to determine disposal options for treated wood to be removed during renovation or demolition activities.

During the Pre-Demolition HBMA site visit, suspected “creosote treated” inorganic (i.e., chromated copper arsenate (CCA)) preservatives appear to have been applied to wood that was used as the foundation of the outhouse. One (1) sample of treated wood (PP-TW1) was collected from the foundation and analyzed for leachable benzo(a)pyrene and leachable cresols to determine whether or not the treated wood would be considered hazardous waste upon removal from the site, if required. The bulk sample description and leachable treated wood parameter analytical results are summarized in Table C3-5, Appendix C3. The sample location and analytical results are graphically illustrated in Figure 3.2, Appendix A3.

Leachable benzo(a)pyrene and leachable cresols were not detected above the RDLs in the treated wood sample PP-TW1; therefore, the concentrations of these leachable treated wood parameters were below the TCLP landfill disposal standards for leachable benzo(a)pyrene (1 µg/L) and leachable cresols (20,000 µg/L) provided in the NL Department of Environment and Conservation (currently the NL MAE), 2015 Guidance Document for Treated Wood Waste Disposal (GD-PPD-075.1).

### **3.3.8.5 Silica**

According to the CPWR – The Center for Construction Research and Training, many common construction materials contain silica including, asphalt, brick, cement, concrete, drywall, grout, mortar, stone, sand and

tile. The dust created by cutting, grinding, drilling or otherwise disturbing these materials can contain crystalline silica particles.

Based on the Pre-Demolition HBMA site visit, silica is expected to be present in concrete used in the construction of the foundation for the accommodations cabin. Silica may also be present in the asphalt shingles used in the construction of the accommodations cabin.

### **3.3.8.6 Radioactive Materials**

A smoke detector was observed in Room 1 of the accommodations cabin during the Pre-Demolition HBMA site visit (refer to Photo 35, Appendix B3). Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called "ion chamber smoke alarms".

## **3.4 CONCLUSIONS AND RECOMMENDATIONS**

Based on observations made and information gathered during the Pre-Demolition HBMA, the following conclusions and recommendations are made with respect to the potential and actual presence of hazardous building materials at Camp #2.

### **3.4.1 ACMs**

Results of the asbestos sampling and analytical program revealed building materials containing greater than 1% asbestos by dry weight, which are considered to be ACMs, are present in the form of non-friable black asphalt shingles on the roof of the accommodations cabin and non-friable black asphalt shingles and tar on the roof of the outhouse.

The asbestos-containing black asphalt shingles visible on the roof of the accommodations cabin (covering an area of approximately 55 m<sup>2</sup>), as observed from the ground surface, appeared to be generally intact and in fair condition. The asbestos-containing black shingle and tar visible on the on the roof of the outhouse (covering an area of approximately 3 m<sup>2</sup>) also appeared to be generally intact and in fair condition.

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to:

- Electrical and mechanical components and insulators such as wiring and gaskets.
- Heat shields inside incandescent/ propane light fixtures.
- Caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations.

Other possible hidden and inaccessible ACMs have the potential to be present within the buildings at Camp #2 but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include concrete leveling compound (existing concrete foundation), possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat

resistant components, concrete lining the interior of hot water tanks, and underground infrastructure or piping.

If other potential ACMs that were not sampled as part of this assessment are encountered in the future, these materials should be treated as ACMs or samples should be collected and tested to verify asbestos content. This should be done as soon as these materials are encountered and before these materials are disturbed. This includes materials that are currently concealed by walls and ceiling systems.

In accordance with the NL Asbestos Abatement Regulations (Reg. 111/98), which provide the legislative requirements for safe handling of ACMs in workplaces in the Province of NL, the following is recommended:

- Safe work procedures shall be established.
- All buildings constructed during the period when asbestos was readily used in construction (generally prior to the early 1980s) or any buildings that are suspected as having asbestos must have a written assessment and management plan (where applicable) for potential ACMs.
- Materials suspected of containing asbestos are required to be handled as ACMs, until analysis by a competent laboratory determines whether or not it does contain asbestos.
- Prior to general demolition, all ACMs must be safely removed from the building and disposed of in accordance with appropriate environmental guidelines by an asbestos abatement contractor registered with the Occupational Health and Safety (OHS) Division of Service NL.
- Most work involving ACMs (i.e., disturbance, removal and encapsulation) must be conducted by a contractor registered with the OHS Division of Service NL.
- ACMs in good condition should be inspected on an annual basis.
- ACMs in poor condition should be removed from the building and transported off-site for proper disposal.
- Workers should don adequate respiratory protection and personal protective equipment (PPE) when working with ACMs.

Prior to the removal and/or abatement of any identified ACMs (or any other hazardous building materials), an abatement plan including technical specifications should be designed, prepared and supervised by a qualified professional and should be undertaken by qualified trades, in accordance with applicable standards. Activities involving the disturbance and/or removal of ACMs should be carried out in a manner that ensures asbestos fiber concentrations do not exceed the applicable American Conference of Governmental Industrial Hygienists (ACGIH) threshold limit value (TLV). ACMs can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.

### **3.4.2 Lead, Mercury and PCBs in Paint**

Results of the paint sampling and analytical program revealed the following:

- **Lead and Leachable Lead in Paint**
  - Concentrations of lead in the six (6) samples (PP-PS1 to PP-PS6) collected from painted surfaces of the accommodations cabin and one (1) sample (PP-PP-PS1) collected from the outhouse ranged from non-detect (<15.0 mg/kg) to 10,400 mg/kg.
  - One paint sample (PP-PS6) contained lead at a concentration (10,400 mg/kg) above the Federal HPA criterion of 90 mg/kg and the former Federal HPA criterion of 5,000 mg/kg. There was

insufficient sample available to conduct a lead leachate analysis to determine disposal option for this paint (red paint on exterior door of the accommodations building).

- Two paint samples (PP-PS1 and PP-PS3) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg; and therefore, these paints are considered to be LBPs but are not likely to be leachable for lead.
- The concentrations of lead in the other four (4) paint samples were below the Federal HPA criterion (90 mg/kg); and therefore, these paints are not considered to be LBPs and are not likely to be leachable for lead.

- **Mercury and Leachable Mercury in Paint**

- The concentrations of mercury in six (6) samples (PP-PS1 to PP-PS6) collected from painted surfaces of the accommodations cabin and one (1) sample (PP-PP-PS1) collected from the outhouse ranged from non-detect (<0.05 mg/kg) to 2.35 mg/kg; below the Federal HPA criterion (10 mg/kg). These paints are not considered to be MBPs and are not likely to be leachable for mercury.

- **PCBs in Paint**

- PCBs were not detected in the six (6) samples (PP-PS1 to PP-PS6) collected from painted surfaces of the accommodations cabin and one (1) sample (PP-PP-PS1) collected from the outhouse were non-detect for PCBs (<0.5 mg/kg) and contained PCBs at concentrations below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg).

Given that the concentration of lead detected in paint sample PP-PS6 (red paint on the exterior door (also potentially on metal window/door covers and window/door trims) of the accommodations cabin) contains lead at a concentration (10, 400 mg/kg) above the former Federal HPA criterion of 5,000 mg/kg, lead leachate analysis is required to determine whether or not the painted surfaces of painted surfaces of the door, window/door covers and window/door trims can be disposed of at a landfill. Alternatively, the metal door and associated trim may be sent to a metal recycling facility, provided the facility is informed about the concentration of lead in the paint. Given the nature of the paint on the exterior door (thin layer of paint on metal), it may not be possible to collect enough volume of paint for leachate analysis.

Based on the paint sample analytical results, the other paint samples collected from accommodations cabin and outhouse are not likely to be leachable for lead, mercury and PCBs; and therefore, should disposal be required (e.g., renovation or demolition activities), the paints analyzed for lead and mercury content may be disposed of at an approved landfill facility, pending landfill and Provincial regulatory approval.

There are potential adverse human health impacts associated with disturbing (e.g., scraping, sanding, burning, etc.) lead-containing paint finishes, due to the potential for dust, mist or fumes to be released and inhaled or ingested by workers. As a precautionary measure, Wood recommends handling these paint finishes, as follows:

- In areas of minor peeling or flaking, the paint should be removed using wet scraping techniques.
- In areas of extensive peeling and flaking, the paint should be removed and more extensive particulate control measures may be required.
- In areas where lead-containing paint finishes are present and in poor condition, an experienced contractor should be utilized for renovating, decommissioning or demolition activities.

- Prior to renovation, dismantling or demolition activities, all areas of extensive peeling and flaking of lead-containing paint finishes and paint debris/dust should be removed and/or remediated to ensure that building occupants/workers are protected from associated dust/particulate.
- Procedures should be implemented to ensure that workers and anyone present in and around areas being renovated, dismantled or demolished are protected. The contractor should also ensure that dust generation and migration is minimized.
- Precautions should be taken to prevent/reduce exposure to paint dust during any disturbance of lead-containing paint finishes, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas.
- Where possible, lead-containing paint finishes should be removed from metal surfaces prior to welding or cutting these materials.

If potential lead, mercury or PCB containing paint finishes that were not sampled during this assessment are encountered in future, prior to any disturbance or removal, samples should be obtained and tested to verify concentrations of lead, mercury and PCBs. This includes materials that are currently concealed by walls and ceiling systems.

Any disturbance or removal of lead, mercury or PCB-containing paint finishes that may generate dust or respirable aerosols must conform to the Federal and Provincial OHS Regulations. All work should be carried out by individuals wearing proper PPE. The type of respiratory protection and control measures to be implemented during the removal of these types of paint finishes should be determined by a qualified person and based on the risk level of a particular work activity (i.e., scraping, sanding, abrasive blasting, etc.). Activities involving the disturbance and/or removal of lead, mercury or PCB-containing paint finishes should be carried out in a manner that ensures paint dust concentrations do not exceed the applicable ACGIH TLVs.

### **3.4.3 Potential UFFI**

The sale and installation of UFFI was banned in 1980; since the original date of construction is unknown, it is possible that UFFI may be present in the building. Visual indicators suggesting the potential presence of UFFI were not observed in the building. It can be inferred that any UFFI present within the building is unlikely to affect the indoor air quality due to the amount of time that has passed since the insulation was likely installed (i.e., pre-1980) along with the likelihood that formaldehyde has off-gassed over this period of time. It should be noted that, the presence and concentration of formaldehyde cannot be determined or quantified without conducting site-specific testing for formaldehyde.

Although there is currently no Provincial regulations requiring that the removal of UFFI be conducted by a licensed/registered abatement contractor, based on discussions with representatives of the OHS Division of Service NL, it is strongly recommended that this material be abated using similar methods as required for asbestos abatement and that the insulation must be removed in a dry condition. Based on discussions with representatives of the NL MAE, for the purposes of disposal of UFFI, this material is permitted to be bagged and transported to an approved WDS and disposed in the special waste area (unlined area) of the site.

#### **3.4.4 Mould**

SVG was noted on much of the ceiling and wall surfaces inside the accommodations cabin during the Pre-Demolition HBMA site visit. The results of mould analysis determined that bulk sample PP-MS1 contained *Cladosporium* mould with abundant growth.

Mould spores are present in all indoor environments and cannot be completely eliminated. Cellulose based building materials provide a nutrient base for many mould species; however, mould cannot grow unless an adequate amount of excess moisture is present. The most effective way to prevent mould growth within a building is the prompt removal of any porous building materials with water damage or mould growth and repairing the building components that lead to the water infiltration.

#### **3.4.5 Potential ODS**

Based on observations made during the site visit, ODSs are present in the accommodations cabin in the form of refrigerant R12 contained in a freezer located in Room 1. This refrigerant (R12) is a hydrochlorofluorocarbon (HCFC) and is regulated under the Federal Halocarbon Regulations.

Ozone depleting substances (ODS), if present, should be removed by an approved contractor prior to disposing of any cooling and/or refrigeration equipment from the building. The use, storage, operation, maintenance, decommissioning, and disposal of ODS containing equipment, in general, is regulated at both a Provincial and Federal level and must comply with the most recent NL Halocarbon Regulations and the Federal Halocarbon Regulations. The status of the potential ODS containing equipment should be confirmed through a mechanical contractor or consultant.

#### **3.4.6 Potential Lead-Containing Materials/Equipment**

Lead solder is likely to be present in plumbing and piping (e.g., cast iron and copper piping) in the accommodations cabin.

The disturbance, control or disposal of lead-containing material/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of lead in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a metal recycling facility and not a landfill. Removal of lead-containing batteries should be completed in a manner that ensures structural integrity and no loss of fluid from the batteries. Should disposal be required, disposal of lead-containing batteries should be completed in accordance with hazardous waste procedures/guidelines (i.e., at an approved facility).

Sampling drinking water for the analysis of lead was not included in the scope of work for the Pre-Demolition HBMA.

#### **3.4.7 Potential Mercury-Containing Materials/Equipment**

Should disposal be required, mercury-containing equipment should be removed intact and returned to the manufacturer for recycling, or disposed of at an approved hazardous waste disposal facility. The disturbance, control or disposal of mercury-containing materials/equipment should be carried out in

accordance with applicable criteria/regulations (refer to Section 1.5 of this report). The presence/absence of mercury in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a recycling or hazardous waste disposal facility and not a landfill.

### **3.4.8 Potential PCB-Containing Materials/Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

If PCB-containing materials or equipment are encountered in the future, and should disposal be required, the PCB content in the materials or equipment should be confirmed prior to disposal.

Any PCB-containing equipment (if present) should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations. Any PCB-containing equipment requiring removal from the building should be transported and disposed of at an approved hazardous waste disposal site, and not a landfill disposal site, by a registered hazardous waste transporter in accordance with applicable regulations.

### **3.4.9 Silica Containing Materials**

Silica is expected to be present in concrete used in the construction of the foundation for the accommodations cabin. Silica may also be present in asphalt shingles used in the construction of accommodations cabin. Precautions should be taken to prevent/reduce exposure to silica dust during any disturbance/ demolition of silica-containing products, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas. Activities involving the disturbance and/or demolition of silica-containing materials should be carried out in a manner that ensures silica dust concentrations do not exceed the applicable ACGIH TLV.

### **3.4.10 Potential Radioactive Materials**

One smoke detector was observed during the Pre-Demolition HBMA site visit (refer to Photo 35, Appendix B3). Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called "ion chamber smoke alarms".

### **3.4.11 Summary of Findings**

Hazardous building materials identified at Camp #2 during this Pre-Demolition HBMA and disposal options, if required, are summarized in Table 3-5. Conclusions and recommendations made with respect to the potential and actual presence of hazardous building materials within the accommodations cabin and outhouse are provided in Section 3.4 and should be reviewed in conjunction with Table 3-5.

**Table 3-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| Hazardous Material | Applicable Acts, Regulations or Guidance Documents   | Description and Location  | Disposal  |
|--------------------|--|---|---|
| <b>ACMs</b>        | NL Asbestos Abatement Regulations (Reg. 111/98)  | <p>Non-friable black shingle (asbestos containing) on the roof of the accommodations cabin (~55m<sup>2</sup>).</p> <p>Non-friable black shingle and tar (asbestos containing) on the roof of the outhouse (~3m<sup>2</sup>).</p> <p>Note that other possible hidden and inaccessible ACMs have the potential to be present within the accommodations building, but were not identified during the Pre-Demolition HBMA site visit.</p> | <p>ACMs cannot be disposed of at a Construction &amp; Demolition Site; however, these materials can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.</p> <p>The transportation and disposal of asbestos should be conducted in accordance with the NL Asbestos Abatement Regulations (Reg. 111/98) and with Standard Operating Procedures (SOPs) for disposal of ACMs at the landfill.</p>   |
| <b>LBP</b>         | <p>Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)</p> <p>Federal HPA (R.S.1985, c. H-3)</p> <p>Federal TDG Act (1992, c. 34)</p> <p>Surface Coating Materials Regulations (SOR/2016-193)</p> | <p>LBP (white) on plywood in Room 1 of accommodations cabin.</p> <p>LBP (red) on concrete on exterior of accommodations cabin.</p> <p>LBP (red) on exterior door and door trim (also potentially on metal window/door covers and window/door trims) of the accommodations cabin (Potentially leachable).</p>  | <p>Paints that were analyzed for lead and contained &lt;5,000 mg/kg lead, may be disposed of at a Regional Solid Waste Disposal Facility (landfill), provided permission is obtained from the landfill owner/operator.</p> <p>Given that the concentration of lead detected in paint sample PP-PS6 (red paint on the exterior door of the accommodations building) contains lead at a concentration (10,400 mg/kg) above the former Federal HPA criterion of 5,000 mg/kg, lead leachate analysis is required to determine whether or not the door can be disposal of at a landfill. Alternatively, the door and associated trim may be sent to a metal recycling facility, provided the facility is informed about the concentration of lead in the paint. Given the nature of the paint on the exterior door (thin layer of paint on metal), it may not be possible to collect enough volume of paint for leachate analysis.</p> |



**Table 3-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b>                                | <b>Applicable Acts, Regulations or Guidance Documents</b>  | <b>Description and Location</b>   | <b>Disposal</b>  |
|--|--|---|--|
| <b>Potential UFFI</b>                                    | Federal HPA (R.S.1985, c. H-3)   | None Identified   | UFFI is permitted to be bagged and transported to an approved WDS and disposed in the special waste area of the site.  |
| <b>Mould</b>   | Mould Guidelines for the Canadian Construction Industry, Canadian Construction Industry (CCI), 2004;<br><br>Mould Abatement Guidelines, Environmental Abatement Council of Ontario (EACO), 2010  | Bulk Sample PP-MS1 contained Cladosporium mould with abundant growth in the accommodations cabin. Quantity unknown. | All mould impacted materials may be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.   |
| <b>Potential ODS</b>                                     | Federal Halocarbon Regulations (SOR/2003-289)  | R12 refrigerant in freezer in Room 1.   | Materials containing ODS should be received by a contractor or facility that has the proper approvals to remove, handle and/or dispose of ODS. The remaining materials can be disposed of at a recycling facility, provided permission is obtained from the facility.  |
| <b>Potential Lead-Containing Materials/ Equipment</b>    | Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)<br><br>Federal HPA (R.S.1985, c. H-3)<br><br>Federal TDG Act (1992, c. 34)<br><br>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301) | Potential lead-containing solder (piping and plumbing)  | Lead-containing materials and equipment can be disposed of at a metal recycling or hazardous waste disposal facility, in accordance with applicable regulations.<br><br>The transportation and disposal of hazardous lead-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility. |
| <b>Potential Mercury-Containing Materials/ Equipment</b> | Federal HPA (R.S.1985, c. H-3)<br><br>Federal TDG Act (1992, c. 34)<br><br>Products Containing Mercury Regulations (SOR/2014-254)  | None identified   | Mercury-containing materials and equipment can be disposed of at a recycling or hazardous waste disposal facility, in accordance with applicable regulations.<br><br>The transportation and disposal of hazardous mercury-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility. |

**Table 3-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| Hazardous Material                                   | Applicable Acts, Regulations or Guidance Documents  | Description and Location       | Disposal  |
|--|---|--------------------------------|---|
| <b>Potential PCB-Containing Materials/ Equipment</b> | Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)<br>Federal TDG Act (1992, c. 34)<br>Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)<br>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301)<br>PCB Regulations (SOR/2008-273)<br>PCB Waste Export Regulations (SOR/97-109)<br>Regulations Amending the PCB Regulations (SOR/2010-57) | None identified                | Any PCB-containing materials and equipment should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations.<br><br>Any PCB-containing materials and equipment requiring removal from the building should be transported and disposed of by a registered hazardous waste transporter in accordance with applicable regulations.<br><br>The transportation and disposal of PCB containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility. |
| <b>Silica-Containing Materials</b>                   | NL OHS Act (RSNL1990 Chapter O-3)<br>NL OHS Regulations (5/12)  | Asphalt shingles and concrete. | These materials can be disposed of at a Regional Solid Waste Disposal Facility (landfill).  |
| <b>Potential Radioactive Materials</b>               | Federal TDG Act (1992, c. 34)   | Smoke detector – Room 2        | Smoke detectors that contain low level radioactive materials must be transported, as per Federal TDG Regulations, to a licensed disposal facility.  |

## **APPENDIX A3**

### **FIGURES**



**NOTES:**  
 1. ALL DIMENSIONS ARE IN METERS.  
 2. DO NOT SCALE FROM FIGURE.  
 3. THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.  
 4. ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.  
 5. THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.  
 6. THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



newfoundland labrador  
**hydro**  
 a nalcor energy company

---

**Wood**  
 Environment & Infrastructure Solutions  
 133 Crosbie Road  
 St. John's, NL A1B 4A5  
 709-722-7023



Drawn by:  
 T. Rideout

Approved by:  
 C. Finney

Scale:  
 As Shown

Project:  
 Pre-Demolition Hazardous Building Materials Assessment,  
 Former Construction Camp Sites,  
 Bay d'Espoir - Avalon Transmission Line, NL



Title:  
 Site Location Plan (Aerial) - Camp #2 Site

Date:  
 April 2019

Project No.  
 TF18104243.2000


Rev. No.  
 0

Figure No.  
 3.1



**LEGEND:**


- ASBESTOS SAMPLE LOCATION - ASBESTOS NOT DETECTED
- ASBESTOS SAMPLE LOCATION - RESULTS > 1% FOR ASBESTOS
- ▲ PAINT SAMPLE LOCATION - NO CRITERIA EXCEEDANCES FOR LEAD OR MERCURY OR PCBs WHERE APPLICABLE
- ▲ PAINT SAMPLE LOCATION - RESULTS EXCEED 90 mg/kg AND LESS THAN 5000 mg/kg FOR LEAD AND NO CRITERIA EXCEEDANCES FOR MERCURY OR PCBs WHERE APPLICABLE
- ▲ PAINT SAMPLE LOCATION - RESULTS EXCEED 5000 mg/kg FOR LEAD AND NO CRITERIA EXCEEDANCES FOR MERCURY OR PCBs WHERE APPLICABLE
- ABUNDANT MOULD GROWTH DETECTED
- Ⓣ TREATED WOOD SAMPLE LOCATION - NO CRITERIA EXCEEDANCES



**NOTES:**


- ALL DIMENSIONS ARE IN METERS.
- DO NOT SCALE FROM FIGURE.
- THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.
- ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.
- THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.
- THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



newfoundland labrador  
a nalcor energy company

**Wood**  
Environment & Infrastructure Solutions  
133 Crosbie Road  
St. John's, NL A1B 4A5  
709-722-7023



Drawn by:  
T. Rideout

Approved by:  
C. Finney

Scale:  
As Shown

Project:  
Pre-Demolition Hazardous Building Materials Assessment,  
Former Construction Camp Sites,  
Bay d'Espoir - Avalon Transmission Line, NL

Title:  
Sample Location Plan - Camp #2 Site

|                                |
|--------------------------------|
| Date:<br>April 2019            |
| Project No.<br>TF18104243.2000 |
| Rev. No.<br>0                  |
| Figure No.<br>3.2              |

**APPENDIX B3**  
**PHOTOGRAPHIC RECORD**



Photo 1: View of the transmission lines near Camp #2, looking south.



Photo 2: View of the gravel access road at Camp #2, looking northeast.



Photo 3: View of the land west of the accommodations cabin at Camp #2.



Photo 4: View of the land east of the accommodations cabin at Camp #2.



Photo 5: View of the accommodations cabin at Camp #2, looking northwest.



Photo 6: View of the accommodations cabin at Camp #2, looking north.



Photo 7: View of the land north of the accommodations cabin at Camp #2, looking north.



Photo 8: View of the kitchen inside the accommodations cabin at Camp #2.





Photo 9: View of the kitchen of the accommodations cabin at Camp #2.



Photo 10: View of the bedroom of the accommodations cabin at Camp #2.



Photo 11: View of the bedroom of the accommodations cabin at Camp #2.



Photo 12: View of the bathroom in the accommodations cabin at Camp #2.



Photo 13: View of outhouse, looking northeast.



Photo 14: View of outhouse foundation, looking southwest.



Photo 15: View of cavity inspection on the exterior of cabin.



Photo 16: View of cavity inspection in the floor of cabin.



Photo 17: View of bulk material sample PP-AS-1, black paper backing and pink fibreglass insulation, cabin interior.



Photo 18: View of bulk material sample PP-AS-2, tar paper, cabin interior.



Photo 19: View of bulk material sample PP-AS-3, black shingle, cabin exterior. **2.2 % Crysotile Asbestos**



Photo 20: View of bulk material sample PP-AS-4, concrete, cabin exterior.



Photo 21: View of bulk material sample PP-AS-5, concrete block and mortar, cabin exterior.



Photo 22: View of bulk material sample PP-PP-AS1, black shingle and tar, outhouse exterior. **1.1 % Cryotile Asbestos**



Photo 23: View of paint sample PP-PS1, floor, cabin interior.



Photo 24: View of paint sample PP-PS2, wall, cabin exterior.



Photo 25: View of paint sample PP-PS3, wall, cabin exterior.



Photo 26: View of paint sample PP-PS4, ceiling, cabin interior.



Photo 27: View of paint sample PP-PS5, wall, cabin exterior.




Photo 28: View of paint sample PP-PS6, wall, cabin exterior.  
**Lead concentration = 10,400 mg/kg**



Photo 29: View of location of paint sample PP-PP-PS1, wall of outhouse exterior.



Photo 30: View of bulk mould sample PP-MS1, wall of cabin interior.



Photo 31: View of kelvinator freezer (R12 refridgerant containing), cabin interior.



Photo 32: View of propane fired refridgerator, cabin interior.



Photo 33: View of propane fired hot water tank and copper pipes, cabin interior.



Photo 34: View of copper piping under bathroom sink, cabin interior.



Photo 35: View of incandescent lighting and smoke detector, cabin interior.



Photo 36: View of ducting from propane stove, cabin interior.

**APPENDIX C3**

**SAMPLE AND ANALYTICAL SUMMARY TABLES**



**Table C3-1: Bulk Sample Descriptions and Asbestos Analytical Results (Camp #2)**

| Sample ID | Room No. | Room Description    | Photo No. | Sample Location | Sample Description                                  | Layers Analyzed     | Analytical Result |
|-----------|----------|---------------------|-----------|-----------------|---|---------------------|-------------------|
| PP-AS-1   | 1        | Kitchen             | 13        | Ceiling         | Black paper backing over pink fibreglass insulation | insulation          | ND                |
| PP-AS-2   | 1        | Kitchen             | 14        | Ceiling         | Tar paper   | tar paper           | ND                |
| PP-AS-3   | Exterior | Exterior            | 15        | Roof            | Black shingle                                       | shingle             | <b>2.20%</b>      |
| PP-AS-4   | Exterior | Exterior            | 16        | Foundation      | Concrete  | concrete            | ND                |
| PP-AS-5   | Exterior | Exterior            | 17        | Foundation      | Concrete block and mortar                           | concrete and mortar | ND                |
| PP-PP-AS1 | Exterior | Exterior - Outhouse | 18        | Roof            | Black shingle and black tar                         | shingle and tar     | <b>1.10%</b>      |

**Notes:**

ACM: Asbestos-Containing Material

DJC: Drywall Joint Compound

VFT: Vinyl Floor Tile

VSF: Vinyl Sheet Flooring

ND: Non-Detect (<0.1%)

\*Brown paper and tar analyzed as one layer because the laboratory could not separate these materials.

**Bold and underlined value indicates asbestos was detected but is below 1% by dry weight.**

Shaded value exceeds 1% asbestos by dry weight and is considered to be an ACM as outlined in the Newfoundland and Labrador Asbestos Abatement Regulations (Reg. 111/98).

**Table C3-2: Paint Sample Descriptions and Lead Analytical Results (Camp #2)**

| Sample ID | Room No. | Room Description | Photo No. | Sample Location | Substrate      | Sample Description                                  | RDL (mg/kg) | Lead (mg/kg)   |
|-----------|----------|------------------|-----------|-----------------|----------------|---|-------------|----------------|
| PP-PS1    | 1        | Kitchen          | 19        | Ceiling         | Plywood        | White on plywood (sample includes plywood)          | 15.0        | <u>103</u>     |
| PP-PS2    | Exterior | Exterior - Cabin | 20        | Wall            | Metal          | Blue on metal siding (sample includes metal siding) | 15.0        | 64             |
| PP-PS3    | Exterior | Exterior - Cabin | 21        | Wall            | Concrete block | Red on concrete (sample includes paint on concrete) | 15.0        | <u>122</u>     |
| PP-PS4    | 2        | Bedroom          | 22        | Floor           | Plywood        | Grey on plywood (sample includes wood)              | 15.0        | <15            |
| PP-PS5    | Exterior | Exterior - Cabin | 23        | Wall            | Wood Trim      | White on wood trim (sample includes wood)           | 15.0        | <15            |
| PP-PS6    | Exterior | Exterior - Cabin | 24        | Exterior Door   | Door           | Red on door   | 15.0        | <b>10,400*</b> |
| PP-PP-PS1 | Exterior | Outhouse         | 25        | Wall            | Plywood        | Grey on plywood (sample includes plywood)           | 15.0        | <15            |

**Notes:**

<X: Non-Detect

\* Insufficient sample to analyze for leachable lead

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

**Bold and underlined value exceeds Federal HPA criterion (90 mg/kg).**

**Shaded value exceeds former Federal HPA criterion (5,000 mg/kg).**

**Table C3-3: Paint Sample Descriptions and Mercury Analytical Results (Camp #2)**

| Sample ID | Room No. | Room Description | Photo No. | Sample Location | Substrate      | Sample Description                                  | RDL (mg/kg) | Mercury (mg/kg) |
|-----------|----------|------------------|-----------|-----------------|----------------|---|-------------|-----------------|
| PP-PS1    | 1        | Kitchen          | 19        | Ceiling         | Plywood        | White on plywood (sample includes plywood)          | 0.05        | 2.35            |
| PP-PS2    | Exterior | Exterior - Cabin | 20        | Wall            | Metal          | Blue on metal siding (sample includes metal siding) | 0.05        | <0.05           |
| PP-PS3    | Exterior | Exterior - Cabin | 21        | Wall            | Concrete block | Red on concrete (sample includes paint on concrete) | 0.05        | 0.78            |
| PP-PS4    | 2        | Bedroom          | 22        | Floor           | Plywood        | Grey on plywood (sample includes wood)              | 0.05        | 0.19            |
| PP-PS5    | Exterior | Exterior - Cabin | 23        | Wall            | Wood Trim      | White on wood trim (sample includes wood)           | 0.05        | <0.05           |
| PP-PS6    | Exterior | Exterior - Cabin | 24        | Exterior Door   | Door           | Red on door   | 0.05        | 0.81            |
| PP-PP-AS1 | Exterior | Outhouse         | 25        | Wall            | Plywood        | Grey on plywood (sample includes plywood)           | 0.05        | 0.16            |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

**Bold and underlined value exceeds Federal HPA criterion (10 mg/kg).**

Shaded value exceeds CCME CSQG for an industrial site (50 mg/kg).

**Table C3-4: Paint Sample Descriptions and PCB Analytical Results (Camp #2)**

| Sample ID | Room No. | Room Description | Photo No. | Sample Location | Substrate      | Sample Description                                  | RDL (mg/kg) | Total PCB (mg/kg) |
|-----------|----------|------------------|-----------|-----------------|----------------|---|-------------|-------------------|
| PP-PS1    | 1        | Kitchen          | 19        | Ceiling         | Plywood        | White on plywood (sample includes plywood)          | 0.5         | <0.5              |
| PP-PS2    | Exterior | Exterior - Cabin | 20        | Wall            | Metal          | Blue on metal siding (sample includes metal siding) | 0.5         | <0.5              |
| PP-PS3    | Exterior | Exterior - Cabin | 21        | Wall            | Concrete block | Red on concrete (sample includes paint on concrete) | 0.5         | <0.5              |
| PP-PS4    | 2        | Bedroom          | 22        | Floor           | Plywood        | Grey on plywood (sample includes wood)              | 0.5         | <0.5              |
| PP-PS5    | Exterior | Exterior - Cabin | 23        | Wall            | Wood Trim      | White on wood trim (sample includes wood)           | 0.5         | <0.5              |
| PP-PS6    | Exterior | Exterior - Cabin | 24        | Exterior Door   | Door           | Red on door   | 0.5         | <0.5              |
| PP-PP-AS1 | Exterior | Outhouse         | 25        | Wall            | Plywood        | Grey on plywood (sample includes plywood)           | 0.5         | <0.5              |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

NL MAE: Newfoundland and Labrador Department of Municipal Affairs and Environment

TDG: Transportation of Dangerous Goods

\*Sample collected by Hydro on May 5, 2018.

**0.5 mg/kg exceeds CCME CSQG for an industrial site (33 mg/kg).**

Shaded value exceeds the criterion for PCB solid provided in the NL MAE Leachable Toxic Waste, Testing and Disposal Guidance Document and the TDG Regulations (50 mg/kg).

**Table C3-5: Bulk Sample Descriptions and Leachable Treated Wood Parameter Analytical Results (Camp #2)**

|                               |               | Data           | Guidelines   |  |  |
|-------------------------------|---------------|----------------|--|--|--|
| Sample ID                     |               | PP-TW1         | ENVC Guidance Document<br>Treated Wood Waste Disposal<br>Amended September 2015 (GD-PPD-075.1) |  | ENVC Guidance Document<br>Leachable Toxic Waste, Testing and Disposal<br>Revised November 2003 (GD-PPD-26.1) |
| Sample Location and Room No.  |               | Outhouse       |  |  |  |
| Detailed Material Description |               | Crosote Wood   |  |  |  |
| Location (Photo No.)          |               | Under Outhouse |  |  |  |
| Parameters                    | RDL<br>(µg/L) | (µg/L)         | Column 2: TCLP Limits<br>(CEPA) (µg/L)   | Column 3: Double TCLP<br>Limits (µg/L) | Schedule II (Interprovincial Movement of<br>Hazardous Waste Regulations (pending))<br>(µg/L)                 |
| Leachable Benzo(a)pyrene      | 0.001         | <0.001         | 1  | 2                                      | 1  |
| Leachable m/p-Cresol          | 0.0           | <0.008         | -  | -                                      | 200,000  |
| Leachable o-Cresol            | 0.0           | <0.004         | -  | -                                      | 200,000  |
| Leachable Cresol Total        | 0.0           | <0.012         | 200,000  | 400,000                                | 200,000  |

**Notes:**

RDL: Reportable detection limit

ENVC: Newfoundland and Labrador Department of Environment and Conservation

TCLP: Toxicity Characteristic Leaching Procedure

CEPA: Canadian Environmental Protection Act

TWW: Treated Wood Waste

-: Value Not Established

**Shaded results indicate that TCLP concentration exceeds Column 2 TCLP limits provided in the TWW Disposal Guidance Document.**

**Underlined results indicate that TCLP concentration exceeds Schedule II TCLP limits provided in the Leachable Toxic Waste Guidance Document.**

Underlined results indicate that TCLP concentration exceeds Column 3 TCLP limits provided in the TWW Disposal Guidance Document.

**Table C3-6: Bulk Sample Descriptions and Mould Analytical Results (Camp #2)**

| Sample ID | Detailed Material Description | Sample Location | Mould Identified    | Analytical Result |
|-----------|-------------------------------|-----------------|---------------------|-------------------|
| PP-MS-1   | Bulk sample (including wood)  | Room 1          | <i>Cladosporium</i> | Abundant          |

**Notes:**

1. Mould growth is subjectively assessed with description terms sparse, moderate and abundant.
2. The presence of spores (lacking other fungal structures associated) is assessed as following: a few spores (< 10 spores average per microscopic field at 400X), some spores (10 - 100 spores average per microscopic field at 400X), many spores (> 100 spores average per microscopic field at 400X).
3. The presence of a few spores generally represents settled spores on the surface of the sample rather than indicating mould growth.

**APPENDIX D3**

**ROOM-BY-ROOM INSPECTION SHEETS**

| Building       | Room #   | Floor # | Room Description | Dimensions                   |
|----------------|----------|---------|------------------|------------------------------|
| Pynns (Camp 2) | Exterior |         | Exterior         | L = 32'<br>W = 18'<br>H = 8' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|--|--|---------------------------|--|
| <del>Floor</del><br>Foundation  | Concrete   |  |                           |  |
| <del>Walls</del><br>(include window caulking)   | Metal siding / Cinderblock   |  |                           |  |
| <del>Ceiling</del>  | black shingles   |  |                           |  |
| <del>Paint</del><br>(and substrate)   | Walls: blue on siding + Redon<br>Ceiling: Cinderblock<br>Floor:<br>Other:                    |  |                           |  |
| <del>Insulation</del><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:   |  |                           |  |
| <del>Piping /<br/>Mechanical<br/>Equipment</del>  |  |  |                           |  |
| <del>Fluorescent<br/>Lighting</del>   | Ballast Manufacturer:<br>Serial #:   | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <del>Other Lighting</del><br>(e.g., incandescent,<br>HID)                                   | 2 → incandescent   |  |                           |  |
| <del>Thermostats</del>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <del>LCMs</del><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 |  |  |                           |  |
| <del>Mould / Water<br/>Staining</del>   | Area impacted  |  |                           |  |
| <del>ODS</del><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext   |  |                           |  |
| <del>Other / Photos</del>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**





| Building        | Room # | Floor # | Room Description | Dimensions                   |
|-----------------|--------|---------|------------------|------------------------------|
| Pynn's (Camp 2) | 1      | 1       | Kitchen          | L = 16'<br>W = 16'<br>H = 8' |

|  | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|--|---|--|---------------------------|--|
| Floor  | Wood  |  |                           |  |
| Walls<br>(include window<br>caulking)  | Wood  |  |                           |  |
| Ceiling  | Wood  |  |                           |  |
| Paint<br>(and substrate)   | Walls: White<br>Ceiling: White<br>Floor: Grey<br>Other:   |  |                           |  |
| Insulation<br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:  |  |                           |  |
| Piping /<br>Mechanical<br>Equipment  |   |  |                           |  |
| Fluorescent<br>Lighting  | Ballast Manufacturer:<br>Serial #:  | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| Other Lighting<br>(e.g., incandescent,<br>HID)                                   | 4 incandescent  |  |                           |  |
| Thermostats  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial   | Casing<br># Observed<br># Checked<br>Circuit switch: Y/N |                           |  |
| LCMs<br>(saundersing, pipes<br>batteries, exit/ emerg<br>lighting,               | Copper pipe on water + propane<br>lines.  |  |                           |  |
| Mould / Water<br>Staining  | Area impacted<br>Ceiling + walls  |  |                           |  |
| ODS<br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>Danby Propane 4<br>Kelvinator CA (Model) R12.   |  |                           |  |
| Other / Photos   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br>Propane stove, oven, fridge |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile - specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile - specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building       | Room # | Floor # | Room Description | Dimensions                   |
|----------------|--------|---------|------------------|------------------------------|
| Pyons (Camp 2) | 2      |         | Bunks            | L = 18'<br>W = 16'<br>H = 8' |

|   | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|---|--|---------------------------|--|
| <b>Floor</b>  | Wood  |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | Wood  |  |                           |  |
| <b>Ceiling</b>  | Wood  |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls:<br>Ceiling: Some<br>Floor:<br>Other:   |  |                           |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer: —<br>Fire Door Serial #: —  |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —   |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #: incandescent.  | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | —   |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                       | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | Copper lines for<br>Propane   |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>on ceiling   |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—   |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br>— |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building       | Room # | Floor # | Room Description | Dimensions                 |
|----------------|--------|---------|------------------|----------------------------|
| Pyrns (Camp 2) | 3      | 1       | Bathroom         | L = 6'<br>W = 6'<br>H = 8' |

|   | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|---|--|----------------------------|--|
| <b>Floor</b>  | WOOD  |  |                            |  |
| <b>Walls</b><br>(include window caulking)   | WOOD  |  |                            |  |
| <b>Ceiling</b>  | WOOD  |  |                            |  |
| <b>Paint</b><br>(and substrate)   | Walls: White<br>Ceiling: White<br>Floor: Grey<br>Other: Grey                                      |  |                            |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:  |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —   |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>—   | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 1 incandescent.   |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                       | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | Copper pipes.   |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>Ceiling  |  |                            |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—   |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br>— |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                 |
|----------|--------|---------|------------------|----------------------------|
| Camp 2   |        |         | Outhouse         | L = 6'<br>W = 5'<br>H = 7' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|--|--|----------------------------|--|
| <b>Floor</b>  | —  |  |                            |  |
| <b>Walls</b><br>(include window caulking)   | Wood (Int + Ext)   |  |                            |  |
| <b>Ceiling</b>  | Wood<br>black shingles   |  |                            |  |
| <b>Paint</b><br>(and substrate)   | Walls: Grey<br>Ceiling:<br>Floor:<br>Other:  |  |                            |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:   |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —  |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>—  | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   |  |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 |  |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted  |  |                            |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext   |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br>* Creosote timber<br>* Building blown away from foundation * * |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

## TABLE OF CONTENTS

|         |   |      |
|---------|---|------|
| 4.0     | MITCHELL’S POND CAMP .....  | 4-1  |
| 4.1     | BUILDING DESCRIPTION.....   | 4-1  |
| 4.2     | ROOM DESIGNATION.....   | 4-2  |
| 4.3     | FINDINGS.....   | 4-2  |
| 4.3.1   | Asbestos-Containing Materials (ACMs) .....                        | 4-3  |
| 4.3.1.1 | Friable Materials.....  | 4-3  |
| 4.3.2   | Paint Additives .....   | 4-5  |
| 4.3.2.1 | Lead in Paint.....  | 4-5  |
| 4.3.2.2 | Mercury in Paint.....   | 4-6  |
| 4.3.2.3 | PCBs in Paint.....  | 4-6  |
| 4.3.3   | Urea Formaldehyde Foam Insulation (UFFI).....                     | 4-6  |
| 4.3.4   | Suspected Visible Mould Growth (SVG).....                         | 4-6  |
| 4.3.5   | Mercury-Containing Thermostats .....                              | 4-6  |
| 4.3.6   | PCB-Containing Light Ballasts.....                                | 4-7  |
| 4.3.7   | Potential Sources of ODS and Halocarbons.....                     | 4-7  |
| 4.3.8   | Other Potentially Hazardous Building Materials or Substances..... | 4-7  |
| 4.3.8.1 | Lead-Containing Materials and Equipment .....                     | 4-7  |
| 4.3.8.2 | Mercury-Containing Materials and Equipment.....                   | 4-8  |
| 4.3.8.3 | PCB-Containing Materials and Equipment.....                       | 4-8  |
| 4.3.8.4 | Treated Wood Chemicals .....                                      | 4-8  |
| 4.3.8.5 | Silica .....  | 4-8  |
| 4.3.8.6 | Radioactive Materials.....  | 4-8  |
| 4.4     | CONCLUSIONS AND RECOMMENDATIONS .....                             | 4-9  |
| 4.4.1   | ACMs.....   | 4-9  |
| 4.4.2   | Lead, Mercury and PCBs in Paint .....                             | 4-10 |
| 4.4.3   | Potential UFFI.....   | 4-11 |
| 4.4.4   | Mould.....  | 4-12 |
| 4.4.5   | Potential ODS .....   | 4-12 |
| 4.4.6   | Potential Lead-Containing Materials/Equipment.....                | 4-12 |
| 4.4.7   | Potential Mercury-Containing Materials/Equipment.....             | 4-13 |
| 4.4.8   | Potential PCB-Containing Materials/Equipment .....                | 4-13 |
| 4.4.9   | Silica Containing Materials.....                                  | 4-13 |
| 4.4.10  | Potential Radioactive Materials.....                              | 4-13 |
| 4.4.11  | Summary of Findings.....  | 4-14 |

## APPENDICES

- APPENDIX A4 Figures
- APPENDIX B4 Photographic Record
- APPENDIX C4 Sample and Analytical Summary Tables
- APPENDIX D4 Room-By-Room Inspection Sheets

#### 4.0 MITCHELL’S POND CAMP

Mitchell’s Pond Camp is located on Mitchell’s Pond, approximately 36 km northwest of the Town of Terrenceville, NL (refer to Figure 4.1, Appendix A4), and was accessed via a gravel access road. Mitchell’s Pond Camp is comprised of an accommodations cabin and an outhouse.

#### 4.1 BUILDING DESCRIPTION

The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 71 m<sup>2</sup>. The floor plan of the cabin consists of a kitchen with sleeping areas, a pantry and a washroom (refer to Figure 4.2, Appendix A4). The foundation of the accommodations cabin consists of concrete block footings. The structure of the accommodations cabin consists of brick. The exterior walls on the accommodations cabin are finished with brick and the roof is finished with asphalt shingles. The window and exterior door openings on the accommodations cabin are barricaded with metal covers for security purposes (refer to Photos 1 to 3, Appendix B2). Interior wall and ceiling finishes in the accommodations cabin consists of painted plywood. Floors/floor finishes consist of plywood (refer to Photos 4 to 7, Appendix B2). Incandescent and fluorescent lighting was observed on the interior of the cabin. The accommodations cabin is not currently heated.

The outhouse is a one-storey, rectangular structure with a footprint area of approximately 3 m<sup>2</sup>. The foundation and structure of the outhouse consists of wood framing and concrete. The exterior walls on the outhouse are finished with plywood and the roof is finished with asphalt shingles (refer to Photos 8 and 9, Appendix B4). Interior wall and ceiling finishes in the outhouse consist of painted plywood. Floor finishes consist of plywood. The outhouse does not contain any lighting or heating.

A description of accommodations cabin is outlined in Table 4-1 and a description of the outhouse is outlined in Table 4-2. Photographs of the buildings are provided in Appendix B4.

**Table 4-1: Site Building Description – Accommodations Cabin**

| Building Name             | Accommodations cabin                   | Photo No. (Appendix B4) |
|---------------------------|--|-------------------------|
| Date of Construction      | Approximately late 1960’s/early 1970’s | -                       |
| Date of Renovations       | Unknown                                | -                       |
| No. of Stories            | One                                    | 1 to 3                  |
| Crawl Space (Yes/No)      | No                                     | -                       |
| Attic (Yes/No)            | Yes                                    | 11                      |
| Type of Structure         | Wood Frame and bricks                  | 12                      |
| Type of Foundation        | Concrete blocks                        | 17 to 20                |
| Exterior                  | Red and Brown brick                    | 1 to 3                  |
| Window/Door Frames        | Painted Metal and Wood                 | 1 to 3                  |
| Exterior Doors            | Painted Metal                          | 1 and 4                 |
| Roofing Materials         | Asphalt Shingles                       | 1 and 21                |
| Interior Walls Finishes   | Painted Plywood                        | 4 to 7                  |
| Interior Ceiling Finishes | Plywood                                | 4 to 6                  |
| Floor Finishes            | Plywood                                | 4 and 5                 |
| Interior Doors            | NA                                     | -                       |
| Interior Lighting         | Fluorescent and Incandescent           | 4 to 6                  |
| Exterior Lighting         | Incandescent                           | 1                       |
| Heating                   | Oil fired heater                       | 32                      |

**Table 4-2: Site Building Description – Outhouse**

| Building Name             | Outhouse                               | Photo No. (Appendix B4) |
|---------------------------|--|-------------------------|
| Date of Construction      | Approximately late 1960’s/early 1970’s | -                       |
| Date of Renovations       | Unknown                                | -                       |
| No. of Stories            | One                                    | 8                       |
| Crawl Space (Yes/No)      | No                                     | -                       |
| Attic (Yes/No)            | No                                     | -                       |
| Type of Structure         | Wood Frame and plywood                 | 8 and 9                 |
| Type of Foundation        | Wood and concrete                      | 8                       |
| Exterior                  | Plywood                                | 8                       |
| Window/Door Frames        | NA                                     | -                       |
| Exterior Doors            | NA                                     | -                       |
| Roofing Materials         | Asphalt Shingles                       | 8 and 24                |
| Interior Walls Finishes   | Painted Plywood                        | 9                       |
| Interior Ceiling Finishes | Plywood                                | -                       |
| Floor Finishes            | NA                                     | -                       |
| Interior Doors            | NA                                     | -                       |
| Interior Lighting         | NA                                     | -                       |
| Exterior Lighting         | NA                                     | -                       |
| Heating                   | NA                                     | -                       |

## 4.2 ROOM DESIGNATION

Each room at Mitchell’s Pond Camp was assigned a specific room name. The designated room names are presented in Table 4-3 and graphically illustrated on the sample location plan (refer to Figure 4.2, Appendix A4).

**Table 4-3: Assigned Rooms**

| Level No. | Room Name – Accommodations Cabin | Room Number |
|-----------|----------------------------------|-------------|
| 1         | Kitchen/Bunk Area                | Room 1      |
| 1         | Pantry                           | Room 2      |
| 1         | Washroom                         | Room 3      |
| 1         | Outhouse                         | Outhouse    |

## 4.3 FINDINGS

The findings documented in this section are based on observations made by Wood personnel at the time of the site visit on August 8, 2018 and the results of laboratory analyses of samples collected from Mitchell’s Pond Camp. During the Pre-Demolition HBMA site visit, Wood personnel were accompanied by a representative of Hydro (Mr. Wayne Lidster). Copies of room-by-room inspection sheets for the accommodations building and outhouse are provided in Appendix D4. Photos of the samples collected from the accommodations building and outhouse during the site visits are provided in Appendix B4.

### **4.3.1 Asbestos-Containing Materials (ACMs)**

There are over 3,000 ACMs that are commercially available, which can be divided into two broad categories: friable and non-friable. ACMs were discontinued from use in Canada in the late 1970s/early 1980s, although non-friable asbestos is still found in many more recent buildings.

During the Pre-Demolition HBMA site visit, a total of 10 building material samples (MP-AS1 to MP-AS10) were collected from the accommodations cabin and two building material samples (MP-PP-AS1 and MP-PP-AS2) were collected from the outhouse (refer to Photos 14 to 25, Appendix B4) and analyzed for asbestos content. Bulk sample descriptions and asbestos analytical results are summarized in Table C4-1, Appendix C4. Sample locations and analytical results are graphically illustrated on Figure 4.2, Appendix A4.

#### **4.3.1.1 Friable Materials**

Friable ACMs are defined as materials that can be crumbled, pulverized and reduced to powder when dry using hand pressure. Typical friable materials include acoustical or decorative spray applications, fireproofing and thermal insulation.

##### **4.3.1.1.1 *Spray-Applied Fireproofing, Insulation and Texture Finishes***

There were no spray-applied fireproofing, insulation or texture finishes observed in the accommodations cabin or outhouse during the Pre-Demolition HBMA site visit; therefore, no samples of these materials were collected for analysis.

##### **4.3.1.1.2 *Building and Thermal System Insulation***

During the Pre-Demolition HBMA site visit, pink fiberglass insulation was observed between the particle board and plywood in the walls of the accommodations cabin. During the Pre-Demolition HBMA site visit, one (1) sample of foil with paper backing (collected from the pink fiberglass insulation) (MP-AS1) was collected from within the wall cavity of the accommodations cabin and analyzed for asbestos content (refer to Photo 14, Appendix B4). Asbestos was not detected in the insulation sample collected from the accommodations cabin.

##### **4.3.1.1.3 *Non-Friable and Potentially Friable Materials***

Non-friable ACMs are hard or manufactured products such as floor tiles, fire blankets, pre-formed manufactured cementitious insulation and wallboards, pipes, and siding, wherein the asbestos fibres are bound to the substrate. Note that although a product may be considered non-friable when new, the product may release fine dust when disturbed (e.g., deterioration, removal, renovations) and the free dust is considered friable.

##### **4.3.1.1.4 *Ceiling Tile***

There were no ceiling tiles observed at Mitchell's Pond Camp during the Pre-Demolition HBMA site visit; therefore, no samples of ceiling tile were collected for analysis.



#### **4.3.1.1.5 Drywall Joint Compound**

There was no drywall joint compound observed at Mitchell's Pond Camp during the Pre-Demolition HBMA site visit; therefore, no samples of drywall joint compound were collected for analysis.

#### **4.3.1.1.6 Vinyl Flooring Products and Mastics**

There was no vinyl flooring or products observed at Mitchell's Pond Camp during the Pre-Demolition HBMA site visit; therefore, no samples of vinyl flooring or products were collected for analysis.

#### **4.3.1.1.7 Baseboard, Carpet and Stair Tread Adhesives/Mastics**

There were no baseboard, carpet or stair tread adhesives/mastics observed at Mitchell's Pond Camp during the Pre-Demolition HBMA site visit; therefore, no samples of these types of adhesives/mastics were collected for analysis.

#### **4.3.1.1.8 Roofing Products**

During the Pre-Demolition HBMA site visit, one (1) sample of black shingle and tar (MP-AS8) was collected from the roof of the accommodations cabin and one (1) sample of black shingle and tar (MP-PP-AS1) was collected from the roof of the outhouse and analyzed for asbestos content (refer to Photos 21 to 24, Appendix B4). Asbestos was not detected in the roofing samples collected from the accommodations cabin and outhouse.

It is important to note that, due to height and safety constraints, no samples of roofing, building materials around roof penetrations (e.g., caulking or sealants around vents or electrical conduit) or roof seams were collected from the accommodations cabin for analysis.

#### **4.3.1.1.9 Caulking/Sealant**

During the Pre-Demolition HBMA site visit, one (1) sample of red sealant (MP-AS9) was collected from around the brick on the accommodations cabin and one (1) sample of white caulking (MP-AS10) was collected from the vent on the exterior of the accommodations building and analyzed for asbestos content (refer to Photos 22 and 23, Appendix B6). Asbestos was not detected in the white caulking sample (MP-AS) collected from the accommodations cabin.

Asbestos was detected in MP-AS10 containing <0.25 % chrysotile asbestos. According to the NL asbestos abatement regulations (Reg. 111/98), this material is not considered an asbestos-containing material.

#### **4.3.1.1.10 Mortar, Grout and Other Cementitious Materials**

During the Pre-Demolition HBMA site visit, one (1) sample of red brick (MP-AS4), one (1) sample of grey mortar on red brick (MP-AS5), one (1) sample of grey mortar on concrete block (MP-AS6) and one (1) sample of concrete block (MP-AS7) were collected from the exterior of the accommodations cabin and one (1) sample of concrete (MP-PP-AS2) collected from the foundation of the outhouse and analyzed for asbestos content (refer to Photos 17, 18, 19, 20 and 25, Appendix B4). Asbestos was not detected in any of the brick, concrete and mortar samples analyzed.

#### **4.3.1.1.11 Fire-Rated Doors**

Fire-rated doors and door frames were not observed during the Pre-Demolition HBMA site visit.

#### **4.3.1.1.12 Other Potential ACMs**

During the Pre-Demolition HBMA site visit, one (1) sample of black pressed board (MP-AS2) and one (1) sample of tar paper (MP-AS3) was collected from the exterior of the accommodations cabin and analyzed for asbestos content (refer to Photos 15 and 16, Appendix B4). Asbestos was not detected in the pressed board and tar paper samples analyzed.

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to, electrical and mechanical components and insulators such as wiring and gaskets, heat shields inside incandescent/fluorescent light fixtures, and caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations (refer to Photos 1, 4, 6, 32, and 36, Appendix B4).

Other possible hidden and inaccessible ACMs have the potential to be present within the accommodations cabin but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components or gaskets inside appliances, concrete lining the interior of hot water tanks, and underground infrastructure or piping.

### **4.3.2 Paint Additives**

Lead compounds have been used in paint as pigment and durability additives since the early 1800s. Mercury compounds have been used in paint as anti-microbial additives up until the 1990s. PCBs have been used in paint as plasticizers and corrosion resistance additives from the 1950s to the 1970s.

During the Pre-Demolition HBMA site visit, three (3) samples (MP-PS1 to MP-PS3) were collected from painted surfaces of the accommodations cabin and two (2) samples (MP-PP-PS1 and MP-PP-PS2) collected from painted surfaces of the outhouse and analyzed for lead, mercury and PCB content (refer to Photos 26 to 30, Appendix B4). Paint sample descriptions and lead, mercury and PCBs analytical results are summarized in Tables C4-2 to C4-4, Appendix C4. Sample locations and analytical results are graphically illustrated on Figure 4.2, Appendix A4.

#### **4.3.2.1 Lead in Paint**

Concentrations of lead in the three (3) samples (MP-PS1 to MP-PS3) were collected from painted surfaces of the accommodations cabin and two (2) samples (MP-PP-PS1 and MP-PP-PS2) collected from painted surfaces of the outhouse ranged from <15 mg/kg to 205 mg/kg (refer to Table C4-2, Appendix C4). Two (2) paint samples (MP-PS1 and MP-PP-PS1) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg (refer to Photos 26 and 30, Appendix B4).

#### **4.3.2.2 Mercury in Paint**

Concentrations of mercury in the three (3) samples (MP-PS1 to MP-PS3) were collected from painted surfaces of the accommodations cabin and two (2) samples (MP-PP-PS1 and MP-PP-PS2) collected from the outhouse ranged from <0.05 to 0.20 mg/kg, and therefore, were below the Federal HPA criterion (10 mg/kg) (refer to Table C4-3, Appendix C4).

#### **4.3.2.3 PCBs in Paint**

PCBs were not detected (<0.5 mg/kg) in any of the paint samples analyzed, and therefore, were below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg) (refer to Table C4-4, Appendix C4).

#### **4.3.3 Urea Formaldehyde Foam Insulation (UFFI)**

Visual indicators suggesting the potential presence of UFFI were not observed at Mitchell's Pond Camp. The nature of the insulation in the walls and ceilings throughout the accommodations cabin consisted of fiberglass insulation.

Since the original date of construction of Mitchell's Pond Camp (assumed construction commenced the same timeframe as the original transmission line, late 1960's/early 1970's) is unknown, it is possible that UFFI may be present.

In the event that UFFI is present, the CMHC state that "tests show that UFFI is not a source of over-exposure to formaldehyde after the initial curing and release of excess gas". The general view based on studies concerning formaldehyde emissions is that as a product ages, the amount of formaldehyde off-gassed from the product decreases over time. The amount of formaldehyde released is reportedly dependent on temperature, humidity and whether or not the product is exposed to excessive moisture or water.

#### **4.3.4 Suspected Visible Mould Growth (SVG)**

Wood inspected the interior areas of the accommodations cabin and outhouse for visual or olfactory evidence of suspected mould. SVG was noted on much of the ceiling and wall surfaces inside the accommodations cabin during the Pre-Demolition HBMA site visit. A sample, MP-MS1, was collected from the wall of Room 1 (refer to Figure 4-1, Appendix A4 and refer to Photo 31, Appendix B4).

The results of mould analysis determined that bulk sample MP-MS1 contained Myxomycete-like, Monodictys-like and Septonema Aspergillus mould with sparse to moderate growth (refer to Table C4-5, Appendix C4).

#### **4.3.5 Mercury-Containing Thermostats**

Thermostats were not identified inside the accommodations cabin at Mitchell's Pond Camp during the Pre-Demolition HBMA site visit.

#### 4.3.6 PCB-Containing Light Ballasts

Fluorescent and incandescent light fixtures were observed on the interior of the accommodations cabin and incandescent light fixtures were observed on the exterior of the accommodations cabin, as observed from the exterior of the cabin, during the Pre-Demolition HBMA site visit (refer to Photos 1, 4, 5 and 6, Appendix B4).

One Gold Label light ballast (Serial #17A240E) was inspected in the Room 1 and was labelled as non-PCB containing (refer to Photo 33, Appendix B4). Note that one light ballast was inspected at the time of the site visit.

#### 4.3.7 Potential Sources of ODS and Halocarbons

During the Pre-Demolition HBMA, a potential source of ODS was identified within the accommodations cabin. Results of the ODS inspection is summarized in Table 4-4.

**Table 4-4: Potential Sources of ODSs**

| Item    | Manufacturer | Model (Serial No.) | Location Observed | Photo No. (Appendix B2) | Refrigerant | Potential ODS |
|---------|--------------|--------------------|-------------------|-------------------------|-------------|---------------|
| Freezer | General      | GC-7-I0L           | Room 1            | 34                      | R12         | Yes           |

Based on observations made during the site visit, ODSs are present in the accommodations cabin in the form of refrigerant R12 contained in a freezer located in Room 1 (refer to Photo 34, Appendix B4). This refrigerant (R12) is a hydrochlorofluorocarbon (HCFC) and is regulated under the Federal Halocarbon Regulations.

Fire extinguishers were not observed at Mitchell’s Pond Camp during the Pre-Demolition HBMA site visit.

#### 4.3.8 Other Potentially Hazardous Building Materials or Substances

Other potentially hazardous building materials or substances identified during this assessment are presented in the following sections.

##### 4.3.8.1 Lead-Containing Materials and Equipment

Lead is typically associated with plumbing solder and older pipe materials (e.g., cast iron pipe joints), as well as products such as radiation protective shielding and lead-acid batteries. Lead can also be present in steel and iron primer, industrial electrical jacketing, roof flashing and tank linings.

Since the actual date that Mitchell’s Pond Camp was constructed is unknown (assumed to be late 1960’s/early 1970’s), it is possible that lead solder is present in plumbing and piping (i.e., cast iron and copper piping) in the accommodations cabin, as lead solder for use in potable water distribution pipes was not banned until the late 1980s (refer to Photos 7 and 35, Appendix B4). Note that the only copper lines observed within the accommodations cabin were associated with the propane stove and oil-fired furnace. No potable water lines were present.

#### **4.3.8.2 Mercury-Containing Materials and Equipment**

The light tubes and bulbs in HID and fluorescent light fixtures often contain limited quantities of mercury in a powder or vapour form. Incandescent light fixtures and fluorescent light fixtures were observed on the exterior and the interior of the accommodations cabin during the Pre-Demolition HBMA site visit (Photos 1, 4, 5 and 6, Appendix B4).

#### **4.3.8.3 PCB-Containing Materials and Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, and as mentioned previously, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

#### **4.3.8.4 Treated Wood Chemicals**

The chemicals that are used to protect and preserve wood products from insect attack and fungal decay may pose risks to human health and the environment. Depending on the wood treatment used, treated wood may be considered a hazardous waste upon disposal. The NL Department of Environment and Conservation (currently the NL MAE), 2015 Guidance Document for Treated Wood Waste Disposal (GD-PPD-075.1) provides landfill disposal standards for "pressure treated" inorganic preservatives (i.e., arsenic and chromium) and creosote (i.e., total cresol and benzo(a)pyrene) and chlorophenolic (i.e., pentachlorophenol) formulations used to preserve wood. These landfill disposal standards for treated wood waste (TWW) are used to assess the results of leachability testing to determine disposal options for treated wood to be removed during renovation or demolition activities.

Treated wood was not identified during the Pre-Demolition HBMA site visit.

#### **4.3.8.5 Silica**

According to the CPWR – The Center for Construction Research and Training, many common construction materials contain silica including, asphalt, brick, cement, concrete, drywall, grout, mortar, stone, sand and tile. The dust created by cutting, grinding, drilling or otherwise disturbing these materials can contain crystalline silica particles.

Based on the Pre-Demolition HBMA site visit, silica is expected to be present in concrete used in the construction of the foundation for the accommodations building. Silica may also be present in the asphalt shingles used in the construction of the accommodations building.

#### **4.3.8.6 Radioactive Materials**

Smoke detectors were not observed during the Pre-Demolition HBMA site visit. Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called "ion chamber smoke alarms".

## 4.4 CONCLUSIONS AND RECOMMENDATIONS

Based on observations made and information gathered during the Pre-Demolition HBMA, the following conclusions and recommendations are made with respect to the potential and actual presence of hazardous building materials at Mitchell's Pond Camp.

### 4.4.1 ACMs

Results of the asbestos sampling and analytical program for the Mitchell's Pond Camp revealed that all building materials sampled contained less than 1% asbestos by dry weight, and not considered asbestos-containing.

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to:

- Electrical and mechanical components and insulators such as wiring and gaskets.
- Heat shields inside incandescent/ fluorescent light fixtures.
- Caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations.

Other possible hidden and inaccessible ACMs have the potential to be present within the buildings at Mitchell's Pond Camp but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include concrete leveling compound (existing concrete foundation), possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components, and underground infrastructure or piping.

If other potential ACMs that were not sampled as part of this assessment are encountered in the future, these materials should be treated as ACMs or samples should be collected and tested to verify asbestos content. This should be done as soon as these materials are encountered and before these materials are disturbed. This includes materials that are currently concealed by walls and ceiling systems.

In accordance with the NL Asbestos Abatement Regulations (Reg. 111/98), which provide the legislative requirements for safe handling of ACMs in workplaces in the Province of NL, the following is recommended:

- Safe work procedures shall be established.
- All buildings constructed during the period when asbestos was readily used in construction (generally prior to the early 1980s) or any buildings that are suspected as having asbestos must have a written assessment and management plan (where applicable) for potential ACMs.
- Materials suspected of containing asbestos are required to be handled as ACMs, until analysis by a competent laboratory determines whether or not it does contain asbestos.
- Prior to general demolition, all ACMs must be safely removed from the building and disposed of in accordance with appropriate environmental guidelines by an asbestos abatement contractor registered with the Occupational Health and Safety (OHS) Division of Service NL.
- Most work involving ACMs (i.e., disturbance, removal and encapsulation) must be conducted by a

contractor registered with the OHS Division of Service NL.

- ACMs in good condition should be inspected on an annual basis.
- ACMs in poor condition should be removed from the building and transported off-site for proper disposal.
- Workers should don adequate respiratory protection and personal protective equipment (PPE) when working with ACMs.

Prior to the removal and/or abatement of any identified ACMs (or any other hazardous building materials), an abatement plan including technical specifications should be designed, prepared and supervised by a qualified professional and should be undertaken by qualified trades, in accordance with applicable standards. Activities involving the disturbance and/or removal of ACMs should be carried out in a manner that ensures asbestos fiber concentrations do not exceed the applicable American Conference of Governmental Industrial Hygienists (ACGIH) threshold limit value (TLV). ACMs can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.

#### **4.4.2 Lead, Mercury and PCBs in Paint**

Results of the paint sampling and analytical program revealed the following:

- **Lead in Paint**
  - Concentrations of lead in three (3) samples (MP-PS1 to MP-PS3) were collected from painted surfaces of the accommodations cabin and two (2) samples (MP-PP-PS1 and MP-PP-PS2) collected from painted surfaces of the outhouse ranged from <15 mg/kg to 205 mg/kg.
  - Two (2) paint samples (MP-PS1 and MP-PP-PS1) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg; therefore, these paints are considered to be LBPs, but are not likely to be leachable for lead.
- **Mercury in Paint**
  - Concentrations of mercury in the three (3) samples (MP-PS1 to MP-PS3) were collected from painted surfaces of the accommodations cabin and two (2) samples (MP-PP-PS1 and MP-PP-PS2) collected from the outhouse ranged from <0.05 to 0.20 mg/kg; below the Federal HPA criterion of 10 mg/kg. These paints are not considered to be MBPs and are not likely to be leachable for mercury.
- **PCBs in Paint**
  - PCBs were not detected (<0.5 mg/kg) in the three (3) samples (MP-PS1 to MP-PS3) collected from painted surfaces of the accommodations cabin and two (2) samples (MP-PP-PS1 and MP-PP-PS2) from the painted surfaces of the outhouse, and therefore, below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg).

Based on the paint sample analytical results, painted surfaces of the accommodations cabin and outhouse that were sampled are not likely to be leachable for lead, PCBs or mercury; therefore, should disposal be required (e.g., renovation or demolition activities), the paints analyzed for lead and mercury content may be disposed of at an approved landfill facility, pending landfill and Provincial regulatory approval.

There are potential adverse human health impacts associated with disturbing (e.g., scraping, sanding, burning, etc.) lead, mercury or PCB-containing paint finishes, due to the potential for dust, mist or fumes to be released and inhaled or ingested by workers. Given that lead-based paint was identified at the site, as a precautionary measure, Wood recommends handling these paint finishes, as follows:

- In areas of minor peeling or flaking, the paint should be removed using wet scraping techniques.
- In areas of extensive peeling and flaking, the paint should be removed and more extensive particulate control measures may be required.
- In areas where lead-containing paint finishes are present and in poor condition, an experienced contractor should be utilized for renovating, decommissioning or demolition activities.
- Prior to renovation, dismantling or demolition activities, all areas of extensive peeling and flaking of lead-containing paint finishes and paint debris/dust should be removed and/or remediated to ensure that building occupants/workers are protected from associated dust/particulate.
- Procedures should be implemented to ensure that workers and anyone present in and around areas being renovated, dismantled or demolished are protected. The contractor should also ensure that dust generation and migration is minimized.
- Precautions should be taken to prevent/reduce exposure to paint dust during any disturbance of lead-containing paint finishes, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas.
- Where possible, lead-containing paint finishes should be removed from metal surfaces prior to welding or cutting these materials.

If potential lead, mercury or PCB containing paint finishes that were not sampled during this assessment are encountered in future, prior to any disturbance or removal, samples should be obtained and tested to verify concentrations of lead, mercury and PCBs. This includes materials that are currently concealed by walls and ceiling systems.

Any disturbance or removal of lead, mercury or PCB-containing paint finishes that may generate dust or respirable aerosols must conform to the Federal and Provincial OHS Regulations. All work should be carried out by individuals wearing proper PPE. The type of respiratory protection and control measures to be implemented during the removal of these types of paint finishes should be determined by a qualified person and based on the risk level of a particular work activity (i.e., scraping, sanding, abrasive blasting, etc.). Activities involving the disturbance and/or removal of lead, mercury or PCB-containing paint finishes should be carried out in a manner that ensures paint dust concentrations do not exceed the applicable ACGIH TLVs.

#### **4.4.3 Potential UFFI**

The sale and installation of UFFI was banned in 1980; since the original date of construction is unknown, it is possible that UFFI may be present in the building. Visual indicators suggesting the potential presence of UFFI were not observed in the building. It can be inferred that any UFFI present within the building is unlikely to affect the indoor air quality due to the amount of time that has passed since the insulation was likely installed (i.e., pre-1980) along with the likelihood that formaldehyde has off-gassed over this period of time. It should be noted that, the presence and concentration of formaldehyde cannot be determined or quantified without conducting site-specific testing for formaldehyde.



Although there is currently no Provincial regulations requiring that the removal of UFFI be conducted by a licensed/registered abatement contractor, based on discussions with representatives of the OHS Division of Service NL, it is strongly recommended that this material be abated using similar methods as required for asbestos abatement and that the insulation must be removed in a dry condition. Based on discussions with representatives of the NL MAE, for the purposes of disposal of UFFI, this material is permitted to be bagged and transported to an approved WDS and disposed in the special waste area (unlined area) of the site.

#### **4.4.4 Mould**

SVG was noted on ceiling and wall surfaces inside the accommodations cabin during the Pre-Demolition HBMA site visit. The results of mould analysis determined that bulk sample MP-MS1 contained Myxomycete-like, Monodictys-like and Septonema Aspergillus mould with sparse to moderate growth.

Mould spores are present in all indoor environments and cannot be completely eliminated. Cellulose based building materials provide a nutrient base for many mould species; however, mould cannot grow unless an adequate amount of excess moisture is present. The most effective way to prevent mould growth within a building is the prompt removal of any porous building materials with water damage or mould growth, and repairing the building components that lead to the water infiltration.

#### **4.4.5 Potential ODS**

Based on observations made during the site visit, ODSs are present in the accommodations cabin in the form of refrigerant R12 contained in a freezer located in Room 1. This refrigerant (R12) is a hydrochlorofluorocarbon (HCFC) and is regulated under the Federal Halocarbon Regulations.

Ozone depleting substances (ODS), if present, should be removed by an approved contractor prior to disposing of any cooling and/or refrigeration equipment from the building. The use, storage, operation, maintenance, decommissioning, and disposal of ODS containing equipment, in general, is regulated at both a Provincial and Federal level and must comply with the most recent NL Halocarbon Regulations and the Federal Halocarbon Regulations. The status of the potential ODS containing equipment should be confirmed through a mechanical contractor or consultant.

#### **4.4.6 Potential Lead-Containing Materials/Equipment**

Lead solder may be present in the copper piping within the accommodations cabin (i.e. copper propane and fuel lines). No copper lines associated with drinking water was observed at the time of the site visit.

The disturbance, control or disposal of lead-containing material/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of lead in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a metal recycling facility and not a landfill. Removal of lead-containing batteries should be completed in a manner that ensures structural integrity and no loss of fluid from the batteries. Should disposal be required, disposal of lead-containing batteries should be completed in accordance with hazardous waste procedures/guidelines (i.e., at an approved facility).

#### **4.4.7 Potential Mercury-Containing Materials/Equipment**

Should disposal be required, mercury-containing equipment should be removed intact and returned to the manufacturer for recycling or disposed of at an approved hazardous waste disposal facility. The disturbance, control or disposal of mercury-containing materials/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of mercury in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a recycling or hazardous waste disposal facility and not a landfill.

#### **4.4.8 Potential PCB-Containing Materials/Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

If PCB-containing materials or equipment are encountered in the future, and should disposal be required, the PCB content in the materials or equipment should be confirmed prior to disposal. Any leaking light ballasts identified, whether PCB containing or not, should be removed and replaced to avoid potential concerns with electrical equipment in the future. All ballasts that are removed should be placed in a proper storage container(s). Leaks or stained areas should be cleaned and/or removed in accordance with applicable regulations or industry standards. Florescent lights are present inside the accommodations cabin.

Any PCB-containing equipment (if present) should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations. Any PCB-containing equipment requiring removal from the building should be transported and disposed of at an approved hazardous waste disposal site, and not a landfill disposal site, by a registered hazardous waste transporter in accordance with applicable regulations.

#### **4.4.9 Silica Containing Materials**

Silica is expected to be present in concrete used in the construction of the foundation for the accommodations cabin. Silica may also be present in asphalt shingles used in the construction of accommodations cabin. Precautions should be taken to prevent/reduce exposure to silica dust during any disturbance/ demolition of silica-containing products, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas. Activities involving the disturbance and/or demolition of silica-containing materials should be carried out in a manner that ensures silica dust concentrations do not exceed the applicable ACGIH TLV.

#### **4.4.10 Potential Radioactive Materials**

Smoke detectors were not observed during the Pre-Demolition HBMA site visit. Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called "ion chamber smoke alarms".

#### 4.4.11 Summary of Findings

Hazardous building materials identified at Hungry Grove Camp during this Pre-Demolition HBMA and disposal options, if required, are summarized in Table 4-5. Conclusions and recommendations made with respect to the potential and actual presence of hazardous building materials within the accommodations cabin and outhouse are provided in Section 4.4 and should be reviewed in conjunction with Table 4-5.

**Table 4-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| Hazardous Material    | Applicable Acts, Regulations or Guidance Documents  | Description and Location  | Disposal   |
|-----------------------|---|---|--|
| <b>ACMs</b>           | NL Asbestos Abatement Regulations (Reg. 111/98)   | None identified at locations sampled.<br><br>Note that other possible hidden and inaccessible ACMs have the potential to be present within the accommodations building but were not identified during the Pre-Demolition HBMA site visit. | ACMs cannot be disposed of at a Construction & Demolition Site; however, these materials can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.<br><br>The transportation and disposal of asbestos should be conducted in accordance with the NL Asbestos Abatement Regulations (Reg. 111/98) and with Standard Operating Procedures (SOPs) for disposal of ACMs at the landfill. |
| <b>LBP</b>            | Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)<br>Federal HPA (R.S.1985, c. H-3)<br>Federal TDG Act (1992, c. 34)<br>Surface Coating Materials Regulations (SOR/2016-193) | LBP (grey) on plywood floor of accommodations cabin.<br><br>LBP (grey) on plywood exterior of outhouse.   | Paints that were analyzed for lead and contained <5,000 mg/kg lead, may be disposed of at a Regional Solid Waste Disposal Facility (landfill), provided permission is obtained from the landfill owner/operator.   |
| <b>Potential UFFI</b> | Federal HPA (R.S.1985, c. H-3)  | None Identified   | UFFI is permitted to be bagged and transported to an approved WDS and disposed in the special waste area of the site.  |

**Table 4-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| Hazardous Material                                       | Applicable Acts, Regulations or Guidance Documents  | Description and Location   | Disposal  |
|--|---|--|---|
| <b>Mould</b>   | <p>Mould Guidelines for the Canadian Construction Industry, Canadian Construction Industry (CCI), 2004;</p> <p>Mould Abatement Guidelines, Environmental Abatement Council of Ontario (EACO), 2010</p>  | <p>Bulk sample MP-MS1 contained Myxomycete-like, Monodictys-like and Septonema Aspergillus mould with sparse to moderate growth in the accommodations cabin. Quantity unknown.</p> | <p>All mould impacted materials may be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.</p>   |
| <b>Potential ODS</b>                                     | <p>Federal Halocarbon Regulations (SOR/2003-289)</p>  | <p>R12 refrigerant in freezer in Room 1.</p>   | <p>Materials containing ODS should be received by a contractor or facility that has the proper approvals to remove, handle and/or dispose of ODS. The remaining materials can be disposed of at a recycling facility, provided permission is obtained from the facility.</p>  |
| <b>Potential Lead-Containing Materials/ Equipment</b>    | <p>Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)</p> <p>Federal HPA (R.S.1985, c. H-3)</p> <p>Federal TDG Act (1992, c. 34)</p> <p>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301)</p> | <p>Potential lead-containing solder (i.e. copper piping for propane and fuel oil in the accommodations cabin).</p>   | <p>Lead-containing materials and equipment can be disposed of at a metal recycling or hazardous waste disposal facility, in accordance with applicable regulations.</p> <p>The transportation and disposal of hazardous lead-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility.</p> |
| <b>Potential Mercury-Containing Materials/ Equipment</b> | <p>Federal HPA (R.S.1985, c. H-3)</p> <p>Federal TDG Act (1992, c. 34)</p> <p>Products Containing Mercury Regulations (SOR/2014-254)</p>  | <p>None identified</p>   | <p>Mercury-containing materials and equipment can be disposed of at a recycling or hazardous waste disposal facility, in accordance with applicable regulations.</p> <p>The transportation and disposal of hazardous mercury-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility.</p> |

**Table 4-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b>                            | <b>Applicable Acts, Regulations or Guidance Documents</b>   | <b>Description and Location</b>  | <b>Disposal</b>   |
|--|---|--|---|
| <b>Potential PCB-Containing Materials/ Equipment</b> | Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)<br>Federal TDG Act (1992, c. 34)<br>Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)<br>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301)<br>PCB Regulations (SOR/2008-273)<br>PCB Waste Export Regulations (SOR/97-109)<br>Regulations Amending the PCB Regulations (SOR/2010-57) | None identified.<br><br>Note that only one florescent light ballast was inspected as part of the HBMA. All light ballast should be inspected for PCBs prior to removal and disposal. | Any PCB-containing materials and equipment should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations.<br><br>Any PCB-containing materials and equipment requiring removal from the building should be transported and disposed of by a registered hazardous waste transporter in accordance with applicable regulations.<br><br>The transportation and disposal of PCB containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility. |
| <b>Silica-Containing Materials</b>                   | NL OHS Act (RSNL1990 Chapter O-3)<br>NL OHS Regulations (5/12)  | Asphalt shingles and concrete.   | These materials can be disposed of at a Regional Solid Waste Disposal Facility (landfill).  |
| <b>Potential Radioactive Materials</b>               | Federal TDG Act (1992, c. 34)   | None Identified  | Smoke detectors that contain low level radioactive materials must be transported, as per Federal TDG Regulations, to a licensed disposal facility.  |

**APPENDIX A4**

**FIGURES**



**NOTES:**  
 1. ALL DIMENSIONS ARE IN METERS.  
 2. DO NOT SCALE FROM FIGURE.  
 3. THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.  
 4. ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.  
 5. THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.  
 6. THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



newfoundland labrador  
 a nalcor energy company

**Wood**  
 Environment & Infrastructure Solutions  
 133 Crosbie Road  
 St. John's, NL A1B 4A5  
 709-722-7023



Drawn by:  
T. Rideout

Approved by:  
C. Finney

Scale:  
As Shown

Project:  
Pre-Demolition Hazardous Building Materials Assessment,  
Former Construction Camp Sites,  
Bay d'Espoir - Avalon Transmission Line, NL



Title:  
Site Location Plan (Aerial) - Mitchell's Pond Camp Site

Date:  
April 2019

Project No.  
TF18104243.2000

Rev. No.  
0


Figure No.  
4.1



ACCOMMODATIONS CABIN

**LEGEND:**


- ASBESTOS SAMPLE LOCATION - ASBESTOS NOT DETECTED
- ASBESTOS SAMPLE LOCATION - RESULTS < 1% FOR ASBESTOS
- ▲ PAINT SAMPLE LOCATION - NO CRITERIA EXCEEDANCES FOR LEAD OR MERCURY OR PCBs WHERE APPLICABLE
- ▲ PAINT SAMPLE LOCATION - RESULTS EXCEED 90 mg/kg AND LESS THAN 5000 mg/kg FOR LEAD AND NO CRITERIA EXCEEDANCES FOR MERCURY OR PCBs WHERE APPLICABLE
- SPARSE TO MODERATE MOULD GROWTH DETECTED



**NOTES:**


- ALL DIMENSIONS ARE IN METERS.
- DO NOT SCALE FROM FIGURE.
- THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.
- ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.
- THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.
- THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



a nalcor energy company

**Wood**  
 Environment & Infrastructure Solutions  
 133 Crosbie Road  
 St. John's, NL A1B 4A5  
 709-722-7023



Drawn by:  
T. Rideout

Approved by:  
C. Finney

Scale:  
As Shown

Project:  
Pre-Demolition Hazardous Building Materials Assessment,  
Former Construction Camp Sites,  
Bay d'Espoir - Avalon Transmission Line, NL

Title:  
Sample Location Plan - Mitchell's Pond Camp Site

|             |                 |
|-------------|-----------------|
| Date:       | April 2019      |
| Project No. | TF18104243.2000 |
| Rev. No.    | 0               |
| Figure No.  | 4.2             |



**APPENDIX B4**  
**PHOTOGRAPHIC RECORD**



Photo 1: View of the accommodations cabin at Mitchell's Pond Camp, looking northeast.



Photo 2: View of the accommodations cabin at Mitchell's Pond Camp, looking north.



Photo 3: View of the accommodations cabin at Mitchell's Pond Camp, looking north.



Photo 4: View of the kitchen area of the accommodations cabin at Mitchell's Pond Camp.



Photo 5: View of the bunk area of the accommodations cabin at Mitchell's Pond Camp.



Photo 6: View of the pantry area at Mitchell's Pond Camp.



Photo 7: View of the bathroom at Mitchell's Pond Camp.



Photo 8: View of the outhouse at Mitchell's Pond Camp.



Photo 9: View of the interior of the outhouse at Mitchell's Pond Camp.



Photo 10: View of the cavity inspection in the interior wall of Room 1 at Mitchell's Pond Camp.



Photo 11: View of attic of accommodations cabin at Mitchell's Pond Camp.



Photo 12: View of cavity inspection in the wall of the exterior of the accommodations cabin at Mitchell's Pond Camp.



Photo 13: View of floor cavity inspection at the the accommodations cabin at Mitchell's Pond Camp.



Photo 14: View of bulk material sample MP-AS1, foil with paper backing, Room 1.



Photo 15: View of bulk material sample MP-AS2, black pressboard, Room 1.



Photo 16: View of bulk material sample MP-AS3, tar paper, cabin exterior.



Photo 17: View of bulk material sample MP-AS4, red brick, cabin exterior.



Photo 18: View of bulk material sample MP-AS5, grey mortar, cabin exterior.



Photo 19: View of bulk material sample MP-AS6, grey mortar, cabin exterior.



Photo 20: View of bulk material sample NP-AS7, concrete block, cabin exterior.



Photo 21: View of bulk material sample MP-AS8, shingle and tar, cabin exterior.



Photo 22: View of bulk material sample MP-AS9, red sealant, cabin exterior.



Photo 23: View of bulk material sample MP-AS10, white caulking, cabin exterior.



Photo 24: View of bulk material sample MP-PP-AS1, black shingle and tar, cabin exterior.



Photo 25: View of bulk material sample MP-PP-AS2, concrete, outhouse exterior.



Photo 26: View of paint sample MP-PS1, grey, cabin interior.




Photo 27: View of paint sample MP-PS2, white, cabin interior.



Photo 28: View of paint sample MP-PS3, white, cabin exterior.





Photo 29: View of paint sample MP-PP-PS1, grey, outhouse exterior.



Photo 30: View of paint sample MP-PP-PS2, white, outhouse interior.



Photo 31: View of mould sample MP-MS1, cabin interior.



Photo 32: View of oil fired heater, cabin interior.



Photo 33: View of fluorescent light ballast, cabin interior.



Photo 34: View of freezer, containing R12 reffridgerant, cabin interior.



Photo 35: View of kitchen sink plumbing, cabin interior.



Photo 36: View of electrical panel, cabin interior.

**APPENDIX C4**

**SAMPLE AND ANALYTICAL SUMMARY TABLES**

**Table C4-1: Bulk Sample Descriptions and Asbestos Analytical Results (Mitchell's Pond Camp)**

| Sample ID | Room No. | Room Description    | Photo No. | Sample Location | Sample Description            | Layers Analyzed        | Analytical Result |
|-----------|----------|---------------------|-----------|-----------------|-------------------------------|------------------------|-------------------|
| MP-AS1    | 1        | Kitchen             | 14        | Interior Wall   | Foil with paper backing       | Foil and paper backing | ND                |
| MP-AS2    | 1        | Kitchen             | 15        | Interior Wall   | Black pressboard              | Pressboard             | ND                |
| MP-AS3    | 1        | Kitchen             | 16        | Interior Wall   | Tar paper                     | Tar paper              | ND                |
| MP-AS4    | Exterior | Exterior - Cabin    | 17        | Wall            | Red brick                     | Brick                  | ND                |
| MP-AS5    | Exterior | Exterior - Cabin    | 18        | Wall            | Grey mortar on red brick      | Mortar                 | ND                |
| MP-AS6    | Exterior | Exterior - Cabin    | 19        | Foundation      | Grey mortar on concrete block | Mortar                 | ND                |
| MP-AS7    | Exterior | Exterior - Cabin    | 20        | Foundation      | Concrete block                | Concrete               | ND                |
| MP-AS8    | Exterior | Exterior - Cabin    | 21        | Roof            | Black shingle and black tar   | Shingle and tar        | ND                |
| MP-AS9    | Exterior | Exterior - Cabin    | 22        | Chimney         | Red sealant                   | Sealant                | ND                |
| MP-AS10   | Exterior | Exterior - Cabin    | 23        | Vent            | White caulking                | Caulking               | <0.25%            |
| MP-PP-AS1 | Exterior | Exterior - Outhouse | 24        | Roof            | Black shingle and black tar   | Shingle and tar        | ND                |
| MP-PP-AS2 | Exterior | Exterior - Outhouse | 25        | Foundation      | Concrete                      | Concrete               | ND                |

**Notes:**

ACM: Asbestos-Containing Material

DJC: Drywall Joint Compound

VFT: Vinyl Floor Tile

VSF: Vinyl Sheet Flooring

ND: Non-Detect (<0.1%)

\*Brown paper and tar analyzed as one layer because the laboratory could not separate these materials.

**Bold and underlined value indicates asbestos was detected but is below 1% by dry weight.**

Shaded value exceeds 1% asbestos by dry weight and is considered to be an ACM as outlined in the Newfoundland and Labrador Asbestos Abatement Regulations (Reg. 111/98).

**Table C4-2: Paint Sample Descriptions and Lead Analytical Results (Mitchell's Pond Camp)**

| Sample ID | Room No. | Room Description  | Photo No. | Sample Location | Substrate | Sample Description                         | RDL (mg/kg) | Lead (mg/kg) |
|-----------|----------|-------------------|-----------|-----------------|-----------|--|-------------|--------------|
| MP-PS1    | 1        | Kitchen           | 26        | Floor           | Plywood   | Grey on plywood (sample includes plywood)  | 15.0        | <u>199</u>   |
| MP-PS2    | 1        | Kitchen           | 27        | Wall            | Plywood   | White on plywood (sample includes plywood) | 15.0        | 56           |
| MP-PS3    | Exterior | Cabin Exterior    | 28        | Exterior        | Wood      | White on wood trim (sample includes wood)  | 15.0        | 18           |
| MP-PP-PS1 | Exterior | Outhouse Exterior | 29        | Wall            | Plywood   | Grey on wood (sample includes wood)        | 15.0        | <u>205</u>   |
| MP-PP-PS2 | Interior | Outhouse Interior | 30        | Exterior        | Plywood   | White on Plywood (sample includes plywood) | 15.0        | <15          |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

**Bold and underlined value exceeds Federal HPA criterion (90 mg/kg).**

Shaded value exceeds former Federal HPA criterion (5,000 mg/kg).

**Table C4-3: Paint Sample Descriptions and Mercury Analytical Results (Mitchell's Pond Camp)**

| Sample ID | Room No. | Room Description  | Photo No. | Sample Location | Substrate | Sample Description                         | RDL (mg/kg) | Mercury (mg/kg) |
|-----------|----------|-------------------|-----------|-----------------|-----------|--|-------------|-----------------|
| MP-PS1    | 1        | Kitchen           | 26        | Floor           | Plywood   | Grey on plywood (sample includes plywood)  | 0.05        | 0.20            |
| MP-PS2    | 1        | Kitchen           | 27        | Wall            | Plywood   | White on plywood (sample includes plywood) | 0.05        | 0.08            |
| MP-PS3    | Exterior | Cabin Exterior    | 28        | Exterior        | Wood      | White on wood trim (sample includes wood)  | 0.05        | <0.05           |
| MP-PP-PS1 | Exterior | Outhouse Exterior | 29        | Wall            | Plywood   | Grey on wood (sample includes wood)        | 0.05        | 0.10            |
| MP-PP-PS2 | Interior | Outhouse Interior | 30        | Exterior        | Plywood   | White on Plywood (sample includes plywood) | 0.05        | <0.05           |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

**Bold and underlined value exceeds Federal HPA criterion (10 mg/kg).**

Shaded value exceeds CCME CSQG for an industrial site (50 mg/kg).

**Table C4-4: Paint Sample Descriptions and PCB Analytical Results (Mitchell's Pond Camp)**

| Sample ID | Room No. | Room Description  | Photo No. | Sample Location | Substrate | Sample Description                         | RDL (mg/kg) | Total PCB (mg/kg) |
|-----------|----------|-------------------|-----------|-----------------|-----------|--|-------------|-------------------|
| MP-PS1    | 1        | Kitchen           | 26        | Floor           | Plywood   | Grey on plywood (sample includes plywood)  | 0.5         | <0.5              |
| MP-PS2    | 1        | Kitchen           | 27        | Wall            | Plywood   | White on plywood (sample includes plywood) | 0.5         | <0.5              |
| MP-PS3    | Exterior | Cabin Exterior    | 28        | Exterior        | Wood      | White on wood trim (sample includes wood)  | 0.5         | <0.5              |
| MP-PP-PS1 | Exterior | Outhouse Exterior | 29        | Wall            | Plywood   | Grey on wood (sample includes wood)        | 0.5         | <0.5              |
| MP-PP-PS2 | Interior | Outhouse Interior | 30        | Exterior        | Plywood   | White on Plywood (sample includes plywood) | 0.5         | <0.5              |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

NL MAE: Newfoundland and Labrador Department of Municipal Affairs and Environment

TDG: Transportation of Dangerous Goods

\*Sample collected by Hydro on May 5, 2018.

**Shaded value exceeds the criterion for PCB solid provided in the NL MAE Leachable Toxic Waste, Testing and Disposal Guidance Document and the TDG Regulations (50 mg/kg).**

**Shaded value exceeds the criterion for PCB solid provided in the NL MAE Leachable Toxic Waste, Testing and Disposal Guidance Document and the TDG Regulations (50 mg/kg).**

**Table C4-5: Bulk Sample Descriptions and Mould Analytical Results (Mitchell's Pond Camp)**

| Sample ID | Detailed Material Description | Sample Location | Mould Identified   | Analytical Result  |
|-----------|-------------------------------|-----------------|--|--------------------|
| MP-MS1    | Wood trim on wall             | Room 1          | <i>Myxomycete</i> -like<br><i>Monodictys</i> -like<br><i>Septonema Aspergillus</i> | Sparse to Moderate |

**Notes:**

1. Mould growth is subjectively assessed with description terms sparse, moderate and abundant.
2. The presence of spores (lacking other fungal structures associated) is assessed as following: a few spores (< 10 spores average per microscopic field at 400X).  
some spores (10 - 100 spores average per microscopic field at 400X), many spores (> 100 spores average per microscopic field at 400X).
3. The presence of a few spores generally represents settled spores on the surface of the sample rather than indicating mould growth.



**APPENDIX D4**

**ROOM-BY-ROOM INSPECTION SHEETS**

| Building        | Room # | Floor # | Room Description | Dimensions                   |
|-----------------|--------|---------|------------------|------------------------------|
| Mitchells Pond. | 1      | 1       | Kitchen          | L = 32'<br>W = 24'<br>H = 8' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|--|--|---------------------------|--|
| <b>Floor</b>  | Wood   |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | Wood   |  |                           |  |
| <b>Ceiling</b>  | Wood.  |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls: White<br>Ceiling: White<br>Floor: Grey<br>Other:                                      |  |                           |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:   |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | /  |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>2 → 1'x4' 2 bulb<br>Gold Label 17A240E                 | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 4 → incandescent   |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(soldering, pipes<br>batteries, exit/ emerg<br>lighting.                 | Copper water & propane lines.  |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted  |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>Deepfreeze, General freezer, Model G-7-I-L, SN FB04053                           |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building       | Room # | Floor # | Room Description | Dimensions                  |
|----------------|--------|---------|------------------|-----------------------------|
| Mitchells Pond | 2      | 1       | Pantry/Porch     | L = 10'<br>W = 8'<br>H = 8' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|--|--|----------------------------|--|
| <b>Floor</b>  | Wood   |  |                            |  |
| <b>Walls</b><br>(include window caulking)   | Wood   |  |                            |  |
| <b>Ceiling</b>  | Wood   |  |                            |  |
| <b>Paint</b><br>(and substrate)   | Walls: Same<br>Ceiling:<br>Floor:<br>Other:  |  |                            |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer: —<br>Fire Door Serial #:   |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —  |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>—  | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 1 incandescent   |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted —<br>Dial                                | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —  |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>—   |  |                            |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—  |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building       | Room # | Floor # | Room Description | Dimensions                 |
|----------------|--------|---------|------------------|----------------------------|
| Mitchells Pond | 3      | 1       | Wash room        | L = 6'<br>W = 6'<br>H = 8' |

|   | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|---|--|---------------------------|--|
| <b>Floor</b>  | Wood  |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | Wood  |  |                           |  |
| <b>Ceiling</b>  | WOOD  |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls:<br>Ceiling: Same<br>Floor:<br>Other:   |  |                           |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer: —<br>Fire Door Serial #:  |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —   |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #: —  | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 1 Incandescent  |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                       | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —   |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>—  |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—   |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br>— |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building       | Room # | Floor # | Room Description | Dimensions                |
|----------------|--------|---------|------------------|---------------------------|
| Mitchells Pond |        |         | Exterior         | L = 32'<br>W = 24'<br>H = |

|  | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|--|--|--|---------------------------|--|
| <del>Floor</del><br>Foundation   | Cinderblock  |  |                           |  |
| Walls<br>(include window caulking)   | Red Brick  |  |                           |  |
| Ceiling  | Black shingles.  |  |                           |  |
| Paint<br>(and substrate)   | Walls:<br>Ceiling:<br>Floor:<br>Other: —   |  |                           |  |
| Insulation<br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #: —   |  |                           |  |
| Piping /<br>Mechanical<br>Equipment  | —  |  |                           |  |
| Fluorescent<br>Lighting  | Ballast Manufacturer:<br>Serial #: —   | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| Other Lighting<br>(e.g., incandescent,<br>HID)                                   | 2 - incandescent   |  |                           |  |
| Thermostats  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| LCMs<br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 |  |  |                           |  |
| Mould / Water<br>Staining  | Area impacted  |  |                           |  |
| ODS<br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext   |  |                           |  |
| Other / Photos   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building       | Room # | Floor # | Room Description | Dimensions                 |
|----------------|--------|---------|------------------|----------------------------|
| Mitchells Pond |        |         | Outhouse         | L = 6'<br>W = 5'<br>H = 8' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|--|--|---------------------------|--|
| <b>Floor</b>  | Concrete & Wood  |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | Wood   |  |                           |  |
| <b>Ceiling</b>  | Wood<br>Felt on roof.  |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls: Grey (Ext)<br>Ceiling: White (int)<br>Floor:<br>Other:                                |  |                           |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | —<br>Fire Door Manufacturer:<br>Fire Door Serial #:  |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —  |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #: —   | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   |  |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 |  |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted  |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext   |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

## TABLE OF CONTENTS

|         |  |      |
|---------|--|------|
| 5.0     | HUNGRY GROVE POND CAMP .....                                       | 5-1  |
| 5.1     | BUILDING DESCRIPTION .....   | 5-1  |
| 5.2     | ROOM DESIGNATION .....   | 5-2  |
| 5.3     | FINDINGS .....   | 5-3  |
| 5.3.1   | Asbestos-Containing Materials (ACMs) .....                         | 5-3  |
| 5.3.1.1 | Friable Materials .....  | 5-3  |
| 5.3.1.2 | Non-Friable and Potentially Friable Materials .....                | 5-3  |
| 5.3.2   | Paint Additives .....  | 5-5  |
| 5.3.2.1 | Lead in Paint .....  | 5-6  |
| 5.3.2.2 | Mercury in Paint .....   | 5-6  |
| 5.3.2.3 | PCBs in Paint .....  | 5-6  |
| 5.3.3   | Urea Formaldehyde Foam Insulation (UFFI) .....                     | 5-6  |
| 5.3.4   | Suspected Visible Mould Growth (SVG) .....                         | 5-6  |
| 5.3.5   | Mercury-Containing Thermostats .....                               | 5-7  |
| 5.3.6   | PCB-Containing Light Ballasts .....                                | 5-7  |
| 5.3.7   | Potential Sources of ODS and Halocarbons .....                     | 5-7  |
| 5.3.8   | Other Potentially Hazardous Building Materials or Substances ..... | 5-7  |
| 5.3.8.1 | Lead-Containing Materials and Equipment .....                      | 5-7  |
| 5.3.8.2 | Mercury-Containing Materials and Equipment .....                   | 5-7  |
| 5.3.8.3 | PCB-Containing Materials and Equipment .....                       | 5-7  |
| 5.3.8.4 | Treated Wood Chemicals .....                                       | 5-8  |
| 5.3.8.5 | Silica .....   | 5-8  |
| 5.3.8.6 | Radioactive Materials .....  | 5-8  |
| 5.3.8.7 | Bat Feces .....  | 5-8  |
| 5.4     | CONCLUSIONS AND RECOMMENDATIONS .....                              | 5-9  |
| 5.4.1   | ACMs .....   | 5-9  |
| 5.4.2   | Lead, Mercury and PCBs in Paint .....                              | 5-10 |
| 5.4.3   | Potential UFFI .....   | 5-11 |
| 5.4.4   | Mould .....  | 5-12 |
| 5.4.5   | Potential ODS .....  | 5-12 |
| 5.4.6   | Potential Lead-Containing Materials/Equipment .....                | 5-12 |
| 5.4.7   | Potential Mercury-Containing Materials/Equipment .....             | 5-13 |
| 5.4.8   | Potential PCB-Containing Materials/Equipment .....                 | 5-13 |
| 5.4.9   | Silica Containing Materials .....                                  | 5-13 |
| 5.4.10  | Potential Radioactive Materials .....                              | 5-14 |
| 5.4.11  | Bats and Bat Feces .....   | 5-14 |
| 5.4.12  | Summary of Findings .....  | 5-14 |

## APPENDICES

- APPENDIX A5 Figures
- APPENDIX B5 Photographic Record
- APPENDIX C5 Sample and Analytical Summary Tables
- APPENDIX D5 Room-By-Room Inspection Sheets

## 5.0 HUNGRY GROVE POND CAMP

Hungry Grove Camp is located approximately 47 km east of the Town of Milltown-Head of Bay d’Espoir and is accessed via gravel access road from the Bay d’Espoir Highway (Route 360) (refer to Figure 5.1, Appendix A5 and Photos 1 to 8, Appendix B5). The site is comprised of an accommodations cabin and an outhouse.

At the time of the Pre-Demolition HBMA site visit, a thorough assessment of the interior of the accommodations cabin was not possible due to unsafe conditions that resulted from the presence of a large quantity of bats occupying the structure and an abundance of bat feces. As a result, there is limited information available concerning the presence/absence of hazardous building materials and equipment present within the cabin. Observations were recorded from the doorway and windows of the cabin, where possible. Please refer to hazardous building materials observed at other Former Construction Camp Sites assess along the former Bay d’Espoir – Avalon Transmission Line.

### 5.1 BUILDING DESCRIPTION

The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 65 m<sup>2</sup>. The floor plan of the cabin consists of a kitchen with sleeping areas, and three additional rooms (refer to Figure 5.2, Appendix A5). The foundation of the accommodations cabin consists of concrete block footings. The structure of the accommodations cabin consists of brick. The exterior walls on the accommodations cabin are finished with brick and the roof is finished with asphalt shingles. The window and exterior door openings on the accommodations cabin are barricaded with metal covers for security purposes. There were building upgrades completed at the site, reportedly in the mid 1990’s. The new areas are brown brick and the original areas are red brick (refer to Photos 1 to 4, Appendix B5). Interior wall and ceiling finishes in the accommodations cabin consists of painted plywood. Floors/floor finishes consist of plywood. Incandescent and fluorescent lighting was observed on the interior of the cabin. The accommodations cabin is not currently heated.

The outhouse is a one-storey, rectangular structure with a footprint area of approximately 3 m<sup>2</sup>. The foundation and structure of the outhouse consists of wood framing and concrete. The exterior walls on the outhouse are finished with plywood and the roof is finished with asphalt shingles (refer to Photos 7 to 9, Appendix B5). Interior wall and ceiling finishes in the outhouse consist of painted plywood. Floor finishes consist of plywood. The outhouse does not contain any lighting or heating.

A description of accommodations cabin is outlined in Table 5-1 and a description of the outhouse is outlined in Table 5-2. Photographs of the buildings are provided in Appendix B5.

**Table 5-1: Site Building Description – Accommodations Cabin**

| Building Name        | Accommodations cabin                   | Photo No. (Appendix B5) |
|----------------------|--|-------------------------|
| Date of Construction | Approximately late 1960’s/early 1970’s | -                       |
| Date of Renovations  | Unknown                                | -                       |
| No. of Stories       | One                                    | 1 to 4                  |
| Crawl Space (Yes/No) | No                                     | -                       |
| Attic (Yes/No)       | Yes                                    | 10                      |
| Type of Structure    | Wood Frame and Bricks                  | 1 to 4                  |
| Type of Foundation   | Concrete Block Footings                | 11                      |



**Table 5-1: Site Building Description – Accommodations Cabin**

| Building Name             | Accommodations cabin         | Photo No. (Appendix B5) |
|---------------------------|------------------------------|-------------------------|
| Exterior                  | Red and Brown brick          | 1 to 4                  |
| Window/Door Frames        | Painted Metal and Wood       | 1                       |
| Exterior Doors            | Painted Metal                | 1                       |
| Roofing Materials         | Asphalt Shingles             | 3 and 20                |
| Interior Walls Finishes   | Painted Plywood              | 5 and 6                 |
| Interior Ceiling Finishes | Painted Plywood              | 5 and 6                 |
| Floor Finishes            | Painted Plywood              | 5 and 6                 |
| Interior Doors            | NA                           | -                       |
| Interior Lighting         | Fluorescent and Incandescent | 5 to 6                  |
| Exterior Lighting         | Incandescent                 | 1                       |
| Heating                   | NA                           | -                       |

**Table 5-2: Site Building Description – Outhouse**

| Building Name             | Outhouse                               | Photo No. (Appendix B4) |
|---------------------------|--|-------------------------|
| Date of Construction      | Approximately late 1960's/early 1970's | -                       |
| Date of Renovations       | Unknown                                | -                       |
| No. of Stories            | One                                    | 7 and 8                 |
| Crawl Space (Yes/No)      | No                                     | -                       |
| Attic (Yes/No)            | No                                     | -                       |
| Type of Structure         | Plywood Frame                          | 7 and 8                 |
| Type of Foundation        | Concrete and Wood Frame                | 7                       |
| Exterior                  | Plywood                                | 8                       |
| Window/Door Frames        | NA                                     | -                       |
| Exterior Doors            | NA                                     | -                       |
| Roofing Materials         | Asphalt Shingles                       | 27                      |
| Interior Walls Finishes   | Painted Plywood                        | 8                       |
| Interior Ceiling Finishes | Plywood                                | -                       |
| Floor Finishes            | NA                                     | -                       |
| Interior Doors            | NA                                     | -                       |
| Interior Lighting         | NA                                     | -                       |
| Exterior Lighting         | NA                                     | -                       |
| Heating                   | NA                                     | -                       |

## 5.2 ROOM DESIGNATION

Each room at Hungry Grove Camp was assigned a specific room name. The designated room names are presented in Table 5-3 and graphically illustrated on the sample location plan (refer to Figure 5.2, Appendix A5).

**Table 5-3: Assigned Rooms**

| Level No. | Room Name – Accommodations Cabin | Room Number |
|-----------|----------------------------------|-------------|
| 1         | Kitchen/Bunk Area                | Room 1      |
| 1         | Unknown                          | Room 2      |
| 1         | Unknown                          | Room 3      |
| 1         | Unknown                          | Room 4      |
| 1         | Outhouse                         | Outhouse    |

## 5.3 FINDINGS

The findings documented in this section are based on observations made by Wood personnel at the time of the site visit on August 7, 2018 and the results of laboratory analyses of samples collected from Hungry Grove Camp. During the Pre-Demolition HBMA site visit, Wood personnel were accompanied by a representative of Hydro (Mr. Wayne Lidster). Copies of room-by-room inspection sheets for the accommodations building and outhouse are provided in Appendix D5. Photos of the samples collected from the accommodations building and outhouse during the site visits are provided in Appendix B5.

As previously stated in Section 5.0, a thorough assessment of the interior of the accommodations cabin was not possible due to unsafe conditions that resulted from the presence of a large quantity of bats occupying the structure and an abundance of bat feces (i.e. unsafe access conditions).

### 5.3.1 Asbestos-Containing Materials (ACMs)

There are over 3,000 ACMs that are commercially available, which can be divided into two broad categories: friable and non-friable. ACMs were discontinued from use in Canada in the late 1970s/early 1980s, although non-friable asbestos is still found in many more recent buildings.

During the Pre-Demolition HBMA site visit, a total of 13 building material samples (HG-AS1 to HG-AS13) were collected from the accommodations cabin and two building material samples (HG-PP-AS1 and HG-PP-AS2) were collected from the outhouse (refer to Photos 13 to 27, Appendix B5) and analyzed for asbestos content. Bulk sample descriptions and asbestos analytical results are summarized in Table C5-1, Appendix C5. Sample locations and analytical results are graphically illustrated on Figure 5.2, Appendix A5.

#### 5.3.1.1 Friable Materials

Friable ACMs are defined as materials that can be crumbled, pulverized and reduced to powder when dry using hand pressure. Typical friable materials include acoustical or decorative spray applications, fireproofing and thermal insulation.

##### 5.3.1.1.1 *Spray-Applied Fireproofing, Insulation and Texture Finishes*

There were no spray-applied fireproofing, insulation or texture finishes observed in the accommodations cabin or outhouse during the Pre-Demolition HBMA site visit; therefore, no samples of these materials were collected for analysis.

##### 5.3.1.1.2 *Building and Thermal System Insulation*

During the Pre-Demolition HBMA site visit, pink fiberglass insulation was observed between the particle board and plywood in the walls of the accommodations cabin. No samples of fiberglass insulation materials were collected for analysis.

#### 5.3.1.2 Non-Friable and Potentially Friable Materials

Non-friable ACMs are hard or manufactured products such as floor tiles, fire blankets, pre-formed manufactured cementitious insulation and wallboards, pipes, and siding, wherein the asbestos fibres are bound to the substrate. Note that although a product may be considered non-friable when new, the

product may release fine dust when disturbed (e.g., deterioration, removal, renovations) and the free dust is considered friable.

#### **5.3.1.2.1 Ceiling Tile**

There were no ceiling tiles observed at Hungry Grove Camp during the Pre-Demolition HBMA site visit; therefore, no samples of ceiling tile were collected for analysis.

#### **5.3.1.2.2 Drywall Joint Compound**

There was no drywall joint compound observed at Hungry Grove Camp during the Pre-Demolition HBMA site visit; therefore, no samples of drywall joint compound were collected for analysis.

#### **5.3.1.2.3 Vinyl Flooring Products and Mastics**

There was no vinyl flooring or products observed at Hungry Grove Camp during the Pre-Demolition HBMA site visit; therefore, no samples of vinyl flooring or products were collected for analysis.

#### **5.3.1.2.4 Baseboard, Carpet and Stair Tread Adhesives/Mastics**

There were no baseboard, carpet or stair tread adhesives/mastics observed at Hungry Grove Camp during the Pre-Demolition HBMA site visit; therefore, no samples of these types of adhesives/mastics were collected for analysis.

#### **5.3.1.2.5 Roofing Products**

During the Pre-Demolition HBMA site visit, one (1) sample of black shingle and tar (HG-AS9) was collected from the roof of the accommodations cabin and one (1) sample of black shingle and tar (HG-PP-AS2) was collected from the roof of the accommodations cabin and analyzed for asbestos content (refer to Photo 21 and 27, Appendix B5). Asbestos was detected in HG-AS9 containing 4.8 % chrysotile asbestos. According to the NL asbestos abatement regulations (Reg. 111/98), this material is considered asbestos-containing materials. Asbestos was not detected in the other shingle and tar sample collected from the outhouse.

Given that the accommodations cabin and outhouse were most likely constructed at the same time and it possible that same roof materials (asphalt shingles and tar) were used on both buildings, for the purpose of this HBMA, it has been assumed that the asphalt shingles on the outhouse are also asbestos-containing.

It is important to note that, due to height and safety constraints, no samples of roofing, building materials around roof penetrations (e.g., caulking or sealants around vents or electrical conduit) or roof seams were collected from the accommodations cabin for analysis.

#### **5.3.1.2.6 Caulking/Sealant**

During the Pre-Demolition HBMA site visit, one (1) sample of white caulking (HG-AS3) was collected from around the brick on the accommodations cabin, one (1) sample of black caulking (HG-AS8) was collected from the flashing on the roof of the accommodations cabin, and one (1) sample of red sealant (HG-AS10)

was collected from previous location of the chimney on the accommodations cabin, and analyzed for asbestos content (refer to Photos 15, 20 and 22, Appendix B5). Asbestos was not detected in the caulking/sealant samples analyzed.

#### **5.3.1.2.7 Mortar, Grout and Other Cementitious Materials**

During the Pre-Demolition HBMA site visit, one (1) sample of brown brick (HG-AS1), one (1) sample of grey mortar on brown brick (HG-AS2), one (1) sample of grey mortar on red brick (HG-AS4), one (1) sample of red brick (HG-AS5), one (1) sample of concrete (HG-AS6) and one (1) sample of grey mortar on concrete (HG-AS7) were collected from the exterior of the accommodations cabin and one (1) sample of concrete (HG-PP-AS1) was collected from the foundation of the outhouse and analyzed for asbestos content (refer to Photos 13, 14, 16, 17, 18, 19 and 26, Appendix B5). Asbestos was not detected in the brick, concrete and mortar samples analyzed.

#### **5.3.1.2.8 Fire-Rated Doors**

Fire-rated doors and door frames were not observed during the Pre-Demolition HBMA site visit.

#### **5.3.1.2.9 Other Potential ACMs**

During the Pre-Demolition HBMA site visit, two (2) samples of tar paper (HG-AS11 and HG-AS13) and one (1) sample of black pressed board (HG-AS-12) were collected from the exterior of the accommodations building and analyzed for asbestos content (refer to Photo 23 to 25, Appendix B5). Asbestos was not detected in the pressed board or tar paper samples analyzed.

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to, electrical and mechanical components and insulators such as wiring and gaskets, heat shields inside incandescent/fluorescent light fixtures, and caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations (refer to Photos 1, 5, and 6, Appendix B5).

Other possible hidden and inaccessible ACMs have the potential to be present within the accommodations cabin but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components or gaskets inside appliances, concrete lining the interior of hot water tanks, and underground infrastructure or piping.

### **5.3.2 Paint Additives**

Lead compounds have been used in paint as pigment and durability additives since the early 1800s. Mercury compounds have been used in paint as anti-microbial additives up until the 1990s. PCBs have been used in paint as plasticizers and corrosion resistance additives from the 1950s to the 1970s.

During the Pre-Demolition HBMA site visit, two (2) samples (HG-PS1 and HG-PS2) were collected from painted surfaces of the accommodations cabin and one (1) sample (HG-PP-PS1) collected from painted surfaces of the outhouse and analyzed for lead, mercury and PCB content (refer to Photos 28 to 30,

Appendix B5). Paint sample descriptions and lead, mercury and PCBs analytical results are summarized in Tables C5-2 to C5-4, Appendix C5. Sample locations and analytical results are graphically illustrated on Figure 5.2, Appendix A5.

### **5.3.2.1 Lead in Paint**

Concentrations of lead in the two (2) samples (HG-PS1 and HG-PS2) collected from painted surfaces of the accommodations cabin and one (1) sample (HG-PP-PS1) collected from the outhouse ranged from 228 mg/kg to 868 mg/kg (refer to Table C5-2, Appendix C5). All three paint samples contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg.

### **5.3.2.2 Mercury in Paint**

Concentrations of mercury in the two (2) samples (HG-PS1 and HG-PS2) collected from painted surfaces of the accommodations cabin and one (1) sample (HG-PP-PS1) collected from the outhouse ranged from 0.09 to 0.55 mg/kg, therefore, the concentrations of mercury in these samples were below the Federal HPA criterion (10 mg/kg) (refer to Table C5-3, Appendix C5).

### **5.3.2.3 PCBs in Paint**

PCBs were not detected (<0.5 mg/kg), and therefore, were below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg) (refer to Table C5-4, Appendix C5).

## **5.3.3 Urea Formaldehyde Foam Insulation (UFFI)**

Visual indicators suggesting the potential presence of UFFI were not observed at Hungry Grove Camp. The nature of the insulation in the walls and ceilings throughout the accommodations cabin consisted of fiberglass insulation.

Since the original date of construction of Hungry Grove Camp (assumed construction commenced the same timeframe as the original transmission line, late 1960's/early 1970's) is unknown, it is possible that UFFI may be present.

In the event that UFFI is present, the CMHC state that "tests show that UFFI is not a source of over-exposure to formaldehyde after the initial curing and release of excess gas". The general view based on studies concerning formaldehyde emissions is that as a product ages, the amount of formaldehyde off-gassed from the product decreases over time. The amount of formaldehyde released is reportedly dependent on temperature, humidity and whether or not the product is exposed to excessive moisture or water.

## **5.3.4 Suspected Visible Mould Growth (SVG)**

Wood inspected the interior areas of the accommodations cabin and outhouse for visual or olfactory evidence of suspected mould. SVG was noted on much of the ceiling and wall surfaces inside the accommodations cabin, observed from the entrance, during the Pre-Demolition HBMA site visit. Due to

presence of bats and bat feces on the surfaces of the accommodations cabin, it was unsafe to enter the building to obtain a sample (refer to Photos 5 and 6, Appendix B5).

### **5.3.5 Mercury-Containing Thermostats**

Thermostats were not identified inside the accommodations cabin at Hungry Grove Camp during the Pre-Demolition HBMA site visit, as observed from the exterior of the cabin. Based on inspections of other similar cabins along the transmission line, it is unlikely that there are any thermostats present.

### **5.3.6 PCB-Containing Light Ballasts**

Fluorescent and incandescent light fixtures were observed on the interior of the accommodations cabin, as observed from the exterior of the cabin, during the Pre-Demolition HBMA site visit (refer to Photos 5 and 6, Appendix B5). No light ballasts were inspected during the Pre-Demolition HBMA site visit.

### **5.3.7 Potential Sources of ODS and Halocarbons**

Wood were no able to assess whether or not there were potential sources of ODS within accommodations cabin, as observed from the exterior of the cabin, during the Pre-Demolition HBMA site visit.

### **5.3.8 Other Potentially Hazardous Building Materials or Substances**

Other potentially hazardous building materials or substances identified during this assessment are presented in the following sections.

#### **5.3.8.1 Lead-Containing Materials and Equipment**

Lead is typically associated with plumbing solder and older pipe materials (e.g., cast iron pipe joints), as well as products such as radiation protective shielding and lead-acid batteries. Lead can also be present in steel and iron primer, industrial electrical jacketing, roof flashing and tank linings.

Since the actual date that Hungry Grove Camp was constructed is unknown (assumed to be late 1960's/early 1970's), it is possible that lead solder is present in any plumbing and piping (i.e., cast iron and copper piping) in the accommodations cabin, as lead solder for use in potable water distribution pipes was not banned until the late 1980s (refer to Photo 6, Appendix B5).

#### **5.3.8.2 Mercury-Containing Materials and Equipment**

The light tubes and bulbs in HID and fluorescent light fixtures often contain limited quantities of mercury in a powder or vapour form. Both incandescent and fluorescent light fixtures were observed on the exterior and the interior of the accommodations cabin during the Pre-Demolition HBMA site visit (Photos 1, 5 and 6, Appendix B5).

#### **5.3.8.3 PCB-Containing Materials and Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, and as mentioned previously, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

#### **5.3.8.4 Treated Wood Chemicals**

The chemicals that are used to protect and preserve wood products from insect attack and fungal decay may pose risks to human health and the environment. Depending on the wood treatment used, treated wood may be considered a hazardous waste upon disposal. The NL Department of Environment and Conservation (currently the NL MAE), 2015 Guidance Document for Treated Wood Waste Disposal (GD-PPD-075.1) provides landfill disposal standards for “pressure treated” inorganic preservatives (i.e., arsenic and chromium) and creosote (i.e., total cresol and benzo(a)pyrene) and chlorophenolic (i.e., pentachlorophenol) formulations used to preserve wood. These landfill disposal standards for treated wood waste (TWW) are used to assess the results of leachability testing to determine disposal options for treated wood to be removed during renovation or demolition activities.

Treated wood was not identified during the Pre-Demolition HBMA site visit.

#### **5.3.8.5 Silica**

According to the CPWR – The Center for Construction Research and Training, many common construction materials contain silica including, asphalt, brick, cement, concrete, drywall, grout, mortar, stone, sand and tile. The dust created by cutting, grinding, drilling or otherwise disturbing these materials can contain crystalline silica particles.

Based on the Pre-Demolition HBMA site visit, silica is expected to be present in concrete blocks used in the construction of the foundation for the accommodations cabin. Silica may also be present in the asphalt shingles used in the construction of the accommodations cabin and outhouse.

#### **5.3.8.6 Radioactive Materials**

Smoke detectors were not observed during the Pre-Demolition HBMA site visit; however, observation of the interior of the accommodations cabin was limited to the doorway and windows, so it is possible that smoke detectors are present. Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called “ion chamber smoke alarms”.

#### **5.3.8.7 Bat Feces**

At the time of the Pre-Demolition HBMA site visit, there was a large quantity of bats occupying the accommodations cabin and an abundance of bat feces present inside the structure.

Employees entering the building and workers involved removing accumulations bat feces are at risk of exposure to airborne fungal spores (and other microbial hazards) likely to be released when this material is disturbed. Bat droppings should be presumed to be contaminated with the fungi *Histoplasma capsulatum*, *Cryptococcus neoformans*, and other infectious hazards. Many of these microorganisms are known to cause respiratory infections in workers exposed during construction, maintenance or demolition disturbance, and use of property personal protective equipment is recommended (EACO Mould Abatement Guidelines, Edition 3 (2015)).

Materials contaminated with bat feces may be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the owner/operator of the landfill.

## 5.4 CONCLUSIONS AND RECOMMENDATIONS

Based on observations made and information gathered during the Pre-Demolition HBMA, the following conclusions and recommendations are made with respect to the potential and actual presence of hazardous building materials at Hungry Grove Camp.

### 5.4.1 ACMs

Results of the asbestos sampling and analytical program revealed building materials containing greater than 1% asbestos by dry weight, which are considered to be ACMs, are present in the form of non-friable black shingle and black tar on the roof of the accommodations cabin.

The asbestos-containing black shingle and tar visible on the roof of the accommodations cabin (approximately 65 m<sup>2</sup>), as observed, appeared to be generally intact and in fair condition. Given that the accommodations cabin and outhouse were most likely constructed at the same time and it possible that same roof materials (asphalt shingles and tar) were used on both buildings, for the purpose of this HBMA, it has been assumed that the asphalt shingles on the outhouse (covering an area of approximately 3 m<sup>2</sup>) are also asbestos-containing.

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to:

- Electrical and mechanical components and insulators such as wiring and gaskets.
- Heat shields inside incandescent/ fluorescent light fixtures.
- Caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations.

Other possible hidden and inaccessible ACMs have the potential to be present within the buildings at Hungry Grove Camp but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include concrete leveling compound (existing concrete foundation), possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components, concrete lining the interior of hot water tanks, and underground infrastructure or piping.

If other potential ACMs that were not sampled as part of this assessment are encountered in the future, these materials should be treated as ACMs or samples should be collected and tested to verify asbestos content. This should be done as soon as these materials are encountered and before these materials are disturbed. This includes materials that are currently concealed by walls and ceiling systems.

In accordance with the NL Asbestos Abatement Regulations (Reg. 111/98), which provide the legislative requirements for safe handling of ACMs in workplaces in the Province of NL, the following is recommended:

- Safe work procedures shall be established.
- All buildings constructed during the period when asbestos was readily used in construction (generally prior to the early 1980s) or any buildings that are suspected as having asbestos must have a written assessment and management plan (where applicable) for potential ACMs.
- Materials suspected of containing asbestos are required to be handled as ACMs, until analysis by a



competent laboratory determines whether or not it does contain asbestos.

- Prior to general demolition, all ACMs must be safely removed from the building and disposed of in accordance with appropriate environmental guidelines by an asbestos abatement contractor registered with the Occupational Health and Safety (OHS) Division of Service NL.
- Most work involving ACMs (i.e., disturbance, removal and encapsulation) must be conducted by a contractor registered with the OHS Division of Service NL.
- ACMs in good condition should be inspected on an annual basis.
- ACMs in poor condition should be removed from the building and transported off-site for proper disposal.
- Workers should don adequate respiratory protection and personal protective equipment (PPE) when working with ACMs.

Prior to the removal and/or abatement of any identified ACMs (or any other hazardous building materials), an abatement plan including technical specifications should be designed, prepared and supervised by a qualified professional and should be undertaken by qualified trades, in accordance with applicable standards. Activities involving the disturbance and/or removal of ACMs should be carried out in a manner that ensures asbestos fiber concentrations do not exceed the applicable American Conference of Governmental Industrial Hygienists (ACGIH) threshold limit value (TLV). ACMs can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.

#### 5.4.2 Lead, Mercury and PCBs in Paint

Results of the paint sampling and analytical program revealed the following:

- **Lead and Leachable Lead in Paint**
  - Concentrations of lead in the two (2) samples (HG-PS1 and HG-PS2) collected from painted surfaces of the accommodations cabin and one (1) sample (HG-PP-PS1) collected from the outhouse ranged from 228 mg/kg to 868 mg/kg.
  - All three (3) paint samples (HG-PS1 and HG-PS2 and HG-PP-PS1) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg; therefore, these paints are considered to be LBPs but are not likely to be leachable for lead.
- **Mercury and Leachable Mercury in Paint**
  - Concentrations of mercury in the two (2) samples (HG-PS1 and HG-PS2) collected from painted surfaces of the accommodations cabin and one (1) sample (HG-PP-PS1) collected from the outhouse ranged from 0.09 to 0.55 mg/kg; below the Federal HPA criterion (10 mg/kg). These paints are not considered to be MBPs and are not likely to be leachable for mercury.
- **PCBs in Paint**
  - PCBs were not detected (<0.5 mg/kg) in the two (2) samples (HG-PS1 and HG-PS2) collected from painted surfaces of the accommodations cabin and one (1) sample (HG-PP-PS1) from the painted surfaces of the outhouse, and therefore, below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg).

Based on the paint sample analytical results, painted surfaces of the accommodations cabin and outhouse are not likely to be leachable for lead, PCBs or mercury; therefore, should disposal be required (e.g.,

renovation or demolition activities), the paints analyzed for lead, mercury and PCB content may be disposed of at an approved landfill facility, pending landfill and Provincial regulatory approval.

There are potential adverse human health impacts associated with disturbing (e.g., scraping, sanding, burning, etc.) lead, mercury PCB-containing paint finishes, due to the potential for dust, mist or fumes to be released and inhaled or ingested by workers. Given the lead-based paints were identified at the site, as a precautionary measure, Wood recommends handling these paint finishes, as follows:

- In areas of minor peeling or flaking, the paint should be removed using wet scraping techniques.
- In areas of extensive peeling and flaking, the paint should be removed and more extensive particulate control measures may be required.
- In areas where lead-containing paint finishes are present and in poor condition, an experienced contractor should be utilized for renovating, decommissioning or demolition activities.
- Prior to renovation, dismantling or demolition activities, all areas of extensive peeling and flaking of lead-containing paint finishes and paint debris/dust should be removed and/or remediated to ensure that building occupants/workers are protected from associated dust/particulate.
- Procedures should be implemented to ensure that workers and anyone present in and around areas being renovated, dismantled or demolished are protected. The contractor should also ensure that dust generation and migration is minimized.
- Precautions should be taken to prevent/reduce exposure to paint dust during any disturbance of lead-containing paint finishes, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas.
- Where possible, lead-containing paint finishes should be removed from metal surfaces prior to welding or cutting these materials.

If potential lead, mercury or PCB containing paint finishes that were not sampled during this assessment are encountered in future, prior to any disturbance or removal, samples should be obtained and tested to verify concentrations of lead, mercury and PCBs. This includes materials that are currently concealed by walls and ceiling systems.

Any disturbance or removal of lead, mercury or PCB-containing paint finishes that may generate dust or respirable aerosols must conform to the Federal and Provincial OHS Regulations. All work should be carried out by individuals wearing proper PPE. The type of respiratory protection and control measures to be implemented during the removal of these types of paint finishes should be determined by a qualified person and based on the risk level of a particular work activity (i.e., scraping, sanding, abrasive blasting, etc.). Activities involving the disturbance and/or removal of lead, mercury or PCB-containing paint finishes should be carried out in a manner that ensures paint dust concentrations do not exceed the applicable ACGIH TLVs.

### **5.4.3 Potential UFFI**

The sale and installation of UFFI was banned in 1980; since the original date of construction is unknown, it is possible that UFFI may be present in the building. Visual indicators suggesting the potential presence of UFFI were not observed in the building. It can be inferred that any UFFI present within the building is unlikely to affect the indoor air quality due to the amount of time that has passed since the insulation was likely installed (i.e., pre-1980) along with the likelihood that formaldehyde has off-gassed over this period

of time. It should be noted that, the presence and concentration of formaldehyde cannot be determined or quantified without conducting site-specific testing for formaldehyde.

Although there are currently no Provincial regulations requiring that the removal of UFFI be conducted by a licensed/registered abatement contractor, based on discussions with representatives of the OHS Division of Service NL, it is strongly recommended that this material be abated using similar methods as required for asbestos abatement and that the insulation must be removed in a dry condition. Based on discussions with representatives of the NL MAE, for the purposes of disposal of UFFI, this material is permitted to be bagged and transported to an approved WDS and disposed in the special waste area (unlined area) of the site.

#### **5.4.4 Mould**

Wood inspected the interior areas of the accommodations cabin, from the entrance, and outhouse for visual or olfactory evidence of suspected mould. SVG was noted on much of the ceiling and wall surfaces inside the accommodations cabin during the Pre-Demolition HBMA site visit. Due to presence of bats and bat feces on the surfaces of the accommodations cabin, it was unsafe to enter the building to obtain a sample.

Mould spores are present in all indoor environments and cannot be completely eliminated. Cellulose based building materials provide a nutrient base for many mould species; however, mould cannot grow unless an adequate amount of excess moisture is present. The most effective way to prevent mould growth within a building is the prompt removal of any porous building materials with water damage or mould growth and repairing the building components that lead to the water infiltration.

#### **5.4.5 Potential ODS**

Wood were no able to assess whether or not there were potential sources of ODS within accommodations cabin, as observed from the exterior of the cabin, during the Pre-Demolition HBMA site visit.

Ozone depleting substances (ODS), if present, should be removed by an approved contractor prior to disposing of any cooling and/or refrigeration equipment from the building. The use, storage, operation, maintenance, decommissioning, and disposal of ODS containing equipment, in general, is regulated at both a Provincial and Federal level and must comply with the most recent NL Halocarbon Regulations and the Federal Halocarbon Regulations. The status of the potential ODS containing equipment should be confirmed through a mechanical contractor or consultant.

#### **5.4.6 Potential Lead-Containing Materials/Equipment**

Lead solder is likely to be present in plumbing and piping (e.g., cast iron and copper piping) in the accommodations cabin.

The disturbance, control or disposal of lead-containing material/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of lead in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a metal recycling facility and not a landfill. Removal of lead-containing batteries should be completed in a manner that ensures structural integrity and no loss of fluid from the batteries. Should disposal be required, disposal of lead-containing

batteries should be completed in accordance with hazardous waste procedures/guidelines (i.e., at an approved facility).

Sampling drinking water for the analysis of lead was not included in the scope of work for the Pre-Demolition HBMA.

#### **5.4.7 Potential Mercury-Containing Materials/Equipment**

Should disposal be required, mercury-containing equipment should be removed intact and returned to the manufacturer for recycling or disposed of at an approved hazardous waste disposal facility. The disturbance, control or disposal of mercury-containing materials/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of mercury in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a recycling or hazardous waste disposal facility and not a landfill.

#### **5.4.8 Potential PCB-Containing Materials/Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

If PCB-containing materials or equipment are encountered in the future, and should disposal be required, the PCB content in the materials or equipment should be confirmed prior to disposal. Florescent light fixtures are present within the accommodations cabin. Any leaking light ballasts identified, whether PCB containing or not, should be removed and replaced to avoid potential concerns with electrical equipment in the future. All ballasts that are removed should be placed in a proper storage container(s). Leaks or stained areas should be cleaned and/or removed in accordance with applicable regulations or industry standards.

Any PCB-containing equipment (if present) should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations. Any PCB-containing equipment requiring removal from the building should be transported and disposed of at an approved hazardous waste disposal site, and not a landfill disposal site, by a registered hazardous waste transporter in accordance with applicable regulations.

#### **5.4.9 Silica Containing Materials**

Silica is expected to be present in concrete used in the construction of the foundation for the accommodations cabin. Silica may also be present in asphalt shingles used in the construction of accommodations cabin. Precautions should be taken to prevent/reduce exposure to silica dust during any disturbance/ demolition of silica-containing products, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas. Activities involving the disturbance and/or demolition of silica-containing materials should be carried out in a manner that ensures silica dust concentrations do not exceed the applicable ACGIH TLV.

#### **5.4.10 Potential Radioactive Materials**

Smoke detectors were not observed during the Pre-Demolition HBMA site visit; however, observation of the interior of the accommodations cabin was limited to the doorway and windows, so it is possible that smoke detectors are present. Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called "ion chamber smoke alarms".

#### **5.4.11 Bats and Bat Feces**

At the time of the Pre-Demolition HBMA site visit, there was a large quantity of bats occupying the accommodations cabin and an abundance of bat feces present inside the structure.

Employees entering the building and workers involved removing accumulations bat feces are at risk of exposure to airborne fungal spores (and other microbial hazards) likely to be released when this material is disturbed. Bat droppings should be presumed to be contaminated with the fungi *Histoplasma capsulatum*, *Cryptococcus neoformans*, and other infectious hazards. Many of these microorganisms are known to cause respiratory infections in workers exposed during construction, maintenance or demolition disturbance, and use of property personal protective equipment is recommended (EACO Mould Abatement Guidelines, Edition 3 (2015)). Materials contaminated with bat feces may be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.

Prior to demolition or disturbance of materials at the cabin, it is recommended that the presence of bats within the accommodations cabin be reported to the NL Department of Fisheries and Land Resources' Wildlife Division. Avoid entering the cabin and seek non-destruction methods to deal with the bats.

#### **5.4.12 Summary of Findings**

Hazardous building materials identified at Hungry Grove Camp during this Pre-Demolition HBMA and disposal options, if required, are summarized in Table 5-4. Conclusions and recommendations made with respect to the potential and actual presence of hazardous building materials within the accommodations cabin and outhouse are provided in Section 5.4 and should be reviewed in conjunction with Table 5-4.

**Table 5-4: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| Hazardous Material    | Applicable Acts, Regulations or Guidance Documents   | Description and Location   | Disposal  |
|-----------------------|--|--|---|
| <b>ACMs</b>           | NL Asbestos Abatement Regulations (Reg. 111/98)  | <p>Black shingle and tar on the roof of the accommodations cabin (~67m<sup>2</sup>) and the outhouse (~3m<sup>2</sup>).</p> <p>Note that other possible hidden and inaccessible ACMs have the potential to be present within the accommodations building, but were not identified during the Pre-Demolition HBMA site visit.</p> | <p>ACMs cannot be disposed of at a Construction &amp; Demolition Site; however, these materials can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.</p> <p>The transportation and disposal of asbestos should be conducted in accordance with the NL Asbestos Abatement Regulations (Reg. 111/98) and with Standard Operating Procedures (SOPs) for disposal of ACMs at the landfill.</p> |
| <b>LBP</b>            | <p>Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)</p> <p>Federal HPA (R.S.1985, c. H-3)</p> <p>Federal TDG Act (1992, c. 34)</p> <p>Surface Coating Materials Regulations (SOR/2016-193)</p> | <p>LBP (grey) on plywood floor of accommodations cabin.</p> <p>LBP (white) on wood door trim on interior of accommodations cabin.</p> <p>LBP (grey) on plywood interior accommodations cabin.</p>  | <p>Paints that were analyzed for lead and contained &lt;5,000 mg/kg lead, may be disposed of at a Regional Solid Waste Disposal Facility (landfill), provided permission is obtained from the landfill owner/operator.</p>  |
| <b>Potential UFFI</b> | Federal HPA (R.S.1985, c. H-3)   | None Identified  | UFFI is permitted to be bagged and transported to an approved WDS and disposed in the special waste area of the site.   |
| <b>Mould</b>          | <p>Mould Guidelines for the Canadian Construction Industry, Canadian Construction Industry (CCI), 2004;</p> <p>Mould Abatement Guidelines, Environmental Abatement Council of Ontario (EACO), 2010</p>               | <p>Some water staining noted on walls and ceiling in the accommodations cabin.</p> <p>Due to presence of bats and bat feces on the surfaces of the accommodations cabin, it was unsafe to enter the building to obtain a sample.</p>   | <p>All mould impacted materials may be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.</p>   |

**Table 5-4: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b>                                | <b>Applicable Acts, Regulations or Guidance Documents</b>  | <b>Description and Location</b>  | <b>Disposal</b>  |
|--|--|--|--|
| <b>Potential ODS</b>                                     | Federal Halocarbon Regulations (SOR/2003-289)  | Wood were no able to assess whether or not there were potential sources of ODS within accommodations cabin, as observed from the exterior of the cabin, during the Pre-Demolition HBMA site visit.   | Materials containing ODS should be received by a contractor or facility that has the proper approvals to remove, handle and/or dispose of ODS. The remaining materials can be disposed of at a recycling facility, provided permission is obtained from the facility.  |
| <b>Potential Lead-Containing Materials/ Equipment</b>    | Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)<br>Federal HPA (R.S.1985, c. H-3)<br>Federal TDG Act (1992, c. 34)<br>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301) | Potential lead-containing solder (piping and plumbing).<br><br>Other lead containing materials may also be present.  | Lead-containing materials and equipment can be disposed of at a metal recycling or hazardous waste disposal facility, in accordance with applicable regulations.<br><br>The transportation and disposal of hazardous lead-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility. |
| <b>Potential Mercury-Containing Materials/ Equipment</b> | Federal HPA (R.S.1985, c. H-3)<br>Federal TDG Act (1992, c. 34)<br>Products Containing Mercury Regulations (SOR/2014-254)  | Fluorescent light fixtures are present inside accommodations cabin. The light tubes in fluorescent light fixtures often contain limited quantities of mercury in a powder or vapour form.<br><br>Other mercury containing materials may also be present. | Mercury-containing materials and equipment can be disposed of at a recycling or hazardous waste disposal facility, in accordance with applicable regulations.<br><br>The transportation and disposal of hazardous mercury-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility. |

**Table 5-4: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| Hazardous Material                                   | Applicable Acts, Regulations or Guidance Documents  | Description and Location   | Disposal  |
|--|---|--|---|
| <b>Potential PCB-Containing Materials/ Equipment</b> | Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)<br>Federal TDG Act (1992, c. 34)<br>Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)<br>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301)<br>PCB Regulations (SOR/2008-273)<br>PCB Waste Export Regulations (SOR/97-109)<br>Regulations Amending the PCB Regulations (SOR/2010-57) | Fluorescent light fixtures are present inside accommodations cabin. The ballast of the fluorescent light fixtures may contain PCBs.<br><br>Other PCB containing materials may also be present. | Any PCB-containing materials and equipment should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations.<br><br>Any PCB-containing materials and equipment requiring removal from the building should be transported and disposed of by a registered hazardous waste transporter in accordance with applicable regulations.<br><br>The transportation and disposal of PCB containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility. |
| <b>Silica-Containing Materials</b>                   | NL OHS Act (RSNL1990 Chapter O-3)<br>NL OHS Regulations (5/12)  | Asphalt shingles and concrete.   | These materials can be disposed of at a Regional Solid Waste Disposal Facility (landfill).  |
| <b>Potential Radioactive Materials</b>               | Federal TDG Act (1992, c. 34)   | Wood were no able to assess whether or not there were any smoke detectors present within accommodations cabin, due to unsafe access (bats and feces).  | Smoke detectors that contain low level radioactive materials must be transported, as per Federal TDG Regulations, to a licensed disposal facility.  |



**Table 5-4: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b> | <b>Applicable Acts, Regulations or Guidance Documents</b> | <b>Description and Location</b>          | <b>Disposal</b>   |
|---------------------------|---|--|---|
| <b>Bats and Fat Feces</b> | EACO Mould Abatement Guidelines, Edition 3 (2015))        | Present inside the accommodations cabin. | <p>Materials contaminated with bat feces may be disposed of at a Regional Solid Waste Disposal Facility, provided permission is obtained from the landfill owner/operator.</p> <p>Prior to demolition or disturbance of materials at the cabin, it is recommended that the presence of bats within the accommodations cabin be reported to the NL Department of Fisheries and Land Resources' Wildlife Division. Avoid entering the cabin and seek non-destruction methods to deal with the bats.</p> |

**APPENDIX A5**

**FIGURES**



**NOTES:**  
 1. ALL DIMENSIONS ARE IN METERS.  
 2. DO NOT SCALE FROM FIGURE.  
 3. THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.  
 4. ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.  
 5. THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.  
 6. THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



newfoundland labrador  
**hydro**  
 a nalcor energy company

---

**Wood**  
 Environment & Infrastructure Solutions  
 133 Crosbie Road  
 St. John's, NL A1B 4A5  
 709-722-7023



Drawn by:  
 T. Rideout

Approved by:  
 C. Finney

Scale:  
 As Shown

Project:  
 Pre-Demolition Hazardous Building Materials Assessment,  
 Former Construction Camp Sites,  
 Bay d'Espoir - Avalon Transmission Line, NL





Title:  
 Site Location Plan (Aerial) - Hungry Grove Camp Site

Date:  
 April 2019

Project No.  
 TF18104243.2000

Rev. No.  
 0

Figure No.  
 5.1



**LEGEND:**

- ASBESTOS SAMPLE LOCATION - ASBESTOS NOT DETECTED
- ASBESTOS SAMPLE LOCATION - RESULTS > 1% FOR ASBESTOS
- ▲ PAINT SAMPLE LOCATION - NO CRITERIA EXCEEDANCES FOR LEAD OR MERCURY OR PCBs WHERE APPLICABLE
- ▲ PAINT SAMPLE LOCATION - RESULTS EXCEED 90 mg/kg AND LESS THAN 5000 mg/kg FOR LEAD AND NO CRITERIA EXCEEDANCES FOR MERCURY OR PCBs WHERE APPLICABLE

**NOTES:**

- ALL DIMENSIONS ARE IN METERS.
- DO NOT SCALE FROM FIGURE.
- THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.
- ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.
- THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.
- THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:

**Wood**  
Environment & Infrastructure Solutions  
133 Crosbie Road  
St. John's, NL A1B 4A5  
709-722-7023

Drawn by:  
T. Rideout

Approved by:  
C. Finney

Scale:  
As Shown

Project:  
Pre-Demolition Hazardous Building Materials Assessment,  
Former Construction Camp Sites,  
Bay d'Espoir - Avalon Transmission Line, NL

Title:  
Sample Location Plan - Hungry Grove Camp Site

Date:  
April 2019

Project No.  
TF18104243.2000

Rev. No.  
0

Figure No.  
5.2

**APPENDIX B5**  
**PHOTOGRAPHIC RECORD**



Photo 1: View of the accommodations cabin at Hungry Grove Pond Camp, looking northwest.



Photo 2: View of the accommodations cabin at Hungry Grove Pond Camp, looking north.



Photo 3: View of the accommodations cabin at Hungry Grove Pond Camp, looking west.



Photo 4: View of the accommodations cabin at Hungry Grove Pond Camp, looking east.



Photo 5: View of the kitchen/bunk area at Hungry Grove Pond Camp.



Photo 6: View of the kitchen/bunk area at Hungry Grove Pond Camp.



Photo 7: View of the outhouse at Hungry Grove Pond Camp, looking north.



Photo 8: View of the interior of the outhouse at Hungry Grove Pond Camp.



Photo 9: View of the interior of the outhouse at Hungry Grove Pond Camp.



Photo 10: View of attic in accommodations cabin at Hungry Grove Pond Camp.



Photo 11: View of cavity inspection below floors in accommodations cabin at Hungry Grove Pond Camp.



Photo 12: View of cavity inspection in wall from exterior accommodations cabin at Hungry Grove Pond Camp.





Photo 13: View of bulk material sample HG-AS1, brown brick, cabin exterior.



Photo 14: View of bulk material sample HG-AS2, grey mortar, cabin exterior.



Photo 15: View of bulk material sample HG-AS3, white caulking, cabin exterior.



Photo 16: View of bulk material sample HG-AS4, grey mortar, cabin exterior.



Photo 17: View of bulk material sample HG-AS5, red brick, cabin exterior.



Photo 18: View of bulk material sample HG-AS6, concrete block, cabin exterior.



Photo 19: View of bulk material sample HG-AS7, grey mortar, cabin exterior.



Photo 20: View of bulk material sample HG-AS8, black caulking, cabin exterior.



Photo 21: View of bulk material sample HG-AS9, black shingle and tar, cabin exterior. **4.8 % Crysofile Asbestos.**



Photo 22: View of bulk material sample HG-AS10, red sealant, cabin exterior.



Photo 23: View of bulk material sample HG-AS11, tar paper, cabin exterior.



Photo 24: View of bulk material sample HG-AS12, pressed board, cabin exterior.



Photo 25: View of bulk material sample HG-AS-13, tar paper, cabin exterior.



Photo 26: View of bulk material sample HG-PP-AS1, concrete, outhouse exterior.



Photo 27: View of paint sample HG-PP-AS2, shingle and tar, outhouse exterior.



Photo 28: View of paint sample HG-PS1, grey, accommodations cabin interior.



Photo 29: View of paint sample HG-PS2, grey, accommodations cabin interior.



Photo 30: View of paint sample HG-PS1, grey, outhouse interior.

**APPENDIX C5**

**SAMPLE AND ANALYTICAL SUMMARY TABLES**

**Table C5-1: Bulk Sample Descriptions and Asbestos Analytical Results (Hungry Grove Pond Camp Site)**

| Sample ID | Room No. | Room Description    | Photo No. | Sample Location | Sample Description              | Layers Analyzed | Analytical Result |
|-----------|----------|---------------------|-----------|-----------------|---------------------------------|-----------------|-------------------|
| HG-AS1    | Exterior | Exterior - Cabin    | 13        | Wall            | Brown brick                     | Brick           | ND                |
| HG-AS2    | Exterior | Exterior - Cabin    | 14        | Wall            | Grey mortar (on brown brick)    | Mortar          | ND                |
| HG-AS3    | Exterior | Exterior - Cabin    | 15        | Wall            | White caulking (around brick)   | Caulking        | ND                |
| HG-AS4    | Exterior | Exterior - Cabin    | 16        | Wall            | Grey mortar (on red brick)      | Mortar          | ND                |
| HG-AS5    | Exterior | Exterior - Cabin    | 17        | Wall            | Red brick                       | Brick           | ND                |
| HG-AS6    | Exterior | Exterior - Cabin    | 18        | Wall            | Concrete block                  | Concrete        | ND                |
| HG-AS7    | Exterior | Exterior - Cabin    | 19        | Wall            | Grey mortar (on concrete block) | Mortar          | ND                |
| HG-AS8    | Exterior | Exterior - Cabin    | 20        | Roof            | Black sealant on flashing       | Sealant         | ND                |
| HG-AS9    | Exterior | Exterior - Cabin    | 21        | Roof            | Black shingle and black tar     | Shingle and tar | 4.80%             |
| HG-AS10   | Exterior | Exterior - Cabin    | 22        | Chimney         | Red sealant                     | Sealant         | ND                |
| HG-AS11   | Exterior | Exterior - Cabin    | 23        | Wall            | Tar paper                       | Tar paper       | ND                |
| HG-AS12   | Exterior | Exterior - Cabin    | 24        | Wall            | Black pressed board             | Pressed board   | ND                |
| HG-AS13   | Exterior | Exterior - Cabin    | 25        | Wall            | Tar paper                       | Tar paper       | ND                |
| HG-PP-AS1 | Exterior | Exterior - Outhouse | 26        | Foundation      | Concrete                        | Concrete        | ND                |
| HG-PP-AS2 | Exterior | Exterior - Outhouse | 27        | Roof            | Black shingle and black tar     | Shingle and tar | ND                |

**Notes:**

ACM: Asbestos-Containing Material

DJC: Drywall Joint Compound

VFT: Vinyl Floor Tile

VSF: Vinyl Sheet Flooring

ND: Non-Detect (<0.1%)

\*Brown paper and tar analyzed as one layer because the laboratory could not separate these materials.

**Bold and underlined value indicates asbestos was detected but is below 1% by dry weight.**

Shaded value exceeds 1% asbestos by dry weight and is considered to be an ACM as outlined in the Newfoundland and Labrador Asbestos Abatement Regulations (Reg. 111/98).

**Table C5-2: Paint Sample Descriptions and Lead Analytical Results (Hungry Grove Pond Camp Site)**

| Sample ID | Room No. | Room Description | Photo No. | Sample Location | Substrate        | Sample Description                             | RDL (mg/kg) | Lead (mg/kg)      |
|-----------|----------|------------------|-----------|-----------------|------------------|--|-------------|-------------------|
| HG-PS1    | 1        | Kitchen          | 28        | Floor           | Plywood          | Grey on wood floor (sample includes wood)      | 15.0        | <b><u>868</u></b> |
| HG-PS2    | 1        | Kitchen          | 29        | Wall            | Wooden baseboard | White on wood baseboard (sample includes wood) | 15.0        | <b><u>228</u></b> |
| HG-PP-PS1 | Exterior | Outhouse         | 30        | Exterior        | Plywood          | Grey on wood (sample includes wood)            | 15.0        | <b><u>280</u></b> |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

**Bold and underlined value exceeds Federal HPA criterion (90 mg/kg).**

Shaded value exceeds former Federal HPA criterion (5,000 mg/kg).



**Table C5-3: Paint Sample Descriptions and Mercury Analytical Results (Hungry Grove Pond Camp Site)**

| Sample ID | Room No. | Room Description | Photo No. | Sample Location | Substrate        | Sample Description                             | RDL (mg/kg) | Mercury (mg/kg) |
|-----------|----------|------------------|-----------|-----------------|------------------|--|-------------|-----------------|
| HG-PS1    | 1        | Kitchen          | 28        | Floor           | Plywood          | Grey on wood floor (sample includes wood)      | 0.05        | 0.44            |
| HG-PS2    | 1        | Kitchen          | 29        | Wall            | Wooden baseboard | White on wood baseboard (sample includes wood) | 0.05        | 0.55            |
| HG-PP-PS1 | Exterior | Outhouse         | 30        | Exterior        | Plywood          | Grey on wood (sample includes wood)            | 0.05        | 0.09            |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

**Bold and underlined value exceeds Federal HPA criterion (10 mg/kg).**

Shaded value exceeds CCME CSQG for an industrial site (50 mg/kg).

**Table C5-4: Paint Sample Descriptions and PCB Analytical Results (Hungry Grove Pond Camp Site)**

| Sample ID | Room No. | Room Description | Photo No. | Sample Location | Substrate        | Sample Description                             | RDL (mg/kg) | Total PCB (mg/kg) |
|-----------|----------|------------------|-----------|-----------------|------------------|--|-------------|-------------------|
| HG-PS1    | 1        | Kitchen          | 28        | Floor           | Plywood          | Grey on wood floor (sample includes wood)      | 0.5         | <0.5              |
| HG-PS2    | 1        | Kitchen          | 29        | Wall            | Wooden baseboard | White on wood baseboard (sample includes wood) | 0.5         | <0.5              |
| HG-PP-PS1 | Exterior | Outhouse         | 30        | Exterior        | Plywood          | Grey on wood (sample includes wood)            | 0.5         | <0.5              |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

NL MAE: Newfoundland and Labrador Department of Municipal Affairs and Environment

TDG: Transportation of Dangerous Goods

#Sample collected by Hydro on May 5, 2018.

**Shaded value exceeds the criterion for PCB solid provided in the NL MAE Leachable Toxic Waste, Testing and Disposal Guidance Document and the TDG Regulations (50 mg/kg).**

Shaded value exceeds the criterion for PCB solid provided in the NL MAE Leachable Toxic Waste, Testing and Disposal Guidance Document and the TDG Regulations (50 mg/kg).

**APPENDIX D5**

**ROOM-BY-ROOM INSPECTION SHEETS**

| Building           | Room # | Floor # | Room Description | Dimensions  |
|--------------------|--------|---------|------------------|---|
| HG<br>Hungry Group |        |         | Kitchen          | L = 24'<br>W = 18'<br>H = 8' } Based on previous camp |

|   | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|---|--|---------------------------|--|
| <b>Floor</b>  | Wood  |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | Wood  |  |                           |  |
| <b>Ceiling</b>  | Wood  |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls: white / beige<br>Ceiling:<br>Floor: grey<br>Other:   |  |                           | HG-PS2<br>HG-PS1                               |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer: <i>Estimote (cannot read)</i><br>Fire Door Serial #:                                      |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —   |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #: 2  | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 2   |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial   | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —   |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br><i>Get feces<br/>Mould</i>   |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—   |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br><br>* No Access * |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9'); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                |
|----------|--------|---------|------------------|---------------------------|
| HG       |        |         | Exterior         | L = 30'<br>W = 24'<br>H = |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)                    | Samples Collected<br>(actual/visual reference) |
|---|--|--|--|--|
| <b>Floor</b><br>Foundation  | Cinder block w grey mortar   |  | Block<br>Mortar                              | HG-AS6<br>HG-AS7                               |
| <b>Walls</b><br>(include window<br>caulking)  | Red brick w grey mortar on 1/2<br>Brown brick w grey mortar on 1/2                           |  | Mortar<br>Red brick<br>Brown brick<br>Mortar | HG-AS4<br>HG-AS5<br>HG-AS1<br>HG-AS2           |
| <b>Ceiling</b><br>Roof  | Black shingles w tar   |  | Shingle<br>Sealant                           | HG-AS9<br>HG-AS8                               |
| <b>Paint</b><br>(and substrate)   | Walls:<br>Ceiling:<br>Floor:<br>Other: Caulking white  |  |  | HG-AS3   |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Red caulking<br>around former<br>Chimney<br>Fire Door Manufacturer:<br>Fire Door Serial #:   |  | Red caulking                                 | HG-AS10  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | Black tar paper<br>Black press board<br>Black tar paper (-in)                                |  |  | HG-AS11<br>HG-AS12<br>HG-AS13                  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:   | Leaking / Other  | # Total:<br><br># Checked:                   | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 1  |  |  |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |  |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 |  |  |  |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>Bat feces   |  |  |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext   |  |  |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |  |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description        | Dimensions                 |
|----------|--------|---------|-------------------------|----------------------------|
| HG       |        |         | Out house<br>(interior) | L = 5'<br>W = 6'<br>H = 7' |

|   | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|---|--|----------------------------|--|
| <b>Floor</b>  | Concrete  |  |                            |  |
| <b>Walls</b><br>(include window caulking)   | Wood  |  |                            |  |
| <b>Ceiling</b>  | Wood  |  |                            |  |
| <b>Paint</b><br>(and substrate)   | Walls:<br>Ceiling: Grey<br>Floor:<br>Other:   |  |                            | HG-PP-PS 1                                     |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Pink fiberglass no back'ng<br>Fire Door Manufacturer:<br>Fire Door Serial #:                      |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —   |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>—   | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 1 incandescent  |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                       | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —   |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>—  |  |                            |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—   |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br>— |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description        | Dimensions                 |
|----------|--------|---------|-------------------------|----------------------------|
| HG       |        |         | Out-house<br>(Exterior) | L = 6'<br>W = 5'<br>H = 7' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|--|--|----------------------------|--|
| <b>Floor</b>  | Concrete   |  |                            | HG-PF-AS1                                      |
| <b>Walls</b><br>(include window<br>caulking)  | Wood   |  |                            |  |
| <b>Ceiling</b>  | Shingles   |  |                            | HG-PF-AS2                                      |
| <b>Paint</b><br>(and substrate)   | Walls:<br>Ceiling:<br>Floor:<br>Other:<br>Grey   |  |                            |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:   |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  |  |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:   | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   |  |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 |  |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted  |  |                            |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext   |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

## TABLE OF CONTENTS

|         |  |      |
|---------|--|------|
| 6.0     | CAMP 100 .....   | 6-1  |
| 6.1     | BUILDING DESCRIPTION .....   | 6-1  |
| 6.2     | ROOM DESIGNATION .....   | 6-2  |
| 6.3     | FINDINGS .....   | 6-3  |
| 6.3.1   | Asbestos-Containing Materials (ACMs) .....                         | 6-3  |
| 6.3.1.1 | Friable Materials .....  | 6-3  |
| 6.3.1.2 | Non-Friable and Potentially Friable Materials .....                | 6-4  |
| 6.3.2   | Paint Additives .....  | 6-5  |
| 6.3.2.1 | Lead in Paint .....  | 6-6  |
| 6.3.2.2 | Mercury in Paint .....   | 6-6  |
| 6.3.2.3 | PCBs in Paint .....  | 6-6  |
| 6.3.3   | Urea Formaldehyde Foam Insulation (UFFI) .....                     | 6-6  |
| 6.3.4   | Suspected Visible Mould Growth (SVG) .....                         | 6-7  |
| 6.3.5   | Mercury-Containing Thermostats .....                               | 6-7  |
| 6.3.6   | PCB-Containing Light Ballasts .....                                | 6-7  |
| 6.3.7   | Potential Sources of ODS and Halocarbons .....                     | 6-7  |
| 6.3.8   | Other Potentially Hazardous Building Materials or Substances ..... | 6-7  |
| 6.3.8.1 | Lead-Containing Materials and Equipment .....                      | 6-7  |
| 6.3.8.2 | Mercury-Containing Materials and Equipment .....                   | 6-8  |
| 6.3.8.3 | PCB-Containing Materials and Equipment .....                       | 6-8  |
| 6.3.8.4 | Treated Wood Chemicals .....                                       | 6-8  |
| 6.3.8.5 | Silica .....   | 6-8  |
| 6.3.8.6 | Radioactive Materials .....  | 6-8  |
| 6.4     | CONCLUSIONS AND RECOMMENDATIONS .....                              | 6-9  |
| 6.4.1   | ACMs .....   | 6-9  |
| 6.4.2   | Lead, Mercury and PCBs in Paint .....                              | 6-10 |
| 6.4.3   | Potential UFFI .....   | 6-12 |
| 6.4.4   | Mould .....  | 6-12 |
| 6.4.5   | Potential ODS .....  | 6-13 |
| 6.4.6   | Potential Lead-Containing Materials/Equipment .....                | 6-13 |
| 6.4.7   | Potential Mercury-Containing Materials/Equipment .....             | 6-13 |
| 6.4.8   | Potential PCB-Containing Materials/Equipment .....                 | 6-13 |
| 6.4.9   | Silica Containing Materials .....                                  | 6-14 |
| 6.4.10  | Potential Radioactive Materials .....                              | 6-14 |
| 6.4.11  | Summary of Findings .....  | 6-14 |

## APPENDICES

|             |                                      |
|-------------|--------------------------------------|
| APPENDIX A6 | Figures                              |
| APPENDIX B6 | Photographic Record                  |
| APPENDIX C6 | Sample and Analytical Summary Tables |
| APPENDIX D6 | Room-By-Room Inspection Sheets       |



## 6.0 CAMP 100

Camp 100 is located approximately 37 km east of the Town of Milltown-Head of Bay d’Espoir, NL, and is accessed via gravel access road from the Bay d’Espoir Highway (Route 360) (refer to Figure 6.1, Appendix A6). Camp 100 is comprised of an accommodations cabin and an outhouse.

At the time of the Pre-Demolition HBMA site visit, a thorough assessment of the interior of the accommodations cabin was not possible due to unsafe conditions, as parts of the foundation and walls of the structure had previously collapsed (refer to Photo 2, 3 and 9, Appendix B2). As a result, there is limited information available concerning the presence/absence of hazardous building materials and equipment present within the cabin. Observations were recorded from the doorway and open wall cavities of the cabin, where possible. Please refer to hazardous building materials observed at other Former Construction Camp Sites assess along the former Bay d’Espoir – Avalon Transmission Line.

### 6.1 BUILDING DESCRIPTION

The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 70 m<sup>2</sup>. The floor plan of the cabin consists of one large room and two smaller rooms (refer to Figure 6.2, Appendix A6). The foundation of the accommodations cabin consists of concrete block footings. The structure of the accommodations cabin consists of brick. The exterior walls on the accommodations cabin are finished with brick and the roof is finished with asphalt shingles. The window and exterior door openings on the accommodations cabin are barricaded with metal covers for security purposes (refer to Photos 1 to 4, Appendix B6). Interior wall and ceiling finishes in the accommodations cabin consists of painted plywood. Floors/floor finishes consist of plywood. Fluorescent lighting was observed on the interior of the cabin. The interior area was observed from the building doorway/openings only. There were building upgrades completed at the site, reportedly in the mid 1990’s. The new areas are brown brick and the original areas are red brick. At the time of the sit visit, it was observed that parts of the foundation and walls were dilapidated.

The outhouse is a one-storey, rectangular structure with a footprint area of approximately 3 m<sup>2</sup>. The foundation and structure of the outhouse consists of wood framing and concrete. The exterior walls on the outhouse are finished with plywood and the roof is finished with asphalt shingles (refer to Photos 10 to 12, Appendix B6). Interior wall and ceiling finishes in the outhouse consist of painted plywood. Floor finishes consist of plywood. The outhouse does not contain any lighting or heating.

A description of accommodations cabin is outlined in Table 6-1 and a description of the outhouse is outlined in Table 6-2. Photographs of the buildings are provided in Appendix B6.

**Table 6-1: Site Building Description – Accommodations Cabin**

| Building Name        | Accommodations cabin                   | Photo No. (Appendix B6) |
|----------------------|--|-------------------------|
| Date of Construction | Approximately late 1960’s/early 1970’s | -                       |
| Date of Renovations  | Unknown                                | -                       |
| No. of Stories       | One                                    | 1 to 5                  |
| Crawl Space (Yes/No) | No                                     | -                       |
| Attic (Yes/No)       | Yes                                    | -                       |
| Type of Structure    | Wood Frame and bricks                  | 1 to 5                  |
| Type of Foundation   | Wood Frame and concrete block footing  | 5                       |

**Table 6-1: Site Building Description – Accommodations Cabin**

| Building Name             | Accommodations cabin   | Photo No. (Appendix B6) |
|---------------------------|------------------------|-------------------------|
| Exterior                  | Red and Brown brick    | 1 to 5                  |
| Window/Door Frames        | Painted Metal and Wood | 1, 2 and 5              |
| Exterior Doors            | Painted Metal          | 1, 2 and 5              |
| Roofing Materials         | Asphalt Shingles       | 1                       |
| Interior Walls Finishes   | Painted Plywood        | 6 to 8                  |
| Interior Ceiling Finishes | Plywood                | 6 and 7                 |
| Floor Finishes            | Plywood                | 6 and 7                 |
| Interior Doors            | NA                     | -                       |
| Interior Lighting         | Fluorescent            | 6 and 7                 |
| Exterior Lighting         | Incandescent           | 1 and 2                 |
| Heating                   | NA                     | -                       |

**Table 6-2: Site Building Description – Outhouse**

| Building Name             | Outhouse                               | Photo No. (Appendix B6) |
|---------------------------|--|-------------------------|
| Date of Construction      | Approximately late 1960's/early 1970's | -                       |
| Date of Renovations       | Unknown                                | -                       |
| No. of Stories            | One                                    | 10 to 12                |
| Crawl Space (Yes/No)      | No                                     | -                       |
| Attic (Yes/No)            | No                                     | -                       |
| Type of Structure         | Plywood                                | 10 to 12                |
| Type of Foundation        | Concrete and Wood Frame                | -                       |
| Exterior                  | Plywood                                | 11                      |
| Window/Door Frames        | NA                                     | -                       |
| Exterior Doors            | NA                                     | -                       |
| Roofing Materials         | Asphalt Shingles                       | 19                      |
| Interior Walls Finishes   | Painted Plywood                        | 12                      |
| Interior Ceiling Finishes | Painted Plywood                        | -                       |
| Floor Finishes            | NA                                     | -                       |
| Interior Doors            | NA                                     | -                       |
| Interior Lighting         | NA                                     | -                       |
| Exterior Lighting         | NA                                     | -                       |
| Heating                   | NA                                     | -                       |

## 6.2 ROOM DESIGNATION

Each room at Camp 100 was assigned a specific room name. The designated room names are presented in Table 2-2 and graphically illustrated on the sample location plan (refer to Figure 6.2, Appendix A6).

**Table 6-3: Assigned Rooms**

| Level No. | Room Name – Accommodations Cabin | Room Number |
|-----------|----------------------------------|-------------|
| 1         | Kitchen/Bunk Area                | Room 1      |
| 1         | Pantry                           | Room 2      |
| 1         | Other - Collapsed                | Room 3      |
| 1         | Outhouse                         | Outhouse    |

## 6.3 FINDINGS

The findings documented in this section are based on observations made by Wood personnel at the time of the site visit on August 8, 2018 and the results of laboratory analyses of samples collected from Camp 100. During the Pre-Demolition HBMA site visit, Wood personnel were accompanied by a representative of Hydro (Mr. Wayne Lidster). Copies of room-by-room inspection sheets for the accommodations building and outhouse are provided in Appendix D6. Photos of the samples collected from the accommodations building and outhouse during the site visits are provided in Appendix B6.

### 6.3.1 Asbestos-Containing Materials (ACMs)

There are over 3,000 ACMs that are commercially available, which can be divided into two broad categories: friable and non-friable. ACMs were discontinued from use in Canada in the late 1970s/early 1980s, although non-friable asbestos is still found in many more recent buildings.

During the Pre-Demolition HBMA site visit, a total of six (6) building material samples (C100-AS-1 to C100-AS-6) were collected from the accommodations cabin and two (2) building material samples (C100-PP-AS1 and C100-PP-AS2) were collected from the outhouse (refer to Photos 13 to 20, Appendix B6) and analyzed for asbestos content. Bulk sample descriptions and asbestos analytical results are summarized in Table C6-1, Appendix C6. Sample locations and analytical results are graphically illustrated on Figure 6.2, Appendix A6.

Due to the level of dilapidation at the accommodations cabin, it was unsafe to enter the building to obtain any additional asbestos samples (refer to Photo 2, 3 and 9, Appendix B2).

#### 6.3.1.1 Friable Materials

Friable ACMs are defined as materials that can be crumbled, pulverized and reduced to powder when dry using hand pressure. Typical friable materials include acoustical or decorative spray applications, fireproofing and thermal insulation.

##### 6.3.1.1.1 *Spray-Applied Fireproofing, Insulation and Texture Finishes*

There were no spray-applied fireproofing, insulation or texture finishes observed in the accommodations cabin or outhouse during the Pre-Demolition HBMA site visit; therefore, no samples of these materials were collected for analysis.

##### 6.3.1.1.2 *Building and Thermal System Insulation*

During the Pre-Demolition HBMA site visit, fiberglass insulation was observed between the particle board and plywood in the walls of the accommodations cabin. Due to the level of dilapidation around the sides of the cabin, the technician kept a safe distance away to ensure personal safety, and therefore no insulation samples could be collected.

### **6.3.1.2 Non-Friable and Potentially Friable Materials**

Non-friable ACMs are hard or manufactured products such as floor tiles, fire blankets, pre-formed manufactured cementitious insulation and wallboards, pipes, and siding, wherein the asbestos fibres are bound to the substrate. Note that although a product may be considered non-friable when new, the product may release fine dust when disturbed (e.g., deterioration, removal, renovations) and the free dust is considered friable.

#### **6.3.1.2.1 Ceiling Tile**

There were no ceiling tiles observed at Camp 100 during the Pre-Demolition HBMA site visit; therefore, no samples of ceiling tile were collected for analysis.

#### **6.3.1.2.2 Drywall Joint Compound**

There was no drywall joint compound observed at Camp 100 during the Pre-Demolition HBMA site visit; therefore, no samples of drywall joint compound were collected for analysis.

#### **6.3.1.2.3 Vinyl Flooring Products and Mastics**

There was no vinyl flooring or products observed at Camp 100 during the Pre-Demolition HBMA site visit; therefore, no samples of vinyl flooring or products were collected for analysis.

#### **6.3.1.2.4 Baseboard, Carpet and Stair Tread Adhesives/Mastics**

There were no baseboard, carpet or stair tread adhesives/mastics observed at Camp 100 during the Pre-Demolition HBMA site visit; therefore, no samples of these types of adhesives/mastics were collected for analysis.

#### **6.3.1.2.5 Roofing Products**

During the Pre-Demolition HBMA site visit, one (1) sample of black felt and tar (C100-PP-AS1) was collected from the roof of the outhouse and analyzed for asbestos content (refer to Photo 19, Appendix B6). Asbestos was detected in C100-PP-AS1 containing 1.1 % chrysotile asbestos. According to the NL asbestos abatement regulations (Reg. 111/98), this material is considered asbestos-containing materials.

It is important to note, due to height and safety constraints, no samples of shingles or tar, building materials around roof penetrations (e.g., caulking or sealants around vents or electrical conduit) or roof seams were collected from the accommodations cabin for analysis. Given that asbestos was detected in the roofing materials on the outhouse, it can be assumed that the roof materials contains asbestos; alternatively, samples can be collected during demolition of the cabin to assess handling and disposal options for the roofing materials.

#### **6.3.1.2.6 Caulking/Sealant**

During the Pre-Demolition HBMA site visit, one (1) sample of black tar sealant (C100-AS-5) was collected from a vent on the accommodations cabin (currently located on the ground adjacent to the cabin) and

analyzed for asbestos content (refer to Photo 17, Appendix B6). Asbestos was detected in C100-AS-5 containing 21.2 % chrysotile asbestos According to the NL asbestos abatement regulations (Reg. 111/98), this material is considered an asbestos-containing material.

#### **6.3.1.2.7 Mortar, Grout and Other Cementitious Materials**

During the Pre-Demolition HBMA site visit, one (1) sample of grey mortar on brown brick (C100-AS-1), one (1) sample of brown brick (C100-AS-2), one (1) sample of grey mortar on red brick (C100-AS-3) and one (1) sample of red brick (C100-AS-4) were collected from the accommodations cabin and analyzed for asbestos content (refer to Photos 13 to 16, Appendix B6). Asbestos was not detected in the brick and/or mortar samples analyzed.

Additionally, (1) sample of concrete (C100-PP-AS2) was collected from the outhouse and analyzed for asbestos content (refer to Photo 20, Appendix B6). Asbestos was not detected in the concrete sample analyzed.

#### **6.3.1.2.8 Fire-Rated Doors**

Fire-rated doors and door frames were not observed during the Pre-Demolition HBMA site visit.

#### **6.3.1.2.9 Other Potential ACMs**

During the Pre-Demolition HBMA site visit, one (1) sample of black pressed board (C100-AS-6) from the accommodations cabin and analyzed for asbestos content (refer to Photo 18, Appendix B6). Asbestos was not detected in the pressed board sample collected.

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to, electrical and mechanical components and insulators such as wiring and gaskets, heat shields inside incandescent/fluorescent light fixtures, and caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations (refer to Photos 1, 6, 7 and 8, Appendix B6).

Other possible hidden and inaccessible ACMs have the potential to be present within the accommodations cabin but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include concrete leveling compound (existing concrete foundation), possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components or gaskets inside appliances, concrete lining the interior of hot water tanks, and underground infrastructure or piping.

### **6.3.2 Paint Additives**

Lead compounds have been used in paint as pigment and durability additives since the early 1800s. Mercury compounds have been used in paint as anti-microbial additives up until the 1990s. PCBs have been used in paint as plasticizers and corrosion resistance additives from the 1950s to the 1970s.

During the Pre-Demolition HBMA site visit, two (2) samples (C100-PS1 to C100-PS2) were collected from the painted surfaces of the accommodations cabin and two (2) samples (C100-PP-PS1 to C100-PP-PS2) were collected from painted surfaces of the outhouse and analyzed for lead, mercury and PCB content (refer to Photos 17 to 20, Appendix B6). Paint sample descriptions and lead, mercury and PCBs analytical results are summarized in Tables C6-2 to C6-4, Appendix C6. Sample locations and analytical results are graphically illustrated on Figure 6.2, Appendix A6.

Even though it was unsafe to enter the accommodations cabin, only white and grey painted surfaces were observed from the exterior opening of the cabin. The Wood field technician was able to collect representative paint samples of these materials from the exterior doorway and from fallen cabin debris material (outside of the cabin).

### **6.3.2.1 Lead in Paint**

Concentrations of lead in the two (2) samples (C100-PS1 to C100-PS2) collected from painted surfaces of the accommodations cabin and two (2) samples (C100-PP-PS1 to C100-PP-PS2) collected from the painted surfaces of the outhouse ranged from non-detect (<15 mg/kg) to 489 mg/kg (refer to Table C6-2, Appendix C6). Two (2) paint samples (C100-PS1 and C100-PP-PS1) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg (refer to Photos 17 and 19 Appendix B6). The concentrations of lead in the other two (2) samples were below the Federal HPA criterion (90 mg/kg).

### **6.3.2.2 Mercury in Paint**

Concentrations of mercury in the two (2) samples (C100-PS1 to C100-PS2) collected from painted surfaces of the accommodations cabin and two (2) samples (C100-PP-PS1 to C100-PP-PS2) collected from the outhouse ranged from 0.21 mg/kg to 3.83 mg/kg, and therefore, the concentrations of mercury in these samples were below the Federal HPA criterion (10 mg/kg) (refer to Table C6-3, Appendix C6).

### **6.3.2.3 PCBs in Paint**

PCBs were not detected (<0.5 mg/kg) in the paint samples collected, and therefore, below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg) (refer to Table C6-4, Appendix C6).

## **6.3.3 Urea Formaldehyde Foam Insulation (UFFI)**

Visual indicators suggesting the potential presence of UFFI were not observed at Camp 100. The nature of the insulation in the walls and ceilings throughout the accommodations cabin consisted of fiberglass insulation.

Since the original date of construction of Camp 100 (assumed construction commenced the same timeframe as the original transmission line, late 1960's/early 1970's) is unknown, it is possible that UFFI may be present.

In the event that UFFI is present, the CMHC state that "tests show that UFFI is not a source of over-exposure to formaldehyde after the initial curing and release of excess gas". The general view based on

studies concerning formaldehyde emissions is that as a product ages, the amount of formaldehyde off-gassed from the product decreases over time. The amount of formaldehyde released is reportedly dependent on temperature, humidity and whether or not the product is exposed to excessive moisture or water.

#### **6.3.4 Suspected Visible Mould Growth (SVG)**

Wood inspected the interior areas of the accommodations cabin and outhouse for visual or olfactory evidence of suspected mould. SVG was noted on much of the ceiling and wall surfaces inside the accommodations cabin during the Pre-Demolition HBMA site visit. Due to the level of dilapidation at the accommodations cabin, it was unsafe to enter the building to obtain a sample (refer to Photo 8, Appendix B2).

#### **6.3.5 Mercury-Containing Thermostats**

Thermostats were not identified inside the accommodations cabin at Camp 100 during the Pre-Demolition HBMA site visit, as observed from the exterior of the cabin. Based on inspections of other similar cabins along the transmission line, it is unlikely that there are any thermostats present.

#### **6.3.6 PCB-Containing Light Ballasts**

Fluorescent light fixtures were observed on the interior of the accommodations cabin and incandescent light fixtures were observed on the exterior of the accommodations cabin, as observed from the exterior of the cabin, during the Pre-Demolition HBMA site visit (refer to Photos 1, 6 and 7, Appendix B6).

#### **6.3.7 Potential Sources of ODS and Halocarbons**

Wood were no able to assess whether or not there were potential sources of ODS within accommodations cabin, as observed from the exterior of the cabin, during the Pre-Demolition HBMA site visit; however, a chest freezer was identified inside the pantry (Room 2) (refer to Photo 8, Appendix B6). The refrigerant contained within the freezer may contain ODS and should be checked to determine disposal options during demolition.

#### **6.3.8 Other Potentially Hazardous Building Materials or Substances**

Other potentially hazardous building materials or substances identified during this assessment are presented in the following sections.

##### **6.3.8.1 Lead-Containing Materials and Equipment**

Lead is typically associated with plumbing solder and older pipe materials (e.g., cast iron pipe joints), as well as products such as radiation protective shielding and lead-acid batteries. Lead can also be present in steel and iron primer, industrial electrical jacketing, roof flashing and tank linings.

Since the actual date that Camp 100 was constructed is unknown (assumed to be late 1960's/early 1970's), it is possible that lead solder is present in plumbing and piping (i.e., cast iron and copper piping) in the

accommodations cabin (if present), as lead solder for use in potable water distribution pipes was not banned until the late 1980s (refer to Photo 7, Appendix B6).

### **6.3.8.2 Mercury-Containing Materials and Equipment**

The light tubes and bulbs in HID and fluorescent light fixtures often contain limited quantities of mercury in a powder or vapour form. Both incandescent light fixtures and florescent light fixtures were observed on the exterior and the interior of the accommodations cabin during the Pre-Demolition HBMA site visit (Photos 1, 6 and 7, Appendix B6).

### **6.3.8.3 PCB-Containing Materials and Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, and as mentioned previously, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

### **6.3.8.4 Treated Wood Chemicals**

The chemicals that are used to protect and preserve wood products from insect attack and fungal decay may pose risks to human health and the environment. Depending on the wood treatment used, treated wood may be considered a hazardous waste upon disposal. The NL Department of Environment and Conservation (currently the NL MAE), 2015 Guidance Document for Treated Wood Waste Disposal (GD-PPD-075.1) provides landfill disposal standards for “pressure treated” inorganic preservatives (i.e., arsenic and chromium) and creosote (i.e., total cresol and benzo(a)pyrene) and chlorophenolic (i.e., pentachlorophenol) formulations used to preserve wood. These landfill disposal standards for treated wood waste (TWW) are used to assess the results of leachability testing to determine disposal options for treated wood to be removed during renovation or demolition activities.

Treated wood was not identified during the Pre-Demolition HBMA site visit.

### **6.3.8.5 Silica**

According to the CPWR – The Center for Construction Research and Training, many common construction materials contain silica including, asphalt, brick, cement, concrete, drywall, grout, mortar, stone, sand and tile. The dust created by cutting, grinding, drilling or otherwise disturbing these materials can contain crystalline silica particles.

Based on the Pre-Demolition HBMA site visit, silica is expected to be present in the exterior bricks and concrete blocks used in the construction of the foundation for the accommodations cabin. Silica may also be present in the asphalt shingles used in the construction of the accommodations cabin.

### **6.3.8.6 Radioactive Materials**

Smoke detectors were not observed during the Pre-Demolition HBMA site visit; however, observation of the interior of the accommodations cabin was limited to the doorway and open wall cavities so it is possible that smoke detectors are present. Smoke detectors observed may contain very small amounts of



radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called "ion chamber smoke alarms".

## **6.4 CONCLUSIONS AND RECOMMENDATIONS**

Based on observations made and information gathered during the Pre-Demolition HBMA, the following conclusions and recommendations are made with respect to the potential and actual presence of hazardous building materials at Camp 100.

### **6.4.1 ACMs**

Results of the asbestos sampling and analytical program revealed building materials containing greater than 1% asbestos by dry weight, which are considered to be ACMs, are present in the form of non-friable black tar sealant on the vents of the accommodations cabin and non-friable black felt and tar on the roof of the outhouse. Given that asbestos was detected in the roofing materials on the outhouse, it can be assumed that the roof materials contains asbestos; alternatively, samples can be collected during demolition of the cabin to assess handling and disposal options for the roofing materials. In addition, if there is any black tar sealant present around the windows and/or doorways of the cabin when removed, it should be sampled for asbestos or treated as a ACM.

The asbestos-containing black tar sealant visible around the vent present on the ground adjacent to the accommodations cabin (limited quantity); not that there are additional vents present. The asbestos-containing black felt and tar visible on the on the roof of the outhouse (covering an area of approximately 3 m<sup>2</sup>) appeared to be fair to poor condition.

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to:

- Insulation materials present within the wall cavities and attic of the accommodations cabin (unsafe access for sampling during current HBMA site visit). Note that asbestos was not detected in insulation samples collected from other cabin along the transmission line.
- Electrical and mechanical components and insulators such as wiring and gaskets.
- Heat shields inside incandescent/ fluorescent light fixtures.
- Caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations.

Other possible hidden and inaccessible ACMs have the potential to be present within the buildings at Camp 100 but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include concrete leveling compound (existing concrete foundation), possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components, concrete lining the interior of hot water tanks, and underground infrastructure or piping.

If other potential ACMs that were not sampled as part of this assessment are encountered in the future, these materials should be treated as ACMs or samples should be collected and tested to verify asbestos

content. This should be done as soon as these materials are encountered and before these materials are disturbed. This includes materials that are currently concealed by walls and ceiling systems.

In accordance with the NL Asbestos Abatement Regulations (Reg. 111/98), which provide the legislative requirements for safe handling of ACMs in workplaces in the Province of NL, the following is recommended:

- Safe work procedures shall be established.
- All buildings constructed during the period when asbestos was readily used in construction (generally prior to the early 1980s) or any buildings that are suspected as having asbestos must have a written assessment and management plan (where applicable) for potential ACMs.
- Materials suspected of containing asbestos are required to be handled as ACMs, until analysis by a competent laboratory determines whether or not it does contain asbestos.
- Prior to general demolition, all ACMs must be safely removed from the building and disposed of in accordance with appropriate environmental guidelines by an asbestos abatement contractor registered with the Occupational Health and Safety (OHS) Division of Service NL.
- Most work involving ACMs (i.e., disturbance, removal and encapsulation) must be conducted by a contractor registered with the OHS Division of Service NL.
- ACMs in good condition should be inspected on an annual basis.
- ACMs in poor condition should be removed from the building and transported off-site for proper disposal.
- Workers should don adequate respiratory protection and personal protective equipment (PPE) when working with ACMs.

Prior to the removal and/or abatement of any identified ACMs (or any other hazardous building materials), an abatement plan including technical specifications should be designed, prepared and supervised by a qualified professional and should be undertaken by qualified trades, in accordance with applicable standards. Activities involving the disturbance and/or removal of ACMs should be carried out in a manner that ensures asbestos fiber concentrations do not exceed the applicable American Conference of Governmental Industrial Hygienists (ACGIH) threshold limit value (TLV). ACMs can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.

#### **6.4.2 Lead, Mercury and PCBs in Paint**

Results of the paint sampling and analytical program revealed the following:

- **Lead and Leachable Lead in Paint**
  - Concentrations of lead in the two (2) samples (C100-PS1 to C100-PS2) collected from painted surfaces of the accommodations cabin and two (2) samples (C100-PP-PS1 to C100-PP-PS2) collected from the outhouse ranged from non-detect (<15 mg/kg) to 489 mg/kg.
  - Two (2) paint samples (C100-PS1 and C100-PP-PS1) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg and are not likely to be leachable for lead.
  - The concentrations of lead in the other two (2) samples were below the Federal HPA criterion (90 mg/kg); therefore, these paints are not considered to be LBPs and are not likely to be leachable

for lead.

- **Mercury and Leachable Mercury in Paint**

- Concentrations of mercury in the two (2) samples (C100-PS1 to C100-PS2) collected from painted surfaces of the accommodations cabin and two (2) samples (C100-PP-PS1 to C100-PP-PS2) collected from the outhouse ranged from non-detect (<0.05 mg/kg) to 3.83 mg/kg; below the Federal HPA criterion (10 mg/kg). These paints are not considered to be MBPs and are not likely to be leachable for mercury.

- **PCBs in Paint**

- PCBs were not detected (<0.5 mg/kg) in the two (2) samples (C100-PS1 to C100-PS2) collected from painted surfaces of the accommodations cabin and two (2) samples (C100-PP-PS1 to C100-PP-PS2) from the painted surfaces of the outhouse, and therefore, below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg).

Even though, it was unsafe to enter the accommodations cabin, only white and grey painted surfaces were observed from the exterior openings and the Wood field technician was able to collect representative paint samples from these material from the doorway and from cabin debris material at the site.

Based on the paint sample analytical results, the other paint samples collected from accommodations cabin and outhouse are not likely to be leachable for lead, mercury or PCBs, and therefore, should disposal be required (e.g., renovation or demolition activities), the paints analyzed for lead and mercury content may be disposed of at an approved landfill facility, pending landfill and Provincial regulatory approval.

There are potential adverse human health impacts associated with disturbing (e.g., scraping, sanding, burning, etc.) lead, mercury or lead-containing paint finishes, due to the potential for dust, mist or fumes to be released and inhaled or ingested by workers. Given the lead-based paints were identified at the site, as a precautionary measure, Wood recommends handling these paint finishes, as follows:

- In areas of minor peeling or flaking, the paint should be removed using wet scraping techniques.
- In areas of extensive peeling and flaking, the paint should be removed and more extensive particulate control measures may be required.
- In areas where lead-containing paint finishes are present and in poor condition, an experienced contractor should be utilized for renovating, decommissioning or demolition activities.
- Prior to renovation, dismantling or demolition activities, all areas of extensive peeling and flaking of lead-containing paint finishes and paint debris/dust should be removed and/or remediated to ensure that building occupants/workers are protected from associated dust/particulate.
- Procedures should be implemented to ensure that workers and anyone present in and around areas being renovated, dismantled or demolished are protected. The contractor should also ensure that dust generation and migration is minimized.
- Precautions should be taken to prevent/reduce exposure to paint dust during any disturbance of lead-containing paint finishes, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas.
- Where possible, lead-containing paint finishes should be removed from metal surfaces prior to welding

or cutting these materials.

If potential lead, mercury or PCB-containing paint finishes that were not sampled during this assessment are encountered in future, prior to any disturbance or removal, samples should be obtained and tested to verify concentrations of lead, mercury and PCBs. This includes materials that are currently concealed by walls and ceiling systems.

Any disturbance or removal of lead, mercury or PCB-containing paint finishes that may generate dust or respirable aerosols must conform to the Federal and Provincial OHS Regulations. All work should be carried out by individuals wearing proper PPE. The type of respiratory protection and control measures to be implemented during the removal of these types of paint finishes should be determined by a qualified person and based on the risk level of a particular work activity (i.e., scraping, sanding, abrasive blasting, etc.). Activities involving the disturbance and/or removal of lead, mercury or PCB-containing paint finishes should be carried out in a manner that ensures paint dust concentrations do not exceed the applicable ACGIH TLVs.

### **6.4.3 Potential UFFI**

The sale and installation of UFFI was banned in 1980; since the original date of construction is unknown, it is possible that UFFI may be present in the building. Visual indicators suggesting the potential presence of UFFI were not observed in the building, as only fiberglass insulation was observed. It can be inferred that any UFFI present within the building is unlikely to affect the indoor air quality due to the amount of time that has passed since the insulation was likely installed (i.e., pre-1980) along with the likelihood that formaldehyde has off-gassed over this period of time. It should be noted that, the presence and concentration of formaldehyde cannot be determined or quantified without conducting site-specific testing for formaldehyde.

Although there is currently no Provincial regulations requiring that the removal of UFFI be conducted by a licensed/registered abatement contractor, based on discussions with representatives of the OHS Division of Service NL, it is strongly recommended that this material be abated using similar methods as required for asbestos abatement and that the insulation must be removed in a dry condition. Based on discussions with representatives of the NL MAE, for the purposes of disposal of UFFI, this material is permitted to be bagged and transported to an approved WDS and disposed in the special waste area (unlined area) of the site.

### **6.4.4 Mould**

Wood inspected the interior areas of the accommodations cabin and outhouse for visual or olfactory evidence of suspected mould. SVG was noted the ceiling and wall surfaces inside the accommodations cabin during the Pre-Demolition HBMA site visit. Due to the level of dilapidation at the accommodations cabin, it was unsafe to enter the building to obtain a sample.

Mould spores are present in all indoor environments and cannot be completely eliminated. Cellulose based building materials provide a nutrient base for many mould species; however, mould cannot grow unless an adequate amount of excess moisture is present. The most effective way to prevent mould growth within a building is the prompt removal of any porous building materials with water damage or mould growth, and repairing the building components that lead to the water infiltration.

#### **6.4.5 Potential ODS**

Ozone depleting substances (ODS), if present, should be removed by an approved contractor prior to disposing of any cooling and/or refrigeration equipment from the building. The use, storage, operation, maintenance, decommissioning, and disposal of ODS containing equipment, in general, is regulated at both a Provincial and Federal level and must comply with the most recent NL Halocarbon Regulations and the Federal Halocarbon Regulations. The status of the potential ODS containing equipment should be confirmed through a mechanical contractor or consultant.

#### **6.4.6 Potential Lead-Containing Materials/Equipment**

Lead solder is likely to be present in plumbing and piping (e.g., cast iron and copper piping) within the accommodations cabin.

The disturbance, control or disposal of lead-containing material/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of lead in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a metal recycling facility and not a landfill. Removal of lead-containing batteries should be completed in a manner that ensures structural integrity and no loss of fluid from the batteries. Should disposal be required, disposal of lead-containing batteries should be completed in accordance with hazardous waste procedures/guidelines (i.e., at an approved facility).

#### **6.4.7 Potential Mercury-Containing Materials/Equipment**

Should disposal may be required, mercury-containing equipment should be removed intact and returned to the manufacturer for recycling or disposed of at an approved hazardous waste disposal facility. The disturbance, control or disposal of mercury-containing materials/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of mercury in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a recycling or hazardous waste disposal facility and not a landfill.

#### **6.4.8 Potential PCB-Containing Materials/Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

If PCB-containing materials or equipment are encountered in the future, and should disposal be required, the PCB content in the materials or equipment should be confirmed prior to disposal. Florescent light fixtures are present within the accommodations cabin. Any leaking light ballasts identified, whether PCB containing or not, should be removed and replaced to avoid potential concerns with electrical equipment in the future. All ballasts that are removed should be placed in a proper storage container(s). Leaks or stained areas should be cleaned and/or removed in accordance with applicable regulations or industry standards.

Any PCB-containing equipment (if present) should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations. Any PCB-containing equipment requiring removal from the building should be transported and disposed of at an approved hazardous waste disposal site, and not a landfill disposal site, by a registered hazardous waste transporter in accordance with applicable regulations.

#### **6.4.9 Silica Containing Materials**

Silica is expected to be present in exterior bricks and concrete used in the construction of the foundation for the accommodations cabin. Silica may also be present in asphalt shingles used in the construction of accommodations cabin. Precautions should be taken to prevent/reduce exposure to silica dust during any disturbance/ demolition of silica-containing products, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas. Activities involving the disturbance and/or demolition of silica-containing materials should be carried out in a manner that ensures silica dust concentrations do not exceed the applicable ACGIH TLV.

#### **6.4.10 Potential Radioactive Materials**

Smoke detectors were not observed during the Pre-Demolition HBMA site visit; however, observation of the interior of the accommodations cabin was limited to the doorway and open wall cavities, so it is possible that smoke detectors are present. Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called "ion chamber smoke alarms".

#### **6.4.11 Summary of Findings**

Hazardous building materials identified at Camp 100 during this Pre-Demolition HBMA and disposal options, if required, are summarized in Table 6-5. Conclusions and recommendations made with respect to the potential and actual presence of hazardous building materials within the accommodations cabin and outhouse are provided in Section 6.4 and should be reviewed in conjunction with Table 6-5.

**Table 6-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| Hazardous Material | Applicable Acts, Regulations or Guidance Documents     | Description and Location   | Disposal  |
|--------------------|--|--|---|
| <p><b>ACMs</b></p> | <p>NL Asbestos Abatement Regulations (Reg. 111/98)</p> | <p>Non-friable black tar sealant on the vent on exterior of the cabin (limited quantity). Note that asbestos was detected in the tar on a vent currently on the ground. There are other vents present on the exterior of the cabin. If black tar sealant is present around the windows and/or doorways when removed, it should be sampled for asbestos or treated as a ACM.</p> <p>Black felt and tar on the roof of the outhouse (~3m<sup>2</sup>).</p> <p>Given that asbestos was detected in the roofing materials on the outhouse, it can be assumed that the roof materials of the cabin contains asbestos, or samples can be collected during demolition to assess handling and disposal options for the roofing materials (~65 m<sup>2</sup>).</p> <p>Note that other possible hidden and inaccessible ACMs have the potential to be present within the accommodations cabin but were not identified or could not be sampled during the Pre-Demolition HBMA site visit.</p> | <p>ACMs cannot be disposed of at a Construction &amp; Demolition Site; however, these materials can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.</p> <p>The transportation and disposal of asbestos should be conducted in accordance with the NL Asbestos Abatement Regulations (Reg. 111/98) and with Standard Operating Procedures (SOPs) for disposal of ACMs at the landfill.</p> |

**Table 6-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b> | <b>Applicable Acts, Regulations or Guidance Documents</b>   | <b>Description and Location</b>  | <b>Disposal</b>   |
|---------------------------|---|--|---|
| <b>LBP</b> s              | Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)<br>Federal HPA (R.S.1985, c. H-3)<br>Federal TDG Act (1992, c. 34)<br>Surface Coating Materials Regulations (SOR/2016-193) | LBP (grey) on exterior door trim) of accommodations cabin. Same grey paint is present on floor of the cabin.<br>LBP (grey) on plywood on exterior of outhouse.                             | Paints that were analyzed for lead and contained <5,000 mg/kg lead, may be disposed of at a Regional Solid Waste Disposal Facility (landfill), provided permission is obtained from the landfill owner/operator.  |
| <b>Potential UFFI</b>     | Federal HPA (R.S.1985, c. H-3)  | None identified  | UFFI is permitted to be bagged and transported to an approved WDS and disposed in the special waste area of the site.   |
| <b>Mould</b>              | Mould Guidelines for the Canadian Construction Industry, Canadian Construction Industry (CCI), 2004;<br>Mould Abatement Guidelines, Environmental Abatement Council of Ontario (EACO), 2010       | Possible mould observed on walls and ceiling in the accommodations cabin.<br>It was unsafe to enter the building to obtain a sample.   | All mould impacted materials may be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.  |
| <b>Potential ODS</b>      | Federal Halocarbon Regulations (SOR/2003-289)   | A chest freezer was observed in the accommodations cabin. Wood were no able to access the building to inspect the freezer to determine the type of refrigerant present within the freezer. | Materials containing ODS should be received by a contractor or facility that has the proper approvals to remove, handle and/or dispose of ODS. The remaining materials can be disposed of at a recycling facility, provided permission is obtained from the facility. |



**Table 6-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| Hazardous Material  | Applicable Acts, Regulations or Guidance Documents  | Description and Location   | Disposal   |
|---|---|--|--|
| <p><b>Potential Lead-Containing Materials/ Equipment</b></p>    | <p>Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)<br/>           Federal HPA (R.S.1985, c. H-3)<br/>           Federal TDG Act (1992, c. 34)<br/>           Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301)</p> | <p>Potential lead-containing solder (piping and plumbing).<br/><br/>           Other lead containing materials may also be present.</p>  | <p>Lead-containing materials and equipment can be disposed of at a metal recycling or hazardous waste disposal facility, in accordance with applicable regulations.<br/><br/>           The transportation and disposal of hazardous lead-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility.</p> |
| <p><b>Potential Mercury-Containing Materials/ Equipment</b></p> | <p>Federal HPA (R.S.1985, c. H-3)<br/>           Federal TDG Act (1992, c. 34)<br/>           Products Containing Mercury Regulations (SOR/2014-254)</p>  | <p>Fluorescent light fixtures are present inside accommodations cabin. The light tubes in fluorescent light fixtures often contain limited quantities of mercury in a powder or vapour form.<br/><br/>           Other mercury containing materials may also be present.</p> | <p>Mercury-containing materials and equipment can be disposed of at a recycling or hazardous waste disposal facility, in accordance with applicable regulations.<br/><br/>           The transportation and disposal of hazardous mercury-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility.</p> |

**Table 6-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b>                            | <b>Applicable Acts, Regulations or Guidance Documents</b>  | <b>Description and Location</b>   | <b>Disposal</b>  |
|--|--|---|--|
| <b>Potential PCB-Containing Materials/ Equipment</b> | <p>Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)</p> <p>Federal TDG Act (1992, c. 34)</p> <p>Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)</p> <p>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301)</p> <p>PCB Regulations (SOR/2008-273)</p> <p>PCB Waste Export Regulations (SOR/97-109)</p> <p>Regulations Amending the PCB Regulations (SOR/2010-57)</p> | <p>Fluorescent light fixtures are present inside accommodations cabin. The ballast of the fluorescent light fixtures may contain PCBs.</p> <p>Other PCB containing materials may also be present.</p> | <p>Any PCB-containing materials and equipment should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations.</p> <p>Any PCB-containing materials and equipment requiring removal from the building should be transported and disposed of by a registered hazardous waste transporter in accordance with applicable regulations.</p> <p>The transportation and disposal of PCB containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility.</p> |
| <b>Silica-Containing Materials</b>                   | <p>NL OHS Act (RSNL1990 Chapter O-3)</p> <p>NL OHS Regulations (5/12)</p>  | <p>Asphalt shingles, brick and concrete.</p>  | <p>These materials can be disposed of at a Solid Waste Disposal Facility (landfill).</p>   |
| <b>Potential Radioactive Materials</b>               | <p>Federal TDG Act (1992, c. 34)</p>   | <p>Wood were no able to assess whether or not there were any smoke detectors present within accommodations cabin, due to unsafe access.</p>   | <p>Smoke detectors that contain low level radioactive materials must be transported, as per Federal TDG Regulations, to a licensed disposal facility.</p>  |


**APPENDIX A6**

**FIGURES**



**NOTES:**  
 1. ALL DIMENSIONS ARE IN METERS.  
 2. DO NOT SCALE FROM FIGURE.  
 3. THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.  
 4. ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.  
 5. THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.  
 6. THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



newfoundland labrador  
**hydro**  
 a nalcor energy company

---

**Wood**  
 Environment & Infrastructure Solutions  
 133 Crosbie Road  
 St. John's, NL A1B 4A5  
 709-722-7023



Drawn by:  
T. Rideout

Approved by:  
C. Finney

Scale:  
As Shown

Project:  
Pre-Demolition Hazardous Building Materials Assessment,  
Former Construction Camp Sites,  
Bay d'Espoir - Avalon Transmission Line, NL

---


Title:  
Site Location Plan (Aerial) - Camp 100 Site

Date:  
April 2019

Project No.  
TF18104243.2000

Rev. No.  
0

Figure No.  
6.1




**LEGEND:**

- ASBESTOS SAMPLE LOCATION - ASBESTOS NOT DETECTED
- ASBESTOS SAMPLE LOCATION - RESULTS > 1% FOR ASBESTOS
- ▲ PAINT SAMPLE LOCATION - NO CRITERIA EXCEEDANCES FOR LEAD OR MERCURY OR PCBs WHERE APPLICABLE
- ▲ PAINT SAMPLE LOCATION - RESULTS EXCEED 90 mg/kg AND LESS THAN 5000 mg/kg FOR LEAD AND NO CRITERIA EXCEEDANCES FOR MERCURY OR PCBs WHERE APPLICABLE

**NOTES:**

- ALL DIMENSIONS ARE IN METERS.
- DO NOT SCALE FROM FIGURE.
- THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.
- ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.
- THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.
- THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



newfoundland labrador  
**hydro**  
a nalcor energy company

**Wood**  
Environment & Infrastructure Solutions  
133 Crosbie Road  
St. John's, NL A1B 4A5  
709-722-7023



Drawn by:  
T. Rideout

Approved by:  
C. Finney

Scale:  
As Shown

Project:  
Pre-Demolition Hazardous Building Materials Assessment,  
Former Construction Camp Sites,  
Bay d'Espoir - Avalon Transmission Line, NL

Title:  
Sample Location Plan - Camp 100 Site

Date:  
April 2019

Project No.  
TF18104243.2000

Rev. No.  
0

Figure No.  
6.2

**APPENDIX B6**  
**PHOTOGRAPHIC RECORD**



Photo 1: View of the accommodations cabin at Camp 100, looking northwest.



Photo 2: View of the accommodations cabin at Camp 100, looking north.



Photo 3: View of the accommodations cabin at Camp 100, looking northeast.



Photo 4: View of the accommodations cabin at Camp 100, looking east.



Photo 5: View of the accommodations cabin at Camp 100, looking east.



Photo 6: View of the bunk area of the accommodations cabin at Camp 100.



Photo 7: View of the kitchen area of the accommodations cabin at Camp 100.



Photo 8: View of the pantry area in the accommodations cabin at Camp 100.





Photo 9: View of collapsed room, on eastern corner of the accommodations cabin.



Photo 10: View of outhouse, looking east.



Photo 11: View of the exterior of the outhouse at Camp 100.



Photo 12: View of the interior of the outhouse at Camp 100.



Photo 13: View of bulk material sample C100-AS-1, grey mortar, cabin exterior.



Photo 14: View of bulk material sample C100-AS-2, brown brick, cabin exterior.



Photo 15: View of bulk material sample C100-AS-3, grey mortar, cabin exterior.



Photo 16: View of bulk material sample C100-AS-4, red brick, cabin exterior.



Photo 17: View of bulk material sample C100-AS-5, black tar, cabin exterior.  
**21.2 % Cryotile Asbestos**



Photo 18: View of bulk material sample C100-PP-AS-6, black pressed board, outhouse exterior.



Photo 19: View of bulk material sample C100-PP-AS1, black felt and tar, outhouse exterior. **1.1 % Cryotile Asbestos**



Photo 20: View of bulk material sample C100-PP-AS2, concrete, outhouse exterior.



Photo 17: View of paint sample C100-PS-1, grey, cabin interior.



Photo 18: View of paint sample C100-PS-2, white, cabin interior.



Photo 19: View of location of paint sample C100-PP-1, grey, outhouse exterior.



Photo 20: View of location of paint sample C100-PP-2, white, outhouse interior.

**APPENDIX C6**

**SAMPLE AND ANALYTICAL SUMMARY TABLES**

**Table C6-1: Bulk Sample Descriptions and Asbestos Analytical Results (Camp 100)**

| Sample ID   | Room No. | Room Description | Photo No. | Sample Location | Sample Description           | Layers Analyzed | Analytical Result |
|-------------|----------|------------------|-----------|-----------------|------------------------------|-----------------|-------------------|
| C100-AS-1   | Exterior | Exterior         | 13        | Wall            | Grey mortar (on brown brick) | Mortar          | ND                |
| C100-AS-2   | Exterior | Exterior         | 14        | Wall            | Brown brick                  | Brick           | ND                |
| C100-AS-3   | Exterior | Exterior         | 15        | Wall            | Grey mortar (on red brick)   | Mortar          | ND                |
| C100-AS-4   | Exterior | Exterior         | 16        | Wall            | Red brick                    | Brick           | ND                |
| C100-AS-5   | Exterior | Exterior         | 17        | Wall            | Tar sealant                  | Tar sealant     | <b>21.20%</b>     |
| C100-AS-6   | Exterior | Exterior         | 18        | Wall            | Black pressed board          | Board           | ND                |
| C100-PP-AS1 | Exterior | Exterior         | 19        | Roof            | Black felt and tar           | Felt and tar    | <b>1.10%</b>      |
| C100-PP-AS2 | Exterior | Exterior         | 20        | Foundation      | Concrete                     | Concrete        | ND                |

**Notes:**

ACM: Asbestos-Containing Material

DJC: Drywall Joint Compound

VFT: Vinyl Floor Tile

VSF: Vinyl Sheet Flooring

ND: Non-Detect (<0.1%)

\*Brown paper and tar analyzed as one layer because the laboratory could not separate these materials.

**Bold and underlined value indicates asbestos was detected but is below 1% by dry weight.**

**Shaded value exceeds 1% asbestos by dry weight and is considered to be an ACM as outlined in the Newfoundland and Labrador Asbestos Abatement Regulations (Reg. 111/98).**

**Table C6-2: Paint Sample Descriptions and Lead Analytical Results (Camp 100)**

| Sample ID   | Room No. | Room Description | Photo No. | Sample Location | Substrate          | Sample Description                         | RDL (mg/kg) | Lead (mg/kg)      |
|-------------|----------|------------------|-----------|-----------------|--------------------|--|-------------|-------------------|
| C100-PS1    | Exterior | Exterior         | 17        | Wall            | Wood Door and Trim | Grey on wood (sample includes wood)        | 15.0        | <b><u>489</u></b> |
| C100-PS2    | 1        | Kitchen/Bunks    | 18        | Wall            | Plywood            | White on plywood (sample includes plywood) | 15.0        | 17                |
| C100-PP-PS1 | Interior | Outhouse         | 19        | Floor           | Plywood            | Grey on plywood (sample includes plywood)  | 15.0        | <b><u>101</u></b> |
| C100-PP-PS2 | Interior | Outhouse         | 20        | Wall            | Plywood            | White on plywood (sample includes plywood) | 15.0        | 22                |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

**Bold and underlined value exceeds Federal HPA criterion (90 mg/kg).**

Shaded value exceeds former Federal HPA criterion (5,000 mg/kg).

**Table C6-3: Paint Sample Descriptions and Mercury Analytical Results (Camp 100)**

| Sample ID   | Room No. | Room Description | Photo No. | Sample Location | Substrate          | Sample Description                         | RDL (mg/kg) | Mercury (mg/kg) |
|-------------|----------|------------------|-----------|-----------------|--------------------|--|-------------|-----------------|
| C100-PS1    | Exterior | Exterior         | 17        | Wall            | Wood Door and Trim | Grey on wood (sample includes wood)        | 0.05        | 0.52            |
| C100-PS2    | 1        | Kitchen/Bunks    | 18        | Wall            | Plywood            | White on plywood (sample includes plywood) | 0.05        | 3.83            |
| C100-PP-PS1 | Interior | Outhouse         | 19        | Floor           | Plywood            | Grey on plywood (sample includes plywood)  | 0.05        | 0.21            |
| C100-PP-PS2 | Interior | Outhouse         | 20        | Wall            | Plywood            | White on plywood (sample includes plywood) | 0.05        | 1.08            |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

**Bold and underlined value exceeds Federal HPA criterion (10 mg/kg).**

Shaded value exceeds CCME CSQG for an industrial site (50 mg/kg).



**Table C6-4: Paint Sample Descriptions and PCB Analytical Results (Camp 100)**

| Sample ID   | Room No. | Room Description | Photo No. | Sample Location | Substrate          | Sample Description                         | RDL (mg/kg) | Total PCB (mg/kg) |
|-------------|----------|------------------|-----------|-----------------|--------------------|--|-------------|-------------------|
| C100-PS1    | Exterior | Exterior         | 17        | Wall            | Wood Door and Trim | Grey on wood (sample includes wood)        | 0.5         | <0.5              |
| C100-PS2    | 1        | Kitchen/Bunks    | 18        | Wall            | Plywood            | White on plywood (sample includes plywood) | 0.5         | <0.5              |
| C100-PP-PS1 | Interior | Outhouse         | 19        | Floor           | Plywood            | Grey on plywood (sample includes plywood)  | 0.5         | <0.5              |
| C100-PP-PS2 | Interior | Outhouse         | 20        | Wall            | Plywood            | White on plywood (sample includes plywood) | 0.5         | <0.5              |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

NL MAE: Newfoundland and Labrador Department of Municipal Affairs and Environment

TDG: Transportation of Dangerous Goods



**Bold and underlined value exceeds CCME CSQG for an industrial site (33 mg/kg).**

Shaded value exceeds the criterion for PCB solid provided in the NL MAE Leachable Toxic Waste, Testing and Disposal Guidance Document and the TDG Regulations (50 mg/kg).

**APPENDIX D6**

**ROOM-BY-ROOM INSPECTION SHEETS**

| Building | Room # | Floor # | Room Description | Dimensions                   |
|----------|--------|---------|------------------|------------------------------|
| Camp 100 | 1      | 1       | Kitchen          | L = 24'<br>W = 24'<br>H = 8' |

|   | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|---|--|---------------------------|--|
| <b>Floor</b>  | WOOD  |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | WOOD  |  |                           |  |
| <b>Ceiling</b>  | WOOD  |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls: White<br>Ceiling: White<br>Floor: Grey<br>Other:   |  |                           |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:  |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  |   |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>2 → 1'x4' 2 bulb  | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 4 → incandescent  |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial   | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | Water & propane Copper lines  |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted   |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext  |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br> Building ready to collapse, No access  |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                 |
|----------|--------|---------|------------------|----------------------------|
| Camp 100 | 2      | 1       | Pantry           | L = 8'<br>W = 8'<br>H = 8' |

|   | Description   | Condition<br>(good/fair/poor) | Quantity<br>(SF/LF/total)                                | Samples Collected<br>(actual/visual reference) |
|---|---|-------------------------------|--|--|
| <b>Floor</b>  | Wood  |                               |  |  |
| <b>Walls</b><br>(include window caulking)   | WOOD  |                               |  |  |
| <b>Ceiling</b>  | WOOD  |                               |  |  |
| <b>Paint</b><br>(and substrate)   | Walls: white<br>Ceiling: white<br>Floor: grey<br>Other:   |                               |  |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:  |                               |  |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —   |                               |  |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>—   | Leaking / Other               | # Total:<br><br># Checked:                               | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 1 - incandescent  |                               |  |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial   | —                             | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 |   |                               |  |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted   |                               |  |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext  |                               |  |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br><br>* NO ACCESS * |                               |  |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                 |
|----------|--------|---------|------------------|----------------------------|
| Camp 100 | 3      | 1       | Storage          | L = 8'<br>W = 8'<br>H = 8' |

|  | Description  | Condition<br>(good/fair/poor)                               | Quantity<br>(SF/LF/total)                                | Samples Collected<br>(actual/visual reference) |               |
|--|--|---|--|--|---------------|
| Floor  | Same as Room 2   |   |  |  |               |
| Walls<br>(include window<br>caulking)  |  |   |  |  |               |
| Ceiling  |  |   |  |  |               |
| Paint<br>(and substrate)   |  | Walls:<br>Ceiling:<br>Floor:<br>Other:                      |  |  |               |
| Insulation<br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       |  | Fire Door Manufacturer:<br>Fire Door Serial #:              |  |  |               |
| Piping /<br>Mechanical<br>Equipment  |  |   |  |  |               |
| Fluorescent<br>Lighting  |  | Ballast Manufacturer:<br>Serial #:                          | Leaking / Other  | # Total:<br># Checked:                         | Suspect PCBs: |
| Other Lighting<br>(e.g., incandescent,<br>HID)                                   |  |   |  |  |               |
| Thermostats  |  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |  |               |
| LCMs<br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 |  |   |  |  |               |
| Mould / Water<br>Staining  |  | Area impacted   |  |  |               |
| ODS<br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext   |   |  |  |               |
| Other / Photos   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |   |  |  |               |
|  | * NO ACCESS *  |   |  |  |               |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                |
|----------|--------|---------|------------------|---------------------------|
| Camp 100 |        |         | Exterior         | L = 32'<br>W = 24'<br>H = |

|   | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|---|--|---------------------------|--|
| <b>Floor</b><br>Foundation  | Cinder block  |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | Red brick on 2/3<br>Brown brick on 1/3  |  |                           |  |
| <b>Ceiling</b>  | black shingles  |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls:<br>Ceiling:<br>Floor:<br>Other: —  |  |                           |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:  |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —   |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #: —  | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 2 → incandescent.   |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted —<br>Dial   | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —   |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted   |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext  |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br><br>* Limited Access ** |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                 |
|----------|--------|---------|------------------|----------------------------|
| Camp 100 |        |         | Outhouse         | L = 6'<br>W = 5'<br>H = 7' |

|   | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|---|--|---------------------------|--|
| <b>Floor</b>  | Concrete & Wood   |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | Wood interior & Exterior  |  |                           |  |
| <b>Ceiling</b>  | Wood<br>Felt on roof  |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls: Grey Ext, White int.<br>Ceiling: White<br>Floor:<br>Other: =                               |  |                           |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #: —  |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —   |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #: —  | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 1 incandescent  |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                       | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —   |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>—  |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—   |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br>— |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

## TABLE OF CONTENTS

|         |  |      |
|---------|--|------|
| 7.0     | MEDONNEGONIK CAMP .....  | 7-1  |
| 7.1     | BUILDING DESCRIPTION .....   | 7-1  |
| 7.2     | ROOM DESIGNATION .....   | 7-2  |
| 7.3     | FINDINGS .....   | 7-3  |
| 7.3.1   | Asbestos-Containing Materials (ACMs) .....                         | 7-3  |
| 7.3.1.1 | Friable Materials .....  | 7-3  |
| 7.3.2   | Paint Additives .....  | 7-5  |
| 7.3.2.1 | Lead in Paint .....  | 7-6  |
| 7.3.2.2 | Mercury in Paint .....   | 7-6  |
| 7.3.2.3 | PCBs in Paint .....  | 7-6  |
| 7.3.3   | Urea Formaldehyde Foam Insulation (UFFI) .....                     | 7-6  |
| 7.3.4   | Suspected Visible Mould Growth (SVG) .....                         | 7-6  |
| 7.3.5   | Mercury-Containing Thermostats .....                               | 7-7  |
| 7.3.6   | PCB-Containing Light Ballasts .....                                | 7-7  |
| 7.3.7   | Potential Sources of ODS and Halocarbons .....                     | 7-7  |
| 7.3.8   | Other Potentially Hazardous Building Materials or Substances ..... | 7-7  |
| 7.3.8.1 | Lead-Containing Materials and Equipment .....                      | 7-7  |
| 7.3.8.2 | Mercury-Containing Materials and Equipment .....                   | 7-8  |
| 7.3.8.3 | PCB-Containing Materials and Equipment .....                       | 7-8  |
| 7.3.8.4 | Treated Wood Chemicals .....                                       | 7-8  |
| 7.3.8.5 | Silica .....   | 7-9  |
| 7.3.8.6 | Radioactive Materials .....  | 7-9  |
| 7.4     | CONCLUSIONS AND RECOMMENDATIONS .....                              | 7-9  |
| 7.4.1   | ACMs .....   | 7-9  |
| 7.4.2   | Lead, Mercury and PCBs in Paint .....                              | 7-10 |
| 7.4.3   | Potential UFFI .....   | 7-12 |
| 7.4.4   | Mould .....  | 7-12 |
| 7.4.5   | ODS .....  | 7-12 |
| 7.4.6   | Potential Lead-Containing Materials/Equipment .....                | 7-13 |
| 7.4.7   | Potential Mercury-Containing Materials/Equipment .....             | 7-13 |
| 7.4.8   | Potential PCB-Containing Materials/Equipment .....                 | 7-13 |
| 7.4.9   | Silica Containing Materials .....                                  | 7-14 |
| 7.4.10  | Potential Radioactive Materials .....                              | 7-14 |
| 7.4.11  | Summary of Findings .....  | 7-14 |

### APPENDICES

- APPENDIX A7 Figures
- APPENDIX B7 Photographic Record
- APPENDIX C7 Sample and Analytical Summary Tables
- APPENDIX D7 Room-By-Room Inspection Sheets



## 7.0 MEDONNEGONIK CAMP

Medonnegonik Lake Camp is located approximately 24 km east of the Town of Milltown-Head of Bay d’Espoir, NL and is accessed via gravel access road from the Bay d’Espoir Highway (Route 360) (refer to Figure 7.1, Appendix A7). The site is comprised of an accommodations cabin, a helicopter pad and an outhouse.

### 7.1 BUILDING DESCRIPTION

The accommodations cabin is a one-storey, rectangular structure with a footprint area of approximately 66 m<sup>2</sup> (refer to Photos 1 to 8, Appendix B7). The floor plan of the cabin consists of a kitchen, a bathroom and two bedrooms (refer to Figure 7.2, Appendix A7). The foundation of the accommodations cabin consists of concrete block footings and there is a dirt floor crawl space beneath the accommodations cabin (refer to Photo 12, Appendix B7). The structure of the accommodations cabin consists of brick. The exterior walls on the accommodations cabin are finished with brick and the roof is finished with asphalt shingles. The window and exterior door openings on the accommodations cabin are barricaded with metal covers for security purposes (refer to Photos 1 to 4, Appendix B7). Interior wall and ceiling finishes in the accommodations cabin consists of painted plywood. Floors/floor finishes consist of plywood. Fluorescent lighting was observed on the interior of the cabin. The accommodations cabin is not currently heated. There were building upgrades completed at the site, reportedly in the mid 1990’s. The new areas are brown brick and the original areas are red brick (refer to Photos 2 and 3, Appendix B7).

The outhouse is a one-storey, rectangular structure with a footprint area of approximately 3 m<sup>2</sup>. The foundation and structure of the outhouse consists of wood framing and concrete. The exterior walls on the outhouse are finished with plywood and the roof is finished with asphalt shingles (refer to Photos 9 and 10, Appendix B7). Interior wall and ceiling finishes in the outhouse consist of painted plywood. Floor finishes consist of plywood. The outhouse does not contain any lighting or heating.

The helicopter pad is located to the northwest of the accommodations cabin and is comprised of treated wood timbers (refer to Photo 13, Appendix B7).

A description of accommodations cabin is outlined in Table 7-1 and a description of the outhouse is outlined in Table 7-2. Photographs of the buildings are provided in Appendix B7.

**Table 7-1: Site Building Description – Accommodations Cabin**

| Building Name        | Accommodations cabin                   | Photo No. (Appendix B7) |
|----------------------|--|-------------------------|
| Date of Construction | Approximately late 1960’s/early 1970’s | -                       |
| Date of Renovations  | Unknown                                | -                       |
| No. of Stories       | One                                    | 1 to 4                  |
| Crawl Space (Yes/No) | Yes                                    | 12                      |
| Attic (Yes/No)       | Yes                                    | -                       |
| Type of Structure    | Wood Frame and bricks                  | 1 to 4                  |
| Type of Foundation   | Wood Beams and concrete blocks         | 12                      |
| Exterior             | Red and Brown brick                    | 1 to 4                  |
| Window/Door Frames   | Painted Metal and Wood                 | 1 to 4                  |
| Exterior Doors       | Painted Metal                          | 1 and 4                 |

**Table 7-1: Site Building Description – Accommodations Cabin**

| Building Name             | Accommodations cabin         | Photo No. (Appendix B7) |
|---------------------------|------------------------------|-------------------------|
| Roofing Materials         | Asphalt Shingles             | 4                       |
| Interior Walls Finishes   | Painted Plywood              | 5 to 6                  |
| Interior Ceiling Finishes | Plywood                      | 5, 6 and 8              |
| Floor Finishes            | Plywood                      | 5 and 7                 |
| Interior Doors            | NA                           | -                       |
| Interior Lighting         | Fluorescent and Incandescent | 6 and 8                 |
| Exterior Lighting         | Incandescent                 | 1                       |
| Heating                   | Propane stove                | 5                       |

**Table 7-2: Site Building Description – Outhouse**

| Building Name             | Outhouse                               | Photo No. (Appendix B7) |
|---------------------------|--|-------------------------|
| Date of Construction      | Approximately late 1960's/early 1970's | -                       |
| Date of Renovations       | Unknown                                | -                       |
| No. of Stories            | One                                    | 9                       |
| Crawl Space (Yes/No)      | No                                     | -                       |
| Attic (Yes/No)            | No                                     | -                       |
| Type of Structure         | Wood Frame                             | 9 and 10                |
| Type of Foundation        | Wood Frame                             | -                       |
| Exterior                  | Plywood                                | 9                       |
| Window/Door Frames        | NA                                     | -                       |
| Exterior Doors            | Painted wood                           | 9                       |
| Roofing Materials         | Asphalt Shingles                       | 9                       |
| Interior Walls Finishes   | Painted Plywood                        | 10                      |
| Interior Ceiling Finishes | Plywood                                | -                       |
| Floor Finishes            | NA                                     | -                       |
| Interior Doors            | NA                                     | -                       |
| Interior Lighting         | NA                                     | -                       |
| Exterior Lighting         | NA                                     | -                       |
| Heating                   | NA                                     | -                       |

## 7.2 ROOM DESIGNATION

Each room at Medonnegonik Camp was assigned a specific room name. The designated room names are presented in Table 7-3 and graphically illustrated on the sample location plan (refer to Figure 7.2, Appendix A7).

**Table 7-3: Assigned Rooms**

| Level No. | Room Name – Accommodations Cabin | Room Number |
|-----------|----------------------------------|-------------|
| 1         | Kitchen/Bunk Area                | Room 1      |
| 1         | Bathroom                         | Room 2      |
| 1         | Bedroom/Portch                   | Room 3      |
| 1         | Bedroom                          | Room 4      |
| 1         | Outhouse                         | Outhouse    |

## **7.3 FINDINGS**

The findings documented in this section are based on observations made by Wood personnel at the time of the site visit on August 7, 2018 and the results of laboratory analyses of samples collected from Medonnegonik Camp. During the Pre-Demolition HBMA site visit, Wood personnel were accompanied by a representative of Hydro (Mr. Wayne Lidster). Copies of room-by-room inspection sheets for the accommodations building and outhouse are provided in Appendix E6. Photos of the samples collected from the accommodations building and outhouse during the site visits are provided in Appendix B7.

### **7.3.1 Asbestos-Containing Materials (ACMs)**

There are over 3,000 ACMs that are commercially available, which can be divided into two broad categories: friable and non-friable. ACMs were discontinued from use in Canada in the late 1970s/early 1980s, although non-friable asbestos is still found in many more recent buildings.

During the Pre-Demolition HBMA site visit, a total of 11 building material samples (MDX-AS1 to MDX-AS11) were collected from the accommodations cabin and one (1) building material sample (MDX-PP-AS1) from the outhouse (refer to Photos 14 to 25, Appendix B7) and analyzed for asbestos content. Bulk sample descriptions and asbestos analytical results are summarized in Table C7-1, Appendix C7. Sample locations and analytical results are graphically illustrated on Figure 7.2, Appendix A7.

#### **7.3.1.1 Friable Materials**

Friable ACMs are defined as materials that can be crumbled, pulverized and reduced to powder when dry using hand pressure. Typical friable materials include acoustical or decorative spray applications, fireproofing and thermal insulation.

##### **7.3.1.1.1 *Spray-Applied Fireproofing, Insulation and Texture Finishes***

There were no spray-applied fireproofing, insulation or texture finishes observed in the accommodations cabin or outhouse during the Pre-Demolition HBMA site visit; therefore, no samples of these materials were collected for analysis.

##### **7.3.1.1.2 *Building and Thermal System Insulation***

During the Pre-Demolition HBMA site visit, pink fiberglass insulation was observed between the particle board and plywood in the walls of the accommodations cabin. During the Pre-Demolition HBMA site visit, one (1) sample of black paper on pink fiberglass insulation (MDX-AS1) was collected from the wall of the accommodations cabin and analyzed for asbestos content (refer to Photo 14, Appendix B7). Asbestos was not detected in the insulation sample collected from the accommodations cabin.

##### **7.3.1.1.3 *Non-Friable and Potentially Friable Materials***

Non-friable ACMs are hard or manufactured products such as floor tiles, fire blankets, pre-formed manufactured cementitious insulation and wallboards, pipes, and siding, wherein the asbestos fibres are bound to the substrate. Note that although a product may be considered non-friable when new, the

product may release fine dust when disturbed (e.g., deterioration, removal, renovations) and the free dust is considered friable.

#### **7.3.1.1.4 Ceiling Tile**

There were no ceiling tiles observed at Medonnegonik Camp during the Pre-Demolition HBMA site visit; therefore, no samples of ceiling tile were collected for analysis.

#### **7.3.1.1.5 Drywall Joint Compound**

There was no drywall joint compound observed at Medonnegonik Camp during the Pre-Demolition HBMA site visit; therefore, no samples of drywall joint compound were collected for analysis.

#### **7.3.1.1.6 Vinyl Flooring Products and Mastics**

There was no vinyl flooring or products observed at Medonnegonik Camp during the Pre-Demolition HBMA site visit; therefore, no samples of vinyl flooring or products were collected for analysis.

#### **7.3.1.1.7 Baseboard, Carpet and Stair Tread Adhesives/Mastics**

There were no baseboard, carpet or stair tread adhesives/mastics observed at Medonnegonik Camp during the Pre-Demolition HBMA site visit; therefore, no samples of these types of adhesives/mastics were collected for analysis.

#### **7.3.1.1.8 Roofing Products**

During the Pre-Demolition HBMA site visit, one (1) sample of black shingle and tar (MDX-AS10) and one (1) sample of green/black shingle and tar (MDX-AS11) was collected from the roof of the accommodations cabin and one (1) sample of black shingle and tar (MDX-PP-AS1) was collected from the roof of the accommodations cabin and analyzed for asbestos content (refer to Photos 23 to 25, Appendix B7). Asbestos was detected in MDX-PP-AS1 containing 0.79 % chrysotile asbestos. According to the NL asbestos abatement regulations (Reg. 111/98), this material is not considered asbestos-containing materials.

It is important to note that, due to height and safety constraints, no samples of roofing, building materials around roof penetrations (e.g., caulking or sealants around vents or electrical conduit) or roof seams were collected from the accommodations cabin for analysis.

#### **7.3.1.1.9 Caulking/Sealant**

During the Pre-Demolition HBMA site visit, one (1) sample of white caulking (MDX-AS7) was collected from around the brick on the accommodations cabin and analyzed for asbestos content (refer to Photo 20, Appendix B7). Asbestos was not detected in the caulking sample collected from the accommodations cabin.

### **7.3.1.1.10 Mortar, Grout and Other Cementitious Materials**

During the Pre-Demolition HBMA site visit, one (1) sample of grey mortar on red brick (MDX-AS3), one (1) sample of red brick (MDX-AS4), one (1) sample of concrete block (MDX-AS5), one (1) sample of grey mortar on concrete block (MDX-AS6), one (1) sample of brown brick (MDX-AS8) and one (1) sample of grey mortar on brown brick (MDX-AS9) collected from the exterior of the accommodations cabin and analyzed for asbestos content (refer to Photos 16, 17, 18, 19, 21 and 22, Appendix B7). Asbestos was not detected in the brick, concrete and mortar samples analyzed.

### **7.3.1.1.11 Fire-Rated Doors**

Fire-rated doors and door frames were not observed during the Pre-Demolition HBMA site visit.

### **7.3.1.1.12 Other Potential ACMs**

During the Pre-Demolition HBMA site visit, one (1) sample of black pressed board and tar paper (MDX-AS2) from the exterior of the accommodations cabin and analyzed for asbestos content (refer to Photo 15, Appendix B7). Asbestos was not detected in the pressed board / tar paper sample analyzed.

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to, electrical and mechanical components and insulators such as wiring and gaskets, heat shields inside incandescent/fluorescent light fixtures, and caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations (refer to Photos 4, 5, 6 and 8, Appendix B7).

Other possible hidden and inaccessible ACMs have the potential to be present within the accommodations cabin but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components or gaskets inside appliances, concrete lining the interior of hot water tanks, and underground infrastructure or piping.

## **7.3.2 Paint Additives**

Lead compounds have been used in paint as pigment and durability additives since the early 1800s. Mercury compounds have been used in paint as anti-microbial additives up until the 1990s. PCBs have been used in paint as plasticizers and corrosion resistance additives from the 1950s to the 1970s.

During the Pre-Demolition HBMA site visit, three (3) samples (MDX-PS1 to MDX-PS3) were collected from painted surfaces of the accommodations cabin and one (1) sample (MDX-PP-PS1) collected from painted surfaces of the outhouse and analyzed for lead, mercury and PCB content (refer to Photos 26 to 29, Appendix B7). Paint sample descriptions and lead, mercury and PCBs analytical results are summarized in Tables C7-2 to C7-4, Appendix C7. Sample locations and analytical results are graphically illustrated on Figure 7.2, Appendix A7.

### **7.3.2.1 Lead in Paint**

Concentrations of lead in the three (3) samples (MDX-PS1 to MDX-PS3) collected from painted surfaces of the accommodations cabin and one (1) sample (MDX-PP-PS1) collected from the outhouse ranged from 109 mg/kg to 1,110 mg/kg (refer to Table C7-2, Appendix C7). All four (4) paint samples (MDX-PS1 to MDX-PS3 and MDX-PP-PS1) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg (refer to Table C7-2, Appendix C7).

### **7.3.2.2 Mercury in Paint**

Concentrations of mercury in the three (3) samples (MDX-PS1 to MDX-PS3) collected from painted surfaces of the accommodations cabin and one (1) sample (MDX-PP-PS1) collected from the outhouse ranged from 0.06 to 7.87 mg/kg, and therefore, the concentrations of mercury in these samples were below the Federal HPA criterion (10 mg/kg) (refer to Table C7-3, Appendix C7).

### **7.3.2.3 PCBs in Paint**

PCBs were not detected (<0.5 mg/kg) in any of the paint samples analyzed, and therefore, were below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg) (refer to Table C7-4, Appendix C7).

## **7.3.3 Urea Formaldehyde Foam Insulation (UFFI)**

Visual indicators suggesting the potential presence of UFFI were not observed at Medonnegonik Camp. The nature of the insulation in the walls and ceilings throughout the accommodations cabin consisted of fiberglass insulation.

Since the original date of construction of Medonnegonik (assumed construction commenced the same timeframe as the original transmission line, late 1960's/early 1970's) is unknown, it is possible that UFFI may be present.

In the event that UFFI is present, the CMHC state that "tests show that UFFI is not a source of over-exposure to formaldehyde after the initial curing and release of excess gas". The general view based on studies concerning formaldehyde emissions is that as a product ages, the amount of formaldehyde off-gassed from the product decreases over time. The amount of formaldehyde released is reportedly dependent on temperature, humidity and whether or not the product is exposed to excessive moisture or water.

## **7.3.4 Suspected Visible Mould Growth (SVG)**

Wood inspected the interior areas of the accommodations cabin and outhouse for visual or olfactory evidence of suspected mould. SVG was noted on much of the ceiling and wall surfaces inside the accommodations cabin during the Pre-Demolition HBMA site visit. A sample, MDX-MS1, was collected in Room 3 (refer to Figure 7.2, Appendix A7 and Photo 30, Appendix B7).

The results of mould analysis determined that bulk sample MDX-MS1 contained *Cladosporium* *Acremonium* mould with sparse growth (refer to Table C7-5, Appendix C7).

### 7.3.5 Mercury-Containing Thermostats

Thermostats were not identified inside the accommodations cabin at Medonnegonik Camp during the Pre-Demolition HBMA site visit.

### 7.3.6 PCB-Containing Light Ballasts

Fluorescent and incandescent light fixtures were observed on the interior of the accommodations cabin and incandescent light fixtures were observed on the exterior of the accommodations cabin, as observed from the exterior of the cabin, during the Pre-Demolition HBMA site visit (refer to Photos 1, 6 and 8, Appendix B7). No light ballasts were inspected during the Pre-Demolition HBMA site visit.

### 7.3.7 Potential Sources of ODS and Halocarbons

During the Pre-Demolition HBMA, potential sources of ODS was identified within the accommodations cabin. Results of the ODS inspection is summarized in Table 7-4.

**Table 7-4: Potential Sources of ODSs**

| Item         | Manufacturer | Model (Serial No.) | Location Observed | Photo No. (Appendix B2) | Refrigerant | Potential ODS |
|--------------|--------------|--------------------|-------------------|-------------------------|-------------|---------------|
| Freezer      | Woods        | WE25-T6            | Room 3            | 32                      | R12         | Yes           |
| Refrigerator | Danby        | D730               | Room 1            | 5                       | R12         | Yes           |

Based on observations made during the site visit, ODSs are present in the accommodations cabin in the form of refrigerant R12 contained in a refrigerator located in Room 1 (refer to Photo 5, Appendix B7) and a freezer located in Room 3 (refer to Photo 32, Appendix B7). This refrigerant (R12) is a hydrochlorofluorocarbon (HCFC) and is regulated under the Federal Halocarbon Regulations.

Fire extinguishers were not observed at Medonnegonik during the Pre-Demolition HBMA site visit.

### 7.3.8 Other Potentially Hazardous Building Materials or Substances

Other potentially hazardous building materials or substances identified during this assessment are presented in the following sections.

#### 7.3.8.1 Lead-Containing Materials and Equipment

Lead is typically associated with plumbing solder and older pipe materials (e.g., cast iron pipe joints), as well as products such as radiation protective shielding and lead-acid batteries. Lead can also be present in steel and iron primer, industrial electrical jacketing, roof flashing and tank linings.

Since the actual date that Medonnegonik Camp was constructed is unknown (assumed to be late 1960's/early 1970's), it is possible that lead solder is present in plumbing and piping (i.e., cast iron and copper piping) in the accommodations cabin.

### **7.3.8.2 Mercury-Containing Materials and Equipment**

The light tubes and bulbs in HID and fluorescent light fixtures often contain limited quantities of mercury in a powder or vapour form. Fluorescent light fixtures were observed inside the accommodations cabin during the Pre-Demolition HBMA site visit and the light tubes may contain mercury (refer to Photo 6, Appendix B7).

### **7.3.8.3 PCB-Containing Materials and Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, and as mentioned previously, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

### **7.3.8.4 Treated Wood Chemicals**

The chemicals that are used to protect and preserve wood products from insect attack and fungal decay may pose risks to human health and the environment. Depending on the wood treatment used, treated wood may be considered a hazardous waste upon disposal. The NL Department of Environment and Conservation (currently the NL MAE), 2015 Guidance Document for Treated Wood Waste Disposal (GD-PPD-075.1) provides landfill disposal standards for "pressure treated" inorganic preservatives (i.e., arsenic and chromium) and creosote (i.e., total cresol and benzo(a)pyrene) and chlorophenolic (i.e., pentachlorophenol) formulations used to preserve wood. These landfill disposal standards for treated wood waste (TWW) are used to assess the results of leachability testing to determine disposal options for treated wood to be removed during renovation or demolition activities.

During the Pre-Demolition HBMA site visit, suspected "creosote treated" inorganic (i.e., chromated copper arsenate (CCA)) preservatives appear to have been applied to wood that was used as the foundation of the outhouse. One (1) sample of treated wood (MDX-TW1) was collected from the foundation and analyzed for leachable benzo(a)pyrene and leachable cresols to determine whether or not the treated wood would be considered hazardous waste upon removal from the site, if required (refer to Photo 31, Appendix B7). The bulk sample description and leachable treated wood parameter analytical results are summarized in Table C7-6, Appendix C7. The sample location and analytical results are graphically illustrated on Figure 7.2, Appendix A7.

Leachable benzo(a)pyrene and leachable cresols were not detected above the RDLs in the treated wood sample MDX-TW1; therefore, the concentrations of these leachable treated wood parameters were below the TCLP landfill disposal standards for leachable benzo(a)pyrene (1 µg/L) and leachable cresols (20,000 µg/L) provided in the NL Department of Environment and Conservation (currently the NL MAE), 2015 Guidance Document for Treated Wood Waste Disposal (GD-PPD-075.1).



### **7.3.8.5 Silica**

According to the CPWR – The Center for Construction Research and Training, many common construction materials contain silica including, asphalt, brick, cement, concrete, drywall, grout, mortar, stone, sand and tile. The dust created by cutting, grinding, drilling or otherwise disturbing these materials can contain crystalline silica particles.

Based on the Pre-Demolition HBMA site visit, silica is expected to be present in the exterior brick and concrete used in the construction of the foundation for the accommodations building. Silica may also be present in the asphalt shingles used in the construction of the accommodations cabin and outhouse.

### **7.3.8.6 Radioactive Materials**

Smoke detectors were not observed during the Pre-Demolition HBMA site visit. Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called "ion chamber smoke alarms".

## **7.4 CONCLUSIONS AND RECOMMENDATIONS**

Based on observations made and information gathered during the Pre-Demolition HBMA, the following conclusions and recommendations are made with respect to the potential and actual presence of hazardous building materials at Medonnegonik Camp.

### **7.4.1 ACMs**

Results of the asbestos sampling and analytical program for the Medonnegonik Camp revealed that all building materials sampled contained less than 1% asbestos by dry weight, and not considered asbestos-containing.

Other potential ACMs were observed (or suspected to be present) and were not sampled due to the nature of the materials and/or hazards associated with sampling these materials. These materials included, but are not limited to:

- Electrical and mechanical components and insulators such as wiring and gaskets.
- Heat shields inside incandescent/ fluorescent light fixtures.
- Caulking or sealants around or along roof seams, vent pipes, electrical conduits or other penetrations.

Other possible hidden and inaccessible ACMs have the potential to be present within the buildings at Medonnegonik Camp but were not identified during the Pre-Demolition HBMA site visit. These possible ACMs could include concrete leveling compound (existing concrete foundation), possible fireproofing materials in the wall or ceiling cavities, piping/pipe joint sealants/gaskets and packing associated with cast iron pipe joints, fire rated structures or building materials, vapour barriers in walls, undercoatings on sinks, interior heat resistant components, and underground infrastructure or piping.

If other potential ACMs that were not sampled as part of this assessment are encountered in the future, these materials should be treated as ACMs or samples should be collected and tested to verify asbestos

content. This should be done as soon as these materials are encountered and before these materials are disturbed. This includes materials that are currently concealed by walls and ceiling systems.

In accordance with the NL Asbestos Abatement Regulations (Reg. 111/98), which provide the legislative requirements for safe handling of ACMs in workplaces in the Province of NL, the following is recommended:

- Safe work procedures shall be established.
- All buildings constructed during the period when asbestos was readily used in construction (generally prior to the early 1980s) or any buildings that are suspected as having asbestos must have a written assessment and management plan (where applicable) for potential ACMs.
- Materials suspected of containing asbestos are required to be handled as ACMs, until analysis by a competent laboratory determines whether or not it does contain asbestos.
- Prior to general demolition, all ACMs must be safely removed from the building and disposed of in accordance with appropriate environmental guidelines by an asbestos abatement contractor registered with the Occupational Health and Safety (OHS) Division of Service NL.
- Most work involving ACMs (i.e., disturbance, removal and encapsulation) must be conducted by a contractor registered with the OHS Division of Service NL.
- ACMs in good condition should be inspected on an annual basis.
- ACMs in poor condition should be removed from the building and transported off-site for proper disposal.
- Workers should don adequate respiratory protection and personal protective equipment (PPE) when working with ACMs.

Prior to the removal and/or abatement of any identified ACMs (or any other hazardous building materials), an abatement plan including technical specifications should be designed, prepared and supervised by a qualified professional and should be undertaken by qualified trades, in accordance with applicable standards. Activities involving the disturbance and/or removal of ACMs should be carried out in a manner that ensures asbestos fiber concentrations do not exceed the applicable American Conference of Governmental Industrial Hygienists (ACGIH) threshold limit value (TLV). ACMs can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.

#### **7.4.2 Lead, Mercury and PCBs in Paint**

Results of the paint sampling and analytical program revealed the following:

- **Lead in Paint**
  - Concentrations of lead in three (3) samples (MDX-PS1 to MDX-PS3) collected from painted surfaces of the accommodations cabin and one (1) sample (MDX-PP-PS1) collected from the outhouse ranged from 109 mg/kg to 1,110 mg/kg.
  - All four (4) paint samples (MDX-PS1 to MDX-PS3 and MDX-PP-PS1) contained lead at concentrations above the Federal HPA criterion of 90 mg/kg and below the former Federal HPA criterion of 5,000 mg/kg; therefore, these paints are considered to be LBPs, but are not likely to be leachable for lead.

- **Mercury in Paint**

- Concentrations of mercury in the three (3) samples (MDX-PS1 to MDX-PS3) collected from painted surfaces of the accommodations cabin and one (1) sample (MDX-PP-PS1) collected from the outhouse ranged from 0.06 to 7.87 mg/kg; below the Federal HPA criterion (10 mg/kg). These paints are not considered to be MBPs and are not likely to be leachable for mercury.

- **PCBs in Paint**

- PCBs were not detected (<0.5 mg/kg) in the three (3) samples (MDX-PS1 to MDX-PS3) collected from painted surfaces of the accommodations cabin and one (1) sample (MDX-PP-PS1) from the painted surfaces of the outhouse, and therefore, were below the CCME CSQG for PCBs in soil at an industrial site (33 mg/kg) and the applicable criterion for PCB solid (50 mg/kg).

Based on the paint sample analytical results, the other paint samples collected from accommodations cabin and outhouse are not likely to be leachable for lead, PCBs or mercury; therefore, should disposal be required (e.g., renovation or demolition activities), the paints analyzed for lead and mercury content may be disposed of at an approved landfill facility, pending landfill and Provincial regulatory approval.

There are potential adverse human health impacts associated with disturbing (e.g., scraping, sanding, burning, etc.) lead, mercury or PCB-containing paint finishes, due to the potential for dust, mist or fumes to be released and inhaled or ingested by workers. Given the lead-based paints were identified at the site, as a precautionary measure, Wood recommends handling these paint finishes, as follows:

- In areas of minor peeling or flaking, the paint should be removed using wet scraping techniques.
- In areas of extensive peeling and flaking, the paint should be removed and more extensive particulate control measures may be required.
- In areas where lead-containing paint finishes are present and in poor condition, an experienced contractor should be utilized for renovating, decommissioning or demolition activities.
- Prior to renovation, dismantling or demolition activities, all areas of extensive peeling and flaking of lead-containing paint finishes and paint debris/dust should be removed and/or remediated to ensure that building occupants/workers are protected from associated dust/particulate.
- Procedures should be implemented to ensure that workers and anyone present in and around areas being renovated, dismantled or demolished are protected. The contractor should also ensure that dust generation and migration is minimized.
- Precautions should be taken to prevent/reduce exposure to paint dust during any disturbance of lead-containing paint finishes, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas.
- Where possible, lead-containing paint finishes should be removed from metal surfaces prior to welding or cutting these materials.

If potential lead, mercury or PCB-containing paint finishes that were not sampled during this assessment are encountered in future, prior to any disturbance or removal, samples should be obtained and tested to verify concentrations of lead, mercury and PCBs. This includes materials that are currently concealed by walls and ceiling systems.

Any disturbance or removal of lead, mercury or PCB-containing paint finishes that may generate dust or respirable aerosols must conform to the Federal and Provincial OHS Regulations. All work should be carried out by individuals wearing proper PPE. The type of respiratory protection and control measures to be implemented during the removal of these types of paint finishes should be determined by a qualified person and based on the risk level of a particular work activity (i.e., scraping, sanding, abrasive blasting, etc.). Activities involving the disturbance and/or removal of lead, mercury or PCB-containing paint finishes should be carried out in a manner that ensures paint dust concentrations do not exceed the applicable ACGIH TLVs.

### **7.4.3 Potential UFFI**

The sale and installation of UFFI was banned in 1980; since the original date of construction is unknown, it is possible that UFFI may be present in the building. Visual indicators suggesting the potential presence of UFFI were not observed in the building (i.e. only fiberglass insulation was observed). It can be inferred that any UFFI present within the building is unlikely to affect the indoor air quality due to the amount of time that has passed since the insulation was likely installed (i.e., pre-1980) along with the likelihood that formaldehyde has off-gassed over this period of time. It should be noted that, the presence and concentration of formaldehyde cannot be determined or quantified without conducting site-specific testing for formaldehyde.

Although there is currently no Provincial regulations requiring that the removal of UFFI be conducted by a licensed/registered abatement contractor, based on discussions with representatives of the OHS Division of Service NL, it is strongly recommended that this material be abated using similar methods as required for asbestos abatement and that the insulation must be removed in a dry condition. Based on discussions with representatives of the NL MAE, for the purposes of disposal of UFFI, this material is permitted to be bagged and transported to an approved WDS and disposed in the special waste area (unlined area) of the site.

### **7.4.4 Mould**

SVG was noted on much of the ceiling and wall surfaces inside the accommodations cabin during the Pre-Demolition HBMA site visit. The results of mould analysis determined that bulk sample MDX-MS1 contained *Cladosporium* *Acremonium* mould with sparse growth.

Mould spores are present in all indoor environments and cannot be completely eliminated. Cellulose based building materials provide a nutrient base for many mould species; however, mould cannot grow unless an adequate amount of excess moisture is present. The most effective way to prevent mould growth within a building is the prompt removal of any porous building materials with water damage or mould growth and repairing the building components that lead to the water infiltration.

### **7.4.5 ODS**

Based on observations made during the site visit, ODSs are present in the accommodations cabin in the form of refrigerant R12 contained in a refrigerator located in Room 1 and a freezer located in Room 3. This refrigerant (R12) is a hydrochlorofluorocarbon (HCFC) and is regulated under the Federal Halocarbon Regulations.

Ozone depleting substances (ODS), if present, should be removed by an approved contractor prior to disposing of any cooling and/or refrigeration equipment from the building. The use, storage, operation, maintenance, decommissioning, and disposal of ODS containing equipment, in general, is regulated at both a Provincial and Federal level and must comply with the most recent NL Halocarbon Regulations and the Federal Halocarbon Regulations. The status of the potential ODS containing equipment should be confirmed through a mechanical contractor or consultant.

#### **7.4.6 Potential Lead-Containing Materials/Equipment**

Lead solder may be likely to be present in plumbing and piping (e.g., cast iron and copper piping) within the accommodations cabin.

The disturbance, control or disposal of lead-containing material/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of lead in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a metal recycling facility and not a landfill. Removal of lead-containing batteries should be completed in a manner that ensures structural integrity and no loss of fluid from the batteries. Should disposal be required, disposal of lead-containing batteries should be completed in accordance with hazardous waste procedures/guidelines (i.e., at an approved facility).

#### **7.4.7 Potential Mercury-Containing Materials/Equipment**

Should disposal be required, mercury-containing equipment should be removed intact and returned to the manufacturer for recycling or disposed of at an approved hazardous waste disposal facility. The disturbance, control or disposal of mercury-containing materials/equipment should be carried out in accordance with applicable criteria/regulations (refer to Section 1.6 of this report). The presence/absence of mercury in these materials should be confirmed through a contractor or consultant prior to disturbance or disposal of these materials. Typically, these materials are sent to a recycling or hazardous waste disposal facility and not a landfill.

#### **7.4.8 Potential PCB-Containing Materials/Equipment**

According to the USEPA, PCBs may be present in caulking used in windows, door frames, masonry columns and other building materials in buildings built or renovated between 1950 and 1979. In addition, insulating fluids and cooling oils in electrical equipment (i.e., transformers, fluorescent light ballasts, capacitors, etc.) often contained PCBs until around 1980.

If PCB-containing materials or equipment are encountered in the future, and should disposal be required, the PCB content in the materials or equipment should be confirmed prior to disposal. Florescent light fixtures are present within the accommodations cabin. Any leaking light ballasts identified, whether PCB containing or not, should be removed and replaced to avoid potential concerns with electrical equipment in the future. All ballasts that are removed should be placed in a proper storage container(s). Leaks or stained areas should be cleaned and/or removed in accordance with applicable regulations or industry standards.

Any PCB-containing equipment (if present) should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations. Any PCB-containing equipment requiring removal from the building should be transported and disposed of at an approved hazardous waste disposal site, and not a landfill disposal site, by a registered hazardous waste transporter in accordance with applicable regulations.

### 7.4.9 Silica Containing Materials

Silica is expected to be present in concrete used in the construction foundation and bricks of the accommodations cabin. Silica may also be present in asphalt shingles used in the construction of accommodations cabin and outhouse. Precautions should be taken to prevent/reduce exposure to silica dust during any disturbance/ demolition of silica-containing products, such as wetting the surface of the materials to prevent dust emissions, donning respiratory protection, and cleaning tools and clothing prior to exiting work areas. Activities involving the disturbance and/or demolition of silica-containing materials should be carried out in a manner that ensures silica dust concentrations do not exceed the applicable ACGIH TLV.

### 7.4.10 Potential Radioactive Materials

Smoke detectors were not observed during the Pre-Demolition HBMA site visit. Smoke detectors observed may contain very small amounts of radioactive material (i.e., Americium 241). Smoke alarms that use radioactive material incorporated in an ionization chamber are called "ion chamber smoke alarms".

### 7.4.11 Summary of Findings

Hazardous building materials identified at Hungry Grove Camp during this Pre-Demolition HBMA and disposal options, if required, are summarized in Table 7-5. Conclusions and recommendations made with respect to the potential and actual presence of hazardous building materials within the accommodations cabin and outhouse are provided in Section 3.4 and should be reviewed in conjunction with Table 7-5.

**Table 7-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| Hazardous Material | Applicable Acts, Regulations or Guidance Documents | Description and Location   | Disposal   |
|--------------------|--|--|--|
| <b>ACMs</b>        | NL Asbestos Abatement Regulations (Reg. 111/98)    | None identified at locations sampled.<br><br>Note that other possible hidden and inaccessible ACMs have the potential to be present within the accommodations building, but were not identified during the Pre-Demolition HBMA site visit. | ACMs cannot be disposed of at a Construction & Demolition Site; however, these materials can be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.<br><br>The transportation and disposal of asbestos should be conducted in accordance with the NL Asbestos Abatement Regulations (Reg. 111/98) and with Standard Operating Procedures (SOPs) for disposal of ACMs at the landfill. |

**Table 7-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b> | <b>Applicable Acts, Regulations or Guidance Documents</b>   | <b>Description and Location</b>  | <b>Disposal</b>   |
|---------------------------|---|--|---|
| <b>LBP</b>                | Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)<br>Federal HPA (R.S.1985, c. H-3)<br>Federal TDG Act (1992, c. 34)<br>Surface Coating Materials Regulations (SOR/2016-193) | LBP (white) on plywood floor of accommodations cabin.<br>LBP (grey) on door of accommodations cabin.<br>LBP (grey) on plywood interior accommodations cabin.<br>LBP (grey) on plywood interior outhouse. | Paints that were analyzed for lead and contained <5,000 mg/kg lead, may be disposed of at a Regional Solid Waste Disposal Facility (landfill), provided permission is obtained from the landfill.   |
| <b>Potential UFFI</b>     | Federal HPA (R.S.1985, c. H-3)  | None identified  | UFFI is permitted to be bagged and transported to an approved WDS and disposed in the special waste area of the site.   |
| <b>Mould</b>              | Mould Guidelines for the Canadian Construction Industry, Canadian Construction Industry (CCI), 2004;<br><br>Mould Abatement Guidelines, Environmental Abatement Council of Ontario (EACO), 2010   | Bulk sample MDX-MS1 contained Cladosporium Acremonium mould with sparse growth.  | All mould impacted materials may be disposed of at a Regional Solid Waste Landfill, provided permission is obtained from the facility.  |
| <b>Potential ODS</b>      | Federal Halocarbon Regulations (SOR/2003-289)   | R12 refrigerant in refrigerator in Room 1 and freezer of Room 3.   | Materials containing ODS should be received by a contractor or facility that has the proper approvals to remove, handle and/or dispose of ODS. The remaining materials can be disposed of at a recycling facility, provided permission is obtained from the facility. |

**Table 7-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b>                                | <b>Applicable Acts, Regulations or Guidance Documents</b>  | <b>Description and Location</b>   | <b>Disposal</b>  |
|--|--|---|--|
| <b>Potential Lead-Containing Materials/ Equipment</b>    | Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)<br>Federal HPA (R.S.1985, c. H-3)<br>Federal TDG Act (1992, c. 34)<br>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301) | Potential lead-containing solder (piping and plumbing).   | Lead-containing materials and equipment can be disposed of at a metal recycling or hazardous waste disposal facility, in accordance with applicable regulations.<br><br>The transportation and disposal of hazardous lead-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility. |
| <b>Potential Mercury-Containing Materials/ Equipment</b> | Federal HPA (R.S.1985, c. H-3)<br>Federal TDG Act (1992, c. 34)<br>Products Containing Mercury Regulations (SOR/2014-254)  | Fluorescent light fixtures are present inside accommodations cabin. The light tubes in fluorescent light fixtures often contain limited quantities of mercury in a powder or vapour form. | Mercury-containing materials and equipment can be disposed of at a recycling or hazardous waste disposal facility, in accordance with applicable regulations.<br><br>The transportation and disposal of hazardous mercury-containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility. |



**Table 7-5: Summary of Disposal Options for Confirmed and Potential Hazardous Building Materials**

| <b>Hazardous Material</b>                            | <b>Applicable Acts, Regulations or Guidance Documents</b>  | <b>Description and Location</b>  | <b>Disposal</b>  |
|--|--|--|--|
| <b>Potential PCB-Containing Materials/ Equipment</b> | <p>Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149)</p> <p>Federal TDG Act (1992, c. 34)</p> <p>Guidance Document for Leachable Toxic Waste and Disposal (GD-PPD-26.1)</p> <p>Interprovincial Movement of Hazardous Waste Regulations (SOR/2002-301)</p> <p>PCB Regulations (SOR/2008-273)</p> <p>PCB Waste Export Regulations (SOR/97-109)</p> <p>Regulations Amending the PCB Regulations (SOR/2010-57)</p> | <p>Fluorescent light fixtures are present inside accommodations cabin. The ballast of the fluorescent light fixtures may contain PCBs.</p> | <p>Any PCB-containing materials and equipment should be handled, decontaminated, transported and disposed of as per current Federal and Provincial acts and regulations.</p> <p>Any PCB-containing materials and equipment requiring removal from the building should be transported and disposed of by a registered hazardous waste transporter in accordance with applicable regulations.</p> <p>The transportation and disposal of PCB containing materials and equipment should be conducted in accordance with the Federal TDG Act and with SOPs for disposal of hazardous waste at the disposal or recycling facility.</p> |
| <b>Silica-Containing Materials</b>                   | <p>NL OHS Act (RSNL1990 Chapter O-3)</p> <p>NL OHS Regulations (5/12)</p>  | <p>Asphalt shingles, brick and concrete.</p>   | <p>These materials can be disposed of at a Regional Solid Waste Disposal Facility (landfill).</p>  |
| <b>Potential Radioactive Materials</b>               | <p>Federal TDG Act (1992, c. 34)</p>   | <p>None identified.</p>  | <p>Smoke detectors that contain low level radioactive materials must be transported, as per Federal TDG Regulations, to a licensed disposal facility.</p>  |

**APPENDIX A7**

**FIGURES**



**NOTES:**

1. ALL DIMENSIONS ARE IN METERS.
2. DO NOT SCALE FROM FIGURE.
3. THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.
4. ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.
5. THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.
6. THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:



newfoundland labrador  
**hydro**  
a nalcor energy company

**Wood**  
Environment & Infrastructure Solutions  
133 Crosbie Road  
St. John's, NL A1B 4A5  
709-722-7023



Drawn by:  
T. Rideout

Approved by:  
C. Finney

Scale:  
As Shown

Project:  
Pre-Demolition Hazardous Building Materials Assessment,  
Former Construction Camp Sites,  
Bay d'Espoir - Avalon Transmission Line, NL


Title:  
Site Location Plan (Aerial) - Medonnegonik Lake Camp Site

Date:  
April 2019

Project No.  
TF18104243.2000

Rev. No.  
0

Figure No.  
7.1



**LEGEND:**

- ASBESTOS SAMPLE LOCATION - ASBESTOS NOT DETECTED
- ASBESTOS SAMPLE LOCATION - RESULTS < 1% FOR ASBESTOS
- ▲ PAINT SAMPLE LOCATION - NO CRITERIA EXCEEDANCES FOR LEAD OR MERCURY OR PCBs WHERE APPLICABLE
- ▲ PAINT SAMPLE LOCATION - RESULTS EXCEED 90 mg/kg AND LESS THAN 5000 mg/kg FOR LEAD AND NO CRITERIA EXCEEDANCES FOR MERCURY OR PCBs WHERE APPLICABLE
- SPARSE MOULD GROWTH DETECTED
- ⊙ TREATED WOOD SAMPLE LOCATION

**NOTES:**

- ALL DIMENSIONS ARE IN METERS.
- DO NOT SCALE FROM FIGURE.
- THIS FIGURE IS INTENDED TO SHOW RELATIVE LOCATIONS AND CONFIGURATION OF THE STUDY AREA IN SUPPORT OF THIS REPORT.
- ALL LOCATIONS, DIMENSIONS, AND ORIENTATIONS ARE APPROXIMATE.
- THIS FIGURE SHOULD NOT BE USED FOR PURPOSES OTHER THAN THOSE OUTLINED ABOVE.
- THIS FIGURE CONTAINS INTELLECTUAL PROPERTY OF NEWFOUNDLAND LABRADOR HYDRO AND MAY NOT BE REPRODUCED OR COPIED WITHOUT THEIR WRITTEN CONSENT.

Client:

**Wood**  
 Environment & Infrastructure Solutions  
 133 Crosbie Road  
 St. John's, NL A1B 4A5  
 709-722-7023

Drawn by:  
T. Rideout

Approved by:  
C. Finney

Scale:  
As Shown

Project:  
Pre-Demolition Hazardous Building Materials Assessment,  
Former Construction Camp Sites,  
Bay d'Espoir - Avalon Transmission Line, NL

Title:  
Sample Location Plan - Medonnegonik Lake Camp Site

Date:  
April 2019

Project No.  
TF18104243.2000

Rev. No.  
0

Figure No.  
7.2

**APPENDIX B7**  
**PHOTOGRAPHIC RECORD**



Photo 1: View of the accommodations cabin at Medonnegonik Camp, looking south.




Photo 2: View of the accommodations cabin at Medonnegonik Camp, looking south.



Photo 3: View of the accommodations cabin at Medonnegonik Camp, looking east.



Photo 4: View of the accommodations cabin at Medonnegonik Camp, looking northwest.



Photo 5: View of the entryway/kitchen area at Medonnegonik Camp.



Photo 6: View of the kitchen/bunk area at Medonnegonik Camp.



Photo 7: View of the kitchen area at Medonnegonik Camp.



Photo 8: View of the bathroom at Medonnegonik Camp.



Photo 9: View of the outhouse at Medonnegonik Camp.



Photo 10: View of the outhouse at Medonnegonik Camp.



Photo 11: View of cavity inspection in wall of accommodations cabin at Medonnegonik Camp.



Photo 12: View of cavity inspection in the floor of the accommodations cabin at Medonnegonik Camp.





Photo 13: View of helipad adjacent to the accommodations cabin at Medonnegonik Camp.



Photo 14: View of bulk material sample MDX-AS1, black paper on fibreglass insulation, Room 1.



Photo 15: View of bulk material sample MDX-AS2, black pressboard and tar paper, Room 1.



Photo 16: View of bulk material sample MDX-AS3, grey mortar, cabin exterior.



Photo 17: View of bulk material sample MDX-AS4, red brick, cabin exterior.



Photo 18: View of bulk material sample MDX-AS5, concrete block, cabin exterior.



Photo 19: View of bulk material sample MDX-AS6, grey mortar, cabin exterior.



Photo 20: View of bulk material sample MDX-AS7, white caulking, cabin exterior.



Photo 21: View of bulk material sample MDX-AS8, brown brick, cabin exterior.



Photo 22: View of bulk material sample MDX-AS9, grey mortar, cabin exterior.



Photo 23: View of bulk material sample MDX-AS10, black shingle and tar, cabin exterior.



Photo 24: View of bulk material sample MDX-AS11, green/black shingle and tar, cabin exterior.



Photo 25: View of bulk material sample MDX-PP-AS1, black shingle and tar, outhouse exterior.



Photo 26: View of paint sample MDX-PS1, white, cabin interior.



Photo 27: View of paint sample MDX-PS2, grey, cabin exterior.



Photo 28: View of paint sample MDX-PS3, grey, cabin interior.



Photo 29: View of paint sample MDX-PP-PS1, grey, cabin exterior.



Photo 30: View of mould sample MDX-MS-1, cabin interior.



Photo 31: View of treated wood sample MDX-TW1, heli-pad.



Photo 32: View of freezer, containing R12 reffridgerant, cabin interior.

**APPENDIX C7**

**SAMPLE AND ANALYTICAL SUMMARY TABLES**

**Table C7-1: Bulk Sample Descriptions and Asbestos Analytical Results (Medonnegonik Camp Site)**

| Sample ID  | Room No. | Room Description | Photo No. | Sample Location | Sample Description                        | Layers Analyzed            | Analytical Result   |
|------------|----------|------------------|-----------|-----------------|---|----------------------------|---------------------|
| MDX-AS1    | 1        | Kitchen          | 14        | Wall            | Black paper on pink fibreglass insulation | Black paper and insulation | ND                  |
| MDX-AS2    | 1        | Kitchen          | 15        | Wall            | Black pressboard and tar paper            | Pressboard and tar paper   | ND                  |
| MDX-AS3    | Exterior | Exterior         | 16        | Wall            | Grey mortar (on red brick)                | Mortar                     | ND                  |
| MDX-AS4    | Exterior | Exterior         | 17        | Wall            | Red brick                                 | Brick                      | ND                  |
| MDX-AS5    | Exterior | Exterior         | 18        | Foundation      | Concrete block                            | Concrete block             | ND                  |
| MDX-AS6    | Exterior | Exterior         | 19        | Foundation      | Grey mortar (on concrete block)           | Mortar                     | ND                  |
| MDX-AS7    | Exterior | Exterior         | 20        | Wall            | White caulking (on brown brick)           | Caulking                   | ND                  |
| MDX-AS8    | Exterior | Exterior         | 21        | Wall            | Brown brick                               | Brick                      | ND                  |
| MDX-AS9    | Exterior | Exterior         | 22        | Foundation      | Grey mortar (on brown brick)              | Mortar                     | ND                  |
| MDX-AS10   | Exterior | Exterior         | 23        | Roof            | Black shingle and tar                     | Shingle and tar            | ND                  |
| MDX-AS11   | Exterior | Exterior         | 24        | Roof            | Green/black shingle and tar               | Shingle and tar            | ND                  |
| MDX-PP-AS1 | Exterior | Exterior         | 25        | Roof            | Black shingle and tar                     | Shingle and tar            | <b><u>0.79%</u></b> |

**Notes:**

ACM: Asbestos-Containing Material

DJC: Drywall Joint Compound

VFT: Vinyl Floor Tile

VSF: Vinyl Sheet Flooring

ND: Non-Detect (<0.1%)

\*Brown paper and tar analyzed as one layer because the laboratory could not separate these materials.

**Bold and underlined value indicates asbestos was detected but is below 1% by dry weight.**

**Shaded value exceeds 1% asbestos by dry weight and is considered to be an ACM as outlined in the Newfoundland and Labrador Asbestos Abatement Regulations (Reg. 111/98).**

**Table C7-2: Paint Sample Descriptions and Lead Analytical Results (Medonnegonik Camp Site)**

| Sample ID  | Room No. | Room Description | Photo No. | Sample Location | Substrate | Sample Description                         | RDL (mg/kg) | Lead (mg/kg)        |
|------------|----------|------------------|-----------|-----------------|-----------|--|-------------|---------------------|
| MDX-PS1    | 1        | Kitchen          | 26        | Wall            | Plywood   | White on plywood (sample includes plywood) | 5.0         | <b><u>185</u></b>   |
| MDX-PS2    | Exterior | Exterior         | 27        | Exterior        | Metal     | Grey on metal door                         | 5.0         | <b><u>1,110</u></b> |
| MDX-PS3    | 1        | Kitchen          | 28        | Interior        | Concrete  | Grey on floor (sample includes plywood)    | 5.0         | <b><u>725</u></b>   |
| MDX-PP-PS1 | Exterior | Outhouse         | 29        | Wall            | Plywood   | Grey on plywood (sample includes plywood)  | 5.0         | <b><u>109</u></b>   |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

**Bold and underlined value exceeds Federal HPA criterion (90 mg/kg).**

**Shaded value exceeds former Federal HPA criterion (5,000 mg/kg).**



**Table C7-3: Paint Sample Descriptions and Mercury Analytical Results (Medonnegonik Camp Site)**

| Sample ID  | Room No. | Room Description | Photo No. | Sample Location | Substrate | Sample Description                         | RDL (mg/kg) | Mercury (mg/kg) |
|------------|----------|------------------|-----------|-----------------|-----------|--|-------------|-----------------|
| MDX-PS1    | 1        | Kitchen          | 26        | Wall            | Plywood   | White on plywood (sample includes plywood) | 5.0         | <u>7.87</u>     |
| MDX-PS2    | Exterior | Exterior         | 27        | Exterior        | Metal     | Grey on metal door                         | 5.0         | 0.14            |
| MDX-PS3    | 1        | Kitchen          | 28        | Interior        | Concrete  | Grey on floor (sample includes plywood)    | 5.0         | 1.42            |
| MDX-PP-PS1 | Exterior | Outhouse         | 29        | Wall            | Plywood   | Grey on plywood (sample includes plywood)  | 5.0         | 0.06            |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

HPA: Hazardous Products Act

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

**Bold and underlined value exceeds Federal HPA criterion (10 mg/kg).**

Shaded value exceeds CCME CSQG for an industrial site (50 mg/kg).

**Table C7-4: Paint Sample Descriptions and PCB Analytical Results (Medonnegonik Camp Site)**

| Sample ID  | Room No. | Room Description | Photo No. | Sample Location | Substrate | Sample Description                         | RDL (mg/kg) | Total PCB (mg/kg) |
|------------|----------|------------------|-----------|-----------------|-----------|--|-------------|-------------------|
| MDX-PS1    | 1        | Kitchen          | 26        | Wall            | Plywood   | White on plywood (sample includes plywood) | 0.5         | <0.5              |
| MDX-PS2    | Exterior | Exterior         | 27        | Exterior        | Metal     | Grey on metal door                         | 0.5         | <0.5              |
| MDX-PS3    | 1        | Kitchen          | 28        | Interior        | Concrete  | Grey on floor (sample includes plywood)    | 0.5         | <0.5              |
| MDX-PP-PS1 | Exterior | Outhouse         | 29        | Wall            | Plywood   | Grey on plywood (sample includes plywood)  | 0.5         | <0.5              |

**Notes:**

<X: Non-Detect

RDL: Reportable Detection Limit

CCME: Canadian Council of Ministers of the Environment

CSQG: Canadian Soil Quality Guideline

NL MAE: Newfoundland and Labrador Department of Municipal Affairs and Environment

TDG: Transportation of Dangerous Goods

\*Sample collected by Hydro on May 5, 2018.

**Bold and underlined value exceeds CCME CSQG for an industrial site (33 mg/kg).**

Shaded value exceeds the criterion for PCB solid provided in the NL MAE Leachable Toxic Waste, Testing and Disposal Guidance Document and the TDG Regulations (50 mg/kg).

**Table C7-5: Bulk Sample Descriptions and Mould Analytical Results (Medonnegonik Camp Site)**

| Sample ID | Detailed Material Description | Sample Location | Mould Identified               | Analytical Result |
|-----------|-------------------------------|-----------------|--------------------------------|-------------------|
| MDX-MS1   | Tape lift on wall             | Room 3          | <i>Cladosporium Acremonium</i> | Sparse            |

**Notes:**

1. Mould growth is subjectively assessed with description terms sparse, moderate and abundant.
2. The presence of spores (lacking other fungal structures associated) is assessed as following: a few spores (< 10 spores average per microscopic field at 400X), some spores (10 - 100 spores average per microscopic field at 400X), many spores (> 100 spores average per microscopic field at 400X).
3. The presence of a few spores generally represents settled spores on the surface of the sample rather than indicating mould growth.

**Table C7-6: Bulk Sample Descriptions and Leachable Treated Wood Parameter Analytical Results (Medonnegonik Camp Site)**

|                                      |                   | Data         | Guidelines   |  |  |
|--------------------------------------|-------------------|--------------|--|--|--|
| <b>Sample ID</b>                     |                   | MDX-TW1      | ENVC Guidance Document<br>Treated Wood Waste Disposal<br>Amended September 2015 (GD-PPD-075.1) |  | ENVC Guidance Document<br>Leachable Toxic Waste, Testing and Disposal<br>Revised November 2003 (GD-PPD-26.1) |
| <b>Sample Location and Room No.</b>  |                   | Helipad      |  |  |  |
| <b>Detailed Material Description</b> |                   | Treated Wood |  |  |  |
| <b>Location (Photo No.)</b>          |                   | 31           |  |  |  |
| <b>Parameters</b>                    | <b>RDL (µg/L)</b> | (µg/L)       | Column 2: TCLP<br>Limits (CEPA) (µg/L)   | Column 3: Double<br>TCLP Limits (µg/L) | Schedule II (Interprovincial Movement of<br>Hazardous Waste Regulations (pending)) (µg/L)                    |
| Leachable Benzo(a)pyrene             | 0.001             | <0.001       | 1  | 2                                      | 1  |
| Leachable m/p-Cresol                 | 0.0               | <0.008       | -  | -                                      | 200,000  |
| Leachable o-Cresol                   | 0.0               | <0.004       | -  | -                                      | 200,000  |
| Leachable Cresol Total               | 0.0               | <0.012       | 200,000  | 400,000                                | 200,000  |

**Notes:**

RDL: Reportable detection limit

ENVC: Newfoundland and Labrador Department of Environment and Conservation

TCLP: Toxicity Characteristic Leaching Procedure

CEPA: Canadian Environmental Protection Act

TWW: Treated Wood Waste

-: Value Not Established

Shaded results indicate that TCLP concentration exceeds Column 2 TCLP limits provided in the TWW Disposal Guidance Document.

**Bold results indicate that TCLP concentration exceeds Schedule II TCLP limits provided in the Leachable Toxic Waste Guidance Document.**

Underlined results indicate that TCLP concentration exceeds Column 3 TCLP limits provided in the TWW Disposal Guidance Document.

**APPENDIX D7**

**ROOM-BY-ROOM INSPECTION SHEETS**

| Building | Room # | Floor # | Room Description | Dimensions                |
|----------|--------|---------|------------------|---------------------------|
| MDX      | 1      | 1       | Kitchen          | L = 24'<br>W = 18'<br>H = |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|--|--|---------------------------|--|
| <b>Floor</b>  | Wood   |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | Wood:<br>Ply. board type sheeting @ paper backing  |  |                           | MDX-AS-2                                       |
| <b>Ceiling</b>  | Wood:  |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls: Beige<br>Ceiling: Beige<br>Floor: Grey<br>Other: Grey on Metal door                   |  |                           | MDX-PS-1<br>MDX-PS-3<br>MDX-PS-2               |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Pink fibreglass @ paper backing<br>Fire Door Manufacturer:<br>Fire Door Serial #:            |  |                           | MDX-AS-1                                       |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —  |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #: 2 → 2bulb   | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 4 → incandescent   |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 |  |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>Potential mould.  |  |                           | MDX-MS-1                                       |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>Dandy fridge, R12, Model D730, Type HDS  |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9'); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                  |
|----------|--------|---------|------------------|-----------------------------|
| MDX      | 2      | 1       | Pantry           | L = 12'<br>W = 8'<br>H = 8' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|--|--|----------------------------|--|
| <b>Floor</b>  | Wood   |  |                            |  |
| <b>Walls</b><br>(include window caulking)   | Wood   |  |                            |  |
| <b>Ceiling</b>  | Wood   |  |                            |  |
| <b>Paint</b><br>(and substrate)   | Walls:<br>Ceiling: Same as 1<br>Floor:<br>Other:   |  |                            |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer: —<br>Fire Door Serial #:   |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —  |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #: —   | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | (  |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —  |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>Potential. Floors collapsed.<br>Mould                                       |  |                            |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—  |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                  |
|----------|--------|---------|------------------|-----------------------------|
| MDX      | 3      | 1       | Room / Porch     | L = 12'<br>W = 8'<br>H = 8' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|--|--|----------------------------|--|
| <b>Floor</b>  | Wood   |  |                            |  |
| <b>Walls</b><br>(include window caulking)   | Wood   |  |                            |  |
| <b>Ceiling</b>  | Wood   |  |                            |  |
| <b>Paint</b><br>(and substrate)   | Walls:<br>Ceiling:<br>Floor:<br>Other:<br>Same as 1  |  |                            |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:   |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —  |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>—  | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 1  |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —  |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>Mould   |  |                            | MDX-MS-1                                       |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>deep freeze.   |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**



| Building | Room # | Floor # | Room Description | Dimensions                  |
|----------|--------|---------|------------------|-----------------------------|
| MDX      | 4      | 1       | Room             | L = 12'<br>W = 8'<br>H = 8' |

|   | Description   | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)  | Samples Collected<br>(actual/visual reference) |
|---|---|--|----------------------------|--|
| <b>Floor</b>  | Wood  |  |                            |  |
| <b>Walls</b><br>(include window caulking)   | Wood  |  |                            |  |
| <b>Ceiling</b>  | Wood.   |  |                            |  |
| <b>Paint</b><br>(and substrate)   | Walls:<br>Ceiling: Same as /<br>Floor:<br>Other:  |  |                            |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:  |  |                            |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  | —   |  |                            |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:<br>—   | Leaking / Other  | # Total:<br><br># Checked: | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   | 1   |  |                            |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                       | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                            |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 | —   |  |                            |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted<br>Mould Potential  |  |                            |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext<br>—   |  |                            |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials<br>— |  |                            |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                |
|----------|--------|---------|------------------|---------------------------|
| MDX      | 4      |         | Exterior         | L = 30'<br>W = 24'<br>H = |

|  | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total)                              | Samples Collected<br>(actual/visual reference) |
|--|--|--|--|--|
| <del>Floor</del><br>Foundation   | cinder block   |  | Block<br>Mortar  | MDX-AS5<br>MDX-AS6                             |
| Walls<br>(include window<br>caulking)  | Red brick & grey mortar 1/2  |  | Mortar<br>Red Brick                                    | MDX-AS3<br>MDX-AS4                             |
|  | Brown brick & grey mortar 1/2<br>(New 1999)  |  | Brown Brick<br>Mortar                                  | MDX-AS8<br>MDX-AS9                             |
| <del>Ceiling</del><br>Roof   | Black shingles on 1/2<br>Green/black shingles on 1/2   |  | Black Shingles<br>& Tar<br><br>Green Shingles<br>& Tar | MDX-AS10<br><br>MDX-AS11                       |
| Paint<br>(and substrate)   | Walls: Caulking white<br>Ceiling:<br>Floor:<br>Other:  |  |  | MDX-AS7  |
| Insulation<br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:   |  |  |  |
| Piping /<br>Mechanical<br>Equipment  |  |  |  |  |
| Fluorescent<br>Lighting  | Ballast Manufacturer:<br>Serial #:   | Leaking / Other  | # Total:<br><br># Checked:                             | Suspect PCBs:                                  |
| Other Lighting<br>(e.g., incandescent,<br>HID)                                   |  |  |  |  |
| Thermostats  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |  |  |
| LCMs<br>(soldering pipes<br>batteries, exit/emerg<br>lighting,                   |  |  |  |  |
| Mould / Water<br>Staining  | Area impacted  |  |  |  |
| ODS<br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext   |  |  |  |
| Other / Photos   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |  |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

| Building | Room # | Floor # | Room Description | Dimensions                 |
|----------|--------|---------|------------------|----------------------------|
| MDx      |        |         | Outhouse         | L = 6'<br>W = 5'<br>H = 7' |

|   | Description  | Condition<br>(good/fair/poor)                            | Quantity<br>(SF/LF/total) | Samples Collected<br>(actual/visual reference) |
|---|--|--|---------------------------|--|
| <b>Floor</b>  | Wood   |  |                           |  |
| <b>Walls</b><br>(include window caulking)   | Wood (Int+Ext)   |  |                           |  |
| <b>Ceiling</b>  | Wood<br>black shingles   |  |                           |  |
| <b>Paint</b><br>(and substrate)   | Walls: Gray<br>Ceiling:<br>Floor:<br>Other:  |  |                           |  |
| <b>Insulation</b><br>(Piping/Mechanical/<br>Wall/Ceiling/Ducting)                       | Fire Door Manufacturer:<br>Fire Door Serial #:   |  |                           |  |
| <b>Piping /<br/>Mechanical<br/>Equipment</b>  |  |  |                           |  |
| <b>Fluorescent<br/>Lighting</b>   | Ballast Manufacturer:<br>Serial #:   | Leaking / Other  | # Total:<br># Checked:    | Suspect PCBs:                                  |
| <b>Other Lighting</b><br>(e.g., incandescent,<br>HID)                                   |  |  |                           |  |
| <b>Thermostats</b>  | Manufacturer<br>Colour, Shape<br>Wall/Floor Mounted<br>Dial                                  | Casing<br># Observed<br># Checked<br>Mercury switch: Y/N |                           |  |
| <b>LCMs</b><br>(saudering, pipes<br>batteries, exit/ emerg<br>lighting,                 |  |  |                           |  |
| <b>Mould / Water<br/>Staining</b>   | Area impacted  |  |                           |  |
| <b>ODS</b><br>ODSs (e.g.,<br>refrigerator, drinking<br>fountain, fire<br>extinguishers) | Fire ext   |  |                           |  |
| <b>Other / Photos</b>   | e.g. Treated timber, UFFI, CO, VOCs, furnace, ASTs, USTs, drums, silica-containing materials |  |                           |  |

**Legend:** PS (paint sample); VPS (visual reference to PS); AS (asbestos sample); VAS (visual reference to AS); FS (fungal sample); LCM (lead-containing material); ACM (asbestos-containing material); DJC (drywall joint compound); VFT (vinyl floor tile – specify 1 x 1', 9 x 9"); ACT (acoustic ceiling tile – specify pattern e.g. speckled); LF (linear feet); SF (square feet).

**Notes/Comments:**

## TABLE OF CONTENTS

|            |                                      |            |
|------------|--------------------------------------|------------|
| <b>8.0</b> | <b>CLOSURE AND LIMITATIONS .....</b> | <b>8-1</b> |
| 8.1        | QA/QC DISCUSSION.....                | 8-1        |
| 8.1.1      | Surrogate Recoveries.....            | 8-1        |
| 8.1.2      | Laboratory Method Blank Samples..... | 8-1        |
| 8.1.3      | Laboratory Duplicates .....          | 8-1        |
| 8.1.4      | Summary of QA/QC Discussion .....    | 8-1        |
| 8.2        | CLOSURE .....                        | 8-2        |
| 8.3        | REFERENCES.....                      | 8-4        |

## APPENDICES

|             |                                     |
|-------------|-------------------------------------|
| APPENDIX A8 | Laboratory Certificates of Analyses |
| APPENDIX B8 | Report Limitations                  |

## **8.0 CLOSURE AND LIMITATIONS**

### **8.1 QA/QC DISCUSSION**

Details regarding the QC assessment of surrogate recoveries, laboratory blank and laboratory duplicate samples are presented in this section. The QA/QC results are reported on the laboratory certificates of analyses included in Appendix A8.

#### **8.1.1 Surrogate Recoveries**

The surrogate (chrysene-d12) recoveries (69% to 99%) for the treated wood sample analyzed for SVOC's were within the laboratory's acceptable QC limit of 50% - 130% (refer to Appendix A8).

The surrogate (decachlorobiphenyl) recoveries (77% to 123%) for the paint samples analyzed for PCBs were within the laboratory's acceptable QC limits of 50% to 130% (refer to Appendix A8).

#### **8.1.2 Laboratory Method Blank Samples**

Laboratory method blank samples were analyzed for mercury, PCBs, cresols, ortho-cresol, meta & para-cresol and/or benzo(a)pyrene. The purpose of the laboratory blank samples were to assess the quality of the laboratory results with respect to the presence/absence of instrument cross contamination at the laboratory.

Analysis of the laboratory blank samples indicated non-detectable concentrations; therefore, no evidence of cross contamination at the laboratory was identified during the laboratory analytical program (refer to Appendix A8).

#### **8.1.3 Laboratory Duplicates**

The analytical data for the laboratory duplicate and original paint samples analyzed for, mercury, PCBs, cresols, ortho-cresol, meta & para-cresol and/or benzo(a)pyrene were compared as relative percent differences (RPDs). Generally, these evaluations are only applicable when both results are at least five times the reporting limit. RPD values less than 35% are acceptable for lead, mercury, PCBs, cresols, ortho-cresol, meta & para-cresol and benzo(a)pyrene.

The RPDs were not calculable (i.e., concentrations less than five times the reporting limit) for lead, mercury, PCBs, cresols, ortho-cresol, meta & para-cresol and benzo(a)pyrene and not calculable (i.e., concentrations less than two times the reporting limit) (refer to Appendix A8).

#### **8.1.4 Summary of QA/QC Discussion**

Overall, based on these QC reviews, the analytical results are considered representative of the site conditions in the immediate vicinity of the sample locations.

## 8.2 CLOSURE

This report was prepared for the exclusive use of Newfoundland and Labrador Hydro, a Nalcor Energy Company. The findings of this report are based solely on the conditions of the site buildings encountered at the time of the site visit, and are limited by the availability of information at the time of the Pre-Demolition HBMA, lack of accessibility to areas within the buildings, project scope and budget. The findings of this assessment are based on the interpretation of data from a limited number of areas investigated and analytical results pertaining to specific samples. It is possible that materials exist which could not be reasonably identified within the scope of the Pre-Demolition HBMA or which were not apparent or accessible during the site visit. This Report is also subject to the further limitations contained in Appendix B8.

Any use which a third party makes of this report, or any reliance on or decisions to be made based on it, are the responsibility of the third party. Should additional parties require reliance on this report, written authorization from Wood is required. With respect to third parties, Wood has no liability or responsibility for losses of any kind whatsoever, including direct or consequential financial effects on transactions or property values, or requirements for follow-up actions and costs. This assessment has been carried out using commercially reasonable best efforts consistent with the level and skill ordinarily exercised by members of the profession currently practicing under similar conditions.

Except when otherwise specified, Wood disclaims any obligation to update this report for events taking place, or with respect to information that becomes available to Wood after the time during which Wood conducted the hazardous building materials assessment.

In evaluating the property, Wood has relied in good faith on information provided by other individuals noted in this report. Wood has assumed that the information provided is factual and accurate. In addition, some of the findings in this report are based upon information provided by the current owner/occupant. Wood accepts no responsibility for any deficiency, misstatement or inaccuracy contained in this report as a result of omissions, misinterpretations or fraudulent acts of persons interviewed or contacted.

Wood makes no other representations whatsoever, including those concerning the legal significance of its findings, or as to other legal matters touched on in this report, including, but not limited to, ownership of any property, or the application of any law to the facts set forth herein. With respect to regulatory compliance issues, regulatory statutes are subject to interpretation and change. Such interpretations and regulatory changes should be reviewed with legal counsel.

We trust that the information presented in this report meets your current requirements. Should you have any questions, or concerns, please do not hesitate to contact the undersigned.

Respectfully Submitted,

**Wood Environment & Infrastructure Solutions,  
A Division of Wood Canada Limited**

**Prepared By:**



Cheryl Finney, B.Tech., P.Tech.  
Environmental Scientist

**Project Manager:**



Lori Wiseman, P.Eng.  
Senior Geo-Environmental Engineer

**Reviewed By:**



Gary Warren, M.A.Sc.  
Senior Environmental Scientist

### 8.3 REFERENCES

Agency for Toxic Substances and Disease Registry. May 2015. Formaldehyde - ToxFAQs™. <https://www.atsdr.cdc.gov/toxfaqs/tfacts111.pdf>

Canada Mortgage Housing Corporation. 2000. Urea-Formaldehyde Foam Insulation (UFFI). <http://publications.gc.ca/collections/Collection/NH18-24-6E.pdf>

Canadian Construction Association. 2004. Mould Guidelines for the Canadian Construction Industry. <http://www.cca-acc.com/wp-content/uploads/2016/10/PreviewCCA82.pdf>

Canadian Council of Ministers of the Environment. 1999 and various updates. Canadian Environmental Quality Guidelines. <http://ceqg-rcqe.ccme.ca/?config=ccme&thesite=ceqg&words=&image.x=11&image.y=10>

Canadian Council of Ministers of the Environment. 1999 and various updates. Canadian Soil Quality Guidelines for the Protection of Environmental and Human Health. <http://ceqg-rcqe.ccme.ca/?config=ccme&thesite=ceqg&words=&image.x=11&image.y=10>

Canadian Nuclear Association. October 2009. Nuclear Facts: How is nuclear technology used in smoke detectors? <http://teachnuclear.ca/wp-content/uploads/2013/05/18-NuclearFacts-smokedetectors.pdf>

Environmental Abatement Council of Ontario. 2015. Mould Abatement Guidelines, Edition 3. [http://www.eacoontario.com/pdf/2015/EACO\\_Mould\\_Guideline\\_April\\_2015.pdf](http://www.eacoontario.com/pdf/2015/EACO_Mould_Guideline_April_2015.pdf)

Environment Canada. Identification of light Ballast Containing PCBs. Environment Canada's Environmental Protection Series Report (EPS 2/CC/2, August 1991).

Government of Canada. Canadian Environmental Protection Act, 1999 (S.C. 1999, c. 33). <http://laws-lois.justice.gc.ca/eng/acts/C-15.31/>

Government of Canada. Export and Import of Hazardous Waste and Hazardous Recyclable Material Regulations (SOR/2005-149). <http://laws-lois.justice.gc.ca/eng/regulations/SOR-2005-149/index.html>

Government of Canada. Federal Halocarbon Regulations, 2003 (SOR/2003-289). <http://laws.justice.gc.ca/eng/regulations/SOR-2003-289/index.html>

Government of Canada. Hazardous Products Act (R.S.C., 1985, c. H-3). <http://laws-lois.justice.gc.ca/eng/acts/H-3/>

Government of Canada. Interprovincial Movement of Hazardous Waste Regulations (SOR/ 2002-301). <http://laws-lois.justice.gc.ca/eng/regulations/SOR-2002-301/index.html>

Government of Canada. Ozone-depleting Substances Regulations and Halocarbon Alternatives Regulations (SOR/2016-137). <http://laws-lois.justice.gc.ca/eng/regulations/SOR-2016-137/>



Government of Canada. PCB Regulations (SOR/2008-273). <http://laws-lois.justice.gc.ca/eng/regulations/SOR-2008-273/index.html>

Government of Canada. PCB Waste Export Regulations, 1996 (SOR/97-109). <http://laws-lois.justice.gc.ca/eng/regulations/SOR-97-109/index.html>

Government of Canada. Products Containing Mercury Regulations (SOR/2014-254). <http://laws.justice.gc.ca/eng/regulations/SOR-2014-254/>

Government of Canada. Regulations Amending the PCB Regulations (SOR/2010-57). <http://canadagazette.gc.ca/rp-pr/p2/2010/2010-03-31/html/sor-dors57-eng.html>

Government of Canada. Surface Coating Materials Regulations (SOR/2016-193). <http://laws-lois.justice.gc.ca/eng/regulations/SOR-2016-193/index.html>

Government of Canada. Transportation of Dangerous Goods Act, 1992 (1992, c. 34). <http://www.tc.gc.ca/eng/acts-regulations/acts-1992c34.htm>

Government of Canada. Transportation of Dangerous Goods Regulations (SOR/2012-245). <http://www.tc.gc.ca/eng/tdg/clear-menu-497.htm>

Government of Newfoundland and Labrador. Asbestos Abatement Regulations (111/98). <http://assembly.nl.ca/Legislation/sr/regulations/rc980111.htm>

Government of Newfoundland and Labrador. Dangerous Goods Transportation Act (RSNL1990 Chapter D-1). <http://assembly.nl.ca/legislation/sr/statutes/d01.htm>

Government of Newfoundland and Labrador. Dangerous Goods Transportation Regulations (5/96). <http://www.assembly.nl.ca/Legislation/sr/Regulations/rc960005.htm>

Government of Newfoundland and Labrador. Environmental Protection Act (SNL2002 cE-14.2). <http://www.assembly.nl.ca/legislation/sr/statutes/e14-2.htm>

Government of Newfoundland and Labrador. Halocarbon Regulations (41/05). <http://www.assembly.nl.ca/legislation/sr/regulations/rc050041.htm>

Government of Newfoundland and Labrador, Department of Environment, Pollution Prevention Division. Guidance Document, Leachable Toxic Waste, Testing and Disposal (2003, GD-PPD-26.1).

Government of Newfoundland and Labrador, Department of Environment and Conservation. Guidance Document for the Management of Impacted Sites (2014, Version 2.0).

Government of Newfoundland and Labrador, Department of Environment and Conservation, Pollution Prevention Division. Guidance Document for Treated Wood Waste Disposal (2015, GD-PPD-075.1).

Government of Newfoundland and Labrador. Occupational Health and Safety Act (RSNL1990 Chapter O-3). <http://assembly.nl.ca/legislation/sr/statutes/o03.htm>

Government of Newfoundland and Labrador. Occupational Health and Safety Regulations (5/12). <http://www.assembly.nl.ca/legislation/sr/regulations/rc120005.htm>

Government of Newfoundland and Labrador. Storage and Handling of Gasoline and Associated Products Regulations (58/03). <http://www.assembly.nl.ca/legislation/sr/regulations/rc030058.htm>

Government of Newfoundland and Labrador. Storage of PCB Wastes Regulations (61/03). <http://www.assembly.nl.ca/legislation/sr/annualregs/2003/Nr030061.htm>

Health Canada. February 2017. Guidelines for Canadian Drinking Water Quality Summary Table. [http://www.hc-sc.gc.ca/ewh-semt/alt\\_formats/pdf/pubs/water-eau/sum\\_guide-res\\_recom/sum\\_guide-res\\_recom-eng.pdf](http://www.hc-sc.gc.ca/ewh-semt/alt_formats/pdf/pubs/water-eau/sum_guide-res_recom/sum_guide-res_recom-eng.pdf)

National Institute of Building Sciences. 1995. Lead-Based Paint Operations and Maintenance Work Practices Manual for Homes and Buildings.

National Research Council Canada. National Plumbing Code of Canada.

United States Environmental Protection Agency. March 2017. Formaldehyde. <https://www.epa.gov/formaldehyde>

**APPENDIX A8**

**LABORATORY CERTIFICATES OF ANALYSES**

**Camp #1 COAs**

**CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of  
Wood Canada Ltd.  
36 PIPPY PLACE  
St. John's, NL A1B4A5  
(709) 722-5062**

**ATTENTION TO: Lori Wiseman**

**PROJECT: TF18104243**

**AGAT WORK ORDER: 18K378239**

**SOIL ANALYSIS REVIEWED BY: Laura Baker, Inorganics Data Reporter**

**TRACE ORGANICS REVIEWED BY: Amy Hunter, Trace Organics Supervisor, B.Sc.**

**DATE REPORTED: Sep 05, 2018**

**PAGES (INCLUDING COVER): 8**

**VERSION\*: 1**

Should you require any information regarding this analysis please contact your client services representative at (709)747-8573

**\*NOTES**

**All samples will be disposed of within 30 days following analysis. Please contact the lab if you require additional sample storage time.**



## Certificate of Analysis

AGAT WORK ORDER: 18K378239

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
 St. John's, NL  
 CANADA A1E 6A8  
 TEL (709)747-8573  
 FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

### Lead In Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-08-31

| Parameter         | Unit  | SAMPLE DESCRIPTION: |        | C1-PS1     | C1-PS2  | C1-PS3  | C1-PS4  | C1-PS5  | C1-PS6  | C1-PP-PS1 | C1-PP-PS2 |
|-------------------|-------|---------------------|--------|------------|---------|---------|---------|---------|---------|-----------|-----------|
|                   |       | G / S               | RDL    | 9501085    | 9501086 | 9501087 | 9501088 | 9501089 | 9501090 | 9501091   | 9501092   |
| Lead in Paint     | mg/kg | 15                  | 60     | 60         | 57      | 36      | 194     | 300     | 259     | 319       | 122       |
| Total Sample Mass | g     |                     | 0.5030 | 0.4972     | 0.2125  | 0.4995  | 0.4934  | 0.5076  | 0.5033  | 0.4964    |           |
|                   |       | SAMPLE DESCRIPTION: |        | C1-PP-PS3  |         |         |         |         |         |           |           |
|                   |       | SAMPLE TYPE:        |        | Paint      |         |         |         |         |         |           |           |
|                   |       | DATE SAMPLED:       |        | 2018-08-13 |         |         |         |         |         |           |           |
| Parameter         | Unit  | G / S               | RDL    | 9501093    |         |         |         |         |         |           |           |
| Lead in Paint     | mg/kg | 15                  | 40     | 40         |         |         |         |         |         |           |           |
| Total Sample Mass | g     |                     | 0.4964 | 0.4964     |         |         |         |         |         |           |           |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



## Certificate of Analysis

AGAT WORK ORDER: 18K378239

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
 St. John's, NL  
 CANADA A1E 6A8  
 TEL (709)747-8573  
 FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

### Mercury Analysis in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-08-31

| Parameter | Unit  | SAMPLE DESCRIPTION: |       | C1-PS1     | C1-PS2     | C1-PS3     | C1-PS4     | C1-PS5     | C1-PS6     | C1-PP-PS1  | C1-PP-PS2  |
|-----------|-------|---------------------|-------|------------|------------|------------|------------|------------|------------|------------|------------|
|           |       | G / S               | RDL   | Paint      | Paint      | Paint      | Paint      | Paint      | Paint      | Paint      | Paint      |
|           |       | DATE SAMPLED:       |       | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 |
| Mercury   | mg/kg | 0.05                | 0.11  | 1.04       | <0.05      | 1.80       | <0.05      | 0.34       | <0.05      | <0.05      | <0.05      |
|           |       | SAMPLE DESCRIPTION: |       | C1-PP-PS3  |            |            |            |            |            |            |            |
|           |       | SAMPLE TYPE:        |       | Paint      |            |            |            |            |            |            |            |
|           |       | DATE SAMPLED:       |       | 2018-08-13 |            |            |            |            |            |            |            |
| Mercury   | mg/kg | 0.05                | <0.05 |            |            |            |            |            |            |            |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



## Certificate of Analysis

AGAT WORK ORDER: 18K378239

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

### Total Polychlorinated Biphenyls in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-05

| Parameter          |  | Unit  | G / S             | RDL  | C1-PS1 | C1-PS2 | C1-PS3 | C1-PS4 | C1-PS5 | C1-PS6 | C1-PP-PS1 | C1-PP-PS2 |
|--------------------|--|-------|-------------------|------|--------|--------|--------|--------|--------|--------|-----------|-----------|
| Total PCBs         |  | mg/kg | 0.5               | <0.5 | <0.5   | <0.5   | <0.5   | <0.5   | <0.5   | <0.5   | <0.5      | <0.5      |
| Surrogate          |  | Unit  | Acceptable Limits |      |        |        |        |        |        |        |           |           |
| Decachlorobiphenyl |  | %     | 50-130            | 115  | 90     | 77     | 92     | 88     | 92     | 91     | 87        |           |
| Total PCBs         |  | mg/kg | 0.5               | <0.5 |        |        |        |        |        |        |           |           |
| Surrogate          |  | Unit  | Acceptable Limits |      |        |        |        |        |        |        |           |           |
| Decachlorobiphenyl |  | %     | 50-130            | 96   |        |        |        |        |        |        |           |           |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



## Quality Assurance

**CLIENT NAME:** WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of    **AGAT WORK ORDER:** 18K378239  
**PROJECT:** TF18104243    **ATTENTION TO:** Lori Wiseman  
**SAMPLING SITE:**    **SAMPLED BY:**

### Soil Analysis

| RPT Date: |       |              | DUPLICATE |        |     |                   | Method<br>Blank | REFERENCE MATERIAL   |       |          | METHOD BLANK SPIKE   |       |          | MATRIX SPIKE         |       |  |
|-----------|-------|--------------|-----------|--------|-----|-------------------|-----------------|----------------------|-------|----------|----------------------|-------|----------|----------------------|-------|--|
| PARAMETER | Batch | Sample<br>Id | Dup #1    | Dup #2 | RPD | Measured<br>Value |                 | Acceptable<br>Limits |       | Recovery | Acceptable<br>Limits |       | Recovery | Acceptable<br>Limits |       |  |
|           |       |              |           |        |     |                   |                 | Lower                | Upper |          | Lower                | Upper |          | Lower                | Upper |  |

|                                  |         |         |       |       |      |        |      |     |      |      |     |      |      |     |      |
|----------------------------------|---------|---------|-------|-------|------|--------|------|-----|------|------|-----|------|------|-----|------|
| <b>Lead In Paint</b>             |         |         |       |       |      |        |      |     |      |      |     |      |      |     |      |
| Lead in Paint                    | 8312018 | 9507202 | < 15  | < 15  | 0.0% | < 15   | 108% | 70% | 130% | 109% | 70% | 130% | 106% | 70% | 130% |
| <b>Mercury Analysis in Paint</b> |         |         |       |       |      |        |      |     |      |      |     |      |      |     |      |
| Mercury                          | 1       | 9501093 | <0.05 | <0.05 | NA   | < 0.05 | 106% | 70% | 130% | NA   | 70% | 130% | 71%  | 70% | 130% |

*Laura Palm*

**Certified By:** \_\_\_\_\_

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from www.cala.ca and/or www.scc.ca. The tests in this report may not necessarily be included in the scope of accreditation.

Results relate only to the items tested and to all the items tested

## Quality Assurance

**CLIENT NAME:** WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of **AGAT WORK ORDER:** 18K378239  
**PROJECT:** TF18104243 **ATTENTION TO:** Lori Wiseman  
**SAMPLING SITE:** **SAMPLED BY:**

| Trace Organics Analysis |       |           |           |        |     |                |              |                    |       |          |                    |       |              |                   |       |
|-------------------------|-------|-----------|-----------|--------|-----|----------------|--------------|--------------------|-------|----------|--------------------|-------|--------------|-------------------|-------|
| RPT Date:               |       |           | DUPLICATE |        |     |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       | MATRIX SPIKE |                   |       |
| PARAMETER               | Batch | Sample Id | Dup #1    | Dup #2 | RPD | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery     | Acceptable Limits |       |
|                         |       |           |           |        |     |                |              | Lower              | Upper |          | Lower              | Upper |              | Lower             | Upper |

**Total Polychlorinated Biphenyls in Paint**

|            |   |         |      |      |    |       |     |     |      |      |     |      |     |     |      |
|------------|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|-----|-----|------|
| Total PCBs | 1 | 9500855 | <0.5 | <0.5 | NA | < 0.5 | 94% | 60% | 140% | 102% | 60% | 130% | 92% | 60% | 130% |
|------------|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|-----|-----|------|

Comments: If Matrix spike value is NA, the spiked analyte concentration was lower than that of the matrix contribution.  
 If RPD value is NA, the results of the duplicates are less than 5x the RDL and the RPD will not be calculated.

**Total Polychlorinated Biphenyls in Paint**

|            |   |         |      |      |    |       |     |     |      |      |     |      |      |     |      |
|------------|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|------|-----|------|
| Total PCBs | 1 | 9500914 | <0.5 | <0.5 | NA | < 0.5 | 98% | 60% | 140% | 100% | 60% | 130% | 112% | 60% | 130% |
|------------|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|------|-----|------|

Comments: If Matrix spike value is NA, the spiked analyte concentration was lower than that of the matrix contribution.  
 If RPD value is NA, the results of the duplicates are less than 5x the RDL and the RPD will not be calculated.

**Certified By:**





## Method Summary

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of

AGAT WORK ORDER: 18K378239

PROJECT: TF18104243

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

| PARAMETER                      | AGAT S.O.P                       | LITERATURE REFERENCE                | ANALYTICAL TECHNIQUE |
|--------------------------------|----------------------------------|-------------------------------------|----------------------|
| <b>Soil Analysis</b>           |                                  |                                     |                      |
| Lead in Paint                  | MET-121-6105 &<br>MET-121-6103   | EPA SW 846 6020A/3050B & SM<br>3125 | ICP-MS               |
| Total Sample Mass              |                                  |                                     |                      |
| Mercury                        | INOR-121-6101 &<br>INOR-121-6107 | Based on EPA 245.5 & SM 3112B       | CV/AA                |
| <b>Trace Organics Analysis</b> |                                  |                                     |                      |
| Total PCBs                     | ORG-120-5107                     | EPA SW-846 8082                     | GC/ECD               |
| Decachlorobiphenyl             | ORG-120-5106                     | EAP SW846 3510C/8080/8010           | GC/ECD               |





# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 551810146  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

**Attn:** Lori Wiseman  
Wood Env. & Infrastructure Solutions  
PO Box 13216  
133 Crosbie Road  
Saint John's, NL A1B 4A5  
**Phone:** (709) 722-7023  
**Fax:** (709) 722-7353  
**Collected:** 8/13/2018  
**Received:** 8/29/2018  
**Analyzed:** 9/05/2018  
**Proj:** HBMA TL Camps/TF18104243

## Summary Test Report for Asbestos Analysis via EPA 600/R-93/116

**Client Sample ID:** C1-AS1 **Lab Sample ID:** 551810146-0001

**Sample Description:** Camp 1 - Cabin - Wall/Black Paper on Pink Fibreglass Insulation

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black | 3.8%         | 96.2%       | None Detected |         |

**Client Sample ID:** C1-AS2 **Lab Sample ID:** 551810146-0002

**Sample Description:** Camp 1 - Cabin - Ceiling/Black Paper on Yellow Fibreglass Insulation

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black | <0.25%       | 100%        | None Detected |         |

**Client Sample ID:** C1-AS3 **Lab Sample ID:** 551810146-0003

**Sample Description:** Camp 1 - Cabin - Foundation/Concrete

| TEST | Analyzed Date | Color    | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|----------|--------------|-------------|---------------|---------|
|      |               |          | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Gray/Red | 2%           | 98%         | None Detected |         |

**Client Sample ID:** C1-AS4 **Lab Sample ID:** 551810146-0004

**Sample Description:** Camp 1 - Cabin - Foundation/Cinder Block

| TEST | Analyzed Date | Color    | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|----------|--------------|-------------|---------------|---------|
|      |               |          | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Gray/Red | 0%           | 100%        | None Detected |         |

**Client Sample ID:** C1-AS5 **Lab Sample ID:** 551810146-0005

**Sample Description:** Camp 1 - Cabin - Roof/Black Shingle and Tar

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** C1-PP-AS1 **Lab Sample ID:** 551810146-0006

**Sample Description:** Camp 1 - Outhouse - Roof/Black Shingle and Tar

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black | 0.0%         | 100%        | None Detected |         |



## EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 551810146  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

### Summary Test Report for Asbestos Analysis via EPA 600/R-93/116

---

#### Analyst(s):

---

Ioana Taina PLM (2)  
Natalie D'Amico PLM Grav. Reduction (4)

#### Reviewed and approved by:

Matthew Davis or other approved signatory  
or Other Approved Signatory

Samples analyzed by EPA 600/R-93/116 consistent with NLR 111/98. The estimated limit of detection for non-detect samples is <0.1%. Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the US Government.

Samples analyzed by EMSL Canada Inc. Mississauga, ON NVLAP Lab Code 200877-0

Initial report from: 09/05/2018 15:06:43

17



EMSL ANALYTICAL, INC.  
LABORATORY PRODUCTS TRAINING

### Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (Lab Use Only):

551810146

Mississauga, ON L4T 1G3  
PHONE: 289-997-4602  
FAX: 289-997-4607

| Company: Wood Environment & Infrastructure Solutions  |                                 | EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different<br><small>If Bill to is Different note instructions in Comments**</small> |   |
|---|---------------------------------|---|---|
| Street: 133 Crosbie Road  |                                 | <i>Third Party Billing requires written authorization from third party</i>  |   |
| City: St. John's  | State/Province: NL              | Zip/Postal Code: A1B 4A5  | Country: CA   |
| Report To (Name): Lori Wiseman  |                                 | Telephone #: (709) 722-7023   |   |
| Email Address: lori.wiseman@woodplc.com   |                                 | Fax #: (709) 722-7353   | Purchase Order: TF18104243  |
| Project Name/Number: HBMA TL Camps/TF18104243   |                                 | Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail  |   |
| U.S. State Samples Taken: NL  |                                 | CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt   |   |
| <b>Turnaround Time (TAT) Options* - Please Check</b>  |                                 |   |   |
| <input type="checkbox"/> 3 Hour   | <input type="checkbox"/> 6 Hour | <input type="checkbox"/> 24 Hour  | <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input checked="" type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week |
| <small>*For TEM Air 3 hr through 6 hr, please call ahead to schedule. *There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.</small> |                                 |   |   |
| <b>PLM - Bulk (reporting limit)</b>   |                                 | <b>TEM - Bulk</b>   |   |
| <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%)  |                                 | <input type="checkbox"/> TEM EPA NOB - EPA 600/R-93/116 Section 2.5.5.1   |   |
| <input checked="" type="checkbox"/> PLM EPA NOB (<1%), IF REQUIRED BASED ON SAMPLE  |                                 | <input type="checkbox"/> NY ELAP Method 198.4 (TEM)   |   |
| Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)   |                                 | <input type="checkbox"/> Chatfield Protocol (semi-quantitative)   |   |
| Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)   |                                 | <input type="checkbox"/> TEM % by Mass - EPA 600/R-93/116 Section 2.5.5.2   |   |
| <input type="checkbox"/> NIOSH 9002 (<1%)   |                                 | <input type="checkbox"/> TEM Qualitative via Filtration Prep Technique  |   |
| <input type="checkbox"/> NY ELAP Method 198.1 (friable in NY)   |                                 | <input type="checkbox"/> TEM Qualitative via Drop Mount Prep Technique  |   |
| <input type="checkbox"/> NY ELAP Method 198.6 NOB (non-friable-NY)  |                                 | <b>Other</b>  |   |
| <input type="checkbox"/> OSHA ID-191 Modified   |                                 | <input type="checkbox"/>  |   |
| <input type="checkbox"/> Standard Addition Method   |                                 |   |   |
| <input type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Group  |                                 | Date Sampled: August 13, 2018   |   |
| Samplers Name: Craig Taylor   |                                 | Samplers Signature: <i>[Signature]</i>  |   |
| Sample #  | HA #                            | Sample Location   | Material Description  |
| CI-A51  |                                 | Camp 1 - Cabin - Wall   | Black paper on pink fibreglass insulation   |
| CI-A52  |                                 | Camp 1 - Cabin - Ceiling  | Black paper on yellow fibreglass insulation   |
| CI-A53  |                                 | Camp 1 - Cabin - Foundation   | Concrete  |
| CI-A54  |                                 | Camp 1 - Cabin - Foundation   | Cinder block and mortar   |
| CI-A55  |                                 | Camp 1 - Cabin - Roof   | Black shingle and tar   |
| CI-PP-A51   |                                 | Camp 1 - Outhouse - Roof  | Black shingle and tar   |
| Client Sample # (s): -  |                                 | Total # of Samples: 6   |   |
| Relinquished (Client): Lori Wiseman   |                                 | Date: August 24, 2018   | Time: 3:45 p.m.   |
| Received (Lab):   |                                 | Date:   | Time:   |
| <b>Comments/Special Instructions:</b><br><small>Please advise if any samples require PLM NOB analysis.</small>  |                                 |   |   |
| Analyze separate layers in each sample; excluding fibreglass insulation.  |                                 |   |   |

**Camp #2 COAs**



# Laboratory Analysis Report

To:

**Cary Hutchinson**  
AGAT Laboratories Ltd.  
11 Morris Drive, Unit 122  
Dartmouth, Nova Scotia  
B3B 1M2

**EMC LAB REPORT NUMBER:** 67991

**Job/Project Name:**

**Job/Project No:** 18k378220

**No. of Samples:** 1

**Sample Type:** Bulk

**Date Received:** Aug 29/18

**Analysis Method(s):** Direct Microscopic Examination

**Date Analyzed:** Sep 4/18

**Date Reported:** Sep 4/18

**Analyst:** Weizhong Liu, Ph.D., *Mycologist*

**Approved By:** Fajun Chen, Ph.D., *Principal Mycologist*



| Client's Sample ID | Lab Sample No. | Date Sampled | Description/Location | Mould Identified, in Rank Order | Mould Growth |
|--------------------|----------------|--------------|----------------------|---------------------------------|--------------|
| 18k378220          | 296478         | Aug 13/18    | 9500919 – PP-MS1     | <i>Cladosporium</i>             | Abundant     |

**Note:**

- Mould growth is subjectively assessed with description terms sparse, moderate and abundant.
- The presence of spores (lacking other fungal structures associated) is assessed as following: a few spores (< 10 spores average per microscopic field at 400X), some spores (10 - 100 spores average per microscopic field at 400X), many spores (> 100 spores average per microscopic field at 400X).
- The presence of a few spores generally represents settled spores on the surface of the sample rather than indicating mould growth.
- The results are only related to the samples analyzed.



**CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of  
Wood Canada Ltd.  
36 PIPPY PLACE  
St. John's, NL A1B4A5  
(709) 722-5062**

**ATTENTION TO: Lori Wiseman**

**PROJECT: TF18104243**

**AGAT WORK ORDER: 18K378220**

**SOIL ANALYSIS REVIEWED BY: Laura Baker, Inorganics Data Reporter**

**TRACE ORGANICS REVIEWED BY: Pinkal Patel, Report Reviewer**

**DATE REPORTED: Sep 07, 2018**

**PAGES (INCLUDING COVER): 11**

**VERSION\*: 1**

Should you require any information regarding this analysis please contact your client services representative at (709)747-8573

**\*NOTES**

Empty rectangular box for notes.

**All samples will be disposed of within 30 days following analysis. Please contact the lab if you require additional sample storage time.**



## Certificate of Analysis

AGAT WORK ORDER: 18K378220

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
 St. John's, NL  
 CANADA A1E 6A8  
 TEL (709)747-8573  
 FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

### Lead In Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-07

| Parameter         | Unit  | SAMPLE DESCRIPTION: |     | PP-PS1     | PP-PS2     | PP-PS3     | PP-PS4     | PP-PS5     | PP-PS6     | PP-PP-PS1  |
|-------------------|-------|---------------------|-----|------------|------------|------------|------------|------------|------------|------------|
|                   |       | SAMPLE TYPE:        |     | Paint      | Paint      | Paint      | Paint      | Paint      | Paint      | Paint      |
|                   |       | DATE SAMPLED:       |     | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 |
|                   |       | G / S               | RDL | 9500878    | 9500910    | 9500912    | 9500913    | 9500914    | 9500915    | 9500917    |
| Lead in Paint     | mg/kg |                     | 15  | 103        | 64         | 122        | <15        | <15        | 40400      | <15        |
| Total Sample Mass | g     |                     |     | 0.5002     | 0.2166     | 0.5085     | 0.4974     | 0.4975     | 0.4946     | 0.5065     |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



# Certificate of Analysis

AGAT WORK ORDER: 18K378220

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709)747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

## Mercury Analysis in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-07

| Parameter | Unit  | SAMPLE DESCRIPTION: |      | PP-PS1     | PP-PS2     | PP-PS3     | PP-PS4     | PP-PS5     | PP-PS6     | PP-PP-PS1  |
|-----------|-------|---------------------|------|------------|------------|------------|------------|------------|------------|------------|
|           |       | G / S               | RDL  | Paint      | Paint      | Paint      | Paint      | Paint      | Paint      | Paint      |
|           |       |                     |      | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 |
|           |       |                     |      | 9500878    | 9500910    | 9500912    | 9500913    | 9500914    | 9500915    | 9500917    |
| Mercury   | mg/kg | 0.05                | 2.35 | <0.05      | 0.78       | 0.19       | <0.05      | 0.81       | 0.16       |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



## Certificate of Analysis

AGAT WORK ORDER: 18K378220

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
 St. John's, NL  
 CANADA A1E 6A8  
 TEL (709)747-8573  
 FAX (709)747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

### O. Reg. 558 - SVOCs

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-07

|                    |      | SAMPLE DESCRIPTION: PP-TW1 |         |
|--------------------|------|----------------------------|---------|
|                    |      | SAMPLE TYPE: Wood          |         |
|                    |      | DATE SAMPLED: 2018-08-13   |         |
| Parameter          | Unit | G / S                      | RDL     |
|                    |      |                            | 9500920 |
| Cresols            | mg/L | 0.012                      | <0.012  |
| Ortho-Cresol       | mg/L | 0.004                      | <0.004  |
| Meta & Para-Cresol | mg/L | 0.008                      | <0.008  |
| Benzo(a)pyrene     | mg/L | 0.001                      | <0.001  |
| Surrogate          | Unit | Acceptable Limits          |         |
| Chrysene-d12       | %    | 50-130                     | 99      |

**Comments:** RDL - Reported Detection Limit; G / S - Guideline / Standard

**9500920** Due to insufficient sample volume, the Toxicity Characteristic Leaching Procedure (TCLP) was completed using a sample mass which did not meet the prescriptive, minimum sample requirements to perform the TCLP as specified in the reference method (EPA Method 1311) as mandated under R.R.O. 1990, Reg. 347: GENERAL - WASTE MANAGEMENT under Environmental Protection Act, R.S.O. 1990, c. E.19

**Certified By:**



## Certificate of Analysis

AGAT WORK ORDER: 18K378220

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

### Total Polychlorinated Biphenyls in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-07

| Parameter          | Unit  | SAMPLE DESCRIPTION: |      | PP-PS1     | PP-PS2     | PP-PS3     | PP-PS4     | PP-PS5     | PP-PS6     | PP-PP-PS1  |
|--------------------|-------|---------------------|------|------------|------------|------------|------------|------------|------------|------------|
|                    |       | G / S               | RDL  | Paint      | Paint      | Paint      | Paint      | Paint      | Paint      | Paint      |
|                    |       |                     |      | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 | 2018-08-13 |
|                    |       |                     |      | 9500878    | 9500910    | 9500912    | 9500913    | 9500914    | 9500915    | 9500917    |
| Total PCBs         | mg/kg | 0.5                 | <0.5 | <0.5       | <0.5       | <0.5       | <0.5       | <0.5       | <0.5       | <0.5       |
| Surrogate          | Unit  | Acceptable Limits   |      |            |            |            |            |            |            |            |
| Decachlorobiphenyl | %     | 50-130              | 92   | 102        | 84         | 84         | 96         | 109        | 112        |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



## Quality Assurance

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of AGAT WORK ORDER: 18K378220  
 PROJECT: TF18104243 ATTENTION TO: Lori Wiseman  
 SAMPLING SITE: SAMPLED BY:

### Soil Analysis

| RPT Date: Sep 07, 2018           |       |           | DUPLICATE |        |     |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       |          | MATRIX SPIKE      |       |  |
|----------------------------------|-------|-----------|-----------|--------|-----|----------------|--------------|--------------------|-------|----------|--------------------|-------|----------|-------------------|-------|--|
| PARAMETER                        | Batch | Sample Id | Dup #1    | Dup #2 | RPD | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery | Acceptable Limits |       |  |
|                                  |       |           |           |        |     |                |              | Lower              | Upper |          | Lower              | Upper |          | Lower             | Upper |  |
| <b>Mercury Analysis in Paint</b> |       |           |           |        |     |                |              |                    |       |          |                    |       |          |                   |       |  |
| Mercury                          | 1     | 9500917   | 0.13      | 0.16   | NA  | < 0.05         | 92%          | 70%                | 130%  | NA       | 70%                | 130%  | 81%      | 70%               | 130%  |  |

**Certified By:** \_\_\_\_\_

## Quality Assurance

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of AGAT WORK ORDER: 18K378220  
 PROJECT: TF18104243 ATTENTION TO: Lori Wiseman  
 SAMPLING SITE: SAMPLED BY:

| Trace Organics Analysis |       |           |           |        |     |                |              |                    |       |          |                    |       |              |                   |       |
|-------------------------|-------|-----------|-----------|--------|-----|----------------|--------------|--------------------|-------|----------|--------------------|-------|--------------|-------------------|-------|
| RPT Date: Sep 07, 2018  |       |           | DUPLICATE |        |     |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       | MATRIX SPIKE |                   |       |
| PARAMETER               | Batch | Sample Id | Dup #1    | Dup #2 | RPD | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery     | Acceptable Limits |       |
|                         |       |           |           |        |     |                |              | Lower              | Upper |          | Lower              | Upper |              | Lower             | Upper |

**Total Polychlorinated Biphenyls in Paint**

|            |   |         |      |      |    |       |     |     |      |      |     |      |      |     |      |
|------------|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|------|-----|------|
| Total PCBs | 1 | 9500914 | <0.5 | <0.5 | NA | < 0.5 | 98% | 60% | 140% | 100% | 60% | 130% | 112% | 60% | 130% |
|------------|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|------|-----|------|

Comments: If Matrix spike value is NA, the spiked analyte concentration was lower than that of the matrix contribution.  
 If RPD value is NA, the results of the duplicates are less than 5x the RDL and the RPD will not be calculated.

**O. Reg. 558 - SVOCs**

|                    |    |    |    |    |         |     |     |      |     |     |      |    |     |      |
|--------------------|----|----|----|----|---------|-----|-----|------|-----|-----|------|----|-----|------|
| Cresols            | NA | NA | NA | NA | < 0.012 | 89% | 60% | 130% | 87% | 35% | 110% | NA | 30% | 130% |
| Ortho-Cresol       | NA | NA | NA | NA | < 0.004 | 87% | 50% | 130% | 76% | 50% | 130% | NA | 50% | 130% |
| Meta & Para-Cresol | NA | NA | NA | NA | < 0.008 | 81% | 50% | 130% | 94% | 50% | 130% | NA | 50% | 130% |
| Benzo(a)pyrene     | NA | NA | NA | NA | < 0.001 | 87% | 60% | 130% | 99% | 60% | 130% | NA | 60% | 130% |

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

*Jinkal Patel*

**Certified By:** \_\_\_\_\_



## Method Summary

**CLIENT NAME:** WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of     **AGAT WORK ORDER:** 18K378220  
**PROJECT:** TF18104243     **ATTENTION TO:** Lori Wiseman  
**SAMPLING SITE:**     **SAMPLED BY:**

| PARAMETER                      | AGAT S.O.P                       | LITERATURE REFERENCE                | ANALYTICAL TECHNIQUE |
|--------------------------------|----------------------------------|-------------------------------------|----------------------|
| <b>Soil Analysis</b>           |                                  |                                     |                      |
| Lead in Paint                  | MET-121-6105 &<br>MET-121-6103   | EPA SW 846 6020A/3050B & SM<br>3125 | ICP-MS               |
| Total Sample Mass              |                                  |                                     |                      |
| Mercury                        | INOR-121-6101 &<br>INOR-121-6107 | Based on EPA 245.5 & SM 3112B       | CV/AA                |
| <b>Trace Organics Analysis</b> |                                  |                                     |                      |
| Cresols                        | ORG-91-5114                      | EPA SW846 3510C & 8270              | GC/MS                |
| Ortho-Cresol                   | ORG-91-5114                      | EPA SW846 3510C & 8270              | GC/MS                |
| Meta & Para-Cresol             | ORG-91-5114                      | EPA SW846 3510C & 8270              | GC/MS                |
| Benzo(a)pyrene                 | ORG-91-5114                      | EPA SW846 3510C & 8270              | GC/MS                |
| Chrysene-d12                   | ORG-91-5114                      | EPA SW846 3510C & 8270              | GC/MS                |
| Total PCBs                     | ORG-120-5107                     | EPA SW-846 8082                     | GC/ECD               |
| Decachlorobiphenyl             | ORG-120-5106                     | EAP SW846 3510C/8080/8010           | GC/ECD               |



# Laboratories

Unit 1, 57 Old Pennywell Rd  
St John's, NL  
A1E 6A8  
webearth.agatlabs.com • www.agatlabs.com

## Chain of Custody Record

### Report Information

Company: Wood E&I Solutions (formerly Amec Foster Wheeler E&I)  
Contact: Lori Wiseman  
Address: 133 CROSBIE ROAD  
ST. JOHNS, NL A1B 4A5  
Phone: 1-709-722-7023 Fax: 1-709-722-7353  
Client Project #: TF18104-243  
AGAT Quotation: NALCOR ESA (MIS-016)  
Please Note: if quotation number is not provided client will be billed full price for analysis.

### Invoice To

Company: Wood E&I Solutions  
Contact: Sandra LeDrew and Project Manager indicated above  
Address: 133 CROSBIE ROAD  
ST. JOHNS, NL A1B 4A5  
Phone: 1-709-722-7023 Fax: 1-709-722-7353  
PO/Credit Card#:

### Report Information (Please print):

1. Name: Lori Wiseman  
Email: lori.wiseman@woodplc.com  
2. Name: \_\_\_\_\_  
Email: \_\_\_\_\_

### Regulatory Requirements (Check):

List Guidelines on Report  Do not list Guidelines on Report  
 PIRI  Tier 1  Res  Pot  Coarse  
 Tier 2  Corn  N/Pot  Fine  
 Gas  Fuel  Lube  
 CCME  CDWQ  Other TDG; HPA  
 Industrial  Commercial  Res/Park  Agricultural  FWAL  Sediment

### Report Format

Single Sample per page  
 Multiple Samples per page  
 Excel Format Included

P: 709.747.8573 • F: 709.747.2139

### Laboratory Use Only

Arrival Condition:  Good  Poor (see notes)  
Arrival Temperature: 24.6  
Hold Time: \_\_\_\_\_  
AGAT Job Number: 18K378220

### Notes:

### Turnaround Time Required (TAT)

Regular TAT  5 to 7 working days  
Rush TAT  Same day  1 day  
 2 days  3 days

### Date Required:

Drinking Water Sample:  Yes  No Salt Water:  Yes  No

### Reg. No.:

| Sample Identification | Date/Time Sampled | Sample Matrix | # Containers | Comments - Site/Sample Info. Sample Containment | Field Filtered/Preserved | Standard Water Analysis | Metals: <input type="checkbox"/> Total <input type="checkbox"/> Diss <input type="checkbox"/> Available | Mercury | <input type="checkbox"/> BOD <input type="checkbox"/> CBOD | <input checked="" type="checkbox"/> Treated Wood - Create <input type="checkbox"/> TSS <input type="checkbox"/> TDS <input type="checkbox"/> VSS <input type="checkbox"/> Formulate | TKN | Total Phosphorus | Phenols | Tier 1: TPH/BTEX (PIRI) <input type="checkbox"/> low level | Tier 2: TPH/BTEX Fractionation | CME-CWS TPH/BTEX | VOC | THM | HAA | PAH | PCB | TC + EC <input type="checkbox"/> P/A <input type="checkbox"/> MPN <input type="checkbox"/> MF | HPC <input type="checkbox"/> Pseudomonas | Fecal Coliform <input type="checkbox"/> MPN <input type="checkbox"/> MF | Other: <u>Lead</u> | Other: <u>Mould - DME</u> | Hazardous (Y/N) |
|-----------------------|-------------------|---------------|--------------|---|--------------------------|-------------------------|---|---------|--|---|-----|------------------|---------|--|--------------------------------|------------------|-----|-----|-----|-----|-----|---|--|---|--------------------|---------------------------|-----------------|
| PP-PS1                | Aug. 13, 2018     | Paint         | Baggie       | Pin Hill Pond Camp/Cabin                        |                          |                         |   | X       |  |   |     |                  |         |  |                                |                  |     |     |     |     | X   |   |  |   |                    |                           |                 |
| PP-PS2                |                   |               |              |   |                          |                         |   | X       |  |   |     |                  |         |  |                                |                  |     |     |     |     | X   |   |  |   |                    |                           |                 |
| PP-PS3                |                   |               |              |   |                          |                         |   | X       |  |   |     |                  |         |  |                                |                  |     |     |     |     | X   |   |  |   |                    |                           |                 |
| PP-PS4                |                   |               |              |   |                          |                         |   | X       |  |   |     |                  |         |  |                                |                  |     |     |     |     | X   |   |  |   |                    |                           |                 |
| PP-PS5                |                   |               |              |   |                          |                         |   | X       |  |   |     |                  |         |  |                                |                  |     |     |     |     | X   |   |  |   |                    |                           |                 |
| PP-PS6                |                   |               |              |   |                          |                         |   | X       |  |   |     |                  |         |  |                                |                  |     |     |     |     | X   |   |  |   |                    |                           |                 |
| PP-PP-PS1             |                   |               |              |   |                          |                         |   | X       |  |   |     |                  |         |  |                                |                  |     |     |     |     | X   |   |  |   |                    |                           |                 |
| PP-MS1                |                   | Bulk          |              | Pin Hill Pond Camp/Outbase                      |                          |                         |   |         |  |   |     |                  |         |  |                                |                  |     |     |     |     |     |   |  |   |                    |                           |                 |
| PP-TW1                |                   | Wood Bag      |              | Pin Hill Pond Camp/Outbase                      |                          |                         |   |         |  |   |     |                  |         |  |                                |                  |     |     |     |     |     |   |  |   |                    |                           |                 |

Samples Relinquished By (Print Name): Lori Wiseman Date/Time: Aug. 27, 2018  
 Samples Relinquished By (Sign): \_\_\_\_\_ Date/Time: Aug 27, 2018  
 Samples Received By (Print Name): Samantha Murphy Date/Time: 1:50 PM  
 Samples Received By (Sign): SM Murphy Date/Time: Aug 27, 2018  
 Page 1 of 1  
 Pink Copy - Client  
 Yellow Copy - AGAT  
 White Copy - AGAT  
 No.:



# AGAT Laboratories

Unit 1, 57 Old Pennywell Rd  
St John's, NL  
A1E 6A8  
webeath.agatlabs.com • www.agatlabs.com

## Chain of Custody Record

**Report Information**

Company: Wood E&I Solutions (formerly Amec Foster Wheeler E&I)  
 Contact: Lori Wiseman  
 Address: 133 CROSBIE ROAD  
 ST. JOHNS, NL A1B 4A5  
 Phone: 1-709-722-7023 Fax: 1-709-722-7353  
 Client Project #: TF18 10A243  
 AGAT Quotation: NALCOR ESA (MIS-016)  
 Please Note: If quotation number is not provided client will be billed full price for analysis.

**Report Information** (Please print):

1. Name: Lori Wiseman  
 Email: Lori.Wiseman@woodplc.com

2. Name: \_\_\_\_\_  
 Email: \_\_\_\_\_

**Regulatory Requirements** (Check):

List Guidelines on Report  Do not list Guidelines on Report

PIRI  Tier 1  Res  Pot  Coarse  
 Tier 2  Com  N/Pot  Fine  
 Gas  Fuel  Lube

CCME  CDWQ  Other TDG, HPA

**Report Format**

Single Sample per page  
 Multiple Samples per page  
 Excel Format Included

**Invoice To** Same Yes  / No

Company: Wood E&I Solutions  
 Contact: Sandra LeDrew and Project Manager indicated above  
 Address: 133 CROSBIE ROAD  
 ST. JOHNS, NL A1B 4A5  
 Phone: 1-709-722-7023 Fax: 1-709-722-7353  
 PO/Credit Card#: \_\_\_\_\_

**Drinking Water Sample:**  Yes  No  
 Salt Water:  Yes  No

Reg. No.: \_\_\_\_\_

**Laboratory Use Only**

Arrival Condition:  Good  Poor (see notes)  
 Arrival Temperature: 25.4  
 Hold Time: \_\_\_\_\_  
 AGAT Job Number: 18638258

Notes: \_\_\_\_\_

**Turnaround Time Required (TAT)**

**Regular TAT**  5 to 7 working days  
**Rush TAT**  Same day  1 day  2 days  3 days

Date Required: \_\_\_\_\_

| Sample Identification | Date/Time Sampled | Sample Matrix | # Containers | Comments - Site/Sample Info. Sample Containment | Field Filtered/Preserved | Standard Water Analysis | Metals: <input type="checkbox"/> Total <input type="checkbox"/> Diss <input type="checkbox"/> Available | <input type="checkbox"/> BOD <input type="checkbox"/> CBOD | <input type="checkbox"/> TSS <input type="checkbox"/> TDS <input type="checkbox"/> VSS | <input checked="" type="checkbox"/> Treated Wood - Inorganic<br><input checked="" type="checkbox"/> Treated Wood - Chlorophyll<br><input checked="" type="checkbox"/> Formic | Phenols | Tier 1: TPH/BTEX (PIRI) <input type="checkbox"/> low level | Tier 2: TPH/BTEX Fractionation | CCME-CWS TPH/BTEX | VOC | THM | HAA | PAH | PCB | TC + EC <input type="checkbox"/> P/A <input type="checkbox"/> MPN <input type="checkbox"/> MF | HPC <input type="checkbox"/> Pseudomonas | Fecal Coliform <input type="checkbox"/> MPN <input type="checkbox"/> MF | Other: <u>Lead</u> | Other: <u>Mould - DMC</u> | Hazardous (Y/N) |
|-----------------------|-------------------|---------------|--------------|---|--------------------------|-------------------------|---|--|--|--|---------|--|--------------------------------|-------------------|-----|-----|-----|-----|-----|---|--|---|--------------------|---------------------------|-----------------|
| MDX - PS1             | Aug. 7, 2018      | Paint         | Beggie       | Medanngonik Camp/Cabin                          |                          |                         |   |  |  |  |         |  |                                |                   |     |     |     |     |     |   |  |   |                    |                           |                 |
| MDX - PS2             |                   |               |              |   |                          |                         |   |  |  |  |         |  |                                |                   |     |     |     |     |     |   |  |   |                    |                           |                 |
| MDX - PS3             |                   |               |              |   |                          |                         |   |  |  |  |         |  |                                |                   |     |     |     |     |     |   |  |   |                    |                           |                 |
| MDX - PP-PS1          |                   |               |              |   |                          |                         |   |  |  |  |         |  |                                |                   |     |     |     |     |     |   |  |   |                    |                           |                 |
| MDX - MS1             |                   | Bulk          |              | Medanngonik Camp/OutHouse                       |                          |                         |   |  |  |  |         |  |                                |                   |     |     |     |     |     |   |  |   |                    |                           |                 |
| MDX - PT1             |                   | Wood          |              | Medanngonik Camp/Cabin                          |                          |                         |   |  |  |  |         |  |                                |                   |     |     |     |     |     |   |  |   |                    |                           |                 |

Samples Relinquished By (Print Name): Lori Wiseman  
 Date/Time: Aug. 27, 2018

Samples Received By (Print Name): [Signature]  
 Date/Time: Aug 27 11:50 AM

Samples Relinquished By (Sign): \_\_\_\_\_  
 Date/Time: Aug 27 11:18

Samples Received By (Sign): \_\_\_\_\_  
 Date/Time: \_\_\_\_\_

Page 1 of 1

Pink Copy - Client  
 Yellow Copy - AGAT  
 White Copy - AGAT

No: \_\_\_\_\_



# Laboratories

Unit 1, 57 Old Pennywell Rd  
St. John's, NL  
A1E 6A8  
webeathr.agatlabs.com • www.agatlabs.com

## Chain of Custody Record

**Report Information**

Company: Wood E&I Solutions (formerly Amec Foster Wheeler E&I)  
 Contact: Lori Wiseman  
 Address: 133 CROSBIE ROAD  
 ST. JOHNS, NL A1B 4A5  
 Phone: 1-709-722-7023 Fax: 1-709-722-7353  
 Client Project #: TF18104243  
 AGAT Quotation: NALCOR ESA (MIS-016)  
 Please Note: If quotation number is not provided client will be billed full price for analysis.

**Invoice To** Same Yes  / No

Company: Wood E&I Solutions  
 Contact: Sandra LeDrew and Project Manager indicated above  
 Address: 133 CROSBIE ROAD  
 ST. JOHNS, NL A1B 4A5  
 Phone: 1-709-722-7023 Fax: 1-709-722-7353  
 PO/Credit Card#:

**Report Information (Please print):**

1. Name: Lori Wiseman  
 Email: lori.wiseman@woodpl.com  
 2. Name: \_\_\_\_\_  
 Email: \_\_\_\_\_

**Regulatory Requirements (Check):**

List Guidelines on Report  Do not list Guidelines on Report  
 PIRI  
 Tier 1  Res  Pot  Coarse  
 Tier 2  Com  N/Pot  Fine  
 Gas  Fuel  Lube  
 CCME  CDWQ  
 Industrial  Other TDG  
 Commercial HPA  
 Res/Park  
 Agricultural  
 FWAL  
 Sediment

**Report Format**

Single Sample per page  
 Multiple Samples per page  
 Excel Format Included

P: 709.747.8573 • F: 709.747.2139

**Laboratory Use Only**

Arrival Condition:  Good  Poor (see notes)  
 Arrival Temperature: 22.5  
 Hold Time: \_\_\_\_\_  
 AGAT Job Number: 186378265

Notes: \_\_\_\_\_

**Turnaround Time Required (TAT)**

**Regular TAT**  5 to 7 working days  
 Same day  1 day  
**Rush TAT**  2 days  3 days

Date Required: \_\_\_\_\_

Drinking Water Sample:  Yes  No  
 Salt Water:  Yes  No

| Field Filtered/Preserved | Standard Water Analysis | Metals: <input type="checkbox"/> Total <input type="checkbox"/> Diss <input type="checkbox"/> Avail | Mercury                             | <input type="checkbox"/> BOD <input type="checkbox"/> CBOD | pH | <input type="checkbox"/> TSS <input type="checkbox"/> TDS <input type="checkbox"/> VSS | TKN | Total Phosphorus | Phenols | Tier 1: TPH/BTEX (PIRI) <input type="checkbox"/> low level | Tier 2: TPH/BTEX Fractionation | CMC-CWS TPH/BTEX | VOC | THM | HAA | PAH | PCB                                 | TC + EC <input type="checkbox"/> P/A <input type="checkbox"/> MPN <input type="checkbox"/> MF | HPC <input type="checkbox"/> Pseudomonas | Fecal Coliform <input type="checkbox"/> MPN <input type="checkbox"/> MF | Other: <u>Lead</u>                  | Other: <u>Mould - DME</u> | Hazardous (Y/N) |
|--------------------------|-------------------------|---|-------------------------------------|--|----|--|-----|------------------|---------|--|--------------------------------|------------------|-----|-----|-----|-----|-------------------------------------|---|--|---|-------------------------------------|---------------------------|-----------------|
|                          |                         |   | <input checked="" type="checkbox"/> |  |    |  |     |                  |         |  |                                |                  |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   | <input checked="" type="checkbox"/> |                           |                 |
|                          |                         |   | <input checked="" type="checkbox"/> |  |    |  |     |                  |         |  |                                |                  |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   | <input checked="" type="checkbox"/> |                           |                 |
|                          |                         |   | <input checked="" type="checkbox"/> |  |    |  |     |                  |         |  |                                |                  |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   | <input checked="" type="checkbox"/> |                           |                 |
|                          |                         |   | <input checked="" type="checkbox"/> |  |    |  |     |                  |         |  |                                |                  |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   | <input checked="" type="checkbox"/> |                           |                 |
|                          |                         |   | <input checked="" type="checkbox"/> |  |    |  |     |                  |         |  |                                |                  |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   | <input checked="" type="checkbox"/> |                           |                 |

| Sample Identification | Date/Time Sampled | Sample Matrix | # Containers | Comments - Site/Sample Info. Sample Containment | Samples Received By (Print Name): | Date/Time     |
|-----------------------|-------------------|---------------|--------------|---|-----------------------------------|---------------|
| MP - P51              | Aug. 8, 2018      | Paint         | Baggie       | Mitchell's Pond Camp/Cabin                      | <u>SM Murphy</u>                  | Aug. 27, 2018 |
| MP - P52              |                   | ↓             |              |   |                                   |               |
| MP - P53              |                   | ↓             |              |   |                                   |               |
| MP - M51              |                   | Bulk          |              |   |                                   |               |
| MP - PP - P51         |                   | Paint         |              | Mitchell's Pond Camp/outhouse                   |                                   |               |
| MP - PP - P52         |                   | ↓             |              |   |                                   |               |

Samples Requisitioned By (Print Name): Lori Wiseman  
 Samples Requisitioned By (Sign): \_\_\_\_\_  
 Date/Time: Aug 27 18

Samples Received By (Print Name): \_\_\_\_\_  
 Samples Received By (Sign): \_\_\_\_\_  
 Date/Time: Aug 27 18

Pink Copy - Client: \_\_\_\_\_  
 Yellow Copy - AGAT: \_\_\_\_\_  
 White Copy - AGAT: \_\_\_\_\_

Page 1 of 1

No. \_\_\_\_\_



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
http://www.EMSL.com / torontolab@emsl.com

EMSL Canada Order 551810131  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

**Attn:** Lori Wiseman  
Wood Env. & Infrastructure Solutions  
PO Box 13216  
133 Crosbie Road  
Saint John's, NL A1B 4A5  
**Phone:** (709) 722-7023  
**Fax:** (709) 722-7353  
**Collected:** 8/13/2018  
**Received:** 8/29/2018  
**Analyzed:** 9/05/2018  
**Proj:** HBMA TL CMAPS/TF18104243

## Summary Test Report for Asbestos Analysis via EPA 600/R-93/116

**Client Sample ID:** PP-AS1 **Lab Sample ID:** 551810131-0001

**Sample Description:** PIN HILL POND CAMP - CABIN - WALL/BLACK PAPER ON PINK FIBREGLOSS INSULATION

| TEST | Analyzed Date | Color            | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|------------------|--------------|-------------|---------------|---------|
|      |               |                  | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/05/2018    | Brown/Black/Pink | 90%          | 10%         | None Detected |         |

**Client Sample ID:** PP-AS2 **Lab Sample ID:** 551810131-0002

**Sample Description:** PIN HILL POND CAMP - CABIN - WALL/TAR PAPER

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/05/2018    | Brown | 90%          | 10%         | None Detected |         |

**Client Sample ID:** PP-AS3 **Lab Sample ID:** 551810131-0003

**Sample Description:** PIN HILL POND CAMP - CABIN - ROOF/BLACK SHINGLE

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos        | Comment |
|---------------------|---------------|-------|--------------|-------------|-----------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |                 |         |
| PLM Grav. Reduction | 09/05/2018    | Black | 0.0%         | 97.8%       | 2.2% Chrysotile |         |

**Client Sample ID:** PP-AS4 **Lab Sample ID:** 551810131-0004

**Sample Description:** PIN HILL POND CAMP - CABIN - FOUNDATION/CONCRETE

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/05/2018    | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** PP-AS5 **Lab Sample ID:** 551810131-0005

**Sample Description:** PIN HILL POND CAMP - CABIN/CINDERBLOCK AND MORTAR

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/05/2018    | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** PP-PP-AS1 **Lab Sample ID:** 551810131-0006

**Sample Description:** PIN HILL POND CAMP - OUTHOUSE/BLACK SHINGLE AND TAR

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos        | Comment |
|---------------------|---------------|-------|--------------|-------------|-----------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |                 |         |
| PLM Grav. Reduction | 09/05/2018    | Black | 0.0%         | 98.9%       | 1.1% Chrysotile |         |



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
http://www.EMSL.com / torontolab@emsl.com

EMSL Canada Order 551810131  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

**Attn:** Lori Wiseman  
Wood Env. & Infrastructure Solutions  
PO Box 13216  
133 Crosbie Road  
Saint John's, NL A1B 4A5  
**Phone:** (709) 722-7023  
**Fax:** (709) 722-7353  
**Collected:** 8/13/2018  
**Received:** 8/29/2018  
**Analyzed:** 9/05/2018  
**Proj:** HBMA TL CMAPS/TF18104243

The samples in this report were submitted for asbestos bulk analysis. The reference number for these samples is the Order ID above. Please use this reference number when calling about these samples.

Sample Receipt Date: 08/29/2018      Sample Receipt Time: 5:00 pm  
Analysis Completed Date: 09/05/2018      Analysis Completed Time: 3:23 pm

**Analyst(s):**

**Signature Not Loaded**

Caroline Allen PLM Grav. Reduction (2)

**Signature Not Loaded**

Ioana Taina PLM (4)

**Reviewed and approved by:**

Matthew Davis or other approved signatory  
or Other Approved Signatory

Samples analyzed by EPA 600/R-93/116 consistent with NLR 111/98. The estimated limit of detection for non-detect samples is <0.1%. Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the US Government.

Samples analyzed by EMSL Canada Inc. Mississauga, ON NVLAP Lab Code 200877-0



EMSL ANALYTICAL, INC.  
LABORATORY • PRODUCTS • TRAINING

### Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (Lab Use Only):

551810131

Mississauga, ON L4T 1G3  
PHONE: 289-997-4602  
FAX: 289-997-4607

|   |                           |   |                                   |
|---|---------------------------|---|-----------------------------------|
| <b>Company:</b> Wood Environment & Infrastructure Solutions |                           | <b>EMSL-Bill to:</b> <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different<br>If Bill to is Different note instructions in Comments** |                                   |
| <b>Street:</b> 133 Crosbie Road                             |                           | Third Party Billing requires written authorization from third party   |                                   |
| <b>City:</b> St. John's                                     | <b>State/Province:</b> NL | <b>Zip/Postal Code:</b> A1B 4A5   | <b>Country:</b> CA                |
| <b>Report To (Name):</b> Lori Wiseman                       |                           | <b>Telephone #:</b> (709) 722-7023  |                                   |
| <b>Email Address:</b> lori.wiseman@woodplc.com              |                           | <b>Fax #:</b> (709) 722-7353  | <b>Purchase Order:</b> TF18104243 |
| <b>Project Name/Number:</b> HBMA TL Camps/TF18104243        |                           | <b>Please Provide Results:</b> <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail                         |                                   |
| <b>U.S. State Samples Taken:</b> NL                         |                           | <b>CT Samples:</b> <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt  |                                   |

**Turnaround Time (TAT) Options\* - Please Check**

3 Hour  
  6 Hour  
  24 Hour  
  48 Hour  
  72 Hour  
  96 Hour  
 1 Week  
 2 Week

\*For TEM Air 3 hr through 6 hr, please call ahead to schedule. \*There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

|   |   |   |  |
|---|---|---|--|
| <b>PLM - Bulk (reporting limit)</b>   |   | <b>TEM - Bulk</b>   |  |
| <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%)  | <input type="checkbox"/> TEM EPA NOB - EPA 600/R-93/116 Section 2.5.5.1 | <input type="checkbox"/> NY ELAP Method 198.4 (TEM)                       |  |
| <input checked="" type="checkbox"/> PLM EPA NOB (<1%), IF REQUIRED BASED ON SAMPLE                    | <input type="checkbox"/> Chatfield Protocol (semi-quantitative)         | <input type="checkbox"/> TEM % by Mass - EPA 600/R-93/116 Section 2.5.5.2 |  |
| Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)               | <input type="checkbox"/> TEM Qualitative via Filtration Prep Technique  | <input type="checkbox"/> TEM Qualitative via Drop Mount Prep Technique    |  |
| Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) | <b>Other</b>  |   |  |
| <input type="checkbox"/> NIOSH 9002 (<1%)   | <input type="checkbox"/>  |   |  |
| <input type="checkbox"/> NY ELAP Method 198.1 (friable in NY)   |   |   |  |
| <input type="checkbox"/> NY ELAP Method 198.6 NOB (non-friable-NY)                                    |   |   |  |
| <input type="checkbox"/> OSHA ID-191 Modified   |   |   |  |
| <input type="checkbox"/> Standard Addition Method   |   |   |  |

Check For Positive Stop - Clearly Identify Homogenous Group      Date Sampled: August 13, 2018

Samplers Name: Craig Taylors      Samplers Signature: *[Signature]*

| Sample #  | HA # | Sample Location                         | Material Description                      |
|-----------|------|---|---|
| PP-As1    |      | Pin Hill Pond Camp - Cabin - Wall       | Black paper on pink fibreglass insulation |
| PP-As2    |      | Pin Hill Pond Camp - Cabin - Wall       | Tar paper                                 |
| PP-As3    |      | Pin Hill Pond Camp - Cabin - Roof       | Black shingle                             |
| PP-As4    |      | Pin Hill Pond Camp - Cabin - Foundation | Concrete                                  |
| PP-As5    |      | Pin Hill Pond Camp - Cabin              | Cinder block and mortar                   |
| PP-PP-As1 |      | Pin Hill Pond Camp - Outhouse           | Black shingle and tar                     |
|           |      |   |   |
|           |      |   |   |

**Client Sample # (s):** -      **Total # of Samples:** 6

**Relinquished (Client):** Lori Wiseman      **Date:** August 27, 2018      **Time:** 9:47 a.m.

**Received (Lab):**      **Date:**      **Time:**

**Comments/Special Instructions:**  
Please advise if any samples require PLM NOB analysis  
Analyze separate layers in each sample; excluding fibreglass insulation.

**Mitchell's Pond Camp Site COAs**



# Laboratory Analysis Report

To:

**Cary Hutchinson**  
AGAT Laboratories Ltd.  
11 Morris Drive, Unit 122  
Dartmouth, Nova Scotia  
B3B 1M2

**EMC LAB REPORT NUMBER:** 67992

**Job/Project Name:**

**Job/Project No:** 18k378265

**No. of Samples:** 1

**Sample Type:** Bulk


**Date Received:** Aug 28/18

**Analysis Method(s):** Direct Microscopic Examination

**Date Analyzed:** Sep 4/18

**Date Reported:** Sep 4/18

**Analyst:** Fajun Chen, Ph.D., *Principal Mycologist*



| Client's Sample ID | Lab Sample No. | Date Sampled | Description/Location | Mould Identified, in Rank Order  | Mould Growth       |
|--------------------|----------------|--------------|----------------------|--|--------------------|
| 18k378265          | 296479         | Aug 8/18     | 9501710 – MP-MS1     | Myxomycete-like<br><i>Monodictys</i> -like<br><i>Septonema</i><br><i>Aspergillus</i> | Sparse to moderate |

**Note:**

- Mould growth is subjectively assessed with description terms sparse, moderate and abundant.
- The presence of spores (lacking other fungal structures associated) is assessed as following: a few spores (< 10 spores average per microscopic field at 400X), some spores (10 - 100 spores average per microscopic field at 400X), many spores (> 100 spores average per microscopic field at 400X).
- The presence of a few spores generally represents settled spores on the surface of the sample rather than indicating mould growth.
- The results are only related to the samples analyzed.

VP



### Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (Lab Use Only):

551810130

Mississauga, ON L4T 1G3  
PHONE: 289-997-4602  
FAX: 289-997-4607

EMSL ANALYTICAL, INC.  
LABORATORY • PRODUCTS • TRAINING

|  |                    |   |                            |
|--|--------------------|---|----------------------------|
| Company: Wood Environment & Infrastructure Solutions |                    | EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different<br><small>If Bill to is Different note instructions in Comments**</small> |                            |
| Street: 133 Crosbie Road                             |                    | Third Party Billing requires written authorization from third party   |                            |
| City: St. John's                                     | State/Province: NL | Zip/Postal Code: A1B 4A5  | Country: CA                |
| Report To (Name): Lori Wiseman                       |                    | Telephone #: (709) 722-7023   |                            |
| Email Address: lori.wiseman@woodplc.com              |                    | Fax #: (709) 722-7353   | Purchase Order: TF18104243 |
| Project Name/Number: HBMA TL Camps/TF18104243        |                    | Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail  |                            |
| U.S. State Samples Taken: NL                         |                    | CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt   |                            |

Turnaround Time (TAT) Options\* - Please Check

- 3 Hour  
  6 Hour  
  24 Hour  
  48 Hour  
  72 Hour  
  96 Hour  
 1 Week  
 2 Week

\*For TEM Air 3 hr through 6 hr, please call ahead to schedule \*\*There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT You will be asked to sign an authorization form for this service Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

PLM - Bulk (reporting limit)

- PLM EPA 600/R-93/116 (<1%)
- PLM EPA NOB (<1%), IF REQUIRED BASED ON SAMPLE  
Point Count  400 (<0.25%)  1000 (<0.1%)  
Point Count w/Gravimetric  400 (<0.25%)  1000 (<0.1%)
- NIOSH 9002 (<1%)
- NY ELAP Method 198.1 (friable in NY)
- NY ELAP Method 198.6 NOB (non-friable-NY)
- OSHA ID-191 Modified
- Standard Addition Method

TEM - Bulk

- TEM EPA NOB - EPA 600/R-93/116 Section 2.5.5.1
- NY ELAP Method 198.4 (TEM)
- Chatfield Protocol (semi-quantitative)
- TEM % by Mass - EPA 600/R-93/116 Section 2.5.5.2
- TEM Qualitative via Filtration Prep Technique
- TEM Qualitative via Drop Mount Prep Technique

Other

Check For Positive Stop - Clearly Identify Homogenous Group      Date Sampled: August 8, 2018

Samplers Name: Craig Taylor

Samplers Signature: *[Signature]*

| Sample # | HA # | Sample Location                     | Material Description       |
|----------|------|-------------------------------------|----------------------------|
| MP-AS1   |      | Mitchell's Pond Camp - Cabin - Wall | Foil with paper backing    |
| MP-AS2   |      | " " Camp - Cabin - Wall             | Black pressboard           |
| MP-AS3   |      | " " Camp - Cabin - Wall             | Tar paper                  |
| MP-AS4   |      | " " Camp - Cabin - Exterior         | Red brick                  |
| MP-AS5   |      | " " Camp - Cabin - Exterior         | Gray mortar (red brick)    |
| MP-AS6   |      | " " Camp - Cabin - Foundation       | Grey mortar (cinder block) |
| MP-AS7   |      | " " Camp - Cabin - Foundation       | Cinder block               |
| MP-AS8   |      | " " Camp - Cabin - Roof             | Black shingle and tar      |
| MP-AS9   |      | " " Camp - Cabin - chimney          | Red sealant                |
| MP-AS10  |      | " " Camp - Cabin - Exterior         | White caulking (vent)      |

Client Sample # (s): -      Total # of Samples: 11

Relinquished (Client): Lori Wiseman      Date: August 24, 2018      Time: 4:45 p.m.

Received (Lab):      Date:      Time:

Comments/Special Instructions:  
Please advise if any samples require PLM NOB analysis.

Analyze separate layers in each sample, where applicable.





**CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of  
Wood Canada Ltd.  
36 PIPPY PLACE  
St. John's, NL A1B4A5  
(709) 722-5062**

**ATTENTION TO: Lori Wiseman**

**PROJECT: TF18104543**

**AGAT WORK ORDER: 18K378265**

**SOIL ANALYSIS REVIEWED BY: Laura Baker, Inorganics Data Reporter**

**TRACE ORGANICS REVIEWED BY: Amy Hunter, Trace Organics Supervisor, B.Sc.**

**DATE REPORTED: Sep 06, 2018**

**PAGES (INCLUDING COVER): 8**

**VERSION\*: 1**

Should you require any information regarding this analysis please contact your client services representative at (709)747-8573

**\*NOTES**

**All samples will be disposed of within 30 days following analysis. Please contact the lab if you require additional sample storage time.**



# Certificate of Analysis

AGAT WORK ORDER: 18K378265

PROJECT: TF18104543

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

## Lead In Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-06

| Parameter         | Unit  | SAMPLE DESCRIPTION: |        | MP-PS1     | MP-PS2     | MP-PS3     | MP-PP-PS1  | MP-PP-PS2  |
|-------------------|-------|---------------------|--------|------------|------------|------------|------------|------------|
|                   |       | SAMPLE TYPE:        |        | Paint      | Paint      | Paint      | Paint      | Paint      |
|                   |       | DATE SAMPLED:       |        | 2018-08-08 | 2018-08-08 | 2018-08-08 | 2018-08-08 | 2018-08-08 |
|                   |       | G / S               | RDL    | 9501707    | 9501708    | 9501709    | 9501711    | 9501712    |
| Lead in Paint     | mg/kg | 15                  | 199    | 56         | 18         | 205        | <15        |            |
| Total Sample Mass | g     |                     | 0.4950 | 0.4984     | 0.5044     | 0.4943     | 0.4955     |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



# Certificate of Analysis

AGAT WORK ORDER: 18K378265

PROJECT: TF18104543

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

## Mercury Analysis in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-06

| Parameter | Unit  | SAMPLE DESCRIPTION: |      | MP-PS1     | MP-PS2     | MP-PS3     | MP-PP-PS1  | MP-PP-PS2  |
|-----------|-------|---------------------|------|------------|------------|------------|------------|------------|
|           |       | SAMPLE TYPE:        |      | Paint      | Paint      | Paint      | Paint      | Paint      |
|           |       | DATE SAMPLED:       |      | 2018-08-08 | 2018-08-08 | 2018-08-08 | 2018-08-08 | 2018-08-08 |
|           |       | G / S               | RDL  | 9501707    | 9501708    | 9501709    | 9501711    | 9501712    |
| Mercury   | mg/kg | 0.05                | 0.20 | 0.08       | <0.05      | 0.10       | <0.05      |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



# Certificate of Analysis

AGAT WORK ORDER: 18K378265

PROJECT: TF18104543

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

## Total Polychlorinated Biphenyls in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-06

| Parameter          | Unit        | SAMPLE DESCRIPTION:      |      | MP-PS1     | MP-PS2     | MP-PS3     | MP-PP-PS1  | MP-PP-PS2  |
|--------------------|-------------|--------------------------|------|------------|------------|------------|------------|------------|
|                    |             | SAMPLE TYPE:             |      | Paint      | Paint      | Paint      | Paint      | Paint      |
|                    |             | DATE SAMPLED:            |      | 2018-08-08 | 2018-08-08 | 2018-08-08 | 2018-08-08 | 2018-08-08 |
|                    |             | G / S                    | RDL  | 9501707    | 9501708    | 9501709    | 9501711    | 9501712    |
| Total PCBs         | mg/kg       | 0.5                      | <0.5 | <0.5       | <0.5       | <0.5       | <0.5       | <0.5       |
| <b>Surrogate</b>   | <b>Unit</b> | <b>Acceptable Limits</b> |      |            |            |            |            |            |
| Decachlorobiphenyl | %           | 50-130                   | 86   | 86         | 100        | 93         | 110        |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



## Quality Assurance

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of AGAT WORK ORDER: 18K378265  
 PROJECT: TF18104543 ATTENTION TO: Lori Wiseman  
 SAMPLING SITE: SAMPLED BY:

### Soil Analysis

| RPT Date: Sep 06, 2018           |       |           | DUPLICATE |        |      |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       |          | MATRIX SPIKE      |       |  |
|----------------------------------|-------|-----------|-----------|--------|------|----------------|--------------|--------------------|-------|----------|--------------------|-------|----------|-------------------|-------|--|
| PARAMETER                        | Batch | Sample Id | Dup #1    | Dup #2 | RPD  | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery | Acceptable Limits |       |  |
|                                  |       |           |           |        |      |                |              | Lower              | Upper |          | Lower              | Upper |          | Lower             | Upper |  |
| <b>Mercury Analysis in Paint</b> |       |           |           |        |      |                |              |                    |       |          |                    |       |          |                   |       |  |
| Mercury                          | 1     | 9500917   | 0.13      | 0.16   | NA   | < 0.05         | 92%          | 70%                | 130%  | NA       | 70%                | 130%  | 81%      | 70%               | 130%  |  |
| <b>Lead In Paint</b>             |       |           |           |        |      |                |              |                    |       |          |                    |       |          |                   |       |  |
| Lead in Paint                    | 1     | 9500917   | < 15      | < 15   | 0.0% | < 15           | 100%         | 70%                | 130%  | 105%     | 70%                | 130%  | 120%     | 70%               | 130%  |  |

**Certified By:**



## Quality Assurance

**CLIENT NAME:** WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of    **AGAT WORK ORDER:** 18K378265  
**PROJECT:** TF18104543    **ATTENTION TO:** Lori Wiseman  
**SAMPLING SITE:**    **SAMPLED BY:**

| Trace Organics Analysis |       |           |           |        |     |                |              |                    |       |          |                    |       |              |                   |       |
|-------------------------|-------|-----------|-----------|--------|-----|----------------|--------------|--------------------|-------|----------|--------------------|-------|--------------|-------------------|-------|
| RPT Date: Sep 06, 2018  |       |           | DUPLICATE |        |     |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       | MATRIX SPIKE |                   |       |
| PARAMETER               | Batch | Sample Id | Dup #1    | Dup #2 | RPD | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery     | Acceptable Limits |       |
|                         |       |           |           |        |     |                |              | Lower              | Upper |          | Lower              | Upper |              | Lower             | Upper |

| Total Polychlorinated Biphenyls in Paint |   |         |      |      |    |       |     |     |      |      |     |      |     |     |      |
|--|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|-----|-----|------|
| Total PCBs                               | 1 | 9500855 | <0.5 | <0.5 | NA | < 0.5 | 94% | 60% | 140% | 102% | 60% | 130% | 92% | 60% | 130% |

Comments: If Matrix spike value is NA, the spiked analyte concentration was lower than that of the matrix contribution.  
 If RPD value is NA, the results of the duplicates are less than 5x the RDL and the RPD will not be calculated.

**Certified By:**





## Method Summary

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of

AGAT WORK ORDER: 18K378265

PROJECT: TF18104543

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

| PARAMETER                      | AGAT S.O.P                       | LITERATURE REFERENCE                | ANALYTICAL TECHNIQUE |
|--------------------------------|----------------------------------|-------------------------------------|----------------------|
| <b>Soil Analysis</b>           |                                  |                                     |                      |
| Lead in Paint                  | MET-121-6105 &<br>MET-121-6103   | EPA SW 846 6020A/3050B & SM<br>3125 | ICP-MS               |
| Total Sample Mass              |                                  |                                     |                      |
| Mercury                        | INOR-121-6101 &<br>INOR-121-6107 | Based on EPA 245.5 & SM 3112B       | CV/AA                |
| <b>Trace Organics Analysis</b> |                                  |                                     |                      |
| Total PCBs                     | ORG-120-5107                     | EPA SW-846 8082                     | GC/ECD               |
| Decachlorobiphenyl             | ORG-120-5106                     | EAP SW846 3510C/8080/8010           | GC/ECD               |



Unit 1, 57 Old Pennywell Rd  
St John's, NL  
A1E 6A8  
webearth.agatlabs.com • www.agatlabs.com

AGAT Laboratories

**Chain of Custody Record**

P: 709.747.8573 • F: 709.747.2139

**Report Information**

Company: Wood E&I Solutions (formerly Amec Foster Wheeler E&I)  
Contact: Lori Wiseman  
Address: 133 CROSBIE ROAD  
ST. JOHNS, NL A1B 4A5  
Phone: 1-709-722-7023 Fax: 1-709-722-7353  
Client Project #: TF18104243  
AGAT Quotation: NALCOR ESA (MIS-016)  
Please Note: If quotation number is not provided client will be billed full price for analysis.

**Report Information (Please print):**

1. Name: Lori Wiseman  
Email: lori.wiseman@woodplc.com  
2. Name: \_\_\_\_\_  
Email: \_\_\_\_\_

**Regulatory Requirements (Check):**

List Guidelines on Report  Do not list Guidelines on Report  
 PIRI  Tier 1  Res  Pot  Coarse  
 Tier 2  Corn  N/Pot  Fine  
 Gas  Fuel  Lube  
 CCME  CDWQ  Other TDG  
 Industrial  Commercial HPA  
 Res/Park  Agricultural  FWAL  Sediment

**Invoice To**

Same Yes  / No   
Company: Wood E&I Solutions  
Contact: Sandra LeDrew and Project Manager indicated above  
Address: 133 CROSBIE ROAD  
ST. JOHNS, NL A1B 4A5  
Phone: 1-709-722-7023 Fax: 1-709-722-7353  
PO/Credit Card#: \_\_\_\_\_

**Report Format**

Single Sample per page  
 Multiple Samples per page  
 Excel Format Included

Drinking Water Sample:  Yes  No  
Reg. No.: \_\_\_\_\_

**Turnaround Time Required (TAT)**

Regular TAT  5 to 7 working days  
Rush TAT  Same day  1 day  2 days  3 days  
Date Required: \_\_\_\_\_

**Laboratory Use Only**

Arrival Condition:  Good  Poor (see notes)  
Arrival Temperature: 27.0  
Hold Time: \_\_\_\_\_  
AGAT Job Number: 18K378205

Notes: \_\_\_\_\_

| Field Filtered/Preserved | Standard Water Analysis | Metals: <input type="checkbox"/> Total <input type="checkbox"/> Diss <input type="checkbox"/> Available | Mercury                             | BOD <input type="checkbox"/> CBOD | pH | TSS <input type="checkbox"/> TDS <input type="checkbox"/> YSS | TKN | Total Phosphorus | Phenols | Tier 1: TPH/BTEX (PRI) <input type="checkbox"/> low level | Tier 2: TPH/BTEX Fractionation | CCME-CWS TPH/BTEX | VOC | THM | HAA | PAH | PCB                                 | TC + EC <input type="checkbox"/> P/A <input type="checkbox"/> MPN <input type="checkbox"/> MF | HPC <input type="checkbox"/> Pseudomonas | Fecal Coliform <input type="checkbox"/> MPN <input type="checkbox"/> MF | Other: <u>Lead - DME</u> | Hazardous (Y/N) |  |
|--------------------------|-------------------------|---|-------------------------------------|-----------------------------------|----|---|-----|------------------|---------|---|--------------------------------|-------------------|-----|-----|-----|-----|-------------------------------------|---|--|---|--------------------------|-----------------|--|
|                          |                         |   | <input checked="" type="checkbox"/> |                                   |    |   |     |                  |         |   |                                |                   |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   |                          |                 |  |
|                          |                         |   | <input checked="" type="checkbox"/> |                                   |    |   |     |                  |         |   |                                |                   |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   |                          |                 |  |
|                          |                         |   | <input checked="" type="checkbox"/> |                                   |    |   |     |                  |         |   |                                |                   |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   |                          |                 |  |
|                          |                         |   | <input checked="" type="checkbox"/> |                                   |    |   |     |                  |         |   |                                |                   |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   |                          |                 |  |
|                          |                         |   | <input checked="" type="checkbox"/> |                                   |    |   |     |                  |         |   |                                |                   |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   |                          |                 |  |
|                          |                         |   | <input checked="" type="checkbox"/> |                                   |    |   |     |                  |         |   |                                |                   |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   |                          |                 |  |
|                          |                         |   | <input checked="" type="checkbox"/> |                                   |    |   |     |                  |         |   |                                |                   |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   |                          |                 |  |
|                          |                         |   | <input checked="" type="checkbox"/> |                                   |    |   |     |                  |         |   |                                |                   |     |     |     |     | <input checked="" type="checkbox"/> |   |  |   |                          |                 |  |

**Comments - Site/Sample Info.**

Sample Containment  
Baggie  
Mitchell's Pond Camp/Cabin  
Mitchell's Pond Camp/outhouse

| Sample Identification | Date/Time Sampled   | Sample Matrix | # Containers | Sampler Received By (Print Name): | Date/Time           | Sampler Received By (Sign): |
|-----------------------|---------------------|---------------|--------------|-----------------------------------|---------------------|-----------------------------|
| <u>MP-P51</u>         | <u>Aug. 8, 2018</u> | <u>Paint</u>  | <u>1</u>     | <u>SM Murphy</u>                  | <u>Aug 27, 2018</u> | <u>SM Murphy</u>            |
| <u>MP-P52</u>         | <u>Aug 8, 2018</u>  | <u>Bulk</u>   | <u>1</u>     |                                   |                     |                             |
| <u>MP-P53</u>         | <u>Aug 8, 2018</u>  | <u>Paint</u>  | <u>1</u>     |                                   |                     |                             |
| <u>MP-PP-P51</u>      | <u>Aug 8, 2018</u>  | <u>Paint</u>  | <u>1</u>     |                                   |                     |                             |
| <u>MP-PP-P52</u>      | <u>Aug 8, 2018</u>  | <u>Paint</u>  | <u>1</u>     |                                   |                     |                             |

Sampler Relinquished By (Print Name): Lori Wiseman

Sampler Relinquished By (Sign): \_\_\_\_\_

Sampler Received By (Print Name): SM Murphy

Sampler Received By (Sign): \_\_\_\_\_

Date/Time: 1500PM

Date/Time: Aug 27, 18

Pink Copy - Client  
Yellow Copy - AGAT  
White Copy - AGAT

Page 1 of 1

No: \_\_\_\_\_



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 551810130  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

**Attn:** Lori Wiseman  
Wood Env. & Infrastructure Solutions  
PO Box 13216  
133 Crosbie Road  
Saint John's, NL A1B 4A5  
**Phone:** (709) 722-7023  
**Fax:** (709) 722-7353  
**Collected:** 8/ 8/2018  
**Received:** 8/29/2018  
**Analyzed:** 9/05/2018  
**Proj:** HBMA TL Campus/ TF18104243

## Summary Test Report for Asbestos Analysis via EPA 600/R-93/116

**Client Sample ID:** MP-AS1 **Lab Sample ID:** 551810130-0001

**Sample Description:** Mitchells Pond Camp - Cabin Wall/Foil with paper backing

| TEST | Analyzed Date | Color        | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|--------------|--------------|-------------|---------------|---------|
|      |               |              | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Brown/Silver | 50%          | 50%         | None Detected |         |

**Client Sample ID:** MP-AS2 **Lab Sample ID:** 551810130-0002

**Sample Description:** Mitchells Pond Camp - Cabin Wall/Black Pressboard

| TEST                | Analyzed Date | Color       | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------------|--------------|-------------|---------------|---------|
|                     |               |             | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black/Beige | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** MP-AS3 **Lab Sample ID:** 551810130-0003

**Sample Description:** Mitchells Pond Camp - Cabin Wall/Tar Paper

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** MP-AS4 **Lab Sample ID:** 551810130-0004

**Sample Description:** Mitchells Pond Camp - Cabin Exterior/Red Brick

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Red   | 0%           | 100%        | None Detected |         |

**Client Sample ID:** MP-AS5 **Lab Sample ID:** 551810130-0005

**Sample Description:** Mitchells Pond Camp - Cabin Exterior/Grey Mortar (Red Brick)

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** MP-AS6 **Lab Sample ID:** 551810130-0006

**Sample Description:** Mitchells Pond Camp - Cabin Foundation/Grey Mortar (Cinder Brick)

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** MP-AS7 **Lab Sample ID:** 551810130-0007

**Sample Description:** Mitchells Pond Camp - Cabin Foundation/Cinder Block

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Gray  | 0%           | 100%        | None Detected |         |



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 551810130  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

## Summary Test Report for Asbestos Analysis via EPA 600/R-93/116

**Client Sample ID:** MP-AS8 **Lab Sample ID:** 551810130-0008

**Sample Description:** Mitchells Pond Camp - Cabin Roof/Black Shingle and Tar

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** MP-AS9 **Lab Sample ID:** 551810130-0009

**Sample Description:** Mitchells Pond Camp - Cabin Chimney/Red Sealant

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Brown | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** MP-AS10 **Lab Sample ID:** 551810130-0010

**Sample Description:** Mitchells Pond Camp - Cabin Exterior/White Caulking (vent)

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos          | Comment |
|---------------------|---------------|-------|--------------|-------------|-------------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |                   |         |
| PLM Grav. Reduction | 9/05/2018     | White | 0.0%         | 100%        | <0.25% Chrysotile |         |

**Client Sample ID:** MP-PP-AS1 **Lab Sample ID:** 551810130-0011

**Sample Description:** Mitchells Pond Camp - Outhouse Roof/Shingle and Tar

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** MP-PP-AS2 **Lab Sample ID:** 551810130-0012

**Sample Description:** Mitchells Pond Camp - Outhouse Foundation/Concrete

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Gray  | 0%           | 100%        | None Detected |         |

**Analyst(s):** \_\_\_\_\_

Harman Sohi PLM (6)  
Natalie D'Amico PLM Grav. Reduction (6)

**Reviewed and approved by:**

Matthew Davis or other approved signatory  
or Other Approved Signatory

Samples analyzed by EPA 600/R-93/116 consistent with NLR 111/98. The estimated limit of detection for non-detect samples is <0.1%. Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the US Government.

Samples analyzed by EMSL Canada Inc. Mississauga, ON NVLAP Lab Code 200877-0

Initial report from: 09/05/2018 15:19:51

**Hungry Grove Camp Site COAs**

**CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of  
Wood Canada Ltd.  
36 PIPPY PLACE  
St. John's, NL A1B4A5  
(709) 722-5062**

**ATTENTION TO: Lori Wiseman**

**PROJECT: TF18104243**

**AGAT WORK ORDER: 18K378211**

**SOIL ANALYSIS REVIEWED BY: Laura Baker, Inorganics Data Reporter**

**TRACE ORGANICS REVIEWED BY: Amy Hunter, Trace Organics Supervisor, B.Sc.**

**DATE REPORTED: Sep 05, 2018**

**PAGES (INCLUDING COVER): 8**

**VERSION\*: 1**

Should you require any information regarding this analysis please contact your client services representative at (709)747-8573

**\*NOTES**

**All samples will be disposed of within 30 days following analysis. Please contact the lab if you require additional sample storage time.**

**AGAT** Laboratories (V1)

Member of: Association of Professional Engineers and Geoscientists of Alberta (APEGA)  
Western Enviro-Agricultural Laboratory Association (WEALA)  
Environmental Services Association of Alberta (ESAA)

AGAT Laboratories is accredited to ISO/IEC 17025 by the Canadian Association for Laboratory Accreditation Inc. (CALA) and/or Standards Council of Canada (SCC) for specific tests listed on the scope of accreditation. AGAT Laboratories (Mississauga) is also accredited by the Canadian Association for Laboratory Accreditation Inc. (CALA) for specific drinking water tests. Accreditations are location and parameter specific. A complete listing of parameters for each location is available from [www.cala.ca](http://www.cala.ca) and/or [www.scc.ca](http://www.scc.ca). The tests in this report may not necessarily be included in the scope of accreditation.

Page 1 of 8

*Results relate only to the items tested and to all the items tested  
All reportable information as specified by ISO 17025:2005 is available from AGAT Laboratories upon request*



# Certificate of Analysis

AGAT WORK ORDER: 18K378211

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

## Lead In Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-08-29

| Parameter         | Unit  | SAMPLE DESCRIPTION: |     |        | HG-PS1     | HG-PS2     | HG-PP-PS1  |
|-------------------|-------|---------------------|-----|--------|------------|------------|------------|
|                   |       | SAMPLE TYPE:        |     |        | Paint      | Paint      | Paint      |
|                   |       | DATE SAMPLED:       |     |        | 2018-08-07 | 2018-08-07 | 2018-08-07 |
|                   |       | G / S               | RDL |        | 9500853    | 9500854    | 9500855    |
| Lead in Paint     | mg/kg |                     | 15  | 868    | 228        | 280        |            |
| Total Sample Mass | g     |                     |     | 0.4932 | 0.5029     | 0.5019     |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**





# Certificate of Analysis

AGAT WORK ORDER: 18K378211

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

## Mercury Analysis in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-08-30

| Parameter | Unit  | SAMPLE DESCRIPTION:      |      |            |         |            |
|-----------|-------|--------------------------|------|------------|---------|------------|
|           |       | HG-PS1                   |      | HG-PS2     |         | HG-PP-PS1  |
|           |       | Paint                    |      | Paint      |         | Paint      |
|           |       | DATE SAMPLED: 2018-08-07 |      | 2018-08-07 |         | 2018-08-07 |
|           |       | G / S                    | RDL  | 9500853    | 9500854 | 9500855    |
| Mercury   | mg/kg |                          | 0.05 | 0.44       | 0.55    | 0.09       |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



## Certificate of Analysis

AGAT WORK ORDER: 18K378211

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709)747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

### Total Polychlorinated Biphenyls in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-05

| Parameter          | Unit        | SAMPLE DESCRIPTION:      |     |      | HG-PS1     | HG-PS2     | HG-PP-PS1  |
|--------------------|-------------|--------------------------|-----|------|------------|------------|------------|
|                    |             | SAMPLE TYPE:             |     |      | Paint      | Paint      | Paint      |
|                    |             | DATE SAMPLED:            |     |      | 2018-08-07 | 2018-08-07 | 2018-08-07 |
|                    |             | G / S                    | RDL |      | 9500853    | 9500854    | 9500855    |
| Total PCBs         | mg/kg       |                          | 0.5 | <0.5 | <0.5       | <0.5       |            |
| <b>Surrogate</b>   | <b>Unit</b> | <b>Acceptable Limits</b> |     |      |            |            |            |
| Decachlorobiphenyl | %           | 50-130                   |     | 89   | 104        | 97         |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**

## Quality Assurance

**CLIENT NAME:** WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of    **AGAT WORK ORDER:** 18K378211  
**PROJECT:** TF18104243    **ATTENTION TO:** Lori Wiseman  
**SAMPLING SITE:**    **SAMPLED BY:**

| Soil Analysis                    |         |           |           |        |      |                |              |                    |       |          |                    |       |              |                   |       |
|----------------------------------|---------|-----------|-----------|--------|------|----------------|--------------|--------------------|-------|----------|--------------------|-------|--------------|-------------------|-------|
| RPT Date:                        |         |           | DUPLICATE |        |      |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       | MATRIX SPIKE |                   |       |
| PARAMETER                        | Batch   | Sample Id | Dup #1    | Dup #2 | RPD  | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery     | Acceptable Limits |       |
|                                  |         |           |           |        |      |                |              | Lower              | Upper |          | Lower              | Upper |              | Lower             | Upper |
| <b>Lead In Paint</b>             |         |           |           |        |      |                |              |                    |       |          |                    |       |              |                   |       |
| Lead in Paint                    | 8292018 | 9500282   | 181       | 177    | 2.2% | < 15           | 116%         | 70%                | 130%  | 109%     | 70%                | 130%  | 95%          | 70%               | 130%  |
| <b>Mercury Analysis in Paint</b> |         |           |           |        |      |                |              |                    |       |          |                    |       |              |                   |       |
| Mercury                          | 1       | 9500917   | 0.13      | 0.16   | NA   | < 0.05         | 92%          | 70%                | 130%  | NA       | 70%                | 130%  | 81%          | 70%               | 130%  |

**Certified By:** \_\_\_\_\_



## Quality Assurance

**CLIENT NAME:** WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of **AGAT WORK ORDER:** 18K378211  
**PROJECT:** TF18104243 **ATTENTION TO:** Lori Wiseman  
**SAMPLING SITE:** **SAMPLED BY:**

| Trace Organics Analysis |       |           |           |        |     |                |              |                    |       |          |                    |       |              |                   |       |
|-------------------------|-------|-----------|-----------|--------|-----|----------------|--------------|--------------------|-------|----------|--------------------|-------|--------------|-------------------|-------|
| RPT Date:               |       |           | DUPLICATE |        |     |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       | MATRIX SPIKE |                   |       |
| PARAMETER               | Batch | Sample Id | Dup #1    | Dup #2 | RPD | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery     | Acceptable Limits |       |
|                         |       |           |           |        |     |                |              | Lower              | Upper |          | Lower              | Upper |              | Lower             | Upper |

**Total Polychlorinated Biphenyls in Paint**

|            |   |         |       |       |    |       |     |     |      |      |     |      |     |     |      |
|------------|---|---------|-------|-------|----|-------|-----|-----|------|------|-----|------|-----|-----|------|
| Total PCBs | 1 | 9500855 | < 0.5 | < 0.5 | NA | < 0.5 | 94% | 60% | 140% | 102% | 60% | 130% | 92% | 60% | 130% |
|------------|---|---------|-------|-------|----|-------|-----|-----|------|------|-----|------|-----|-----|------|

Comments: If Matrix spike value is NA, the spiked analyte concentration was lower than that of the matrix contribution.  
 If RPD value is NA, the results of the duplicates are less than 5x the RDL and the RPD will not be calculated.

**Certified By:**





## Method Summary

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of

AGAT WORK ORDER: 18K378211

PROJECT: TF18104243

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

| PARAMETER                      | AGAT S.O.P                       | LITERATURE REFERENCE                | ANALYTICAL TECHNIQUE |
|--------------------------------|----------------------------------|-------------------------------------|----------------------|
| <b>Soil Analysis</b>           |                                  |                                     |                      |
| Lead in Paint                  | MET-121-6105 &<br>MET-121-6103   | EPA SW 846 6020A/3050B & SM<br>3125 | ICP-MS               |
| Total Sample Mass              |                                  |                                     |                      |
| Mercury                        | INOR-121-6101 &<br>INOR-121-6107 | Based on EPA 245.5 & SM 3112B       | CV/AA                |
| <b>Trace Organics Analysis</b> |                                  |                                     |                      |
| Total PCBs                     | ORG-120-5107                     | EPA SW-846 8082                     | GC/ECD               |
| Decachlorobiphenyl             | ORG-120-5106                     | EAP SW846 3510C/8080/8010           | GC/ECD               |



Unit 1, 57 Old Pennywell Rd  
St John's, NL  
A1E 6A8  
webearth.agatlabs.com • www.agatlabs.com

### Chain of Custody Record

**Report Information**  
Company: Wood E&I Solutions (formerly Amec Foster Wheeler E&I)  
Contact: Lori Wiseman  
Address: 133 CROSBIE ROAD  
ST. JOHNS, NL A1B 4A5  
Phone: 1-709-722-7023 Fax: 1-709-722-7353  
Client Project #: TF18104243  
AGAT Quotation: NALCOR ESA (MIS-016)  
Please Note: If quotation number is not provided client will be billed full price for analysis.

**Invoice To** Same Yes  / No   
Company: Wood E&I Solutions  
Contact: Sandra LeDrew and Project Manager indicated above  
Address: 133 CROSBIE ROAD  
ST. JOHNS, NL A1B 4A5  
Phone: 1-709-722-7023 Fax: 1-709-722-7353  
PO/Credit Card#:

**Report Information** (Please print):  
1. Name: Lori Wiseman  
Email: lori.wiseman@wepdpc.com  
2. Name: \_\_\_\_\_  
Email: \_\_\_\_\_

**Regulatory Requirements** (Check):  
 List Guidelines on Report  Do not list Guidelines on Report  
 PIRI  
 Tier 1  Res  Pot  Coarse  
 Tier 2  Com  N/Pot  Fine  
 Gas  Fuel  Lube  
 CCME  CDWQ  Other TDG; HPA  
 Industrial  
 Commercial  
 Res/Park  
 Agricultural  
 FWAL  
 Sediment

**Report Format**  
 Single Sample per page  
 Multiple Samples per page  
 Excel Format Included

P: 709.747.8573 • F: 709.747.2139

**Laboratory Use Only**  
Arrival Condition:  Good  Poor (see notes)  
Arrival Temperature: 23.7C  
Hold Time: \_\_\_\_\_  
AGAT Job Number: 18K378211  
Notes: \_\_\_\_\_

**Turnaround Time Required (TAT)**  
**Regular TAT**  5 to 7 working days  
**Rush TAT**  Same day  1 day  2 days  3 days  
Date Required: \_\_\_\_\_

**Drinking Water Sample:**  Yes  No **Salt Water:**  Yes  No  
Reg. No.: \_\_\_\_\_

| Field Filtered/Preserved | Standard Water Analysis | Metals: <input type="checkbox"/> Total <input type="checkbox"/> Diss <input type="checkbox"/> Available | Mercury                             | BOD <input type="checkbox"/> CBOD | pH | TSS <input type="checkbox"/> TDS <input type="checkbox"/> YSS | TKN | Total Phosphorus | Phenols | Tier 1: TPH/BTEX (PRI) <input type="checkbox"/> low level | Tier 2: TPH/BTEX Fractionation | VOC | THM | HAA | PAH | PCB | TC + EC <input type="checkbox"/> P/A <input type="checkbox"/> MPN <input type="checkbox"/> MF | HPC <input type="checkbox"/> Pseudomonas | Fecal Coliform <input type="checkbox"/> MPN <input type="checkbox"/> MF | Other: <u>Lead</u> | Other: _____ | Hazardous (Y/N) <u>Potential to Contain Bot Focci.</u> |  |
|--------------------------|-------------------------|---|-------------------------------------|-----------------------------------|----|---|-----|------------------|---------|---|--------------------------------|-----|-----|-----|-----|-----|---|--|---|--------------------|--------------|--|--|
|                          |                         |   | <input checked="" type="checkbox"/> |                                   |    |   |     |                  |         |   |                                |     |     |     |     |     |   |  |   |                    |              |  |  |
|                          |                         |   | <input checked="" type="checkbox"/> |                                   |    |   |     |                  |         |   |                                |     |     |     |     |     |   |  |   |                    |              |  |  |

Samples Requisitioned By (Print Name): \_\_\_\_\_  
Date/Time: \_\_\_\_\_  
Samples Received By (Print Name): Samantha Murphy  
Date/Time: Aug 27, 2018  
Samples Requisitioned By (Sign): Lori Wiseman  
Date/Time: Aug 27, 2018  
Samples Received By (Sign): SMurphy  
Date/Time: Aug 27, 2018

Pink Copy - Client  of   
Yellow Copy - AGAT   
White Copy - AGAT



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
http://www.EMSL.com / torontolab@emsl.com

EMSL Canada Order 551810132  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

**Attn:** Lori Wiseman  
Wood Env. & Infrastructure Solutions  
PO Box 13216  
133 Crosbie Road  
Saint John's, NL A1B 4A5  
**Phone:** (709) 722-7023  
**Fax:** (709) 722-7353  
**Collected:** 8/ 7/2018  
**Received:** 8/29/2018  
**Analyzed:** 9/05/2018  
**Proj:** HBMA TL Camps/TF18104243

## Summary Test Report for Asbestos Analysis via EPA 600/R-93/116

**Client Sample ID:** HG-AS1 **Lab Sample ID:** 551810132-0001  
**Sample Description:** Hungry Grove Pond Camp - Cabin - Exterior - Brown Brick

| TEST | Analyzed Date | Color    | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|----------|--------------|-------------|---------------|---------|
|      |               |          | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Gray/Red | 0%           | 100%        | None Detected |         |

**Client Sample ID:** HG-AS2 **Lab Sample ID:** 551810132-0002  
**Sample Description:** Hungry Grove Pond Camp - Cabin - Exterior - Grey mortar (brown brick)

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** HG-AS3 **Lab Sample ID:** 551810132-0003  
**Sample Description:** Hungry Grove Pond Camp - Cabin - Exterior - White caulking (brick)

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 09/05/2018    | White | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** HG-AS4 **Lab Sample ID:** 551810132-0004  
**Sample Description:** Hungry Grove Pond Camp - Cabin - Exterior - Grey mortar (red brick)

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** HG-AS5 **Lab Sample ID:** 551810132-0005  
**Sample Description:** Hungry Grove Pond Camp - Cabin - Exterior - Red brick

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Red   | 0%           | 100%        | None Detected |         |

**Client Sample ID:** HG-AS6 **Lab Sample ID:** 551810132-0006  
**Sample Description:** Hungry Grove Pond Camp - Cabin - Foundation - Cinder block

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** HG-AS7 **Lab Sample ID:** 551810132-0007  
**Sample Description:** Hungry Grove Pond Camp - Cabin - Foundation - Grey mortar (cinder block)

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** HG-AS8 **Lab Sample ID:** 551810132-0008  
**Sample Description:** Hungry Grove Pond Camp - Cabin - Roof - Black caulking/sealant

| TEST                | Analyzed Date | Color       | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------------|--------------|-------------|---------------|---------|
|                     |               |             | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 09/05/2018    | White/Black | 0.0%         | 100%        | None Detected |         |



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
http://www.EMSL.com / torontolab@emsl.com

EMSL Canada Order 551810132  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

## Summary Test Report for Asbestos Analysis via EPA 600/R-93/116

**Client Sample ID:** HG-AS9 **Lab Sample ID:** 551810132-0009

**Sample Description:** Hungry Grove Pond Camp - Cabin - Roof - Black shingle and tar

| TEST                | Analyzed   |       | Non-Asbestos |             | Asbestos        | Comment |
|---------------------|------------|-------|--------------|-------------|-----------------|---------|
|                     | Date       | Color | Fibrous      | Non-Fibrous |                 |         |
| PLM Grav. Reduction | 09/05/2018 | Black | 0.0%         | 95.2%       | 4.8% Chrysotile |         |

**Client Sample ID:** HG-AS10 **Lab Sample ID:** 551810132-0010

**Sample Description:** Hungry Grove Pond Camp - Cabin - Chimney - Red sealant

| TEST                | Analyzed   |       | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|------------|-------|--------------|-------------|---------------|---------|
|                     | Date       | Color | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 09/05/2018 | Brown | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** HG-AS11 **Lab Sample ID:** 551810132-0011

**Sample Description:** Hungry Grove Pond Camp - Cabin - Wall - Tar paper

| TEST                | Analyzed   |             | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|------------|-------------|--------------|-------------|---------------|---------|
|                     | Date       | Color       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 09/05/2018 | Brown/Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** HG-AS12 **Lab Sample ID:** 551810132-0012

**Sample Description:** Hungry Grove Pond Camp - Cabin - Wall - Black pressboard

| TEST                | Analyzed   |             | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|------------|-------------|--------------|-------------|---------------|---------|
|                     | Date       | Color       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 09/05/2018 | Brown/Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** HG-AS13 **Lab Sample ID:** 551810132-0013

**Sample Description:** Hungry Grove Pond Camp - Cabin - Wall - Tar paper

| TEST                | Analyzed   |       | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|------------|-------|--------------|-------------|---------------|---------|
|                     | Date       | Color | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 09/05/2018 | Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** HG-PP-AS1 **Lab Sample ID:** 551810132-0014

**Sample Description:** Hungry Grove Pond Camp - Outhouse-Foundation - Concrete

| TEST | Analyzed   |       | Non-Asbestos |             | Asbestos      | Comment |
|------|------------|-------|--------------|-------------|---------------|---------|
|      | Date       | Color | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018 | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** HG-PP-AS2 **Lab Sample ID:** 551810132-0015

**Sample Description:** Hungry Grove Pond Camp - Outhouse-Roof - Black shingle and tar

| TEST                | Analyzed   |       | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|------------|-------|--------------|-------------|---------------|---------|
|                     | Date       | Color | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 09/05/2018 | Black | 0.0%         | 100%        | None Detected |         |





# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
http://www.EMSL.com / torontolab@emsl.com

EMSL Canada Order 551810132  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

**Attn:** Lori Wiseman  
Wood Env. & Infrastructure Solutions  
PO Box 13216  
133 Crosbie Road  
Saint John's, NL A1B 4A5  
**Phone:** (709) 722-7023  
**Fax:** (709) 722-7353  
**Collected:** 8/ 7/2018  
**Received:** 8/29/2018  
**Analyzed:** 9/05/2018  
**Proj:** HBMA TL Camps/TF18104243

The samples in this report were submitted for asbestos bulk analysis. The reference number for these samples is the Order ID above. Please use this reference number when calling about these samples.

Sample Receipt Date: 08/29/2018      Sample Receipt Time: 10:56 am  
Analysis Completed Date: 09/05/2018      Analysis Completed Time: 3:16 pm

**Analyst(s):**

**Signature Not Loaded**

Caroline Allen PLM Grav. Reduction (8)

**Signature Not Loaded**

Harman Sohi PLM (7)

**Reviewed and approved by:**

Matthew Davis or other approved signatory  
or Other Approved Signatory

Samples analyzed by EPA 600/R-93/116 consistent with NLR 111/98. The estimated limit of detection for non-detect samples is <0.1%. Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the US Government.

Samples analyzed by EMSL Canada Inc. Mississauga, ON NVLAP Lab Code 200877-0

VP



EMSL ANALYTICAL, INC.  
LABORATORY PRODUCTS TRAINING

### Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (Lab Use Only):

551810132

Mississauga, ON L4T 1G3  
PHONE: 289-997-4602  
FAX: 289-997-4607

|  |                    |  |                            |
|--|--------------------|--|----------------------------|
| Company: Wood Environment & Infrastructure Solutions |                    | EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different<br>If Bill to is Different note instructions in Comments** |                            |
| Street: 133 Crosbie Road                             |                    | Third Party Billing requires written authorization from third party  |                            |
| City: St. John's                                     | State/Province: NL | Zip/Postal Code: A1B 4A5   | Country: CA                |
| Report To (Name): Lori Wiseman                       |                    | Telephone #: (709) 722-7023  |                            |
| Email Address: lori.wiseman@woodplc.com              |                    | Fax #: (709) 722-7353  | Purchase Order: TF18104243 |
| Project Name/Number: HBMA TL Camps/TF18104243        |                    | Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail                         |                            |
| U.S. State Samples Taken: NL                         |                    | CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt  |                            |

Turnaround Time (TAT) Options\* - Please Check

3 Hour  
  6 Hour  
  24 Hour  
  48 Hour  
  72 Hour  
  96 Hour  
 1 Week  
 2 Week

\*For TEM Air 3 hr through 6 hr, please call ahead to schedule. \*There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

|   |   |  |  |
|---|---|--|--|
| <b>PLM - Bulk (reporting limit)</b>   |   | <b>TEM - Bulk</b>  |  |
| <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%)  | <input type="checkbox"/> TEM EPA NOB - EPA 600/R-93/116 Section 2.5.5.1   | <input type="checkbox"/> NY ELAP Method 198.4 (TEM)                    | <input type="checkbox"/> Chatfield Protocol (semi-quantitative)        |
| <input checked="" type="checkbox"/> PLM EPA NOB (<1%), IF REQUIRED BASED ON SAMPLE                    | <input type="checkbox"/> TEM % by Mass - EPA 600/R-93/116 Section 2.5.5.2 | <input type="checkbox"/> TEM Qualitative via Filtration Prep Technique | <input type="checkbox"/> TEM Qualitative via Drop Mount Prep Technique |
| Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)               |   | <b>Other</b>   |  |
| Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) |   | <input type="checkbox"/>   |  |
| <input type="checkbox"/> NIOSH 9002 (<1%)   |   |  |  |
| <input type="checkbox"/> NY ELAP Method 198.1 (friable in NY)   |   |  |  |
| <input type="checkbox"/> NY ELAP Method 198.6 NOB (non-friable-NY)                                    |   |  |  |
| <input type="checkbox"/> OSHA ID-191 Modified   |   |  |  |
| <input type="checkbox"/> Standard Addition Method   |   |  |  |

Check For Positive Stop - Clearly Identify Homogenous Group      Date Sampled: August 7, 2018

Samplers Name: Craig Taylor      Samplers Signature:

| Sample # | HA # | Sample Location                           | Material Description       |
|----------|------|---|----------------------------|
| HG-AS1   |      | Hungry Grove Pond Camp - Cabin - Exterior | Brown brick                |
| HG-AS2   |      | " " " Camp - Cabin - Exterior             | Grey mortar (brown brick)  |
| HG-AS3   |      | " " " Camp - Cabin - Exterior             | White caulking (brick)     |
| HG-AS4   |      | " " " Camp - Cabin - Exterior             | Grey mortar (red brick)    |
| HG-AS5   |      | " " " Camp - Cabin - Exterior             | Red brick                  |
| HG-AS6   |      | " " " Camp - Cabin - Foundation           | Cinder block               |
| HG-AS7   |      | " " " Camp - Cabin - Foundation           | Grey mortar (cinder block) |
| HG-AS8   |      | " " " Camp - Cabin - Roof                 | Black caulking/sealant     |
| HG-AS9   |      | " " " Camp - Cabin - Roof                 | Black shingle and tar      |
| HG-AS10  |      | " " " Camp - Cabin - Chimney              | Red sealant                |

Client Sample # (s): -      Total # of Samples: 15

Relinquished (Client): Lori Wiseman      Date: August 24, 2018      Time: 4:30 p.m.

Received (Lab):      Date:      Time:

Comments/Special Instructions:  
Please advise if any samples require PLM NOB analysis.

FDX 7730 7600 1020 VP



**Camp 100 Site COAs**

**CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of  
Wood Canada Ltd.  
36 PIPPY PLACE  
St. John's, NL A1B4A5  
(709) 722-5062**

**ATTENTION TO: Lori Wiseman**

**PROJECT: TF18104243**

**AGAT WORK ORDER: 18K378248**

**SOIL ANALYSIS REVIEWED BY: Laura Baker, Inorganics Data Reporter**

**TRACE ORGANICS REVIEWED BY: Amy Hunter, Trace Organics Supervisor, B.Sc.**

**DATE REPORTED: Sep 05, 2018**

**PAGES (INCLUDING COVER): 8**

**VERSION\*: 1**

Should you require any information regarding this analysis please contact your client services representative at (709)747-8573

**\*NOTES**

**All samples will be disposed of within 30 days following analysis. Please contact the lab if you require additional sample storage time.**



# Certificate of Analysis

AGAT WORK ORDER: 18K378248

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

## Lead In Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-08-30

| Parameter         | Unit  | SAMPLE DESCRIPTION: |        | C100-PS1   | C100-PS2   | C100-PP-PS1 | C100-PP-PS2 |
|-------------------|-------|---------------------|--------|------------|------------|-------------|-------------|
|                   |       | SAMPLE TYPE:        |        | Other      | Other      | Other       | Other       |
|                   |       | DATE SAMPLED:       |        | 2018-08-08 | 2018-08-08 | 2018-08-08  | 2018-08-08  |
|                   |       | G / S               | RDL    | 9501275    | 9501280    | 9501281     | 9501282     |
| Lead in Paint     | mg/kg | 15                  | 489    | 17         | 101        | 22          |             |
| Total Sample Mass | g     |                     | 0.4999 | 0.4985     | 0.4955     | 0.4980      |             |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



# Certificate of Analysis

AGAT WORK ORDER: 18K378248

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

## Mercury Analysis in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-08-30

| Parameter     | Unit  | SAMPLE DESCRIPTION: |            | C100-PS1   | C100-PS2   | C100-PP-PS1 | C100-PP-PS2 |
|---------------|-------|---------------------|------------|------------|------------|-------------|-------------|
|               |       | G / S               | RDL        | Other      | Other      | Other       | Other       |
| DATE SAMPLED: |       | 2018-08-08          | 2018-08-08 | 2018-08-08 | 2018-08-08 | 2018-08-08  | 2018-08-08  |
| Mercury       | mg/kg | 0.05                | 0.52       | 3.83       | 0.21       | 1.08        |             |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



## Certificate of Analysis

AGAT WORK ORDER: 18K378248

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

### Total Polychlorinated Biphenyls in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-05

| Parameter          | Unit  | SAMPLE DESCRIPTION: |      | C100-PS1 | C100-PS2 | C100-PP-PS1 | C100-PP-PS2 |
|--------------------|-------|---------------------|------|----------|----------|-------------|-------------|
|                    |       | G / S               | RDL  | 9501275  | 9501280  | 9501281     | 9501282     |
| Total PCBs         | mg/kg | 0.5                 | <0.5 | <0.5     | <0.5     | <0.5        | <0.5        |
| Surrogate          | Unit  | Acceptable Limits   |      |          |          |             |             |
| Decachlorobiphenyl | %     | 50-130              | 110  | 95       | 105      | 94          |             |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



## Quality Assurance

**CLIENT NAME:** WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of **AGAT WORK ORDER:** 18K378248  
**PROJECT:** TF18104243 **ATTENTION TO:** Lori Wiseman  
**SAMPLING SITE:** **SAMPLED BY:**

| Soil Analysis                    |       |           |           |        |      |                |              |                    |       |          |                    |       |              |                   |       |
|----------------------------------|-------|-----------|-----------|--------|------|----------------|--------------|--------------------|-------|----------|--------------------|-------|--------------|-------------------|-------|
| RPT Date:                        |       |           | DUPLICATE |        |      |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       | MATRIX SPIKE |                   |       |
| PARAMETER                        | Batch | Sample Id | Dup #1    | Dup #2 | RPD  | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery     | Acceptable Limits |       |
|                                  |       |           |           |        |      |                |              | Lower              | Upper |          | Lower              | Upper |              | Lower             | Upper |
| <b>Lead In Paint</b>             |       |           |           |        |      |                |              |                    |       |          |                    |       |              |                   |       |
| Lead in Paint                    | 1     | 9500917   | < 15      | < 15   | 0.0% | < 15           | 100%         | 70%                | 130%  | 105%     | 70%                | 130%  | 120%         | 70%               | 130%  |
| <b>Mercury Analysis in Paint</b> |       |           |           |        |      |                |              |                    |       |          |                    |       |              |                   |       |
| Mercury                          | 1     | 9500917   | 0.13      | 0.16   | NA   | < 0.05         | 92%          | 70%                | 130%  | NA       | 70%                | 130%  | 81%          | 70%               | 130%  |

**Certified By:** \_\_\_\_\_



## Quality Assurance

**CLIENT NAME:** WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of **AGAT WORK ORDER:** 18K378248  
**PROJECT:** TF18104243 **ATTENTION TO:** Lori Wiseman  
**SAMPLING SITE:** **SAMPLED BY:**

| Trace Organics Analysis |       |           |           |        |     |                |              |                    |       |          |                    |       |              |                   |       |
|-------------------------|-------|-----------|-----------|--------|-----|----------------|--------------|--------------------|-------|----------|--------------------|-------|--------------|-------------------|-------|
| RPT Date:               |       |           | DUPLICATE |        |     |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       | MATRIX SPIKE |                   |       |
| PARAMETER               | Batch | Sample Id | Dup #1    | Dup #2 | RPD | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery     | Acceptable Limits |       |
|                         |       |           |           |        |     |                |              | Lower              | Upper |          | Lower              | Upper |              | Lower             | Upper |

**Total Polychlorinated Biphenyls in Paint**

|            |   |         |      |      |    |       |     |     |      |      |     |      |     |     |      |
|------------|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|-----|-----|------|
| Total PCBs | 1 | 9500855 | <0.5 | <0.5 | NA | < 0.5 | 94% | 60% | 140% | 102% | 60% | 130% | 92% | 60% | 130% |
|------------|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|-----|-----|------|

Comments: If Matrix spike value is NA, the spiked analyte concentration was lower than that of the matrix contribution.  
 If RPD value is NA, the results of the duplicates are less than 5x the RDL and the RPD will not be calculated.

**Certified By:**





## Method Summary

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of

AGAT WORK ORDER: 18K378248

PROJECT: TF18104243

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

| PARAMETER                      | AGAT S.O.P                       | LITERATURE REFERENCE                | ANALYTICAL TECHNIQUE |
|--------------------------------|----------------------------------|-------------------------------------|----------------------|
| <b>Soil Analysis</b>           |                                  |                                     |                      |
| Lead in Paint                  | MET-121-6105 &<br>MET-121-6103   | EPA SW 846 6020A/3050B & SM<br>3125 | ICP-MS               |
| Total Sample Mass              |                                  |                                     |                      |
| Mercury                        | INOR-121-6101 &<br>INOR-121-6107 | Based on EPA 245.5 & SM 3112B       | CV/AA                |
| <b>Trace Organics Analysis</b> |                                  |                                     |                      |
| Total PCBs                     | ORG-120-5107                     | EPA SW-846 8082                     | GC/ECD               |
| Decachlorobiphenyl             | ORG-120-5106                     | EAP SW846 3510C/8080/8010           | GC/ECD               |



# Laboratories

Unit 1, 57 Old Pennywell Rd  
St John's, NL  
A1E 6A8  
webearth.agatlabs.com • www.agatlabs.com

## Chain of Custody Record

P: 709.747.8573 • F: 709.747.2139

**Report Information**  
Company: Wood E&I Solutions (formerly Amec Foster Wheeler E&I)  
Contact: Lori Wiseman  
Address: 133 CROSBIE ROAD  
ST. JOHNS, NL A1B 4A5  
Phone: 1-709-722-7023 Fax: 1-709-722-7353  
Client Project #: TF18104243  
AGAT Quotation: NALCOR ESA (MIS-016)  
Please Note: If quotation number is not provided client will be billed full price for analysis.

**Report Information (Please print):**  
1. Name: Lori Wiseman  
Email: lori.wiseman@woodplc.com  
2. Name: \_\_\_\_\_  
Email: \_\_\_\_\_

**Regulatory Requirements (Check):**  
 List Guidelines on Report  Do not list Guidelines on Report  
 PIRI  Tier 1  Res  Pot  Coarse  
 Tier 2  Com  N/Pot  Fine  
 Gas  Fuel  Lube  
 CCME  CDWQ  Other TDG; HPA

**Laboratory Use Only**  
Arrival Condition:  Good  Poor (see notes)  
Arrival Temperature: 22.4  
Hold Time: \_\_\_\_\_  
AGAT Job Number: 185378248  
Notes: \_\_\_\_\_

**Turnaround Time Required (TAT)**  
Regular TAT  5 to 7 working days  
Rush TAT  Same day  1 day  
 2 days  3 days  
Date Required: \_\_\_\_\_

Drinking Water Sample:  Yes  No  
Salt Water:  Yes  No  
Reg. No.: \_\_\_\_\_

**Invoice To** Same Yes  / No   
Company: Wood E&I Solutions  
Contact: Sandra LeDrew and Project Manager indicated above  
Address: 133 CROSBIE ROAD  
ST. JOHNS, NL A1B 4A5  
Phone: 1-709-722-7023 Fax: 1-709-722-7353  
PO/Credit Card#: \_\_\_\_\_

| Sample Identification | Date/Time Sampled | Sample Matrix | # Containers | Comments - Site/Sample Info, Sample Containment | Field Filtered/Preserved | Standard Water Analysis | Metals: <input type="checkbox"/> Total <input type="checkbox"/> Diss <input type="checkbox"/> Available | Mercury | BOD <input type="checkbox"/> CBOD | pH | TSS <input type="checkbox"/> TDS <input type="checkbox"/> YSS | TKN | Total Phosphorus | Phenols | Tier 1: TPH/BTEX (PRI) <input type="checkbox"/> low level | Tier 2: TPH/BTEX Fractionation | CMC-CWS TPH/BTEX | VOC | THM | HAA | PAH | PCB | TC + EC <input type="checkbox"/> P/A <input type="checkbox"/> MPN <input type="checkbox"/> MF | HPC <input type="checkbox"/> Pseudomonas | Fecal Coliform <input type="checkbox"/> MPN <input type="checkbox"/> MF | Other: <u>Lead</u> | Other: | Hazardous (Y/N) |
|-----------------------|-------------------|---------------|--------------|---|--------------------------|-------------------------|---|---------|-----------------------------------|----|---|-----|------------------|---------|---|--------------------------------|------------------|-----|-----|-----|-----|-----|---|--|---|--------------------|--------|-----------------|
| C100-PS1              | Aug. 8, 2018      | Paint         | Baggie       | Camp 100/Cabin                                  |                          |                         |   | X       |                                   |    |   |     |                  |         |   |                                |                  |     |     |     | X   |     |   |  |   |                    |        |                 |
| C100-PS2              |                   |               |              | Camp 100/Cabin                                  |                          |                         |   | X       |                                   |    |   |     |                  |         |   |                                |                  |     |     |     | X   |     |   |  |   |                    |        |                 |
| C100-PP-PS1           |                   |               |              | Camp 100/outhouse                               |                          |                         |   | X       |                                   |    |   |     |                  |         |   |                                |                  |     |     |     | X   |     |   |  |   |                    |        |                 |
| C100-PP-PS2           |                   |               |              | Camp 100/Outhouse                               |                          |                         |   | X       |                                   |    |   |     |                  |         |   |                                |                  |     |     |     | X   |     |   |  |   |                    |        |                 |

Samples Requisitioned By: (Print Name): Lori Wiseman  
Date/Time: Aug. 27, 2018  
Signature: \_\_\_\_\_  
Samples Requisitioned By (Sgn): \_\_\_\_\_

Samples Received By (Print Name): SM Murphy  
Date/Time: Aug 27, 2018  
Signature: \_\_\_\_\_  
Samples Received By (Sgn): \_\_\_\_\_

White Copy - AGAT No: \_\_\_\_\_  
Yellow Copy - AGAT No: \_\_\_\_\_  
Pink Copy - Client No: \_\_\_\_\_

Date/Time: 1500m  
Date/Time: Aug 27, 2018

Page 1 of 1



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
http://www.EMSL.com / torontolab@emsl.com

EMSL Canada Order 551810133  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

**Attn:** Lori Wiseman  
Wood Env. & Infrastructure Solutions  
PO Box 13216  
133 Crosbie Road  
Saint John's, NL A1B 4A5  
**Phone:** (709) 722-7023  
**Fax:** (709) 722-7353  
**Collected:** 8/ 8/2018  
**Received:** 8/29/2018  
**Analyzed:** 9/05/2018  
**Proj:** HBMA TL Camps/TF18104243

## Summary Test Report for Asbestos Analysis via EPA 600/R-93/116

**Client Sample ID:** C100-AS1 **Lab Sample ID:** 551810133-0001  
**Sample Description:** Camp 100 - Cabin - Wall - Grey mortar (brown brick)

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** C100-AS2 **Lab Sample ID:** 551810133-0002  
**Sample Description:** Camp 100 - Cabin - Wall - Brown brick

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Red   | 0%           | 100%        | None Detected |         |

**Client Sample ID:** C100-AS3 **Lab Sample ID:** 551810133-0003  
**Sample Description:** Camp 100 - Cabin - Wall - Grey mortar (red brick)

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** C100-AS4 **Lab Sample ID:** 551810133-0004  
**Sample Description:** Camp 100 - Cabin - Wall - Red brick

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Red   | 0%           | 100%        | None Detected |         |

**Client Sample ID:** C100-AS5 **Lab Sample ID:** 551810133-0005  
**Sample Description:** Camp 100 - Cabin - Wall - Tar paper

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos         | Comment |
|---------------------|---------------|-------|--------------|-------------|------------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |                  |         |
| PLM Grav. Reduction | 09/05/2018    | Black | 0.0%         | 78.8%       | 21.2% Chrysotile |         |

**Client Sample ID:** C100-AS6 **Lab Sample ID:** 551810133-0006  
**Sample Description:** Camp 100 - Cabin - Wall - Black pressboard

| TEST                | Analyzed Date | Color     | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-----------|--------------|-------------|---------------|---------|
|                     |               |           | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 09/05/2018    | Tan/Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** C100-PP-AS1 **Lab Sample ID:** 551810133-0007  
**Sample Description:** Camp 100 - Outhouse - Roof - Black felt and tar

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos        | Comment |
|---------------------|---------------|-------|--------------|-------------|-----------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |                 |         |
| PLM Grav. Reduction | 09/05/2018    | Black | 0.0%         | 98.9%       | 1.1% Chrysotile |         |

**Client Sample ID:** C100-PP-AS2 **Lab Sample ID:** 551810133-0008  
**Sample Description:** Camp 100 - Outhouse - Foundation - Concrete

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 09/04/2018    | Gray  | 0%           | 100%        | None Detected |         |



**EMSL Canada Inc.**

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
http://www.EMSL.com / torontolab@emsl.com

EMSL Canada Order 551810133  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

**Attn:** Lori Wiseman  
Wood Env. & Infrastructure Solutions  
PO Box 13216  
133 Crosbie Road  
Saint John's, NL A1B 4A5  
**Phone:** (709) 722-7023  
**Fax:** (709) 722-7353  
**Collected:** 8/ 8/2018  
**Received:** 8/29/2018  
**Analyzed:** 9/05/2018  
**Proj:** HBMA TL Camps/TF18104243

The samples in this report were submitted for asbestos bulk analysis. The reference number for these samples is the Order ID above. Please use this reference number when calling about these samples.

Sample Receipt Date: 08/29/2018      Sample Receipt Time: 10:55 am  
Analysis Completed Date: 09/05/2018      Analysis Completed Time: 3:51 pm

**Analyst(s):**

**Signature Not Loaded**

Caroline Allen PLM Grav. Reduction (3)

**Signature Not Loaded**

Harman Sohi PLM (5)

**Reviewed and approved by:**

Matthew Davis or other approved signatory  
or Other Approved Signatory

Samples analyzed by EPA 600/R-93/116 consistent with NLR 111/98. The estimated limit of detection for non-detect samples is <0.1%. Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the US Government.

Samples analyzed by EMSL Canada Inc. Mississauga, ON NVLAP Lab Code 200877-0



### Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (Lab Use Only):

551810133

Mississauga, ON L4T 1G3  
PHONE: 289-997-4602  
FAX: 289-997-4607

EMSL ANALYTICAL, INC.  
LABORATORY PRODUCTS TRADING

|   |                    |   |                            |
|---|--------------------|---|----------------------------|
| Company : Wood Environment & Infrastructure Solutions |                    | EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different<br><small>If Bill to is Different note instructions in Comments**</small> |                            |
| Street: 133 Crosbie Road                              |                    | <i>Third Party Billing requires written authorization from third party</i>  |                            |
| City: St. John's                                      | State/Province: NL | Zip/Postal Code: A1B 4A5  | Country: CA                |
| Report To (Name): Lori Wiseman                        |                    | Telephone #: (709) 722-7023   |                            |
| Email Address: lori.wiseman@woodplc.com               |                    | Fax #: (709) 722-7353   | Purchase Order: TF18104243 |
| Project Name/Number: HBMA TL Camps/TF18104243         |                    | Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail  |                            |
| U.S. State Samples Taken: NL                          |                    | CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt   |                            |

**Turnaround Time (TAT) Options\* - Please Check**

3 Hour   
  6 Hour   
  24 Hour   
  48 Hour   
  72 Hour   
  96 Hour   
 1 Week   
 2 Week

\*For TEM Air 3 hr through 6 hr, please call ahead to schedule. \*There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

| PLM - Bulk (reporting limit)  | TEM - Bulk  |
|---|---|
| <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%)  | <input type="checkbox"/> TEM EPA NOB - EPA 600/R-93/116 Section 2.5.5.1   |
| <input checked="" type="checkbox"/> PLM EPA NOB (<1%), IF REQUIRED BASED ON SAMPLE                    | <input type="checkbox"/> NY ELAP Method 198.4 (TEM)                       |
| Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)               | <input type="checkbox"/> Chatfield Protocol (semi-quantitative)           |
| Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) | <input type="checkbox"/> TEM % by Mass - EPA 600/R-93/116 Section 2.5.5.2 |
| <input type="checkbox"/> NIOSH 9002 (<1%)   | <input type="checkbox"/> TEM Qualitative via Filtration Prep Technique    |
| <input type="checkbox"/> NY ELAP Method 198.1 (friable in NY)   | <input type="checkbox"/> TEM Qualitative via Drop Mount Prep Technique    |
| <input type="checkbox"/> NY ELAP Method 198.6 NOB (non-friable-NY)                                    | <b>Other</b>  |
| <input type="checkbox"/> OSHA ID-191 Modified   | <input type="checkbox"/>  |
| <input type="checkbox"/> Standard Addition Method   |   |

Check For Positive Stop - Clearly Identify Homogenous Group      Date Sampled: August 8, 2018

Samplers Name: Craig Taylor      Samplers Signature: *[Signature]*

| Sample #    | HA # | Sample Location                   | Material Description      |
|-------------|------|-----------------------------------|---------------------------|
| C100-A51    |      | Camp 100 - Cabin - Wall           | Grey mortar (brown brick) |
| C100-A52    |      | Camp 100 - Cabin - Wall           | Brown brick               |
| C100-A53    |      | Camp 100 - Cabin - Wall           | Grey mortar (red brick)   |
| C100-A54    |      | Camp 100 - Cabin - Wall           | Red brick                 |
| C100-A55    |      | Camp 100 - Cabin - Wall           | Tar paper                 |
| C100-A56    |      | Camp 100 - Cabin - Wall           | Black pressboard          |
| C100-PP-A51 |      | Camp 100 - Outhouse - Roof        | Black felt and tar        |
| C100-PP-A52 |      | Camp 100 - Out house - Foundation | Concrete                  |

|  |   |
|--|---|
| Client Sample # (s):   | Total # of Samples: <u>8</u>                      |
| Relinquished (Client): <u>Lori Wiseman</u>   | Date: <u>August 27, 2018</u> Time: <u>9:35a.m</u> |
| Received (Lab):  | Date:      Time:                                  |
| Comments/Special Instructions:<br><small>Please advise if any samples require PLM NOB analysis.</small><br><u>Analyze all layers in each sample, where applicable.</u> |   |

**Medonnegonik Lake Camp Site COAs**



# Laboratory Analysis Report

To:

**Cary Hutchinson**  
AGAT Laboratories Ltd.  
11 Morris Drive, Unit 122  
Dartmouth, Nova Scotia  
B3B 1M2

**EMC LAB REPORT NUMBER:** 67993  
**Job/Project Name:**  
**Job/Project No:** 18k378258    **No. of Samples:** 1  
**Sample Type:** Tape Lift    **Date Received:** Aug 29/18  
**Analysis Method(s):** Direct Microscopic Examination  
**Date Analyzed:** Sep 4/18    **Date Reported:** Sep 4/18  
**Analyst:** Weizhong Liu, Ph.D., *Mycologist*  
**Approved By:** Fajun Chen, Ph.D., *Principal Mycologist*



| Client's Sample ID | Lab Sample No. | Date Sampled | Description/Location | Mould Identified, in Rank Order          | Mould Growth |
|--------------------|----------------|--------------|----------------------|--|--------------|
| 18k378258          | 296480         | Aug 7/18     | 9501342 – MDX-MS1    | <i>Cladosporium</i><br><i>Acremonium</i> | Sparse       |

**Note:**

- Mould growth is subjectively assessed with description terms sparse, moderate and abundant.
- The presence of spores (lacking other fungal structures associated) is assessed as following: a few spores (< 10 spores average per microscopic field at 400X), some spores (10 - 100 spores average per microscopic field at 400X), many spores (> 100 spores average per microscopic field at 400X).
- The presence of a few spores generally represents settled spores on the surface of the sample rather than indicating mould growth.
- The results are only related to the samples analyzed.



EMSL ANALYTICAL, INC.  
LABORATORY PRODUCTS TRAINING

### Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (Lab Use Only):

551810148

Mississauga, ON L4T 1G3  
PHONE: 289-997-4602  
FAX: 289-997-4607

|  |                    |  |                            |
|--|--------------------|--|----------------------------|
| Company: Wood Environment & Infrastructure Solutions |                    | EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different<br>If Bill to is Different note instructions in Comments** |                            |
| Street: 133 Crosbie Road                             |                    | Third Party Billing requires written authorization from third party  |                            |
| City: St. John's                                     | State/Province: NL | Zip/Postal Code: A1B 4A5   | Country: CA                |
| Report To (Name): Lori Wiseman                       |                    | Telephone #: (709) 722-7023  |                            |
| Email Address: lori.wiseman@woodpic.com              |                    | Fax #: (709) 722-7353  | Purchase Order: TF18104243 |
| Project Name/Number: HBMA TL Camps/TF18104243        |                    | Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail                         |                            |
| U.S. State Samples Taken: NL                         |                    | CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt  |                            |

**Turnaround Time (TAT) Options\* - Please Check**

3 Hour   
  6 Hour   
  24 Hour   
  48 Hour   
  72 Hour   
  96 Hour   
 1 Week   
 2 Week

\*For TEM Air 3 hr through 6 hr, please call ahead to schedule. \*There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

| PLM - Bulk (reporting limit)  | TEM - Bulk  |
|---|---|
| <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%)  | <input type="checkbox"/> TEM EPA NOB - EPA 600/R-93/116 Section 2.5.5.1   |
| <input checked="" type="checkbox"/> PLM EPA NOB (<1%), IF REQUIRED BASED ON SAMPLE                    | <input type="checkbox"/> NY ELAP Method 198.4 (TEM)                       |
| Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)               | <input type="checkbox"/> Chatfield Protocol (semi-quantitative)           |
| Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) | <input type="checkbox"/> TEM % by Mass - EPA 600/R-93/116 Section 2.5.5.2 |
| <input type="checkbox"/> NIOSH 9002 (<1%)   | <input type="checkbox"/> TEM Qualitative via Filtration Prep Technique    |
| <input type="checkbox"/> NY ELAP Method 198.1 (friable in NY)   | <input type="checkbox"/> TEM Qualitative via Drop Mount Prep Technique    |
| <input type="checkbox"/> NY ELAP Method 198.6 NOB (non-friable-NY)                                    | <b>Other</b>  |
| <input type="checkbox"/> OSHA ID-191 Modified   | <input type="checkbox"/>  |
| <input type="checkbox"/> Standard Addition Method   |   |

Check For Positive Stop - Clearly Identify Homogenous Group      Date Sampled: August 7, 2018

Samplers Name: Craig Taylor      Samplers Signature: *[Signature]*

| Sample # | HA # | Sample Location                  | Material Description                      |
|----------|------|----------------------------------|---|
| MDX-AS1  |      | Medonnegonik Camp - Cabin - Wall | Black paper on pink fibreglass insulation |
| MDX-AS2  |      | " Camp - Cabin - Wall            | Black presboard and tar paper             |
| MDX-AS3  |      | " Camp - Cabin - Exterior        | Grey mortar (red brick)                   |
| MDX-AS4  |      | " Camp - Cabin - Exterior        | Red brick                                 |
| MDX-AS5  |      | " Camp - Cabin - Foundation      | Cinder block                              |
| MDX-AS6  |      | " Camp - Cabin - Foundation      | Grey mortar (cinder block)                |
| MDX-AS7  |      | " Camp - Cabin - Exterior        | White caulking (brick)                    |
| MDX-AS8  |      | " Camp - Cabin - Exterior        | Brown brick                               |
| MDX-AS9  |      | " Camp - Cabin - Exterior        | Grey mortar (brown brick)                 |
| MDX-AS10 |      | " Camp - Cabin - Roof            | Black shingle and tar                     |

Client Sample # (s): -      Total # of Samples: 12

Relinquished (Client): Lori Wiseman      Date: August 24, 2018      Time: 4:00p.m.

Received (Lab):      Date:      Time:

Comments/Special Instructions:  
Please advise if any samples require PLM NOB analysis.

Analyze separate layers in each sample; excluding fibreglass insulation.



**CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of  
Wood Canada Ltd.  
36 PIPPY PLACE  
St. John's, NL A1B4A5  
(709) 722-5062**

**ATTENTION TO: Lori Wiseman**

**PROJECT: TF18104243**

**AGAT WORK ORDER: 18K378258**

**SOIL ANALYSIS REVIEWED BY: Jason Coughtrey, Inorganics Supervisor**

**TRACE ORGANICS REVIEWED BY: Amy Hunter, Trace Organics Supervisor, B.Sc.**

**DATE REPORTED: Sep 10, 2018**

**PAGES (INCLUDING COVER): 9**

**VERSION\*: 1**

Should you require any information regarding this analysis please contact your client services representative at (709)747-8573

**\*NOTES**

**All samples will be disposed of within 30 days following analysis. Please contact the lab if you require additional sample storage time.**



# Certificate of Analysis

AGAT WORK ORDER: 18K378258

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

## Lead In Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-10

| Parameter         | Unit  | SAMPLE DESCRIPTION: |        | MDX-PS1    | MDX-PS2    | MDX-PS3    | MDX-PP-PS1 |
|-------------------|-------|---------------------|--------|------------|------------|------------|------------|
|                   |       | SAMPLE TYPE:        |        | Paint      | Paint      | Paint      | Paint      |
|                   |       | DATE SAMPLED:       |        | 2018-08-07 | 2018-08-07 | 2018-08-07 | 2018-08-07 |
|                   |       | G / S               | RDL    | 9501337    | 9501339    | 9501340    | 9501341    |
| Lead in Paint     | mg/kg | 15                  | 185    | 1110       | 725        | 109        |            |
| Total Sample Mass | g     |                     | 0.5058 | 0.4947     | 0.5003     | 0.5084     |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



# Certificate of Analysis

AGAT WORK ORDER: 18K378258

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
St. John's, NL  
CANADA A1E 6A8  
TEL (709)747-8573  
FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

## Mercury Analysis in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-10

| Parameter | Unit  | SAMPLE DESCRIPTION: |      | MDX-PS1    | MDX-PS2    | MDX-PS3    | MDX-PP-PS1 |
|-----------|-------|---------------------|------|------------|------------|------------|------------|
|           |       | SAMPLE TYPE:        |      | Paint      | Paint      | Paint      | Paint      |
|           |       | DATE SAMPLED:       |      | 2018-08-07 | 2018-08-07 | 2018-08-07 | 2018-08-07 |
|           |       | G / S               | RDL  | 9501337    | 9501339    | 9501340    | 9501341    |
| Mercury   | mg/kg | 0.05                | 7.87 | 0.14       | 1.42       | 0.06       |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**



## Certificate of Analysis

AGAT WORK ORDER: 18K378258

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
 St. John's, NL  
 CANADA A1E 6A8  
 TEL (709)747-8573  
 FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

### O. Reg. 558 - SVOCs

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-10

SAMPLE DESCRIPTION: MDX-PT1  
 SAMPLE TYPE: Wood  
 DATE SAMPLED: 2018-08-07

| Parameter          | Unit | G / S             | RDL   | 9501343 |
|--------------------|------|-------------------|-------|---------|
| Cresols            | mg/L |                   | 0.012 | <0.012  |
| Ortho-Cresol       | mg/L |                   | 0.004 | <0.004  |
| Meta & Para-Cresol | mg/L |                   | 0.008 | <0.008  |
| Benzo(a)pyrene     | mg/L |                   | 0.001 | <0.001  |
| Surrogate          | Unit | Acceptable Limits |       |         |
| Chrysene-d12       | %    | 50-130            |       | 69      |

**Comments:** RDL - Reported Detection Limit; G / S - Guideline / Standard

**9501343** Due to insufficient sample volume, the Toxicity Characteristic Leaching Procedure (TCLP) was completed using a sample mass which did not meet the prescriptive, minimum sample requirements to perform the TCLP as specified in the reference method (EPA Method 1311) as mandated under R.R.O. 1990, Reg. 347: GENERAL - WASTE MANAGEMENT under Environmental Protection Act, R.S.O. 1990, c. E.19

**Certified By:**



## Certificate of Analysis

AGAT WORK ORDER: 18K378258

PROJECT: TF18104243

57 Old Pennywell Road, Unit I  
 St. John's, NL  
 CANADA A1E 6A8  
 TEL (709)747-8573  
 FAX (709) 747-2139  
<http://www.agatlabs.com>

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of Wood Canada Ltd.

ATTENTION TO: Lori Wiseman

SAMPLING SITE:

SAMPLED BY:

### Total Polychlorinated Biphenyls in Paint

DATE RECEIVED: 2018-08-27

DATE REPORTED: 2018-09-10

| Parameter          | Unit        | SAMPLE DESCRIPTION:      |      | MDX-PS1    | MDX-PS2    | MDX-PS3    | MDX-PP-PS1 |
|--------------------|-------------|--------------------------|------|------------|------------|------------|------------|
|                    |             | SAMPLE TYPE:             |      | Paint      | Paint      | Paint      | Paint      |
|                    |             | DATE SAMPLED:            |      | 2018-08-07 | 2018-08-07 | 2018-08-07 | 2018-08-07 |
|                    |             | G / S                    | RDL  | 9501337    | 9501339    | 9501340    | 9501341    |
| Total PCBs         | mg/kg       | 0.5                      | <0.5 | <0.5       | <0.5       | <0.5       | <0.5       |
| <b>Surrogate</b>   | <b>Unit</b> | <b>Acceptable Limits</b> |      |            |            |            |            |
| Decachlorobiphenyl | %           | 50-130                   | 101  | 105        | 113        | 123        |            |

Comments: RDL - Reported Detection Limit; G / S - Guideline / Standard

**Certified By:**





## Quality Assurance

CLIENT NAME: WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of AGAT WORK ORDER: 18K378258  
 PROJECT: TF18104243 ATTENTION TO: Lori Wiseman  
 SAMPLING SITE: SAMPLED BY:

### Soil Analysis

| RPT Date: Sep 10, 2018           |       |           | DUPLICATE |        |      |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       | MATRIX SPIKE |                   |       |
|----------------------------------|-------|-----------|-----------|--------|------|----------------|--------------|--------------------|-------|----------|--------------------|-------|--------------|-------------------|-------|
| PARAMETER                        | Batch | Sample Id | Dup #1    | Dup #2 | RPD  | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery     | Acceptable Limits |       |
|                                  |       |           |           |        |      |                |              | Lower              | Upper |          | Lower              | Upper |              | Lower             | Upper |
| <b>Mercury Analysis in Paint</b> |       |           |           |        |      |                |              |                    |       |          |                    |       |              |                   |       |
| Mercury                          | 1     | 9501339   | 0.14      | 0.15   | NA   | < 0.05         | 93%          | 70%                | 130%  |          | 70%                | 130%  | 95%          | 70%               | 130%  |
| <b>Lead In Paint</b>             |       |           |           |        |      |                |              |                    |       |          |                    |       |              |                   |       |
| Lead in Paint                    | 1     | 9500917   | < 15      | < 15   | 0.0% | < 15           | 100%         | 70%                | 130%  | 105%     | 70%                | 130%  | 120%         | 70%               | 130%  |

**Certified By:**

## Quality Assurance

**CLIENT NAME:** WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of **AGAT WORK ORDER:** 18K378258  
**PROJECT:** TF18104243 **ATTENTION TO:** Lori Wiseman  
**SAMPLING SITE:** **SAMPLED BY:**

### Trace Organics Analysis

| RPT Date: Sep 10, 2018 |       |           | DUPLICATE |        |     |                | Method Blank | REFERENCE MATERIAL |       |          | METHOD BLANK SPIKE |       |          | MATRIX SPIKE      |       |  |
|------------------------|-------|-----------|-----------|--------|-----|----------------|--------------|--------------------|-------|----------|--------------------|-------|----------|-------------------|-------|--|
| PARAMETER              | Batch | Sample Id | Dup #1    | Dup #2 | RPD | Measured Value |              | Acceptable Limits  |       | Recovery | Acceptable Limits  |       | Recovery | Acceptable Limits |       |  |
|                        |       |           |           |        |     |                |              | Lower              | Upper |          | Lower              | Upper |          | Lower             | Upper |  |

**Total Polychlorinated Biphenyls in Paint**

|            |   |         |      |      |    |       |     |     |      |      |     |      |      |     |      |
|------------|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|------|-----|------|
| Total PCBs | 1 | 9500914 | <0.5 | <0.5 | NA | < 0.5 | 98% | 60% | 140% | 100% | 60% | 130% | 112% | 60% | 130% |
|------------|---|---------|------|------|----|-------|-----|-----|------|------|-----|------|------|-----|------|

Comments: If Matrix spike value is NA, the spiked analyte concentration was lower than that of the matrix contribution.  
 If RPD value is NA, the results of the duplicates are less than 5x the RDL and the RPD will not be calculated.

**O. Reg. 558 - SVOCs**

|                    |    |         |         |    |         |     |     |      |     |     |      |    |     |      |
|--------------------|----|---------|---------|----|---------|-----|-----|------|-----|-----|------|----|-----|------|
| Cresols            | TW | < 0.012 | < 0.012 | NA | < 0.012 | 89% | 60% | 130% | 87% | 35% | 110% | NA | 30% | 130% |
| Ortho-Cresol       | TW | < 0.004 | < 0.004 | NA | < 0.004 | 87% | 50% | 130% | 76% | 50% | 130% | NA | 50% | 130% |
| Meta & Para-Cresol | TW | < 0.008 | < 0.008 | NA | < 0.008 | 81% | 50% | 130% | 94% | 50% | 130% | NA | 50% | 130% |
| Benzo(a)pyrene     | TW | < 0.001 | < 0.001 | NA | < 0.001 | 87% | 60% | 130% | 99% | 60% | 130% | NA | 60% | 130% |

Comments: When the average of the sample and duplicate results is less than 5x the RDL, the Relative Percent Difference (RPD) will be indicated as Not Applicable (NA).

**Certified By:**





## Method Summary

**CLIENT NAME:** WOOD ENVIRONMENT & INFRASTRUCTURE SOLUTIONS, a div. of **AGAT WORK ORDER:** 18K378258  
**PROJECT:** TF18104243 **ATTENTION TO:** Lori Wiseman  
**SAMPLING SITE:** **SAMPLED BY:**

| PARAMETER                      | AGAT S.O.P                       | LITERATURE REFERENCE                | ANALYTICAL TECHNIQUE |
|--------------------------------|----------------------------------|-------------------------------------|----------------------|
| <b>Soil Analysis</b>           |                                  |                                     |                      |
| Lead in Paint                  | MET-121-6105 &<br>MET-121-6103   | EPA SW 846 6020A/3050B & SM<br>3125 | ICP-MS               |
| Total Sample Mass              |                                  |                                     |                      |
| Mercury                        | INOR-121-6101 &<br>INOR-121-6107 | Based on EPA 245.5 & SM 3112B       | CV/AA                |
| <b>Trace Organics Analysis</b> |                                  |                                     |                      |
| Cresols                        | ORG-91-5114                      | EPA SW846 3510C & 8270              | GC/MS                |
| Ortho-Cresol                   | ORG-91-5114                      | EPA SW846 3510C & 8270              | GC/MS                |
| Meta & Para-Cresol             | ORG-91-5114                      | EPA SW846 3510C & 8270              | GC/MS                |
| Benzo(a)pyrene                 | ORG-91-5114                      | EPA SW846 3510C & 8270              | GC/MS                |
| Chrysene-d12                   | ORG-91-5114                      | EPA SW846 3510C & 8270              | GC/MS                |
| Total PCBs                     | ORG-120-5107                     | EPA SW-846 8082                     | GC/ECD               |
| Decachlorobiphenyl             | ORG-120-5106                     | EAP SW846 3510C/8080/8010           | GC/ECD               |



# AGAT Laboratories

Unit 1, 57 Old Pennywell Rd  
St. John's, NL  
A1E 6A8  
webearth.agatlabs.com • www.agatlabs.com

## Chain of Custody Record

**Report Information**

Company: Wood E&I Solutions (formerly Amec Foster Wheeler E&I)  
 Contact: Lori Wiseman  
 Address: 133 CROSBIE ROAD  
 ST. JOHNS, NL A1B 4A5  
 Phone: 1-709-722-7023 Fax: 1-709-722-7353  
 Client Project #: TF18104243  
 AGAT Quotation: NALCOR ESA (MIS-016)  
 Please Note: If quotation number is not provided client will be billed full price for analysis.

**Report Information** (Please print):

1. Name: Lori Wiseman  
 Email: lori.wiseman@woodplc.com

2. Name: \_\_\_\_\_  
 Email: \_\_\_\_\_

**Regulatory Requirements (Check):**

List Guidelines on Report  Do not list Guidelines on Report

PIRI  Tier 1  Res  Pot  Coarse  
 Tier 2  Com  N/Pot  Fine  
 Gas  Fuel  Lube

CCME  CDWQ  Other TDG, HPA

**Report Format**

Single Sample per page  
 Multiple Samples per page  
 Excel Format Included

**Invoice To** Same Yes  / No

Company: Wood E&I Solutions  
 Contact: Sandra LeDrew and Project Manager indicated above  
 Address: 133 CROSBIE ROAD  
 ST. JOHNS, NL A1B 4A5  
 Phone: 1-709-722-7023 Fax: 1-709-722-7353  
 PO/Credit Card#: \_\_\_\_\_

**Laboratory Use Only**

Arrival Condition:  Good  Poor (see notes)  
 Arrival Temperature: 25.4  
 Hold Time: \_\_\_\_\_  
 AGAT Job Number: 18K378258

Notes: \_\_\_\_\_

**Turnaround Time Required (TAT)**

Regular TAT  5 to 7 working days  
 Rush TAT  Same day  1 day  
 2 days  3 days

Date Required: \_\_\_\_\_

Drinking Water Sample:  Yes  No Salt Water:  Yes  No

| Sample Identification | Date/Time Sampled | Sample Matrix | # Containers | Comments - Site/Sample Info. Sample Containment | Field Filtered/Preserved | Standard Water Analysis | Metals: <input type="checkbox"/> Total <input type="checkbox"/> Diss <input type="checkbox"/> Available | Mercury | BOD <input type="checkbox"/> CBOD | TSS <input type="checkbox"/> TDS <input type="checkbox"/> VSS | Treated Wood - Inorganic | Treated Wood - Chlorophyll | Total Phosphorus | Tier 1: TPH/BTEX (PRI) <input type="checkbox"/> low level | Tier 2: TPH/BTEX Fractionation | CCME-CWS TPH/BTEX | VOC | THM | HAA | PAH | PCB | TC + EC <input type="checkbox"/> P/A <input type="checkbox"/> MPN <input type="checkbox"/> MF | HPC <input type="checkbox"/> Pseudomonas | Fecal Coliform <input type="checkbox"/> MPN <input type="checkbox"/> MF | Other: <u>Lead</u> | Other: <u>World - DME</u> | Hazardous (Y/N) |
|-----------------------|-------------------|---------------|--------------|---|--------------------------|-------------------------|---|---------|-----------------------------------|---|--------------------------|----------------------------|------------------|---|--------------------------------|-------------------|-----|-----|-----|-----|-----|---|--|---|--------------------|---------------------------|-----------------|
| MDX - P51             | Aug. 7, 2018      | Paint         | Beggie       | Medonsgonik Camp/Cabin                          |                          |                         |   | X       |                                   |   |                          |                            |                  |   |                                |                   |     |     |     | X   | X   |   |  |   |                    |                           |                 |
| MDX - P52             |                   |               |              |   |                          |                         |   | X       |                                   |   |                          |                            |                  |   |                                |                   |     |     |     | X   | X   |   |  |   |                    |                           |                 |
| MDX - P53             |                   |               |              |   |                          |                         |   | X       |                                   |   |                          |                            |                  |   |                                |                   |     |     |     | X   | X   |   |  |   |                    |                           |                 |
| MDX - PP-P51          |                   |               |              |   |                          |                         |   | X       |                                   |   |                          |                            |                  |   |                                |                   |     |     |     | X   | X   |   |  |   |                    |                           |                 |
| MDX - M51             |                   | Bulk          |              | Medonsgonik Camp/Cabin                          |                          |                         |   | X       |                                   |   |                          |                            |                  |   |                                |                   |     |     |     | X   | X   |   |  |   |                    |                           |                 |
| MDX - P.T.1           |                   | Weed          |              | Medonsgonik Camp/Hill-fed                       |                          |                         |   | X       |                                   |   |                          |                            |                  |   |                                |                   |     |     |     | X   | X   |   |  |   |                    |                           |                 |

Sample Relinquished By: (Print Name): Lori Wiseman Date/Time: Aug. 27, 2018

Sample Relinquished By: (Sign): [Signature] Date/Time: Aug 27, 2018

Sample Received By: (Print Name): \_\_\_\_\_ Date/Time: \_\_\_\_\_

Sample Received By: (Sign): \_\_\_\_\_ Date/Time: \_\_\_\_\_

Pink Copy - Client \_\_\_\_\_ Page 1 of 1

Yellow Copy - AGAT \_\_\_\_\_

White Copy - AGAT \_\_\_\_\_ No: \_\_\_\_\_



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 551810148  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

**Attn:** Lori Wiseman  
Wood Env. & Infrastructure Solutions  
PO Box 13216  
133 Crosbie Road  
Saint John's, NL A1B 4A5  
**Phone:** (709) 722-7023  
**Fax:** (709) 722-7353  
**Collected:** 8/ 7/2018  
**Received:** 8/29/2018  
**Analyzed:** 9/05/2018  
**Proj:** HBMA TL Camps/TF18104243

## Summary Test Report for Asbestos Analysis via EPA 600/R-93/116

**Client Sample ID:** MDX-AS1 **Lab Sample ID:** 551810148-0001

**Sample Description:** Medonnegonik Camp - Cabin - Wall/Black Paper on Pink Fibreglass Insulation

| TEST | Analyzed Date | Color       | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------------|--------------|-------------|---------------|---------|
|      |               |             | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Black/Beige | 85%          | 15%         | None Detected |         |

**Client Sample ID:** MDX-AS2 **Lab Sample ID:** 551810148-0002

**Sample Description:** Medonnegonik Camp - Cabin - Wall/Black Pressboard and Tar Paper

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** MDX-AS3 **Lab Sample ID:** 551810148-0003

**Sample Description:** Medonnegonik Camp - Cabin - Exterior/Grey Mortar (Red Brick)

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** MDX-AS4 **Lab Sample ID:** 551810148-0004

**Sample Description:** Medonnegonik Camp - Cabin - Exterior/Red Brick

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Red   | 0%           | 100%        | None Detected |         |

**Client Sample ID:** MDX-AS5 **Lab Sample ID:** 551810148-0005

**Sample Description:** Medonnegonik Camp - Cabin - Foundation/Cinder Block

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** MDX-AS6 **Lab Sample ID:** 551810148-0006

**Sample Description:** Medonnegonik Camp - Cabin - Foundation/Grey Mortar (Cinder Block)

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** MDX-AS7 **Lab Sample ID:** 551810148-0007

**Sample Description:** Medonnegonik Camp - Cabin - Exterior/White Caulking (Brick)

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Gray  | 0.0%         | 100%        | None Detected |         |



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 551810148  
Customer ID: 55MEEN26  
Customer PO: TF18104243  
Project ID:

## Summary Test Report for Asbestos Analysis via EPA 600/R-93/116

**Client Sample ID:** MDX-AS8 **Lab Sample ID:** 551810148-0008

**Sample Description:** Medonnegonik Camp - Cabin - Exterior/Brown Brick

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Brown | 0%           | 100%        | None Detected |         |

**Client Sample ID:** MDX-AS9 **Lab Sample ID:** 551810148-0009

**Sample Description:** Medonnegonik Camp - Cabin - Exterior/Grey Mortar (Brown Brick)

| TEST | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
|      |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM  | 9/05/2018     | Gray  | 0%           | 100%        | None Detected |         |

**Client Sample ID:** MDX-AS10 **Lab Sample ID:** 551810148-0010

**Sample Description:** Medonnegonik Camp - Cabin - Roof/Black Shingle and Tar

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** MDX-AS11 **Lab Sample ID:** 551810148-0011

**Sample Description:** Medonnegonik Camp - Cabin - Roof/Green/Black Shingle and Tar

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos      | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |               |         |
| PLM Grav. Reduction | 9/05/2018     | Black | 0.0%         | 100%        | None Detected |         |

**Client Sample ID:** MDX-PP-AS1 **Lab Sample ID:** 551810148-0012

**Sample Description:** Medonnegonik Camp - Outhouse - Roof/Black Shingle and Tar

| TEST                | Analyzed Date | Color | Non-Asbestos |             | Asbestos         | Comment |
|---------------------|---------------|-------|--------------|-------------|------------------|---------|
|                     |               |       | Fibrous      | Non-Fibrous |                  |         |
| PLM Grav. Reduction | 9/05/2018     | Black | 0.0%         | 99.2%       | 0.79% Chrysotile |         |

### Analyst(s):

Caroline Allen PLM (7)  
Natalie D'Amico PLM Grav. Reduction (5)

### Reviewed and approved by:

Matthew Davis or other approved signatory  
or Other Approved Signatory

Samples analyzed by EPA 600/R-93/116 consistent with NLR 111/98. The estimated limit of detection for non-detect samples is <0.1%. Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the US Government.

Samples analyzed by EMSL Canada Inc. Mississauga, ON NVLAP Lab Code 200877-0

Initial report from: 09/05/2018 15:01:19

**APPENDIX B8**

**REPORT LIMITATIONS**

## **LIMITATIONS**

1. The work performed in the preparation of this report and the conclusions presented are subject to the following:
  - (a) The Standard Terms and Conditions which form a part of our Contract;
  - (b) The Scope of Services;
  - (c) Time and Budgetary limitations as described in our Contract; and,
  - (d) The Limitations stated herein.
2. No other warranties or representations, either expressed or implied, are made as to the professional services provided under the terms of our Contract, or the conclusions presented.
3. The conclusions presented in this report were based, in part, on visual observations of the site and attendant structures. Our conclusions cannot and are not extended to include those portions of the site or structures which were not reasonably available, in Wood's opinion, for direct observation.
4. The environmental conditions at the site were assessed, within the limitations set out above, having due regard for applicable environmental regulations as of the date of the inspection. A review of compliance by past owners or occupants of the site with any applicable local, provincial or federal by-laws, orders-in-council, legislative enactments and regulations was not performed.
5. Where testing was performed it was carried out in accordance with the terms of our contract providing for testing. Other substances, or different quantities of substances testing for, might be present on site and be revealed by different or other testing not provided for in our contract.
6. The findings within this report do not reflect potential ACMs in areas not accessed, such as remote space areas, roof areas, wall cavities and ceilings spaces. During future renovations or demolition activities and subsequent removal of interior wall and ceiling materials, the actual quantities of asbestos containing materials can be verified. Also, at this time, analysis of suspect ACM materials may be required if the appearance differs from that of materials previously confirmed to contain asbestos in adjacent rooms.
7. Because of the limitations referred to above, different environmental conditions from those stated in our report might exist. Should such different conditions be encountered, Wood must be notified in order that it may determine if modifications to the conclusions in the report are necessary.
8. The utilization of Wood's services during the implementation of any remedial measures will allow Wood to observe compliance with the conclusions and recommendations contained in the report. Wood's involvement will also allow for changes to be made as necessary to suit field conditions as they are encountered.
9. This report is for the sole use of the party to whom it is addressed unless expressly stated otherwise in the report or contract. Any use which any third party makes of the report, in whole or the part, or any reliance thereon or decisions made based on any information or conclusions in the report, is the sole responsibility of such third party. Wood accepts no responsibility whatsoever for damages or loss of any nature or kind suffered by any such third party as a result of actions taken or not taken or decisions made in reliance on the report or anything set out therein.
10. This report is not to be given over to any third party for any purpose whatsoever without the written permission of Wood.