

Camp 1

Type of Structure	Concrete blocks and Wood frame.
Type of Foundation	Wood Beams on Concrete and Concrete blocks.
Exterior	Metal Siding.
Roofing Material	Asphalt Shingles.
Interior Finishes	Painted plywood on walls, ceiling and floor.
Lighting	Incandescent light on interior and exterior.
Heating	Previously Oil.
Outhouse	plywood construction.

Hazardous Materials Summary

Asbestos containing materials (ACM)	6 samples collected during HBMA. Laboratory testing determined that ACM was not present.
	samples included building insulation, roofing shingle/tar and concrete block/mortar.
	There may be other hidden or inaccessible ACM not identified during the assessment. If encountered, these materials should be treated as ACM or tested to verify content.
Paint Additives	9 samples collected during the HBMA and tested for lead, mercury and PCB.
	Lead in Paint: concentrations ranged from 36 mg/kg to 319 mg/kg.
	**Red paint on door, window covers and outhouse not sampled. Similar paint at other sites tested above 5000 mg/kg.
	Mercury in Paint: concentrations ranged from non-detect to 1.8 mg/kg.
	PCB in Paint: laboratory results were non detect.
	Paint samples collected during the assessment are likely not leachable and can be disposed of at an approved facility pending appropriate approvals with the exception of red paint noted above.
Ozone Depleting Substances and Halocarbons	1 freezer containing R12 refrigerant is present at the site.
Urea Formaldehyd Foam Insulation (UFFI)	Visual indicators suggest that UFFI were not present at the site.
Suspected Visible Mould Growth (SVG)	No SVG was noted during the assessment.
Potential Lead Solder and Piping	Lead solder is likely present in plumbing and piping in the accomodations cabin.
Mercury-Containing Thermostats	No thermostats were identified during the assessment.
PCB Light Ballasts	Lighting is incandescent and no florescent lights/ballasts were identified.
Treated Wood Products	Treated wood was not identified during the assessment.
Silica Containing Materials	Silica is expceted to be present in concrete and possibly asphalt shingles.
Potential Radioactive Containing Materials	None identified